

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
1	misc ca. 1970 fault data	07/06/70	William R. Dickenson	Comentary and Reconnaissance Photogeologic Map, San Andreas Rift Belt
	misc ca. 1975 fault data			
		06/15/75	Jon C. Cummings, Town Geologist	Memorandum to Olive Mayer re: Fault Traces
		08/01/75	Ken Kodama	An Investigation of a Fault Trace in Woodside, California by the VLP Electromagnetic Technique
		09/23/75	Thomas H. Moses, Mayor	Letter to George Gunias re: "Areas 39" report
		09/26/75	Jon C. Cummings, Town Geologist	Memorandum to Robert Myers, Town Manager re: review of "Areas 39" report.
		10/07/75	Thomas H. Moses, Mayor	Letter to George Gunias re: transmitting Town Geologist's report on "Areas 39" report
		11/03/75	George Gunias	Letter to Thomas H. Moses, Mayor re: 9/23/75 letter
		11/07/75	George Gunias	Letter to Thomas H. Moses, Mayor re: 10/7/75 letter
		02/09/76	George Gunias	Letter to Thomas H. Moses, Mayor re: response to Town Geologist's 6/15/75 Memorandum and 9/26/75/review of "Areas 39" report
no	Geology and Geologic Hazards	05/29/05	Jon C. Cummings, Town Geologist	Geology and Geologic Hazards report fo the Town
1	Geologic Map	01/07/88	William Cotton and Associates	Geologic Map Revisions/Supplemental Geologic Hazard Mapping
1	ALAMEDA DE LAS PULGAS			
	2452 Alameda de las Pilgas	08/07/06	Earth Investigations Consultants	Geotechnical Investigation, proposed Residential Addition
1	ALBION AVENUE			
	129 Albion Avenue	09/24/86	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed-Story Garage
	139 Albion Avenue	04/08/02	Nielsen Geotechnical Incorporated	Soil Report
		11/22/04	Murray Engineers Inc	New Engineer of Record, Residence Improvements
	179 Albion Avenue	09/19/94	Michelucci & Associates, Inc.	Geotechnical Investigation, Planned Improvements
		12/15/00	Nielsen Geotechnical Incorporated	Soil Report
		02/15/01	Nielsen Geotechnical Incorporated	Soil Report
		06/23/05	Murray Engineers, Inc.	New Engineer of Record and Woodside Comment List, Gorden Residence
		04/18/08	Murray Engineers, Inc.	Supplemental Recommendations, New Swimming Pool
		05/18/11	Murray Engineers, Inc.	Supplemental Drilled Pier Foundation Design Criteria, Gordon Swimming Pool
		05/27/11	Murray Engineers, Inc.	Supplemental Recommendations, Gordon Pool Equipment Vault
		08/03/11	Murray Engineers, Inc.	Geotechnical Plan Review, Gordon Pool Spa & Equipment Vault
	196 Albion Avenue	07/03/79	J. Michael Cleary and Associates	Percolation Investigation, Residence
		07/08/79	J. Michael Cleary and Associates	Geotechnical Investigation, Proposed Home
		07/23/79	Walker & Moody Architects	Site Plan, with annotations
		07/26/79	William Cotton and Associates	Geotechnical Review Sheet
		07/27/79	William Cotton and Associates	Schreiber - Geotechnical Review
	219 Albion Avenue	09/06/00	Bay Area Geotechnical Group	Geotechnical Consultation, Proposed Additions, Quist Residence
	222 Albion Avenue	07/10/09	Murray Engineers, Inc.	Geotechnical Investigation, Werbe Residence
		01/19/10	Murray Engineers, Inc.	Supplemental Driveway Recommendations, Werbe Residence
		02/01/10	Murray Engineers, Inc.	Supplemental Spa Recommendations, Werbe Residence
		04/12/11	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Site Retaining Wall, Werbe Residence
	250 Albion Avenue	09/15/03	Nielsen Geotechnical Incorporated	Soil Report, Coast Oak Maintenance Facility & Greenhouse
		10/20/10	Murray Engineers, Inc.	Geotechnical Investigation, Covered Equipment Storage Shed
		01/27/06	Town	Aerial Photographs
		10/14/10	Murray Engineers, Inc.	Geotechnical Investigation, Residence Addition
	278 Albion Avenue	03/21/97	Michelucci & Associates, Inc.	Geotechnical Investigation, Planned Improvements
		03/29/05	Michelucci & Associates, Inc.	Geotechnical Investigation, Planned New Building
		05/11/09	Murray Engineers, Inc.	Geotechnical Investigation, Burgess Residence Improvements
		05/15/09	Murray Engineers, Inc.	Supplemental Information Regarding 35% or Greater Slopes, Burges Property
	Fleishaker Estate Subdivision	06/13/79	Cooper & Clark	Soil Investigation, Proposed Residential Lots and Earth Dam, Fleishaker Property
	329, 331, and 333 Albion Avenue	10/27/80	William Cotton and Associates	Geotechnical Review Sheet
		01/29/81	William Cotton and Associates	Geologic Review, Fleishacker Subdivision #139
		03/09/81	William Cotton and Associates	Geologic Review, Fleishacker Subdivision #139
		11/16/81	Cooper & Clark	Site Geologic Evaluation, proposed Residential Subdivision, Fleisacker Property
		12/02/81	William Cotton and Associates	Review of Slope Stability Analyses for Proposed Residential Lots and Earth Dam, Fleishacker Property
		12/07/81	William Cotton and Associates	Review
		01/05/82	William Cotton and Associates	Geologic Review, Fleishacker Subdivision #139
		01/05/82	William Cotton and Associates	Response to letter dated 1/18/82 from D. Ramer
		03/26/82	Brian Kangas Foulk & Associates	Tentative Map, Fleishacker Estates Subdivision
		03/30/82	Cooper & Clark	Consultation - Responses to Town Geologist's Review Comments on Soil Investigation dated 11/16/81
		0/0/82	County of San Mateo, Department of Public Health & Welfare	SD #139 (Fleishacker) Tentative Map Revised 4/12/82
		04/12/82	William Cotton and Associates	Geologic Review

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		05/11/82	Brian Kangas Fouk & Associates	Estimated Cut and Fill Quantities - Fleishacker Estate Subdivision
		06/01/82	Brian Kangas Fouk & Associates	Inundation Map - Fleishacker Reservoir
		06/08/82	Dames & Moore	Third Party Review of Dam Embankment Analysis, Fleishacker Property
		07/12/82	R. I. Whaley, Town Engineer	Review of Tentative Map and Supporting Data, Fleishacker Estates Subdivision
		07/23/10	William Cotton and Associates	Geologic Review
	329 Albion Avenue	03/01/00	Nielsen Geotechnical Incorporated	Soil Report
		02/08/02	Nielsen Geotechnical Incorporated	Construction Report, Swimming Pool
	331 Albion Avenue	02/28/06	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Residential Remodel and Addition
	354 Albion Avenue	07/24/90	JCP Geologists - Engineers	Additional Soil and Foundation Study, Proposed New Location of Residence, Barn and Swimming Pool
		12/05/90	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence
			William Cotton and Associates	Geotechnical Review Sheet
		12/31/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Fagin, PA #8136
		04/24/91	William Cotton and Associates	Supplemental Geotechnical Review, Fagin, PA #8136-R
		12/04/91	William Cotton and Associates	Supplemental Geotechnical Review, Fagin, PA #8136-R
1	418 Albion Avenue	08/23/94	Clearly Consultants, Inc.	Soil and Geologic Investigation for Living Room Expansion
1A	499 Albion Avenue	07/25/00	Clearly Consultants, Inc.	Geotechnical Investigation, Perry Farm
		11/14/00	Clearly Consultants, Inc.	Evaluation of Leachfield Stadiility
		08/02/01	Clearly Consultants, Inc.	Supplemental Soil Engineering Recommendations and Plan Review Letter, Perry Farm
		10/17/00	Clearly Consultants, Inc.	Review of Revised Architectural Plans
		08/21/02	Clearly Consultants, Inc.	Soil Engineering Obsrvation and Testing Services During Construction, Accessory Buildings A, B, C
		11/20/03	Clearly Consultants, Inc.	Geotechnical Investigation, Lower Garden Improvements
		09/15/07	Clearly Consultants, Inc.	Evaluation of Natural Slope Gradient, Lower Garden Retaining Wall Improvements
	500 Albion Avenue	12/05/80	PSC Associates, Inc.	Soil Engineering Investigation, Proposed House Addition
		10/08/93	Earth Investigations Consultants	Geotechnical Evaluation, Proposed Additions to Existing House
	545 Albion Avenue	05/15/85	PSC Associates, Inc.	Geotechnical Engineering Investigation, Single-Family Residence
		08/14/90	AC&H - Civil Engineers	Topographic Plan with annotations
			William Cotton and Associates	Geotechnical Review Sheet
		09/20/91	William Cotton and Associates	Geologic and Geotechnical Review, Douglas Residence, PA-8501
		09/25/10	Raleigh and Associates	Comment on Seismic Design
		04/29/02	GeoForensics Inc.	Geotechnical Investigation, Proposed Residential Additions, Gessow Property
	550 Albion Avenue	10/31/05	Romig Engineers, Inc.	Geotechnical Investigation, Dorsey Residence Addition
	555 Albion Avenue	07/20/99	William M. McMorrow	Geotechnical Engineering Evaluation, Proposed Alterations and Addition, Portion of Existing Garage
	580 Albion Avenue	07/14/78	Dunham & Associates	Soil Investigation, Proposed Home, APN 072-060-160
		07/14/78	Francis A. Stejer	Engineering Geologic Study (APN 072-060-160)
	585 Albion Avenue	07/27/96	ALB Associates, Inc.	Geotechnical Investigation, Planned Pool, Guest House and Additions
		04/23/07	Romig Engineers, Inc.	Geotechnical Investigation, Campbell Residence Additions
	590 Albion Avenue	03/30/99	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Stim Residence
		08/04/04	Muchael A. Kern, Consulting Engineer	Geotechnical Plan Review
	595 Albion Avenue	06/14/83	Clearly Consultants, Inc.	Geotechnical Investigation, Land Division of Kaisel Property
		05/31/84	Clearly Consultants, Inc.	Geotechnical Investigation, Proposed Perry Residence
		11/06/91	Clearly Consultants, Inc.	Soil and Foundation Investigations, Additions to Perry Residence
			William Cotton and Associates, Inc.	Geotechnical Review Sheet
		05/15/92	Alan Fleming Design	Site Plan
		06/04/92	William Cotton and Associates, Inc.	Geologic and Geotechnical Review, Perry Addition, PA-8809
		01/07/01	Clearly Consultants, Inc.	Geotechnical Engineering Consultation Services, Landscape Water Features
		12/04/09	Clearly Consultants, Inc.	Geotechnical Investigation, New Solar Array Foundations
1A	ALTA MESA ROAD			
	107 Alta Mesa Road	10/31/95	Nicholas Engineering Consultants	Geotechnical Investigation, Proposed Residence Addition
		06/30/04	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence Addition
	111 Alta Mesa Road	07/01/03	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	112 Alta Mesa Road	05/02/91	John Sarmiento & Associates	Preliminary Groundwater Seepage Investigation, Peck Residence
		06/12/97	PGSoils, Inc.	Geotechnical Conditions, Proposed Residential Addition
	120 Alta Mesa Road	04/18/95	Nielsen Geotechnical Incorporated	Soil Report

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	144 Alta Mesa Road	04/24/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Additions
	171 Alta Mesa Road	06/12/05 11/30/89 02/05/90 07/17/90	Town of Woodside GeoForensics, Inc. GeoForensics, Inc. GeoForensics, Inc.	various documents associated with permit, fees and initial review by Town Geologist A Causation Investigation of the Reported Distress at the Crocker Residence Report Supplement, Crocker Residence Subsurface Exploration, Crocker Residence
		06/02/90	Sian Hwi Njo William Cotton Associates Sian Hwi Njo	Foundation Calculations, Crocker Residence Geotechnical Review Sheet Concrete Foundation Plan, Crocker Residence with notes
	175 Alta Mesa Road	08/17/90	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Addition to Residence
	181 Alta Mesa Road	06/18/96	Michelucchi & Associates, Inc.	Geotechnical Investigation, Fitzpatrick/Kingman Residence, Planned Additions and Remodeling
	190 Alta Mesa Road	10/16/92	Nielsen Geotechnical Incorporated	Geotechnical Report
1A	ALTA VISTA COURT			
	103 Alta Vista Court	02/21/09 03/23/10	Frank Lee & Associates Frank Lee & Associates	Foundation Recommendations, Proposed One-Story Single Family Residence Soil and Foundation Investigation, Proposed One-Story Single Family Residence
	123 Alta Vista Court	04/23/93	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, O'Hara Residence
	128 Alta Vista Court	08/19/05	Romig Engineers, Inc.	Geotechnical Services, Residence Addition
	138 Alta Vista Court	06/21/92 06/15/10	GeoForensics, Inc. GeoForensics, Inc.	Foundation Study, Proposed Residential Additions, Hennig Residence Geotechnical Investigation Update, Proposed New Residence, Bet Property
	131 Alta Vista Court	09/22/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
	142 Alta Vista Court	07/11/96	Terrasearch, Inc.	Geotechnical Investigation, Proposed Single Family Residence
	148 Alta Vista Court	06/17/97	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Addition
1A	156 Alta Vista Court	09/08/00 08/07/02	Sigma Prime Geosciences, Inc. Sigma Prime Geosciences, Inc.	Engineering Geologic and Geotechnical Engineering Report Post-Construction Geotechnical Review
2	ARBOR COURT			
	105 Arbor Court	10/09/90 06/24/92 12/29/93 04/24/07	Tejima and Associates, Inc. Tejima and Associates, Inc. Jo Crosby & Associates Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Additions, Existing Maahs Residence Existing Problems, Maahs Residence Geotechnical Investigation, Maahs Residence Geotechnical Investigation, Proposed 2 Car Garage, Retaining Walls, and New Driveway
	115 Arbor Court	03/03/97 06/06/01	Earth Investigations Consultants Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development Geotechnical Design Parameters, Proposed Lap Pool
	135 Arbor Court	04/30/02	Romig Engineers, Inc.	Geotechnical Investigation, Johnson Studio Addition
	145 Arbor Court	10/29/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
2	AUDIFFRED LANE			
	116 Audiffred Lane	12/16/99	Nielsen Geotechnical Incorporated	Soil Report
	122 Audiffred Lane	02/18/93 01/07/00 06/15/00 08/10/01 08/10/01	GeoForensics, Inc. Engineered Soil Repairs, Inc. Fowler & Associates Engineered Soil Repairs, Inc. Engineered Soil Repairs, Inc.	Geotechnical Observations, Reported Residential Distress, Yancy Residence Yancy Residence Underpinning Structural Calculations Engineering Geology Investigation, Yancey Residence Construction Observation Letter *AS-Built Report, Yancy Residence
	122 / 124 Audiffred Lane	10/28/87	Terrasearch, Inc.	Geotechnical Investigation, Proposed Two-Lot Residential Development, Parcel 4 A and B
	122 / 124 Audiffred Lane	04/03/95	Levine-Fricke	Geotechnical Investigation, Yancey and Schwabacher Residences
	124 Audiffred Lane	03/22/95 03/23/95	Levine-Fricke Levine-Fricke	Memo - Field and Laboratory Activities Boring Logs and Locations
	136 Audiffred Lane	10/15/04 06/13/07 01/09/08	Milstone Geotechnical Murray Engineers, Inc. Murray Engineers, Inc.	Geotechnical Investigation, Foundation Distress, Weiss Residence Geotechnical Investigation, Weiss Swimming Pool Supplemental Recommendations, Adams Swimming Pool
2	BARDET ROAD			

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	131 Bardet Road	11/14/05	Murray Engineers, Inc.	Geotechnical Investigation, Madden Residence
	148 Bardet Road	02/14/01	PGSoils, Inc.	Soils Conditions, Proposed Guest House Addition
	155 Bardet Road	03/21/03	Romiq Engineers, Inc.	Geotechnical Consultation, Deck Addition
	164/168 Bardet Road	05/26/97	Earth Systems Consultants, N. C.	Soil Engineerign Study, Voiss Landslide
	168 Bardet Road	10/12/92	Earth Systems Consultants, N. C.	Geologic and Geotechnical Engineering Study, Addition to Novitsky Residence
		02/12/93	Earth Systems Consultants, N. C.	Addendum to Geologic and Geotechnical Engineering Study, Addition to Novitsky Residence
2	BARRETT LANE			
	1 Barrett Lane	03/12/02	Jo Crosby & Associates	Geotechnical Investigation, Planned Residence Addition
		04/02/02	Jo Crosby & Associates	Response to Engineering Geology Review Comments
2	BEAR GULCH ROAD			
	100 Bear Gulch Road	09/05/91	Applied Earth Sciences Consultants	Geotechnical Investigation, Proposed Addition, Martin Residence
		05/30/96	Applied Earth Sciences Consultants	Geotechnical Investigation, Proposed Addition, Martin Residence
		01/12/07	Applied Earth Sciences Consultants	Geotechnical and Geologic Investigation, Proposed Pool House
	185 Bear Gulch Road	04/05/88	Earth Systems Consultants	Geotechnical Evaluation Report, Proposed Residential Addition
		04/06/89	Earth Systems Consultants	Supplemental Recommendations, Proposed Addition
		12/24/92	Earth Systems Consultants	Report Update and Foundation Plan Review, Proposed Additions
		06/03/93	Earth Systems Consultants	Addendum to Geotechnical Evaluation Report, Proposed Residential Additions
2	BIG TREE ROAD			
	5 Big Tree Road	06/05/01	GeoForensics Inc.	Geotechnical Investigation, Proposed Residential Additions, Gottfried Property
		06/26/01	Steven F. Connelly	Engineering Geologic Investigation, Proposed Remodel, Gottfried Residence
		10/28/01	GeoForensics Inc.	Report Supplement, Gottfried Property
		03/15/05	GeoForensics Inc.	Construction Observations, Driveway
		09/07/05	GeoForensics Inc.	Response to Town Comments on 8/4/05 GF1 letter
		09/19/05	A.C.&H. Civil Engineers, Inc.	Response to 9/9/05 Town Comments
	6 Big Tree Road	03/28/73	W.A. Wahler & Associates	Site and Foundation Investigation, Proposed Campbell Residence
2	BIG TREE WAY			
	45 Big Tree Way	06/15/73	Dunham and Associates	Preliminary Soil and Geologic Investigation, Proposed Three-Lot Subdivision
		02/01/74	Dunham and Associates	Preliminary Soil and Geologic Investigation, Proposed Building Site
		03/19/85	Earth Systems Consultants	Soil Engineering Report, Proposed Single Family Residence, Haimson Property
			William Cotton and Associates	Geotechnical Review Sheet
		07/31/85	Earth Systems Consultants	Foundation Plan Review, Haimson Residence
		08/07/85	Joseph M. Bauer	Calculations, Proposed Haimson Residence
		09/05/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Haimson Property
			?	Site Plan, with annotations
2A	BLUE RIDGE LANE			
	6 Blue Ridge Lane	01/26/76	Dunham & Associates	Geologic and Soil Engineering Evaluation, Parcel 2, End of Blue Ridge Lane
		02/27/76	Town of Woodside	Review of Dunham & Associates Report
		11/10/75	Brian Kangas Foulk & Associates	Land Division Map No. 222, Tentative Parcel Map, Subdivision of Parcel B, Land Division Map No. 210
		06/30/87	Terratech, Inc.	Geotechnical Investigation, Clark Residence
		03/10/97	Nielsen Geotechnical Incorporated	Soil Report
	11 Blue Ridge Lane	03/15/99	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Addition & Remodeling
	19 Blue Ridge Lane	08/31/93	Clearly Consultants, Inc.	Geotechnical Investigation, New Residence
		09/30/94	Nielsen Geotechnical Incorporated	Soil Report, Swimming Pool and Pool House
		06/12/07	Clearly Consultants, Inc.	Geotechnical Investigation, Guest House
2A	BRIDLE LANE			
	Bridle Lane	08/20/73	William Cotton and Associates	Review of Tentative Map
		8/0/74	Edwin H. Smith	Subdivision Map
		04/16/74	Geolabs-Northern California, Inc.	Magnetometer Survey, Proposed Forerst Glade Estates
		06/21/74	Geolabs-Northern California, Inc.	Subsurface Investigation of Splinter Fault Trace, Proposed Forest Glade Estates
		07/15/74	Geolabs-Northern California, Inc.	Evaluation of Landslide Located Southwest of Site and Liquefaction Potential of On-Site Soils, Proposed Forest Glade Estates
		08/11/74	William Cotton and Associates	Review Letter ?
		10/08/74	Mr. George Gunias, Woodside Citizen	Questions in Regard to Forest Glade Estates
		10/08/74	Town of Woodside	Minures of Town Council Meeting

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		10/25/74	Jo Crosby & Associates	Letter of Resignation - Forest Glade Estates
		07/30/75	Board of Registration for Geologists and Geophysicists	Complaint
	1, 2, 3 Bridle Lane	11/10/69	Crosby & Associates	
		04/16/74	Geolabs - Northern California, Inc.	Magnetometer Survey, Proposed Forest Glade Estates
		06/21/74	Geolabs - Northern California, Inc.	Subsurface Investigation of Splinter Fault Trace
		07/25/77	Richard E. Rowland	Geologic Report on a portion of the Hume Property
	1 Bridle Lane	11/11/69	Crosby & Associates	Soil & Geologic Investigation, Forest Glade Estates, Hooper property
		03/06/87	Perry R. Wood	Soil Conditions, Lot 3, Bridle Lane, Forest Glade Estates
		03/16/87	Crosby & Associates	Lot 3, Forest Glade Estates
		04/01/87	William Fredrick Heijn Architect	Plans with annotations
			William Cotton and Associates	Geotechnical Review Sheet
		06/03/87	Crosby & Associates	Lot 3, Forest Glade Estates
		06/11/87	William Cotton and Associates	Geologic and Geotechnical Review, Bosse, Lot 3 Forest Glade Estates, P.A. #4078
		9/0/89		site photographs
		05/20/93	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation, Lands of First Franklin
		04/28/94	Terrasearch, Inc.	Geotechnical Investigation, Proposed Additions, Tennis Court & Swimming Pool
	2 Bridle Lane	03/22/88	Perry R. Wood	Soil Percolation Tests and Recommended Spetic Drainfield, Parcel 2/Bridle Lane
		03/18/88	Terrasearch, Inc.	Soil Investigation, Parcel 2 / Bridle Lane, Proposed Residence
	3 Bridle Lane	07/20/01	Harlan Tait Associates	Geotechnical Investigation, Residence
		03/15/03	Harlan Tait Associates	Geotechnical Consultation, Residence
		09/15/05	Connell Geotechnical, Inc.	Geotechnical Consultation, Underground Water Storage Tank
	4 Bridle Lane	03/08/89	Terrasearch, Inc.	Geotechnical Engineering Investigation, Parcel 4, Bridle Lane, Proposed Residence
			William Cotton and Associates	Geotechnical Review Sheet
		06/21/89	J. Thomas Jakaby	Structural Calculations, Miller Residence
		09/13/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Miller, PA-7466
		09/20/89	Terrasearch, Inc.	Response to Geotechnical Consultant Review and Grading and Foundation Plan Review
		10/03/89	William Cotton and Associates	Supplemental Geotechnical Review, <iller, PA-7466
		10/30/89	William Cotton and Associates	Supplemental Geotechnical Review
		04/18/00	Romig Engineers, Inc.	Geotechnical Engineering Investigation, Miller Guest House
		03/19/07	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Mees Residential Additions and Swimming Pool
	5 Bridle Lane	00/00/97	Lowney Associates	?
2A	BROOKWOOD ROAD			
	110 Brookwood Road	01/22/03	Carl W. Garbe	Geotechnical Consultation, Proposed Deck
		03/09/06	Romig Engineers, Inc.	Geotechnical Investigation, Bergeron Residence Additions
	130 Brookwood Road	07/02/10	ADCO Engineering	Soil an Foundation Investigation, Proposed Addition
		08/05/10	ADCO Engineering	Revised Soil an Foundation Investigation, Proposed Addition
		10/15/10	Ali M. Oskoorouchi	Foundation & Soil Investigations, Proposed Addition to Makel Residence
	135 Brookwood Road	06/25/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed House and Garage Addition
	165 Brookwood Road	03/31/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	180 Brookwood Road	04/19/01	Bay Area Geotechnical Group	Foundation Invstigation Report, Proposed Residential Addition
	185 Brookwood Road	10/02/96	SIA Consulting Engineers	Geotechnical Investigation
2A	215 Brookwood Road	02/23/00	Romig Consulting Engineers	Geotechnical Investigation, Salpeter Residence Improvements
		07/13/01	Romig Consulting Engineers	Geotechnical Plan Review, Residence Improvements
		03/15/05	Romig Engineers, Inc.	Supplemental Recommendations, Residence Addition
3	BUCK COURT			
	Buck Estates Subdivision	10/0/80	Frahm Elder Cannis	First Study Plan, Lands of Hagen
		12/29/80	William Cotton and Associates	Geotechnical Review Sheet
		01/20/81	William Cotton and Associates	Geologic Review - Lands of Hagen, Buck Estates
		01/29/81	William Cotton and Associates	Review
		02/26/81	Jo Crosby & Associates	Geotechnical Investigation, 11+ Acres, Buck Estates
		07/13/81	Donald A. Woolfe and Associates	Environmental Setting Survey, Buck Estate
		08/05/81	Frahm Elder Cannis	Preliminary Map
		08/12/81	William Cotton and Associates	Review - Buck Estates/B & P Subdivision, SD #140
	Briggs Subdivision	07/30/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Briggs Subdivision
		07/16/86	William Cotton and Associates	Geotechnical Review Sheet
		08/21/86	Toen of Woodside	Results of Meeting with Subdivision Review Committee, Subdivision #147

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		09/23/86	Tillson-Bliss & Associates	Replies to Results of Subdivision Review Committee Notes
		10/08/86	Jo Crosby & Associates	Geotechnical Investigation, Briggs Estate
		02/18/87	Charles M. Salter Associates, Inc.	Briggs Estate - Accoustical Consulting
	10 Buck Court	07/02/98	Nielsen Geotechnical Incorporated	Soil Report, Lots 2, 3 & 7, Buck Estate, Northgate Drive
		05/14/00	Nielsen Geotechnical Incorporated	Plan Review, New House, Lot 3
		09/13/00	Nielsen Geotechnical Incorporated	Plan Review 3rd Review, New House, Lot 3, Buck Estate
		11/09/00	Nielsen Geotechnical Incorporated	Review of Revised Retaining Wall Plan, New House
		12/03/01	Nielsen Geotechnical Incorporated	Construction Report, Lot 3
	20 Buck Court	07/02/98	Nielsen Geotechnical Incorporated	Soil Report, Lots 2, 3 & 7, Buck Estate, Northgate Drive
		08/29/02	Nielsen Geotechnical Incorporated	Construction Report, Residential Project, 20 Buck Court (Lot 2, Buck Estate)
		04/11/08	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Swimming Pool
	30 Buck Court	05/08/01	Nielsen Geotechnical Incorporated	Soil Report
	40 Buck Court	07/02/98	Nielsen Geotechnical Incorporated	Soil Report, Lots 2, 3 & 7, Buck Estate, Northgate Drive
		01/04/00	Bay Area Geotechnical Group	Foundation Investigation, Proposed Single Family Residence, Lot 7, Buck Court
	50 Buck Court	11/07/02	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Swimming Pool, Lot 6, Buck Estates
		12/04/03	Nielsen Geotechnical Incorporated	Review of Plans & Structural Calculations, Retaining Wall
	60 Buck Court	07/22/98	Bay Area Geotechnical Group	Geotechnical Investigation, Lot 5 / Buck Court, Proposed Single Family Residence
3	CANADA LANE			
	1491 Canada Lane	03/28/00	Nielsen Geotechnical Incorporated	Soil Report
	1515 Canada Lane	05/22/00	GeoForensics, Inc.	Geotechnical Investigation Update, Proposed Residential Addition, Griffen Property
		11/08/00	GeoForensics, Inc.	Response to Review Comments, Proposed Addition
	1580 Canada Lane	03/21/86	Howard F. Donley & Associates	Soil and Foundation Investigation, Proposed Addition to Office Building
	1583 Canada Lane	04/07/06	Romig Engineers, Inc.	Geotechnical Study, Foundation Improvements
		04/24/08	Romig Engineers, Inc.	Updated Design Parameters, Dickinson Residence Upgrade
	1589/1591 Canada Lane	06/30/82	PSC Associates, Inc.	Geotechnical Engineering Investigation, Proposed Residence, Parcels (1589) and C (1591)
			William Cotton and Associates	Geotechnical Review Sheet
		12/27/89	PSC Associates, Inc.	Geotechnical Report Update, Lot C (1591)
		12/05/90	Edward W. Baca	Topographical Survey
		03/28/91	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Vanos, SD #35 and Exc to SD #72
		04/23/91	PSC Associates, Inc.	Supplemental Geotechnical Investigation and Response to Cotton Review Letter for Proposed Residence on Parcel C
		11/08/91	William Cotton and Associates	Geologic and Geotechnical Review, Vanos, SD #39
		06/30/92	William Cotton and Associates	Geologic and Geotechnical Review, Vanos, PA #8830 and 8832
		08/24/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Vanos, #8830 and #8832
	1595 Canada Lane	07/10/02	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence
		07/07/05	GeoForensics Inc.	Geotechnical Recommendations, Proposed New Pool, Canada Lane Property
	3030 Canada Lane	03/21/86	Howard F. Donley & Associates	Soil and Foundation Investigation, Proposed Addition to Office Building
		01/08/86	Charlie Chu, Jr. & Associates	Existing Site Plan with New Addition, with annotations
		04/17/86	William Cotton and Associates	Geotechnical Review Sheet
		04/23/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Gadbois Office Addition
		05/05/86	Howard F. Donley & Associates	Response to Cotton's Letter dated 4/23/86, Proposed Office Addition
		05/14/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Gadbois Office Addition
3	CANADA ROAD			
	811 Canada Road	07/10/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Two Lot Subdivision
	833 Canada Road	03/19/85	Howard F. Doneley & Associates	Geotechnical Investigation
		06/04/85	Lea Engineering	Structural Calculations
		06/28/85	Howard F. Doneley & Associates	Foundation Plan Review, Proposed Residence
				Septic System Plan
		08/26/85	William Cotton and Associates	Geotechnical Review Sheet
		09/04/85	William Cotton and Associates	Preliminary Geologic Review and Geotechnical Investigation Evaluation, Soma, Parcel #068-253-100
		09/27/85	Howard F. Doneley & Associates	Soil Expansivity
		10/11/85	William Cotton and Associates	Supplemental Geotechnical Review, Soma, Parcel #068-253-100
	839 Canada Road	07/28/97	Nielsen Geotechnical Incorporated	Soil Report
	937 Canada Road	10/01/07	PGSoil, Inc.	Geotechnical Investigation, Proposed House Addition
		11/30/07	PGSoil, Inc.	Supplement to Geotechnical Investigation, Proposed House Additions

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	1025 Canada Road	08/18/77	Cooper - Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
		08/13/87	Cooper Engineers, Inc.	Geotechnical Investigation, Parcel A/Land Division 243, Proposed Single-Family Residence
3	1030 Canada Road	05/02/05	Cleary Consultants, Inc.	Geotechnical Investigation, New Accessory Buildings (2), Greenhouses (2), and Lath House
3A	1034 Canada Road	01/29/96	Earth Investigations Consultants	Fault Investigation Waiver, Proposed Improvements
	1036 Canada Road	04/07/78	Jo Crosby & Associates	Geologic and Soils Investigation (APN 072-060-406)
		05/23/78	Joe Crosby & Associates	Addendum to Geologic and Soils Investigation
		06/20/02	Cleary Consultants, Inc.	Geotechnical Investigation, New Barns (2) on Indian House Ranch (APN 072-060-390)
	1166 Canada Road	04/07/06	Romig Engineers, Inc.	Geotechnical Investigation, Addicott Barn, Pool House and Residence Improvements
	1177 Canada Road	03/08/98	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Foundation Improvements and Detached New Garage
		01/25/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Cabana
	1185 Canada Road	04/26/92	GeoForensics, Inc.	Foundation Study, Mattman Residence
			William Cotton and Associates	Geotechnical Review Study
		06/15/92	William Cotton and Associates	Geologic and Geotechnical Review, Mattman Addition, BP-8810
	1210 Canada Road	04/06/77	Terrasearch, Inc	Soil and Geologic Investigation, Lands of Chamberlain
		12/09/76	Perry R. Woods	Percolation Test Results and Logs
		03/18/77	Fram Elder Cannis	Preliminary Map, Land Division, Lands of Chamberlain, showing Parcel B with percolation test pit locations
		03/19/01	Terrasearch, Inc	Geotechnical Investigation, Proposed Wine Cellar
	1221 Canada Road	06/17/91	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
			William Cotton and Associates	Geotechnical Review Sheet
		01/10/91	William Cotton and Associates	Supplemental Geotechnical Review, Pugh Residence, PA-8491
		10/07/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
		12/05/91	GeoForensics, Inc.	Geotechnical Plan Review, Proposed New Residence
	1240 Canada Road	01/12/70	Reynolds & Associates	Foundation Investigation, Chamberlain Residence
	1250 Canada Road	07/30/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Residence
		08/04/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Guest House and Retaining Wall, Brouscob Property
		01/20/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool, Brouscob Property
	1260 Canada Road	02/05/85	PSC Associates, Inc.	Geotechnical Engineering Report
		07/15/85	PSC Associates, Inc.	Geologic and Geotechnical Engineering Investigation, Proposed Residence, Lot 1 near Glenwood Avenue
		05/22/95	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development
		06/29/95	Earth Investigations Consultants	Geotechnical Investigation, Response to Town Review, Proposed Residential Development
	1300 Canada Road	07/15/85	PSC Associates, Inc.	Geologic and Geotechnical Engineering Investigation, Proposed Residence, Lot 1 near Glenwood Avenue
	1302 Canada Road	06/17/81	Terrasearch Inc.	Geologic Feasibility Evaluation, Proposed Servants's Dwelling
		06/17/86	Purcell, Rhodes & Associates	Soil Engineering and Geotechnical Report, Proposed Cabana, McNaughton Residence
3A	1308 Canada Road	10/11/99	John W. Leonard	Geotechnical Engineering Investigation, Coast Oak Property, Single-Family Residential Property
4	1385 Canada Road	04/15/97	Associated Terra Consultants, Inc.	Geologic Investigation
		09/02/97	Michelucchi & Associates, Inc.	Geotechnical Investigation of Landslide, Proposed 3-Lot Subdivision
		10/25/02	Romig Engineers, Inc.	Geotechnical Investigation, Edwards Garage Addition
		02/02/10	Murray Engineers, Inc.	Geotechnical Investigation, Edwards Residence
	1395 Canada Road	04/21/95	Lee Engineers, Inc.	Soil Investigation, Noyes Residence Addition & Swimming Pool Site Development
	1450 Canada Road	05/13/09	Neil O. Anderson and Associates	Geotechnical Investigation, Solomon Residence Swimming Pool
	1470 Canada Road	12/09/93	Fowler & Associates	Geological and Geotechnical Investigation, Proposed Single Family Residence
		01/24/94	Fowler & Associates	Supplemental Geological and Geotechnical Investigation, Proposed Single Family Residence
		04/08/98	Fowler & Associates	Supplemental Geotechnical Investigation, Proposed Barn
		11/16/01	Fowler & Associates	Geotechnical Consultation, Proposed Barn
4	CEDAR LANE			
	2 Cedar Lane	11/24/97	Nielsen Geotechnical Incorporated	Soil Report
	3 Cedar Lane	07/28/95	Fowler & Associates	Geotechnical Investigation, Proposed Two New Accessory Structures
		04/01/02	Fowler & Associates	Geotechnical Consultation and Plan Review
	4 Cedar Lane	08/09/07	Romig Engineers, Inc.	Geotechnical Investigation, Lacob Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	5 Cedar Lane	04/17/95	Nielsen Geotechnical Incorporated	Soil Report
		11/30/97	Nielsen Geotechnical Incorporated	Supplemental Soil Report
4	CHURCHILL AVENUE			
	198 Churchill Avenue	02/28/87	J. V. Lowney & Associates	Geotechnical Investigation, Distressed Garage and Residence Addition
			William Cotton and Associates	Geotechnical Review Sheet
		11/23/87	Stoeker and Northway Architects incorporated	Site Plan, Residential Remodel
		07/06/05	Romig Engineers, Inc.	Geotechnical Investigation, Front Porch and Foundation Repair
4	CINNABAR ROAD			
	Cinnabar Road	09/12/66	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Woodside Hills Unit No. 6
	240 Cinnabar Road	04/24/89	J. V. Lowney & Associates	Geotechnical Investigation, McCarthy Residence
		09/20/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Swimming Pool, McCarthy Property
		06/16/06	Bay Area Geotechnical Group	Geotechnical Consultation, Proposed Residential Improvements
	245 Cinnabar Road	12/29/77	Jo Crosby & Associates	Geology and Soils Investigation Report, 48 Acres/Harcross Road
		10/17/97	Dibble - Wright Associates	Geologic Inspection (APN 069-380-120)
		09/20/99	Jo Crosby & Associates	Geotechnical Investigation, Proposed Tennis Court Development
		05/16/00	Jo Crosby & Associates	Response to Town Comments on 9/20/99 Report
4	CORTO LANE			
	35 Corto Lane	11/07/03	Romig Engineers, Inc.	Geotechnical Investigation, Werdegar Residence Addition
	50 Corto Lane	06/05/96	Lee Engineers, Inc.	Soil Investigation Report, Proposed Swimming Pool Reconstruction
		06/10/03	Lee Engineers, Inc.	Sunroom Site Condition Reconnaissance and Recommendations
	70 Corto Lane	06/28/99	GeoForensics Inc.	Limited Geotechnical Investigation, Proposed New Residential Additions
		06/06/01	GeoForensics Inc.	Construction Observations, Residence Additions
		09/28/05	GeoForensics Inc.	Report Supplement, Cleary Residence
4	CREST ROAD			
	115 Crest Road	06/17/97	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Addition
	120 Crest Road	06/13/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Pool House and Patios, Johnson Property
	145 Crest Road	12/14/05	Hydro-Geo Consultants, Inc.	Geotechnical Assessment, Addition to Existing Alexander Nemirovsky Residence (APN 069-142-010)
	150 Crest Road	06/29/10	Romig Engineers, Inc.	Geotechnical Investigation, Legros Residence Addition & Deck
		02/01/11	Romig Engineers, Inc.	Geotechnical Recommendations, Spa, Pool, and Pool Deck
	160 Crest Road	02/15/05	Advance Soil Technology, Inc.	Geotechnical / Soil and Foundation Investigation, Proposed Single Family Residence
	Crest Road	09/12/66	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Woodside Hills Unit No. 6
4	189 Crest Road	04/10/87	Tejima and Associates, Inc.	Geotechnical Investigation, Proposed D'Amico Residence
4A	CROYDEN WAY			
	120 Croydon Way	01/09/04	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence Additions, Harris Property
		04/10/08	GeoForensics, Inc.	Updated Recommendations Letter for Proposed Landscape Improvements
	121 Croyden Way	01/28/93	Carl W. Garbe	Soils and Foundation Report, Proposed Improvements
4A	DEAN ROAD			
	120 Dean Road	02/21/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Residence
	130 Dean Road	03/18/03	Romig Engineers, Inc.	Geotechnical Investigation
	140 Dean Road	01/25/01	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Residence
		06/19/03	Terrasearch, Inc.	Geotechnical Recommendations, New Swimming Pool
		10/29/03	Terrasearch, Inc.	Response to Town Comments
4A	DRY CREEK LANE			
	180 Dry Creek Lane	04/08/00	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residence Addition, Foley Property

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
4A	EAST VIEW WAY			
	507 East View Way	07/23/93	Steve Dal Associates	Limited Geotechnical Study Remodel/Addition, Existing Adams Residence
	522 East View Way	10/29/98 05/06/05 09/23/06	J. Yang and Associates J. Yang and Associates J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence Geotechnical Site Investigation, Swimming Pool Geotechnical Site Investigation, Proposed New Residence
	535 East View Way	06/23/94	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Single Family Residence and Vineyard, Lands of Rogers
	538 East View Way	10/30/98	J. Yang and Associates	Geotechnical Site Investigation, Proposed Residence
	575 East View Way	07/30/90 04/30/01	Upp Geotechnology, Inc. Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Rogers Geotechnical Report Update and Plan Review, Proposed Basement Addition, Rogers Residence
	623 East View Way	08/23/90	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Rogers
4A	ECHO LANE			
	15 Echo Lane	02/21/06	Romig Engineers, Inc.	Geotechnical Review, Van Rheeman Residence
4A	ELEANOR DRIVE			
	115 Eleanor Drive	02/13/09 05/18/09 06/22/09 07/06/09	United Soil Engineering, Inc. United Soil Engineering, Inc. United Soil Engineering, Inc. United Soil Engineering, Inc.	Geotechnical and Slope Investigation, Proposed New Residence Revised Geotechnical and Slope Investigation, Proposed New Residence Supplemental Geotechnical and Slope Investigation, Proposed New Residence Additional Geotechnical Recommendations (2), Proposed New Residence
	131 Eleanor Drive	12/21/09 11/12/10	Earth Investigations Consultants Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Deck Supplemental Geotechnical Parameters, Proposed Landscape Wall
	139 Eleanor Drive	01/28/11	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Remodeling
	140 Eleanor Drive	09/01/80 11/12/80 12/29/80 01/08/81 01/14/81 01/23/81 01/27/81 02/26/81 03/10/81 05/21/81 07/15/81	Edwin H. Smith Purcell, Rhoades & Associates William Cotton and Associates Town of Woodside Town of Woodside Edwin H. Smith William Cotton and Associates Town of Woodside Edwin H. Smith Purcell, Rhoades & Associates William Cotton and Associates	Preliminary Map, Subdivision of Lot 6 and Portion Lot 5, Block 1, Woodside Heights with annotations Geotechnical Hazards Assessment, APN's 069-222-050 and -070, Eleanor Drive and Northgate Drive Geotechnical Review Sheet, LD #270 Review Letter Summarizing Requirements Review of PRA Hazards Report dated 11/12/80 Response to Review Letter Summarizing Requirements dated 1/8/81 Geologic Review of PRA Hazards Report dated 11/12/80 Review Letter Summarizing Requirements Preliminary Map, LD # 270 - Request for Exception to Water Flow Requirements Soil and Geologic Study, Parcel 8, APN's 069-222-050 and -070 Geologic Review, Gafke, LD #270
		09/15/03 10/03/07	David Jones Associates Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Single Family House Front Entry Area - Proposed Temporary Releveling/Underpinning
	155 Eleanor Drive	06/14/00 03/21/01 04/09/01 04/12/01 06/04/01 10/09/02	Bay Area Geotechnical Group Bay Area Geotechnical Group Geomatrix Consultants Geomatrix Consultants Bay Area Geotechnical Group Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residence Addendum to Geotechnical Investigation, Proposed Residence Geotechnical Review, Smith Residence Basement Height Second Addendum to Geotechnical Investigation Report, Proposed Smith Residence Geotechnical Observation/Testing Services During Construction of Residence
	161 Eleanor Drive	07/28/95	Tom Hui	Visual Structural Inspection Report
	168 Eleanor Drive	01/24/05	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Swimming Pool
	175 Eleanor Drive	02/14/90 05/14/90 07/02/90 06/03/94	JCP Geologists Engineers William Cotton and Associates Lea Engineering JCP Geologists Engineers Harlan Tait Associates	Geologic and Soil & Foundation Services, Distressed Home Geotechnical Review Sheet Structural Calculations Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence Letter of Transmittal
	200 Eleanor Drive	04/01/86	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Addition to Home
	205 Eleanor Drive	01/30/86 09/07/05 12/02/05	JCP Geologists - Engineers GeoForensics Inc. GeoForensics Inc.	Soil and Foundation Study, Proposed Additions at 205 Eleanor Drive Geotechnical Investigation, Spa and Replacement Retaining Walls, Jimerson Property Limited Geotechnical Evaluation, Proposed Additions
	228 Eleanor Drive	09/28/98	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	233 Eleanor Drive	12/09/96	J. Yang and Associates	Geotechnical Site Investigation, Poland Residence Addition
		07/14/01	J. Yang and Associates	Geotechnical Site Investigation, Proposed Kahn Residence
		07/24/01	Steven F. Connelly	Engineering Geology Investigation, Proposed Residence, Kahn Property
		09/22/06	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Swimming Pool
	238 Eleanor Drive	09/09/75	Berloger, Long & Associates	Engineering Geologic Investigation, Proposed Parcel Split
		01/22/76	Berloger, Long & Associates	Soil Investigation, Proposed Residence
		02/27/76	Town of Woodside	Review of Berloger, Long & Associates
		04/15/96	Nielsen Geotechnical Incorporated	Soil Report
4A	265 Eleanor Drive	06/09/94	Rutherford & Chekene	Geotechnical Investigation and Design Recommendations, Starr Residence Remodel
5	270 Eleanor Drive	12/02/98	Nielsen Geotechnical Incorporated	Soil Report
		02/15/99	Nielsen Geotechnical Incorporated	Supplemental Soil Report,
		03/31/99	Nielsen Geotechnical Incorporated	Review - Geotechnical Investigation Report, Proposed Additions and Retaining Wall
		05/17/99	Nielsen Geotechnical Incorporated	Plan Review, Addition and Remodel
		06/01/01	Nielsen Geotechnical Incorporated	Response to Inquiry, Retaining Walls
		06/19/01	Geomatrix Consultants	Geotechnical Review, Rossi Retaining Wall and Site Improvements
		10/02/01	Nielsen Geotechnical Incorporated	Foundation Observations, Rear-Yard Retaining Wall
		02/07/02	Nielsen Geotechnical Incorporated	Foundation Pier Bore Observations, Driveway Retaining Wall
		12/06/02	Nielsen Geotechnical Incorporated	Construction Report
	275 Eleanor Drive	07/25/11	GeoQuest	Geotechnical Investigation, Addition to Roizen Residence
		07/25/11	GeoQuest	Plan Review - Geotechnical Investigation, Addition to Roizen Residence
	289 Eleanor Drive	12/17/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Second Story Addition
	315 Eleanor Drive	02/10/10	Romig Engineers, Inc.	Geotechnical Slope Review, McLaughlin Garage Addition
		03/15/10	Romig Engineers, Inc.	Geotechnical Investigation, McLaughlin Detached Garage and Guest House
	292 Eleanor Drive	09/04/07	Romig Engineers, Inc.	Geotechnical Investigation, Canessa Residence Improvements
		11/03/08	Romig Engineers, Inc.	Supplemental Recommendations, Garage Conversion
	353 Eleanor Drive	05/18/99	Romig Consulting Engineers	Geotechnical Investigation, Barrocas Residence Addition
	380 Eleanor Drive	01/29/00	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions and Future Pool
		10/06/00	PGSoils, Inc.	Geotechnical Investigation, Proposed Deck, MacDonald Property
		03/02/05	PGSoils, Inc.	Geotechnical Report Update, Proposed House Addition
	408 Eleanor Drive	09/12/08	Romig Engineers, Inc.	Geotechnical Investigation, Residential Subdivision
	447 Eleanor Drive	04/14/86	JCP Geologist-Engineers	Review of Soil Engineering Aspects, Foundation Plan, Proposed Addition
		07/02/05	Raymond J. Dodson	Dressing Room Addition
		09/01/05	Raymond J. Dodson	Dressing Room Addition
	461 Eleanor Drive	04/11/06	Murray Engineers, Inc.	Geotechnical Investigation, Pollack Residence
		04/06/07	Murray Engineers, Inc.	Supplemental Recommendations, Spa Addition to Pool
	465 Eleanor Drive	07/19/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
		07/30/02	Romig Engineers, Inc.	Geotechnical Plan Review, Residence Addition
	475 Eleanor Drive	04/08/04	Nielsen Geotechnical Incorporated	Foundation Recommendations
	469 Eleanor Drive	03/21/02	PGSoils, Inc.	Geotechnical Conditions, Proposed Carport Upgrade and Addition
		12/01/04	Earth Investigations Consultants	Geotechnical Investigation, Proposed Concrete Block Culvert
	485 Eleanor Drive	04/14/08	Neil O. Anderson and Associates	Forensic Investigation, Hausman Residence Swimming Pool
	528 Eleanor Drive	08/19/99	Nielsen Geotechnical Incorporated	Soil Report
		12/17/01	Nielsen Geotechnical Incorporated	Construction Report, House, Retaining Walls and Pool
	538 Eleanor Drive	02/22/87	William M. McMorrow & Associates	Geotechnical Engineering Investigation, Relative Distress to Single-Family Residence, Beisler Property
		03/28/88	William M. McMorrow & Associates	Review of Design Documents, proposed Repairs to Beisler Residence
		06/10/88	William M. McMorrow & Associates	Geotechnical Engineering Consultation & Observation Services, Repairs to Beisler Residence
		09/21/01	Romig Engineers, Inc.	Geotechnical Investigation, Mone-Choplin Residence
		06/08/06	Romig Engineers, Inc.	Supplemental Recommendations, Residence Additions
	580 Eleanor Drive	05/28/98	NielsenGeotechnical Incorporated	Soil Report, Lot 4, Buck Estate
		11/30/01	NielsenGeotechnical Incorporated	Construction Report, Residential project, Lot 4, Buck Estate
		07/06/07	Charles H. Hartsoog	Soils Report, Bacolini Project
5	ESPINOSA ROAD			

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	750 (?) Espinosa Road	03/31/95	Milstone Geotechnical	Geotechnical Reconnaissance Investigation, Schilling Lake Spillway, Thornewood Open Space Preserve
	750/764 Espinosa Road	08/23/83	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Espinosa Road Landslide
		?	?	Detailed Map of Landslide and Associated Features with Section Sketch on Back
		06/24/83	Skyline County Water District	Letter to Mr. Bock
		06/29/83	Town of Woodside	Stop Work Notice
		06/29/08	Mr. Bock	Letter to Town Council
		07/12/83	Town Engineer	Report to Town Council - Item #8 - Appeal of Requiring Investigation and Permit for Landslide Repair
		07/12/83	Tim J. Manzagol	Temporary Slide Repair for Downdropped Portion of Espinosa Road - Bock Property
		07/12/83	Homewoners	Letter to Town Council - Repair of Private Road
		07/18/83	William Cotton and Associates	Geologic Review, Boch Landslide
		09/13/83	William Cotton and Associates	Geologic Review - Espinosa Road (Boch) Landslide Complex
		10/17/83	Freeman-Kern Associates, Inc.	Completion Report, Espinosa Road Landslide Repair
	810 Espinosa Road	09/15/04	Micheluci & Associates	Geotechnical Consultation, Planned Modifications to Residence
	885 Espinosa Road	01/23/03	Romig Engineers, Inc.	Geotechnical Services, Residence Addition
	895 Espinosa Road	01/20/00	Micheluci & Associates	Preliminary Geotechnical Evaluation, Planned Swimming Pool
		06/19/00	Micheluci & Associates	Review of Plans, Planned Swimming Pool
		09/14/01	Micheluci & Associates	Engineering Observations of Landscape Improvements
	905 Espinosa Road	11/10/72	Jo Crosby & Associates	Geologic and Foundation Investigation, Varian Lot
		12/22/76	Purcell, Rhodes & Associates	Soil and Geologic Investigation, Rhodens of Lot 31/Portola Hills
		01/19/77	Purcell, Rhodes & Associates	Addendum to Soil, Geologic and Percolation Investigation Report 12/22/76
		01/20/77	Leighton and Associates	Review
		04/25/77	Leighton and Associates	Proposed Building Addition
		03/01/78	Purcell, Rhodes & Associates	Addendum to Soil and Geologic Investigation, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
		04/03/78	Leighton and Associates	Request for Additional Information
		04/19/78	Purcell, Rhodes & Associates	Additional Geotechnical Data, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
		05/10/78	Purcell, Rhodes & Associates	Project Status, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
		06/06/78	Purcell, Rhodes & Associates	Clarification of Previously Submitted Geotechnical Data, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
		06/16/78	Leighton and Associates	review
		07/11/78	J. Walter Hoskins	Grading Plan and Proposed Residence, with annotations
		09/06/78	Purcell, Rhodes & Associates	Supplemental Information, Portion of Lot 31, Map of Portola Hills, Book 7 of Maps, Page 20
		05/28/79	Purcell, Rhodes & Associates	(Plan Review) Gano Residence
		04/28/03	Michelucci & Associates, Inc.	Geotechnical Consultation, Planned Subfloor Modification to Residence
	920 Espinosa Road	08/05/83	William F. Jones, Inc.	Geotechnical Investigation, Donath Property
		09/16/83	William Cotton and Associates	Geotechnical Review Sheet
		09/27/83	William Cotton and Associates	Review - Donath Landslide
	950 Espinosa Road	04/11/01	Romig Engineers, Inc.	Geotechnical Investigation, Dubbs Residence
		02/12/03	Romig Engineers, Inc.	Supplemental Recommendations, Driveway Retaining Wall
5	Espinosa Road @ Grandview Drive	12/05/74	Berlogar, Long & Associates	Soils Engineering and Engineering Geologic Investigation, Single Family Residence, cr. Grandview Drive
5A	EUCALYPTUS COURT			
	1 Eucalyptus Court	08/18/77	Cooper-Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
		12/31/03	Romig Engineers, Inc.	Geotechnical Investigation, Sammut Pool House
		03/24/11	Michelucci & Associates, Inc.	Drainage Evaluation, Existing Residence and Adjacent Lawn Areas and Installation of Two Groundwater Monitoring Piezometers
		07/12/11	Michelucci & Associates, Inc.	Review of Plans and Supplemental Design Recommendations, Proposed New Landscape Retaining Walls
	2 Eucalyptus Court	08/18/77	Cooper-Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
	3 Eucalyptus Court	08/18/77	Cooper-Clark & Associates	Geologic Site Evaluation, Proposed Residential Subdivision
5A	EUGENIA LANE			
	20 Eugenia Lane	04/28/97	Jo Crosby & Associates	Geotechnical Investigation
	25 Eugenia Lane	03/10/90	Purcell, Rhodes & Associates	Geotechnical Study, Addition
	31 Eugenia Lane	03/23/05	GeoForensics, Inc.	Geotechnical Investigation, Proposed Spa, Kibble Property
		10/17/05	GeoForensics, Inc.	Driveway Reconstruction
5A	FAMILY FARM ROAD (DRIVE)			
	Family Farm Road Bridge	02/07/00	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Proposed Bridge at Sausal Creek
		04/30/00	Upp Geotechnology, Inc.	Supplemental Information, Geotechnical Evaluation, Proposed Bridge
	200/201 Family Farm Road	02/09/82	William Cotton and Associates	Review - Smith Land Division

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		1/0/82	Skierka & Fisher Land Surveys	Preliminary Map
	200 Family Farm Road	04/13/87	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Detached Garage, Swimming Pool, and Retaining Wall
	218 Family Farm Road	12/16/94	Clearly Consultants, Inc.	Fault Location Investigation Report
		05/10/95	Clearly Consultants, Inc.	Geotechnical Investigation Report, New Residence
		06/30/96	Clearly Consultants, Inc.	Fault Location Investigation Report, Guest Home/Pool and Caretakers Cottage
	(195 Farm Road)	09/20/96	Clearly Consultants, Inc.	Geotechnical Investigation, Caretakers Cottage
		06/12/98	Clearly Consultants, Inc.	Proposed Caretakers Cottage Project
	220 Family Farm Road	12/21/00	Romig Engineers, Inc.	Geotechnical Investigation, Sullivan Residence Addition
	230 Family Farm Road	06/20/00	John Coyle & Associates, Inc.	Fault Location Map, Existing Pool House
		06/25/99	Nielsen Geotechnical Incorporated	Soil Report
		08/07/02	Nielsen Geotechnical Incorporated	Basement Recommendations, Remodel Existing Suesthouse
		05/19/03	Nielsen Geotechnical Incorporated	Soil Report, Basement and Attached Garage
		04/28/06	Murray Engineers, Inc.	Supplemental Recommendations, Driveway Retaining Wall
	250 Family Farm Road	04/19/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Soil Foundation Investigation, Proposed New Structures
			William Cotton and Associates	Geotechnical Review Sheet
		09/20/83	Vincent F. Kong	Structural Calculations, Markkula Residence Addition
		09/23/83	Leonard E. Lincoln	Site Plan, with annotations
		11/04/83	William Cotton and Associates	Review- Markkula Residential Addition
		11/14/83	Purcell, Rhodes & Associates	Plan Review, Addition
		11/23/83	William Cotton and Associates	Review- Markkula Residential Addition
		06/28/01	Terrasearch, Inc.	Preliminary Geotechnical Recommendations Regarding Foundation Design, Proposed Room Addition
		07/25/01	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Addition and Remodel for Existing Residence
		06/28/01	Terrasearch, Inc.	Preliminary Geotechnical Recommendations Regarding Foundation Design, Proposed Room Addition
		03/12/02	Earth Investigations Consultants	Soil and Foundation Investigation & Plan Review, Proposed Dry-stack Landscape Retaining Walls, Craft-Malcolm Property
	260 Family Farm Road	03/01/78	Fischer Land Surveys	Tentative Map, Proposed Resubdivision of APN 75-293-110, with annotations
		06/19/78	Purcell, Rhoades & Associates	Geotechnical Hazard Investigation, Parcel 2, Proposed Resubdivision of APN 75-293-110
		09/10/78	William Cotton and Associates	Geologic Review, Eyler Land Division
	270 Family Farm Road	10/03/97	Upp Geotechnology, Inc.	Geotechnical Investigation, New House, Pool and Pool House, Lands of Bonora
		11/18/97	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation, Proposed Leachfield, Bonora Property
		05/21/98	Upp Geotechnology, Inc.	Responses to Geotechnical Review, Proposed House, Pool House, and Pool, Lands of Bonora
		07/02/98	Upp Geotechnology, Inc.	Supplemental Plan Review, Proposed House and Pool House, Lands of Bonora
		08/10/98	Upp Geotechnology, Inc.	Construction Monitoring, Drilled Pier Excavation and Grade Beam Voids, Lands of Bonora
		08/20/98	Upp Geotechnology, Inc.	Supplemental Plan Review, Revisions to Foundation Plan, Lands of Bonora
		08/24/98	Upp Geotechnology, Inc.	Foundation Revisions
		09/17/98	Upp Geotechnology, Inc.	Construction Monitoring, Grade Beam Voids, Bonora Residence and Pool House
		01/30/01	Upp Geotechnology, Inc.	Construction Observation, Pool House, Swimming Pool and Site Retaining Wall
		02/29/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Swimming Pool Extension
	290 Family Farm Road	11/08/82	Perry R. Wood	Proposed On-Site Septec Drainfield, Parcel 2, Lands of Cooper
		04/27/83	Site Characteristics, Inc.	Lands of Cooper Fault Investigation
		05/04/83	William Cotton and Associates	Geotechnical Review Sheet
		05/23/83	William Cotton and Associates	Review, Proposed Land Division, Cooper Parcel
	300 Family Farm Road	07/29/03	Romig Engineers, Inc.	Geotechnical Investigation, Stanton Residence Improvements
		10/04/04	Romig Engineers, Inc.	Responses to Town's Review Comments
		08/15/05	Source 1	Well Permit and Well Log
		04/27/06	Romig Engineers, Inc.	Geotechnical Plan Review Letter, Water Tank and Vault
	310 Family Farm Road	02/03/77	Berloger Long & Associates	Geologic Faulty Investigation
	320 Family Farm Road	07/06/95	Nielsen Geotechnical Incorporated	Foundation Recommendations, Remodel and Second Story Addition
		07/18/95	Nielsen Geotechnical Incorporated	Supplemental Foundation Information, Remodel and Second Story Addition
		07/18/01	Associated Terra Consultants, Inc.	Soils and Foundation Investigation, Retaining Walls
		08/06/02	Associated Terra Consultants, Inc.	Addendum to Soils and Foundation Investigation for Retaining Walls
		08/29/03	Associated Terra Consultants, Inc.	Plan Review of Front and Rear Retaining Walls and Small Landscaping Wall Designs
		09/18/03	Associated Terra Consultants, Inc.	Project Geotechnical Soils Investigation
		10/09/03	Cotton, Shires & Associates	Geotechnical Engineering Review, Cormgan Residence
		10/28/03	Associated Terra Consultants, Inc.	Responses to Comments from Town's Geotechnical Consultant
	350 Family Farm Road	08/24/89	J. V. Lowney & Associates	Geotechnical Investigation, Huggins Residence Addition
			William Cotton and Associates	Geotechnical Review Sheet
		08/09/89	Rinne & Peterson	Structural Calculations
		09/12/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Huggins, Residential Addition PA #7470
	370 Family Farm Road	06/06/02	GeoForensics, Inc.	Geotechnical Consultation, Proposed Garage
		07/03/04	Town	Engineering Geology and Plan Review

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		08/02/04	GeoForensics, Inc.	Review of Plans
		08/08/04	Town	Permit Approval
		12/17/04	GeoForensics, Inc.	Construction Observations (#2)
		06/06/05	GeoForensics, Inc.	Geotechnical Evaluation, Proposed Kitchen Expansions
	381 Family Farm Road	03/29/79	Geoconsultants, Inc.	Fault Location Investigation, McKean Property
		04/10/79	Howard Donely Associates, Inc.	Fault Location Investigation, McKean Property
		05/18/79	William Cotton and Associates	Review
		07/10/79	Howard Donely Associates, Inc.	Geologic and Fault Location Investigation, McKean Property
		08/04/79	William Cotton and Associates	Review
		08/21/79	Howard Donely Associates, Inc.	Fault Setback Locations, McKean Property
		12/28/79	William Cotton and Associates	Review
	420 Family Farm Road	10/09/01	Kern Consulting, Inc.	Geologic and Geotechnical Evaluation, Sandhe/Henry Residence
		10/17/04	Geomatrix Consultants	Geotechnical Review
		10/19/04	Town	Plan Review
		10/30/04	Town	Plan Review
5A	425 Family Farm Road	07/22/05	PGSoils, Inc.	Geotechnical Conditions, Proposed Residential Remodeling
6	FARM HILL ROAD			
	Barkley Park/Fields	?		Report to Planning Commission - Peninsula Christian Center
		05/18/79	Harding-Lawson Associates	Soil and Geological Investigation, Proposed Peninsula Christian Center
		08/30/79	Donald A. Woolfe and Associates	Dreft Environmental Impact Report, Peninsula Christian Center
		11/07/79	William Cotton and Associates	Geotechnical Review Sheet
		11/20/79	Harding-Lawson Associates	Consultation Regarding Soils and Geology, Peninsula Christian Center
		08/25/80	Harding-Lawson Associates	Retaining Wall Design
		11/13/79	William Cotton and Associates	Review of Environmental Impact Report
		0/0/80	Oleg V. Miram, Structural Engineer	Retaining Wall Design
		02/09/81	William Cotton and Associates	Review of Soils and Geological Investigation, Proposed Peninsula Christian Center
		03/05/81	Harding-Lawson Associates	Additional Consultation, Retaining Wall Design
		04/07/81	William Cotton and Associates	Review of 3/5/81 HLA letter
6	FARM ROAD			
	110 Farm Road	09/17/75	Rhoades and Associates	Soil and Geologic Investigation, Earl Residence
		10/20/75	Town of Woodside	Review of 9/17/75 Rhoades and Associates Soil and Geologic Investigation, Earl Residence
		10/20/75	Purcell Rhoades & Associates	Addendum to Soil and geologic Report of September 17, 1975
		10/20/75	Purcell Rhoades & Associates	Determination of Drain Field for Lot 5, Hidden Valley Farms
		10/21/75	Purcell Rhoades & Associates	Utility Fault Crossing Recommendations
		11/13/75	Town of Woodside	Legal Notice
		01/07/76	Purcell Rhoades & Associates	Soil and Geologic Investigation, Lot 5 Hidden Valley Farms
		05/26/76	Purcell Rhoades & Associates	Inspection of Foundation Pier Drilling, Wayne Earl Property
		07/31/85	Leonard E. Lincoln, Architect	Site Plan, with annotations
		08/08/85	Purcell Rhoades & Associates	Soil Report Update, Additions to Existing Foundations
		08/15/85	Town of Woodside	Geotechnical Review Sheet
		08/20/85	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Earl Residential Addition
		11/01/85	William Cotton and Associates	Geologic Review Billing Breakdown, Earl Residential Addition
		01/29/86	Wayne L. Earl	Small Claims Court Claim and Summons
	115 Farm Road (113 Farm Road)	09/17/86	Perry R. Wood	Fault Exploration Trench, Parcel 076-294-01
		03/16/87	Stoecker and Northway Architects incorporated	Request for Variance Plans
	(113 Farm Road)	06/22/87	Perry R. Wood	Fault Exploration Trench, Near Stables
		11/10/87	Dunham & Associates	Foundation Recommendations, Proposed House Addition
		11/16/09	Dunham & Associates	Plan Review, Proposed Addition
			William Cotton and Associates	Geotechnical Review Sheet
		12/28/87	William Cotton and Associates	Geologic and Geotechnical Review, Jacobson Residential Addition, PA #4425
		04/28/97	Steven F. Connelly, C.E.G.	Fault Investigation, Jacobson Property
	(113 Farm Road)	07/31/97	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Dwelling Unit
	120 Farm Road	08/07/06	Earth Investigations Consultants	Geotechnical Investigations, Proposed Residential Remodel
	135 Farm Road	09/17/86	Perry R. Wood	"Fault Investigation"
	165 Farm Road	05/22/02	GeoForensics Inc.	Geotechnical Investigation, Proposed New Deck Supports, Gifford Property
		04/16/03	GeoForensics Inc.	Geotechnical Investigation, Evaluation of New Basement and Retaining Walls
		01/29/04	GeoForensics Inc.	Geotechnical Investigation, Evaluation of the New Accessory Structure, Basement, and Retaining Walls (revised)
		08/18/08	GeoForensics Inc.	Geotechnical Investigation, Proposed Barn, Gifford Property
	170 Farm Road	11/04/74	Berlogar, Long & Associates	Fault Investigation, Lot No. 15, Gerstley Property
		05/15/95	Clearly Consultants, Inc.	Preliminary Geological Investigation, Lot 15, APN 076-029-040
		06/14/96	Lowney Associates	Geotechnical and Geologic Investigation, Volckmann Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		03/27/97	Lowney Associates	Supplemental Geotechnical Recommendations
		09/29/97	Lowney Associates	Proposed Swimming Pool
	185 Farm Road	4/30/81		Structural Calculations for Loustaunou Guest House
			William Cotton and Associates	Geotechnical Review Sheet
		09/03/81	Terratech	Foundation Inspection, Loustaunou Property
		11/05/08	Murray Engineers, Inc.	Geotechnical Services, Harvey Barn & Caretaker Residence
	195 Farm Road	09/20/96	Cleary Consultants, Inc.	Geotechnical Investigation, Caretakers Cottage
6	FERNSIDE STREET			
	1700 Fernside Street	10/09/01	Harlan Tait Associates	Geotechnical Investigation, Lovazzano Residence Addition
		06/05/03	Charles H. Hartsog	Soils/Geotechnical Report
		07/14/04	Charles H. Hartsog	Final Delineated Geotechnical Conditions, Proposed Pool, Response to Comments
		07/14/04	Charles H. Hartsog	Final Delineated Geotechnical Conditions, Proposed Pool, Plan Review
	1730 Fernside Street	05/20/94	Upp Geotechnology, Inc.	Limited Soils Investigation, Additions to Allen Residence and New Pool Cabana
6	FOX HOLLOW ROAD			
	105 Fox Hollow Road	11/09/96	Nielsen Geotechnical Incorporated	Soil Report
		02/28/00	Nielsen Geotechnical Incorporated	Soil Report
		11/05/01	Nielsen Geotechnical Incorporated	Construction Report
	120 Fox Hollow Road	01/28/07	Earth Investigations Consultants	Geotechnical Investigation Update, Proposed Residential Development
		04/04/07	Earth Investigations Consultants	Supplemental Geotechnical Parameters, Basement, Proposed Residential Development
		06/08/09	Earth Investigations Consultants	Geotechnical Investigation Update, Proposed Residential Development
	121 Fox Hollow Road	02/05/09	Romig Engineers, Inc.	Geotechnical Investigation, Caldwell Swimming Pool
		01/14/11	Romig Engineers, Inc.	Geotechnical Investigation, Caldwell Residence Addition
	125 Fox Hollow Road	09/28/07	Murray Engineers, Inc.	Geotechnical Investigation, Creek Bank Stabilization
		08/13/08	Murray Engineers, Inc.	Supplemental Geotechnical Evaluation, Creek Bank Stabilization, Sterling Property
		10/08/08	Murray Engineers, Inc.	Supplemental Information, Geotechnical Investigation, Creek Bank Stabilization, Sterling Property
	130 Fox Hollow Road	10/28/04	Murray Engineers Inc.	Limited Geotechnical Study, Pool House Improvements
	131 Fox Hollow Road	04/20/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed New House
		10/16/95	Earth Investigations Consultants	Geotechnical Investigation, Proposed Creek Repair
		11/27/96	Earth Investigations Consultants	Geotechnical Services, Proposed Creek Repair
		07/25/01	Earth Investigations Consultants	Geotechnical Investigation
		03/28/02	Earth Investigations Consultants	Engineering Geologic Review
	180 Fox Hollow Road	11/19/68	Crosby and Associates	Preliminary Geologic & Soil Investigation, Play Pen Subdivision
		06/26/95	Jo Crosby & Associates	Addendum to the Geotechnical Investigation for the Planned Guest Cottage
		02/27/06	Michelucci & Associates, Inc.	Geotechnical Consultation
6	190 Fox Hollow Road	11/05/90	Tejima and Associates, Inc.	Geotechnical Investigation, Proposed One-Story Guest House, Existing Herzig/Wohlers Residence
		03/16/93	Carl W. Garbe, P.E.	Soils and Foundation Report, Proposed Outbuilding
		05/23/06	Murray Engineers, Inc.	Geotechnical Investigation, Wohlers/Herzig Residence
6A	FRIARS LANE			
	2, 4, 6, 8 Friars Lane	6/0/75	Paul E. Nowack	Preliminary Map, Lands of Tsugagawa
		04/19/76	Dunham & Associates	Soil and Geologic Investigation, Proposed 4-Lot Subdivision, Lands of Tsukagawa, La Honda Road
		05/12/76	Town of Woodside	Review of Soil and Geologic Investigation Report
		05/27/76	Town of Woodside	Review of Preliminary Map of Proposed Curtain Drains as Mitigation Measure to Control Potential Slope Instability in Leach Field areas
		06/14/76	Town of Woodside	Review of Modified Preliminary Map
		06/16/76	Town of Woodside	Summary of Review and Recommendations Concerning Tsukagawa
		06/22/76	Town of Woodside	Planning Commission Minutes
		07/20/76	Dunham & Associates	Addendum, Proposed 4-Lot Subdivision, Lands of Tsukagawa, La Honda Road
		08/09/76	Town of Woodside	Review of Supplemental Geologic Report
		08/19/76	F. A. Stejer	Supplementary Geologic Report No. 2 - Proposed 4-Lot Subdivision, Lands of Tsukagawa
		08/25/76	Town of Woodside	Review of Supplemental Geologic Report No. 2
		01/23/77	Allan E. Newlands	Letter to Town Council
		?	?	Site Plan, Plate 1
		?	?	Cross Section A-A', Plate 2
		02/08/77	Town of Woodside	Review of Revised Preliminary Map dated 2/4/77
	2 Friars Lane	07/04/77	?	Site Plan, with annotations
		07/13/77	Town of Woodside	Review of Revised Building Site on Plot Plan dated 7/4/77
		07/20/77	Town of Woodside	Discussion of Cut Slopes, Land Division No. 224, Tsukagawa (Cooper-Hamilton)
	2 Friars Lane	03/23/78	Walter Boike	Letter to Woodside Planning Commission

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	2 Friars Lane	03/23/78	Fred Banning	Letter to Woodside Planning Commission
	2 Friars Lane	03/28/78	Town of Woodside	Report to the Planning Commission
	8 Friars Lane	05/01/97	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, proposed Tennis Court, Shaw Property
6A	GLENCRAG WAY			
	626 Glencrag Way	03/13/78	Howard Donley Associates	Geotechnical and Drainfield Investigation, Proposed Single Family Residence, Lots 11-15, Block 204, APN 68-142-190, Nance
		03/12/78	Howard Donley Associates	Summary Slope Stability
		04/18/78	Leighton and Associates	call to applicant re: consultant charges
		04/24/78	County of San Mateo	Proposed Variance #229 (Nance)
		06/14/78	Leighton and Associates	Review of 3/13/78 Report
		11/15/78	Howard Donley Associates	Response to 10/30/78 Memorandum from Town Geologist
		1/0/78	Fred Blomquist & Associates	Site Plan & Topographic Map
	650 Glencrag Way	07/16/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition and Detached Studio
	655 Glencrag Way	03/25/85	J. V. Lowney & Associates	Geotechnical Investigation, Harrington Residence
	700 Glencrag Way	12/05/08	Murray Engineers, Inc.	Limited Geotechnical Investigation, Carport/Deck Reconstruction, Krensky
		09/29/09	Murray Engineers, Inc.	Supplemental, Limited Geotechnical Investigation, Retaining Wall Reconstruction, Krensky Property
	799 Glencrag Way	07/07/78	Dunham & Associates	Soil Investigation, Proposed Land Division, Lots 14-23, Block 200 - Cowan
		08/25/78	Edward A. Danehy	Engineering Geologic Investigation of Septic Drain-Field Sites, Proposed Resubdivision of Lots 14-23, Block 200, Emerald Lake Estates, SD2
		9/0/78	Redmond Walsh	Proposed Lot Line Adjustment, Lots 14-23, Block 200, Emerald Lake Estates, Subdivision 2, one with annotations
		12/12/78	William Cotton and Associates	Summary of Field Review of Casey Land Division 255 and Soil and Geologic Report
		05/18/79	William Cotton and Associates	Review of above
		01/18/82	Dunham & Associates	Soil Investigation, Proposed Home, Parcel "B", Block 200, Estates of Emerald Lake No. 2 (APN 068-292-180)
		10/16/07	Carl W. Garbe	Soil Conditions, Landscaped Area (below and adjacent to house)
		03/07/08	Carl W. Garbe	Landscaping
		05/20/08	Carl W. Garbe	Proposed Landscaping
	841 Glencrag Way	07/16/97	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Foundation Improvements
6A	GLENWOOD AVENUE			
	104 Glenwood Avenue	11/10/92	JCP Geologists - Engineers	Soil and Foundation Service, Proposed Additions to Home
	140 Glenwood Avenue	05/31/96	Upp Geotechnology, Inc.	Geotechnical Investigation, Proposed Residence, Pinkerton Property
		07/06/04	Upp Geotechnology, Inc.	Geotechnical Update, Proposed New Garage, Pinkerton Property
	207 Glenwood Avenue	4/0/88	Applied Earth Sciences Consultants	Soil and Geologic Investigation
		09/14/88	William Cotton and Associates	Geotechnical Review Sheet
		02/22/08	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Chivington Addition, VAR-438
		undated	Applied Earth Sciences Consultants	Geotechnical Investigation, Driveway Improvements, Chivington Residence
		08/14/09	various	Package Containing Various Documents Pertaining to Driveway Remediation Plan
		02/22/08	Milstone Geotechnical	Geotechnical Design Memorandum - Retaining Wall Design Parameters
		02/22/08	Applied Earth Sciences Consultants	Cross Section A-A' Showing Existing and Original Ground Surfaces
	232 Glenwood Avenue	08/13/09	GeoForensics, Inc.	Geotechnical Investigation, New Residence and Relocated Detached Garage
	235 Glenwood Avenue	07/09/93	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Foundation Modifications
	240 Glenwood Avenue	10/10/05	Romig Engineers, Inc.	Foundation Recommendations, Proposed Bath Room
	243 Glenwood Avenue	04/20/89	Richard Hanson, Civil Engineer	Structural Calculations
		04/25/89	Upp Geotechnology, Inc.	Geotechnical Investigation
		06/09/89	Upp Geotechnology, Inc.	Review of Foundation Plans, Russo Residence
			William Cotton and Associates	Geotechnical Review Sheet
	271 Glenwood Avenue	09/30/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel and Second-Story Addition
		10/02/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Detached Deck, Burson Residence
	303 Glenwood Avenue	11/19/02	J. Yang and Associates	Geotechnical Site Inspection, Proposed Remodel of House
		02/05/03	J. Yang and Associates	Review Comments
		02/10/03	J. Yang and Associates	Geologic Cross Section
	308 Glenwood Avenue	12/29/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Additions
		01/06/04	Earth Investigations Consultants	Supplemental Foundation Recommendations
	421 Glenwood Avenue	05/23/94	Michelucci & Associates, Inc.	Geotechnical Investigation, Gerhardt Residence
		01/26/05	Romig Engineers, Inc.	Geotechnical Update, Gerhardt Residence Addition

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	475 Glenwood Avenue	09/19/79	PSC Associates, Inc.	Soil and Geologic Investigation, Proposed Residence on Parcels 073-063-190 and 073-063-200
		08/22/80	William Cotton, Town Geologist	Geotechnical Review, Ratcliff
		10/06/80	PSC Associates, Inc.	Additional Work, Soil and Geologic Investigation, Proposed Residence on Parcels 073-063-190 and 073-063-200
6A	GODETIA DRIVE			
	988 Godetia Drive	12/20/00	Upp Geotechnology, Inc.	Geotechnical Feasibility Investigation, Three-Parcel Subdivision, Lands of Alexanyan
		06/19/02	Upp Geotechnology, Inc.	Limited Soils and Foundation Investigation, Proposed Addition to Residence, Alexanyan Property
		05/02/03	Upp Geotechnology, Inc.	Supplemental Limited Soil and Foundation Investigation, Alexanyan Property
	999 Godetia Drive	05/22/09	JF Consulting, Inc.	Geotechnical Investigation, New Residence
		11/23/09	JF Consulting, Inc.	Revision of Seismic Parameters, Basement Retaining Walls, New Residence
	1000 Godetia Drive	09/10/03	Carl W. Garbe, P.E.	Soil/Foundation Report, Proposed Retaining Wall
		09/11/07	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Improvements
	1104 Godetia Drive	04/02/79	William Cotton and Associates	Review Comments - Lot Line Adjustment
		04/11/79	J. R. Mackay	Site Plan
		04/30/79	William Cotton and Associates	Geotechnical Review Sheet
	1011 Godetia Drive	10/11/78	Dunham & Associates	Soil Investigation, Proposed Home
	1020 Godetia Drive	12/29/06	Earth Investigations Consultants	Geotechnical Investigations
	1075 Godetia Drive	06/25/78	Purcell, Rhodes & Associates	Soil Investigation, Proposed Swimming Pool
		11/19/02	Earth Investigations Consultants	Soil and Foundation Investigation
	Godetia Road/Summerset Place Subdivision	09/09/81	Cleary Consultants, Inc.	Preliminary Geotechnical Investigation, 6.9 Acre Parcel at Canada Road and Godetia Road
		09/28/10	William Cotton and Associates	Godetia School Site/Redwood City School District Property
	1225 Godetia Road	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision
			William Cotton and Associates	Geotechnical Review Sheet
		05/28/89	Kwan & Associates	Structural Calculations
		09/15/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Bianchini, PA #7382
		09/25/89	Cleary Consultants, Inc.	Review of Grading and Foundation Plans, Lot 2
		09/26/89	Cleary Consultants, Inc.	Review of Landscape Plans, Lot 1
		09/27/89	Cleary Consultants, Inc.	Supplemental Geotechnical Review, Bianchini, PA #7382
		07/07/89	The Russell Group, Architects	Site Plan, with geologic annotations
	1250 Godetia Drive	04/25/05	Romig Engineers, Inc.	Geotechnical Investigation, Gregory Pool House
		02/13/09	Romig Engineers, Inc.	Supplemental Recommendations, New Deck
		10/12/09	Romig Engineers, Inc.	Supplemental Recommendations, New Retaining Wall and Patio
6A	1270 Godetia Drive	03/01/76	Geo-Ekta Laboratories / Gross & Associates, Inc.	Foundation Soils Investigation and Geologic Investigation, Lot 1 and Lot 5
		02/23/94	J. Yang and Associates	Geotechnical Site Investigation - draft
		05/09/94	Darwin Meyers Associates	Geologic Hazards Reconnaissance
		06/02/94	J. Yang and Associates	Geotechnical Site Investigation
		06/24/04	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
		08/13/04	Steven F. Connelly, C.E.G.	Feasibility Investigation, Proposed Subdivision
7	GRANDVIEW DRIVE			
	125 Grandview Drive	05/05/92	JCP Geologists - Engineers	Geotechnical Services for Distressed Home
		04/10/96	Hoexter Consulting, Inc. / Romig Consulting Engineers	Engineering Geologic Reconnaissance and Feasibility Evaluation, Proposed Renovation and Additions
	136, 140, 166 Grandview Drive	03/11/74	Geolabs - Northern California, Inc.	Foundation Engineering and Engineering Geology Investigation, 4.65-Acre Parcel
		03/16/74	William Cotton	Review of GNC 3/11/74 Foundation Engineering and Engineering Geology Investigation, 4.65-Acre Parcel Report
		01/20/77	Leighton and Associates	Review of GNC 3/11/74 Foundation Engineering and Engineering Geology Investigation, 4.65-Acre Parcel Report
		01/27/77	Gordon Dowsett, Architect	Proposed Residence
		02/09/77	Purcell, Rhodes & Associates	Geologic Review and Reconnaissance, 4.65-Acre Parcel 1
		02/18/77	Leighton and Associates	Review of 2/9/77 PRA Geologic Review and Reconnaissance, 4.65-Acre Parcel 1
		04/04/77	Purcell, Rhodes & Associates	Foundation Plan Review
		07/28/77	Purcell, Rhodes & Associates	Soil and Geologic Investigation, Proposed Home, Lot 12, Block 3, Skywood Acres
		08/01/77	Watry Engineering, Inc.	Structural Calculations
		08/18/77	Leighton and Associates	Review of PRA 8/4/77 Foundation Plan Review
	277 Grandview Drive	04/05/02	Upp Geotechnology, Inc.	Reconnaissance Geologic Investigation, Lands of Denko/Hudson APN 75-220-240
		05/22/03	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Denko/Hudson
	280 Grandview Drive	02/20/90	Earth Systems Consultants	Soil Report, Davison Residence Addition
		02/09/05	Earth Systems Consultants	Update Soil Engineering Study, Davison Residence Addition (Proposed)
		06/03/05	Earth Systems Consultants	update Soil Engineering Study Supplement, Proposed Davison Residence Additions

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	300 Grandview Drive	10/14/97	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residential Addition
		07/27/07	Murray Engineers, Inc.	Geotechnical Investigation, Retaining Wall Improvements
		07/29/10	Romig Engineers, Inc.	Geotechnical Status Report, Retaining Wall Improvements
	303 Grandview Drive	08/15/85	Tim J. Manzagol	Letter and Deposit requesting Town Geologist Field Inspection of LD Boring in Landslide
		8/16, 19/85	William Cotton and Associates	Internal Memo on Field Inspection Request
		08/20/85	William Cotton and Associates	Phone Notes on call with Tim Manzagol
7	GREENWAYS DRIVE			
	2132 Greenways Drive	07/19/04	Romig Engineers, Inc.	Geotechnical Investigation, Foundation Improvements
		06/04/08	Romig Engineers, Inc.	Supplemental Geotechnical Investigation, Nieva Detached Garage and Swimming Pool
		09/22/08	Romig Engineers, Inc.	Geotechnical Investigation, Nieva Residence, Garage, and Pool
	2185 Greenways Drive	04/03/08	Michelucci & Associates, Inc.	Preliminary Geotechnical Investigation, Existing Single-Family Residence
7	GREER ROAD			
	151 Greer Road	08/12/08	Milstone Geotechnical	Geotechnical Investigation, Proposed Kitchen Addition, Barry Residence
	161 Greer Road	09/02/93	Dunham & Associates	Geotechnical Engineering Evaluation, Proposed Addition and Carport
	190 Greer Road	11/09/00	Earth Investigations Consultants	Engineering Geologic Evaluation, Active Faulting Across Property
		03/14/02	Romig Engineers, Inc.	Geotechnical Investigation, Barger Residence
	220 Greer Road	12/15/72	Jo Crosby & Associates	Geologic Investigation, Parcel B, Land Division Map No. 111
		12/06/73	Jo Crosby & Associates	Geologic Exploration, Auchincloss Property
		12/04/98	Nordmo Associates	Geotechnical Report, Proposed Studio and Conservatory
		12/08/98	Hydro-Geo Consultants, Inc.	Preliminary Geologic Conditions, proposed Conservatory and Studio
		01/13/99	Hydro-Geo Consultants, Inc.	Addendum to 12/8/98 Geologic Report, Modified Plot Plan
		06/07/99	Nordmo Associates	Geotechnical Plan Review, proposed New Studio Building
		01/31/00	Upp Geotechnology, Inc.	Engineering Geologic Investigation, Kepecs Property
		02/28/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Information, Kepecs Property
		03/17/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Information (Number 2), Kepecs Property
		04/17/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Information, Kepecs Property
		05/18/00	Nordmo Associates	3rd Geotechnical Plan Review, Proposed New Studio Building
		11/19/01	Romig Engineers, Inc.	Geotechnical Investigation, New pool and Tea House
	223 Greer Road	05/20/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property
		05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Proposed Walker Homesite
		05/24/74	Applied Soil Mechanics	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
		11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Walker Residence (APN 072-051-140)
		08/30/89	Lea Engineering	Structural Calculations
		09/07/89	Lea Engineering	Cantilever Retaining Wall Program
		11/16/89	Roger Kelley Kohler Architect	Site Plan with annotation
			William Cotton and Associates	Geotechnical Review Sheet
		02/21/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Coe Additions, PA #7624
		04/04/90	Applied Soil Mechanics	Update Geologic Evaluation, Proposed Addition to Existing Mitchell-Coe Residence
		04/25/90	Applied Soil Mechanics	Foundation Plan Review, Proposed Addition to Existing Mitchell -Coe Residence
		04/27/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Coe Additions, PA #7624
		05/15/00	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Garage and Addition
	239 Greer Road	05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
		11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Residence (APN 072-051-140)
	250 Greer Road	12/21/71	Jo Crosby & Associates	Geologic and Feasibility Investigation, Proposed Greer Highlands
		01/19/72	Jon C. Cummings, Town of Woodside	Review of Geologic Report and Revised Preliminary Map, Proposed Greer Highlands
		08/13/98	Michelucci & Associates, Inc.	Geotechnical Consultation, Creek Bank Collapse
		06/09/09	Murray Engineers, Inc.	Fault Exploration Trenching, McCown Property
		06/11/09	Murray Engineers, Inc.	Fault Evaluation Investigation
	265 Greer Road	05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
		11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Residence (APN 072-051-140)
	280 Greer Road			
		12/21/71	Jo Crosby & Associates	Geologic and Geasibility Investigation, Proposed Greer Highlands
		01/19/72	Jon C. Cummings	Review of Geologic Report and Revised Preliminary Map, Proposed Greer Highlands
		12/26/78	Cooper-Clark & Associates	Geologic Hazards Evaluation, Phase 1, Residential Subdivision
		01/27/81	William Cotton, Town of Woodside	Geologic Review of above
		06/05/81	Cooper-Clark & Associates	Geotechnical Investigation, Proposed 23-Acre Subdivision
		11/11/88	Upp Geotechnology, Inc.	Reconnaissance Investigation, Proposed Road Alignment, Lands of Pearson, 23 acre Parcel

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		12/16/88	Upp Geotechnology, Inc.	Reconnaissance Geotechnical Investigation, Proposed Building Site, Lands of Pearson, 23 acre Parcel
		01/10/89	Upp Geotechnology, Inc.	Reconnaissance Investigation, Proposed Road Alignment, Lands of Pearson, 23 acre Parcel
		01/15/89	Churchill & Associates	Site Development Application
		09/30/91	Applied Earth Sciences Consultants	Summary of Water Well Drilling and Testing near West Union Creek, Lands of Pearson
		11/26/91	Upp Geotechnology, Inc.	Geotechnical Reconnaissance, Proposed Bridge for Creek Crossing, Lands of Pearson
		02/10/95	Upp Geotechnology, Inc.	Geotechnical Update Letter, Proposed Bridge for Creek Crossing, Lands of Pearson
		05/30/95	Upp Geotechnology, Inc.	Geotechnical Update Letter, Proposed Bridge for Creek Crossing, Lands of Pearson
		09/06/95	Upp Geotechnology, Inc.	Update Reconnaissance Investigation, Proposed Access Way, Lands of Pearson
7	291 Greer Road	05/24/74	Burkland and Associates	Geologic and Seismic Hazards Investigation, Walker Property (APN 072-051-140)
		11/06/74	Applied Soil Mechanics	Soil Investigation, Proposed Residence (APN 072-051-140)
		05/01/95	Nielsen Geotechnical Incorporated	Geotechnical Report
7A	300 Greer Road	0/0/04	Various	File with Drawings, Photographs, and Repair Scheme for Landslide Repair
	381 Greer Road	12/21/71	Jo Crosby & Associates	Geologic and Feasibility Investigation, Proposed Greer Highlands
		01/19/72	Jon C. Cummings	Review of Geologic Report and Revised Preliminary Map, Proposed Greer Highlands
	381 Greer Road	12/21/71	Jo Crosby & Associates	Geologic and Feasibility Investigation, Proposed Greer Highlands
		01/19/72	Jon C. Cummings	Review of Geologic Report and Revised Preliminary Map, Proposed Greer Highlands
7A	HACIENDAS DRIVE			
	38 Haciendas Drive	01/10/75	Berloger, Long & Associates	Soil Engineering and Engineering Geologic Investigation, Lots 19, 20, and 21, Las Haciendas Tract
		04/28/77		Plot Plan with annotations
		08/15/78	William Cotton and Associates (?)	Results of Review
		08/28/78	William Cotton and Associates	Geotechnical Review
		03/13/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Swimming Pool
7A	HARCROSS DRIVE			
	165 Harcross Road	02/17/98	Romig Consulting Engineers	Geotechnical Study, Residence Addition
		08/20/01	Romig Consulting Engineers	Geotechnical Investigation, Retaining Walls
	185 Harcross Road	12/19/89	Hallenbeck & Associates	Preliminary Geotechnical Engineering Inspection
		03/31/90	JR Engineering & Structures	Foundation Plan & Details, Proposed Reveleving of First Floor Level
			William Cotton and Associates	Geotechnical Review Sheet
		04/03/90	JR Engineering & Structures	Floor Re-Leveling Operation, Skarston Residence
	320 / 450/ 460 Harcross Road	12/29/77	Joe Crosby & Associates	Geologic and Soil Investigation, 48 Acres (Rancho De Las Pulgas)
		01/07/78	Perry R. Wood	Soil Percolation Tests, Lots 1-20, Parcel No. 2, Land Division Map No. 162
	320 Harcross Road	01/10/00	Ting & Associates, Inc.	Geotechnical Investigation, Proposed Pool House and Loggia
		03/04/00	Ting & Associates, Inc.	Foundation Plan Review and Supplemental Foundation Drain Recommendations, Proposed Pool House/Loggia
7A	HARDWICK ROAD			
	110 Hardwick Road	01/30/02	Romig Engineers, Inc.	Geotechnical Study, Residence Addition
		08/20/08	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Additions
	150 Hardwick Road	11/22/94	Nielsen Geotechnical Incorporated	Soil Report
		09/29/03	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Addition and Pool House
		06/02/04	Nielsen Geotechnical Incorporated	Revised Geotechnical Recommendations, Addition and Pool House
		04/14/06	Murray Engineers, Inc.	Supplemental Recommendations, Kitchen-Dining Room Addition
		04/13/11	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Entry Trellis Improvements
	155 Hardwick Road	08/16/90	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Second-Story Addition
	160 Hardwick Road	02/11/05	Murray Engineers, Inc.	Geotechnical Investigation, Barhoum Residence Improvements
		05/17/05	Murray Engineers, Inc.	Supplemental Retainig Wall Recommendations & Geotechnical Plan Review, Residence Improvements
	187 Hardwick Road	07/11/02	Earth Systems Consultants, Northern California	Geologic Hazards Evaluation and Soil Engineering Study, Tesfaya Residence (Proposed Remodel and Additions)
		09/12/02	Cotton, Shires & Associates, Inc.	Geotechnical Engineering Review, Tesfaya Residence
		01/13/03	Earth Systems Consultants, Northern California	Additional Geotechnical Engineering Study fo Drainage Dissipater Trench, Tesfaya Residence
		01/13/03	Earth Systems Consultants, Northern California	Response to Geotechnical Engineering Comments
		10/01/07	ES Geotechnologies	Supplement to Soil Engineering Study, Proposed Spa, Tesfaya Residence
	197 Hardwick Road	05/05/06	J. Yang and Associates	Geotechnical Site Investigation, House Addition and Remodel House
		06/03/08	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Sullivan Property
		09/05/08	GeoForensics, Inc.	Geotechnical Slope Evaluation, Sullivan Property
		06/01/09	GeoForensics, Inc.	Geotechnical Slope Evaluation (#3), Sullivan Property
	199 Hardwick Road	07/28/04	GeoForensics, Inc.	Geotechnical Investigation, Proposed Swimming Pool, Kutay Property

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
7A	220 Hardwick Road	02/25/02	Nielsen Geotechnical, Inc.	Soil Report
		11/29/05	Murray Engineers, Inc.	New Engineer-of-Record & Supplemental Recommendations, Site Retaining Walls
8	HIDDEN VALLEY LANE			
	15 Hidden Valley Lane	07/12/67	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Proposed Homesite, Lot 12, Tract 104, Hidden Valley Farms Subdivision
		06/21/00	Romig Engineers, Inc.	Geotechnical Recommendations, Planned Tennis Court
		09/14/00	Romig Engineers, Inc.	Geotechnical Investigation, Davison Residence
		02/21/01	Romig Engineers, Inc.	Fault Trenching Investigation, New Residence
		03/07/01	Louis A. Richardson	Addendum to Fault Investigation
		03/14/01	Romig Engineers, Inc.	Supplemental Recommendations, New Residence
		09/26/11	Romig Engineers, Inc.	Geotechnical Study, Detached Garage
	25 Hidden Valley Lane	11/02/77	Berlogar, Long & Associates	Geotechnical Investigation, Proposed Residence
		05/22/96	Clearly Consultants, Inc.	Geotechnical Investigation, New Guest House
		04/22/99	Nielsen Geotechnical Incorporated	Soil Report
	45 Hidden Valley Lane	04/10/96	Nielsen Geotechnical Incorporated	Review of Existing Foundation, Conversion of Storage Room to Office Space
		11/07/07	Romig Engineers, Inc.	Geotechnical Investigation, Matsumoto Guest House
		03/12/08	Romig Engineers, Inc.	Liquefaction Analysis, Matsumoto Guest House
8	HIGH ROAD			
	High Road @ Woodside Road	11/21/72	Geo-Ekta Laboratories	Preliminary Foundation Soils Investigation
		08/01/72	Edward W. Baca	Tentative Map, Lands of Cavaliere
	880 High Road	07/16/01	Don Hillebrandt Associates	Geotechnical Investigation, Family/Breakfast Room Addition, Master Bathroom Extension and New Front Entry
		09/01/01	Don Hillebrandt Associates	Supplement to 07/16/01 DHA report
		06/13/05	Don Hillebrandt Associates	Geotechnical Investigation, Dining Room Addition & Kitchen Renovation
	929 (?) High Road	03/01/77	Dunham and Associates	Site Evaluation, Proposed Land Division, Mowry
		03/31/77	Leighton and Associates	Review of above report
		04/25/77	Francis A. Stejer	Engineering Geologic Study, Parcel 4 (Vol. 5, LLS page 144), Mowry
		04/27/77	Leighton and Associates	Review of above report
		05/17/77	Francis A. Stejer	Response to Critique by Leighton and Associates re: Engineering Geologic Study, Parcel 4 (Vol. 5, LL page 144)
		05/27/77	Leighton and Associates	Review of above response
		07/26/77	Dunham and Associates	Soil Engineering Evaluation, Proposed Land Division (2 lots), Parcel 4 (Vol. 5, LLS page 144)
		08/16/77	Leighton and Associates	Review of above report
		08/29/77	Francis A. Stejer	Reply to Leighton and Associates Critique dated May 27, 1977
		10/06/77	Leighton and Associates	Review of above response
		10/19/77	San Mateo County	Proposed Land Division #235 (Mowry)
		11/30/77	Dunham and Associates	Proposed Land Division No. 235, High Road
		12/29/77	Dunham and Associates	Proposed Land Division No. 235, High Road
	930 High Road	04/30/97	Earth Investigations Consultants	Geotechnical Services, Geotechnical Design Parameters, Proposed New Patio & Cottage Improvements
		05/26/05	Earth Investigations Consultants	Geotechnical Parameters, Proposed Swimming Pool
	930 / 1040 High Road	08/14/90	Clearly Consultants, Inc.	Geotechnical Investigation, Proposed Property Division and Construction of Two New Residences
	961 High Road	04/10/90	JCP Geologists - Engineers	Soil and Foundations Study, Proposed Residence, Swimming Pool, Cabana and Guest House
			William Cotton and Associates	Geotechnical Review Sheet
		06/13/90	Lea Engineering	Site Study Plan, with annotation
		06/14/90	Lea Engineering	Structural Calculations
		06/15/90	County of San Mateo, Department of Health Services	Review of Septic System, Sculley Parcel
		06/21/90	JCP Geologists - Engineers	Review of Septic Plans
		07/03/90	JCP Geologists - Engineers	Review of House Plans
		07/09/90	Lea Engineering	Comment of 37% slope.
		08/01/90	Town of Woodside	Staff Report for Planning Commission, 941 (961) High Road
		01/12/07	Romig Engineers, Inc.	Geotechnical Investigation, Basement Addition, Garage Wall Repair, and Swimming Pool
		04/12/07	Romig Engineers, Inc.	Underpinning of Dining Room, Maslak Residence
	1031 High Road	04/20/01	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Garage, Foundation Retrofit
	1040 High Road	08/14/90	Clearly Consultants, Inc.	Geotechnical Investigation, Two New Residences
			William Cotton and Associates, inc.	Geotechnical Review Sheet
		03/19/91	William Cotton and Associates, inc.	Supplemental Geotechnical Review, Browne Land Division 313
		04/27/05	Murray Engineers, Inc.	Geotechnical Engineers, Ellis Residence Improvements
	1061 High Road	08/22/90	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Residence
		03/18/91	JCP Geologists - Engineers	Update Services, Proposed Residence
		07/26/93	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Pool House and Swimming Pool

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	1065 High Road	06/29/94	J. Yang and Associates	Soil and Foundation Study, Proposed Residence
		10/27/94	J. Yang and Associates	Soil and Foundation Study, Proposed Residence
8	HIGHLAND TERRACE			
	115 Highland Terrace	12/20/07	PGSoils, Inc.	Geotechnical Investigation
	120 Highland Terrace	01/21/95	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Two-Story Addition and Garage
	127 Highland Terrace	03/30/05	Murray Engineers Inc.	Geotechnical Investigation, Residence Improvements
	150 Highland Terrace	02/01/05	Murray Engineers Inc.	Geotechnical Investigation, Residence Improvements
	251 Highland Terrace	03/14/97	Nielsen Geotechnical Incorporated	Soil Report
		01/15/03	Romig Engineers, Inc.	Geotechnical Investigation, Large Residence Addition
	255 Highland Terrace	01/18/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development
		03/24/03	Earth Investigations Consultants	Supplemental Site Characterization & Preliminary Plan Review, Proposed Residential Development
	303 Highland Terrace	02/08/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Additions
	320 Highland Terrace	02/28/01	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions
	325 Highland Terrace	05/17/96	PGSoils, Inc.	Subsurface Condition, Proposed Residence
8	328 Highland Terrace	11/04/88	Michelucci & Associates, Inc.	Geotechnical Study, Proposed Additions to Residence
8A	HILLSIDE DRIVE			
	127 Hillside Drive	04/29/94	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Proposed Addition/Modifications to Residence
	260 Hillside Drive	01/27/99	GeoForensics, Inc.	Keystone Retaining Wall Design, Wenrick Property
		08/10/01	GeoForensics, Inc.	Proposed Retaining Wall, Wenrick Property
	303 Hillside Drive	11/19/10	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Detached Garage and Evaluation of Replaced Rear House Foundation
		07/01/11	GeoForensics, Inc.	Review of Plans, Proposed Residential Remodel
	307 Hillside Drive	12/10/01	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Exterior Deck
		07/12/02	Michelucci & Associates, Inc.	Review of Plans, Proposed Attached Rear Yard Deck
		11/04/02	Michelucci & Associates, Inc.	Pier Excavation Observation, Attached Elevated Rear Yard Deck
	308 Hillside Drive	01/14/02	Nielsen Geotechnical, Inc.	Foundation Detail / Specifications, Taylor Garage
		06/10/02	Nielsen Geotechnical Incorporated	Plan Review, Replacement Garage
		11/05/02	Nielsen Geotechnical Incorporated	Final report, Replacement Garage
	309 Hillside Drive	09/08/05	Romig Engineers, Inc.	Geotechnical Investigation, Bouthillette Residence
		12/19/07	Romig Engineers, Inc.	Geotechnical Investigation, Residence Remodel
	320 Hillside Drive	05/23/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions and Remodel
	340 Hillside Drive	04/02/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Residence and Garage, Gabittas Property
	404 Hillside Drive	11/30/95	Fowler & Associates	Geotechnical Investigation, Peterson Residence
		06/04/02	Fowler & Associates	Geotechnical Consultation, Proposed Addition
	428 Hillside Drive	08/08/94	Nielsen Geotechnical Incorporated	Modified Soil Report
		04/27/98	Nielsen Geotechnical Incorporated	Plan Review and Supplemental Recommendations
		05/10/04	Nielsen Geotechnical Incorporated	Plan Review
		12/14/07	Murray Engineers, Inc.	Summary of Earthwork Observations, Smith/Leigh Residence & Property Improvements
	444 Hillside Drive	04/06/02	Dave Olnes P.E. Inc.	Geotechnical Reconnaissance
	515 Hillside Drive	11/16/05	Romig Engineers, Inc.	Geotechnical Investigation, Mainz Deck Replacement
8A	HOBART HEIGHTS ROAD			
	155 Hobart Heights Road	08/13/96	United Soil Engineering, Inc.	Geotechnical Investigation, Proposed Residence Addition
		07/08/97	Jo Crosby & Associates	Geological Conditions, Proposed Addition
		08/31/06	Romig Engineers, Inc.	Geotechnical Investigation, Swimming Pool
8A	HOME ROAD			
	1 Home Road	11/13/92	Applied Earth Sciences Consultants	Geologic Investigation, Site Developemnt Feasibility, 6.1-acre Parcel, Parcel B, Woodside Country Club Properties, Subdivision No.1

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	27 Home Road	02/19/93	John Coyle & Associates, Inc.	Geologic Investigation, Proposed Addition, Thurlow Property
		05/17/93	Raleigh Engineering	Foundation Investigation, Proposed Single Family Residence Addition
	1439 Home Road	07/24/00	Nielsen Geotechnical, Inc.	Soil Report
		07/17/06	Romeig Engineers, Inc.	Geotechnical Investigation, Ross Leclerc Residence
9	JANE DRIVE			
	112 Jane Drive	06/17/92	Michelucci & Associates, Inc.	Geotechnical Additions, Proposed Additions
		06/09/93	Haro, Kasunich and Associates, Inc.	Supplemental Geotechnical Investigation and Foundation Design Criteria, Underpinning Two-story Addition
	136 Jane Drive	01/09/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Slope Movement, Drainage and Structural Distress, Berghom Residence
			William Cotton and Associates	Geotechnical Review Sheet
		07/11/87	Upp Geotechnology, Inc.	Review of Retaining Wall Foundation Plans, Finch Property
		04/28/88	Robelo / Kocjan Associates, Inc.	Structural Calculations
		06/13/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Finch Retaining Wall, PA #4666
		07/28/88	William Cotton and Associates	Supplemental Geotechnical Review, Finch Retaining Wall, PA #4666
		09/26/88	Upp Geotechnology, Inc.	Retaining Wall Backfill, Finch Property
	148 Jane Drive	2/12/10	JF Consulting, Inc.	Geotechnical Investigation
	160 Jane Drive	04/28/99	Cleary Consultants, Inc.	Geotechnical Investigation, Planned Additions to Existing Residence
		02/23/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Improvements
		10/22/07	GeoForensics, Inc.	Limited Geotechnical Investigation, Proposed Williams Barn Extension
	165 Jane Drive	05/25/06	Romig Engineers, Inc.	Geotechnical Investigation, Upson Residence
	185 Jane Drive	05/16/05	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Barn
		10/10/06	GeoForensics, Inc.	Geotechnical Recommendations, Proposed New Pool
	190 Jane Drive	09/15/92	John P. Nielsen, Ph.D.	Limited Soil Report
		10/22/07	GeoForensics, Inc.	Limited Geotechnical Investigation, Proposed Barn Extension, Williams Property
	212 Jane Drive	11/08/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Navarro Property
	315 Jane Drive	07/11/86	Purcell, Rhodes & Associates	Soils and Foundation Study, Lot 2, Jane Drive, Meadow Vista Subdivision
	320 Jane Drive	04/15/74	Town of Woodside	Grading on Gilmore-McDowell Property Without Permits
		03/22/74	Berloger, Long & Associates	Proposed Residential Development, Lands of McDowell
		03/25/74	Town of Woodside	Review of Berloger's Report
		09/20/77	Berloger, Long & Associates	Geotechnical Investigation, Proposed Residential Development, Lands of Gilmoree McDowell
		10/07/85	Applied Earth Consultants, Inc.	Soils and Foundation Investigation, Schinaman Property
		10/15/85	Applied Earth Consultants, Inc.	Supplemental Foundation Recommendations, Proposed Wood-Frame Residential Structure, Schinaman Property
		01/07/86	Mr. Schinman	Letter to Town
		01/20/86	William Cotton and Associates	Geologic Review of Proposed Development
		03/06/86	William Cotton and Associates	Geotechnical Review Sheet
		03/12/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
		04/08/86	Applied Earth Consultants, Inc.	Adequacy of Previous Geologic Report, Schinaman Property
	330 Jane Drive	11/25/85	Applied Earth Consultants, Inc.	Soils and Foundation Investigation, Carey Property
		02/11/86	Edward Dominion	Structural Calculations
		03/15/86	Ling Shen Chen	Site Plan
		04/26/86	Applied Earth Consultants, Inc.	Review of Foundation Plans, Proposed Wood-Frane Residential Structure
		06/10/86	Edward L. Pack Associates, Inc.	Exterior and Future Interior Noise Levels
		8/0/86	William Cotton and Associates	Geotechnical Review Sheet
		08/06/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Carey
		08/11/86	Applied Earth Consultants, Inc.	Addendum - Supplemental Foundation Recommendations, Carey Property
		08/25/86	William Cotton and Associates	Supplemental Review, Lands of Carey
		11/11/86	Applied Earth Consultants, Inc.	Inspection of Pier Drilling for Foundation
		07/26/88	William Cotton and Associates	Notes of Distress to Concrete Retaining Wall and Slabs
		07/29/88	William Cotton and Associates	Geotechnical Review of Distress, with photos
	335 Jane Drive	08/06/03	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence Addition, Guest House, and Detached Garage
		06/05/05	GeoForensics, Inc.	Existing Approved Fills, Deheb Property
		06/27/05	GeoForensics, Inc.	Response to Review Comments, Proposed New Residence
		07/07/05	GeoForensics, Inc.	Response to Review Comments (#2), Proposed New Residence
	340 Jane Drive	05/29/86	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Residence and Swimming Pool, Lot 5, Meadow Vista Subdivision
		05/29/86	Brian Kangas Foulk & Associates	Grading Plan, with annotations
		07/22/86	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Grading Plan, Proposed Residence, Lot 5, Meadow Vista Subdivision
		08/01/86	Vaughn Shahninian Associates	Structural Calculations and Details

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		08/05/86	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence, Lot 5, Meadow Vista Subdivision
		08/26/86	William Cotton and Associates	Geotechnical Review Sheet
		08/29/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Juelsgaard, Meadow Vista Subdivision Lot #5
		09/16/86	JCP Geologists - Engineers	Addendum, Soil and Foundation Report, Proposed Residence and Swimming Pool, Lot 5, Meadow Vista Subdivision
		10/06/86	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Juelsgaard, Meadow Vista Subdivision Lot #5
		01/08/96	Terratech, Inc.	Updated Geotechnical Report
	345 Jane Drive	09/18/87	Tejima and Associates, Inc.	Geotechnical Investigation, Proposed Residence, Lot, Meadow Vista Subdivision
		01/08/88	Tejima and Associates, Inc.	Response to (12/22/87) Letter from Woodside Building Department, Proposed Residence, Lot 8, Meadow Vists Subdivision
			Arvind K. Gupta, P.E.	Structural Calculations
			William Cotton and Associates	Geotechnical Review Sheet
		01/27/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Frederick, Meadow Vista Lot 8, PA #4503
		02/10/88	Arvind K. Gupta, P.E.	Response to Comment of Adequacy of Reinforcement in Piers
		02/22/88	Tejima and Associates, Inc.	Response to (12/27/88) Letter from Town Geologist, Proposed Residence, Lot 8 Meadow Vista Subdivision
		03/17/88	William Cotton and Associates	Supplemental Geotechnical Review, Frederick, Meadow Vista Lot 8, PA #4503
		10/29/96	Jo Crosby & Associates	Geologic and Geotechnical Investigation, Residence
		12/07/00	Jo Crosby & Associates	Addendum to Report dated October 29, 1996
		09/17/01	Jo Crosby & Associates	Response to Geotechnical Review Letter
	350 Jane Drive	05/09/86	JCP Geologists Engineers	Soil and Foundation Services, Proposed 6,500 Square Foot Home, Meadow Vista Subdivision
		09/25/86	JCP Geologists Engineers	Addendum, Soil and Foundation Services, Proposed 6,500 Square Foot Home, Meadow Vista Subdivision
		04/17/87	Lea Engineering	Structural Calculations
			William Cotton and Associates	Geotechnical Review Sheet
		07/13/87	JCP Geologists Engineers	Review of Soil Engineering Aspects of Grading and Foundation Plans, propped Residence on Lot #6, Meadow Vista
		09/24/87	James K. Bell, Architect	Application Revision
		09/29/10	JCP Geologists Engineers	Review of Soil Engineering Aspects of Grading and Foundation Plans, propped Residence on Lot #6, Meadow Vista
		11/06/87	William Cotton and Associates	Geologic and Geotechnical Review, Ting Residence, Meadow Vista Lot #6
9	JEFFERSON AVENUE			
	Emerald Lake Hills	10/18/95	Town of Woodside	Emerald Lake Hills Specific Plan and Geologic Map
	4224 Jefferson Avenue	08/21/89	Applied Earth Sciences Consultants	Soil and Geologic Investigation, Undeveloped Parcel, APN 068-243-160
		04/11/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Joseph Residence, VAR-479, Site Dev, 40, Lots 28/29
		01/19/01	Bay Area Geotechnical Group	Geotechnical and Geologic Investigation, Proposed Residence
	4253 Jefferson Avenue	05/08/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Culvert/Headwall Repair, Hartwig Property
		08/08/05	Lowney Associates	Geotechnical Investigation, Hartwig Residence Improvements
	4262 Jefferson Avenue	11/22/95	Nielsen Geotechnical Incorporated	Soil Report
	4275 Jefferson Avenue	06/08/04	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Studio
		11/17/05	Bay Area Geotechnical Group	Addendum, Geotechnical Engineering Investigation, Proposed Studio
9A	JOSSSELYN LANE			
	140 Josselyn Lane	02/17/84	Berlogar, Long & Associates	Geotechnical Investigation (APN 072-112-030)
		03/05/84	Berlogar, Long & Associates	Addendum Report No. 1, Geotechnical Investigation, Josselyn Lane Site
		03/27/84	Mattson and Mattson	Site Plan, with annotations
		04/12/84	Berlogar, Long & Associates	Proposed Gun Residence Plan Review
		04/19/84	William Cotton and Associates	Geotechnical Review Sheet
		04/24/84	William Cotton and Associates	Preliminary Geologic Review and Geotechnical Investigation Evaluation, Calvin Gunn, APN 72-112-03
		05/09/84	Berlogar, Long & Associates	Response to Comments
		05/17/84	Berlogar, Long & Associates	Plan Review
		06/05/84	William Cotton and Associates	Supplemental Geotechnical Information Evaluation, Calvin Gunn, APN 72-112-03
		06/30/84	Perry R. Wood	Soil Percolation Tests and Recommended Septec Drainfield, Parcel No. 072-112-030
		07/05/84	Berlogar, Long & Associates	Plan Review
		07/27/84	William Cotton and Associates	Plan Revision Evaluation, Lands of Gunn, APN 72-112-03
	145 Josselyn Lane	07/27/95	Terrasearch, Inc.	Geologic and Geotechnical Investigation, Proposed Guest House
		09/03/03	Terrasearch, Inc.	Geotechnical Investigation, Proposed Addition and Remodel
		10/27/03	Terrasearch, Inc.	Response to Peer Review Comments, Proposed Addition and Remodel
		12/18/03	Terrasearch, Inc.	Response to Plan Review Letter, Basement Conversion and Addition
		11/23/04	Admo & Associates, Inc.	Structural Issues Associated with Stairwell Retaining Wall, Basement Addition
		09/10/08	Clearly Consultants, Inc.	Geotechnical Investigation, New Residence
	170 Josselyn Lane	01/31/78	Dunham & Associates	Foundation Recommendations, Proposed Guest House
		01/31/78	Francis A Stejer	Geologic Setting, Proposed Guest House, Stent Property
		04/23/97	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Additions
		10/06/97	Fowler & Associates	Geological Investigation, Proposed Remodeling, Stent Residence
	204 Josselyn Lane	09/12/94	Geomatrix Consultants	Observations at the Josselyn Site
		09/14/94	Earth Investigations Consultants	Geologic Investigation, Fault Location

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		05/17/95	Upp Geotechnology, Inc.	Geotechnical Investigation, Distress to George Residence
	210 Josselyn Lane	03/30/00	Upp Geotechnology, Inc.	Pre-Sale Reconnaissance Geotechnical Investigation, Heine Property
		03/31/06	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Residential Remodel
		02/02/07	Bay Area Geotechnical Group	Fault Set Back, Proposed Residential Remodel and Garage Addition
	215 Josselyn Lane	06/25/90	JCP Geologists - Engineers	Geologic and Soil & Foundation Study, Proposed Residence, Detached Garage and Swimming Pool (APN 072-052-140)
			William Cotton and Associates	Geotechnical Review Sheet
		09/06/90	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Services, Proposed Residence, Swimming Pool and Detached Garage
		10/12/90	William Cotton and Associates	Preliminary Geologic Review, Horton, Replacement Residence
		10/29/10	JCP Geologists - Engineers	Slope Stability Sections and Analysis
		01/15/91	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Study, Proposed Residence, Detached Garage and Swimming Pool
		02/13/91	JCP Geologists - Engineers	Alignment of Subsurface Exploration and Stability Analysis Profile, Horton Property
		02/13/91	William Cotton and Associates	Supplemental Geologic Review, Horton, Replacement Residence
			JCP Geologists - Engineers	Logs of Large Diameter Borings
		03/27/91	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Study, Proposed Residence
		03/27/91	JCP Geologists - Engineers	Addendum for Proposed Guest Cottage
		04/29/91	William Cotton and Associates	Geologic and Geotechnical Review, Horton, BP #8290-8295
		05/24/91	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Grading Plans, Proposed Residence and Other Structures
		06/03/91	Lea Engineering	Seismic Design - Lateral Loads
		06/05/91	Lea Engineering	Structural Calculations - Water Tank
		06/15/91	JCP Geologists - Engineers	Addendum to Geologic and Soil & Foundation Study, Proposed Residence, Detached Garage and Swimming Pool
		06/20/91	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans, Proposed Residence and Other Structures
		06/21/91	JCP Geologists - Engineers	Proposed Septic Leach Field
		06/25/91	William Cotton and Associates	Supplemental Geotechnical Review, Horton, BP #8290 to #8295
		07/24/91	JCP Geologists - Engineers	Fault Investigation Study, Proposed Guest House Cottage
		06/24/91	Lea Engineering	Seismic Design
		07/31/91	William Cotton and Associates	Supplemental Geologic Review, Horton Guesthouse, BP #8293
		08/29/91	William Cotton and Associates	Geologic and Geotechnical Review, Horton, BP #8290-8295
		09/18/91	JCP Geologists - Engineers	Supplemental Fault Investigation Study, Proposed Guest House Cottage
		09/27/91	William Cotton and Associates	Supplemental Geologic Review, Horton Guesthouse, BP #8293
			Sinclair Associates, Inc.	Site Plan with annotations
	230 Josselyn Lane	11/22/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	275 Josselyn Lane	02/27/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Room Additions
		12/19/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
		05/18/10	Murray Engineers, Inc.	Geotechnical Investigation, Proposed Residence
	285 Josselyn Lane	09/28/06	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation and Plan Review
9A	Kenmore Way			
	145 Kenmore Way	12/11/07	Murray Engineers, Inc.	Geotechnical Investigation, Site Improvements
	130 Kenmore Way	02/11/92	JR Engineering & Structures	Structural Verifications of Existing Deck Structure
		08/03/92	GeoForensics, Inc.	Geotechnical Observations of Foundations, Austin Deck
10	KINGS MOUNTAIN ROAD			
	Kings Mountain Road Slide	03/31/95	Harlan Tait Associates	project file
	Kings Mountain Road at Squealer	03/02/06	Romig Engineers, Inc.	Geotechnical Investigation, Gabion Wall and Road Stabilization
	155 Kings Mountain Road	06/14/84	PSC Associates, Inc.	Soil and Geologic Investigation Report, New Single Family Residence
		06/14/84	PSC Associates, Inc.	Soil and Geotechnical Investigation, Proposed Residence
		06/24/84	PSC Associates, Inc.	Site and Geologic Investigation Report, Single Family Residence
		07/03/84	PSC Associates, Inc.	Grading and Foundation Plan Review, New Residence
		07/11/84	William Cotton and Associates	Geotechnical Review Sheet
		07/17/84	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Lands of Maltin
		07/30/84	William Cotton and Associates	Geotechnical Plan Review Evaluation, Lands of Maltin, APN 72-141-06
		08/08/84	PSC Associates, Inc.	Revised Grading and Foundation Plan Review, Proposed Residence
		09/27/84	PSC Associates, Inc.	Geotechnical Observation of Foundation Pir Drilling
		10/29/84	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Maltin Swimming Pool
		06/11/85	PSC Associates, Inc.	Maltin Pool Site
		10/31/96	GeoForensics, Inc.	Geotechnical Investigation, New Barn, Belden Property
		04/30/07	Romig Engineers, Inc.	Geotechnical Investigation, New Garage and Basement
10	179 Kings Mountain Road	02/01/90	Applied Earth Sciences Consultants	Select Geologic, San Andreas Fault, Ground Water, and Soil Percolation Investigations, Whittell Trust
		11/26/90	Applied Earth Sciences Consultants	Geotechnical Investigation of Subsurface Conditions Adjacent to the Theater Building
		04/22/92	Applied Earth Sciences Consultants	Supplemental San Andreas Fault and Liquefaction Investigations, Markkula Estate
		03/25/91	Applied Earth Sciences Consultants	Supplemental Data for Shallow Ground Water Development
		04/24/92	Applied Earth Sciences Consultants	Findings of Soil Percolation, Dewatering Trench Installation, and Ground Water Monitoring Investigations

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		6/0/91	California Archaeological Consultants	Archaeological Survey Report
		08/28/92	Applied Earth Sciences Consultants	Geotechnical Review, Conceptual Subdivision Plans
		09/05/92	Applied Earth Sciences Consultants	Review of Norwak and Associates Tentative Subdivision Maps
		09/15/92	Nowack and Associates, Inc.	Natural Land Features Study, Markkula Estate
		12/15/92	H T Harvey & Associates	Hydrologic Assessment of Pond Performance
		12/16/92	William Cotton and Associates	Geologic and Geotechnical Review
		12/22/92	H T Harvey & Associates	Alternative Analysis for the Presence of Bass and Stream Gates on the Project Site
		01/04/93	H T Harvey & Associates	Delineation of Jurisdictional Waters
		01/15/93	Applied Earth Sciences Consultants	Geotechnical Review of Seismic Related Issues Regarding Proposed New Bridge, Existing Pond and Utilities
		01/18/93	H T Harvey & Associates	Addendum, Kings Mountain Road Project
		01/19/93	Nowack and Associates, Inc.	Natural Land Features Study, Markkula Estate (2nd Revision)
		05/24/93	Applied Earth Sciences Consultants	Geotechnical Investigation for the Main Residence
		07/16/93	Applied Earth Sciences Consultants	Summary Groundwater Report and Siting of On-site Sewage Disposal Systems
		8/0/93	?	Chronology of Events at 179 Kings Mountain Road
		09/10/93	Applied Earth Sciences Consultants	Geotechnical Investigation, Lot 3 Single Family Residence (Caretaker's Residence)
		03/07/94	Applied Earth Sciences Consultants	Response to Town Geologist's Request for Documents Related to 9/10/93 Report
		12/14/94	Applied Earth Sciences Consultants	Preliminary Review of Tentative Grading and Architectural Plans and Septic System, Markkula Estate
		05/09/95	Applied Earth Sciences Consultants	Geotechnical Investigation, Lot 2 Gatehouse Residence
		10/14/96	Applied Earth Sciences Consultants	Supplemental Report, Tentative Plan Review
		03/10/97	Applied Earth Sciences Consultants	On-Site Sewage Disposal System Design, Construction and Maintenance, Lot 3 Main House and Guest House
10A	238 Kings Mountain Road	10/20/08	Romig Engineers, Inc.	Geotechnical Investigation, MacDonald Residence, Garage, and Swimming Pool
	288 Kings Mountain Road	01/10/85	William Cotton and Associates	Geotechnical Review Sheet
		01/16/85	William Cotton and Associates	Preliminary Geologic Review, Kehoe Residence, APN 072-120-030
		08/10/88	Trans Pacific Geotechnical Consultants, Inc.	Geologic Studies and Geotechnical Investigation, Proposed Single-Family Residence
			William Cotton and Associates	Geotechnical Review Sheet
		01/16/89	William Cotton and Associates	?
		06/14/89	Trans Pacific Geotechnical Consultants, Inc.	Supplemental Information, Geotechnical Investigation, Proposed Single-Family Residence
		08/05/89	Edward Dominioni	Structural Calculations with 7/31/89 Addendum #1
		08/10/89	William Cotton and Associates	Preliminary Geologic Review, White, Project #7424 - Feasibility Evaluation
		08/17/89	Trans Pacific Geotechnical Consultants, Inc.	Geotechnical Investigation, Proposed Single-Family Residence
		09/14/89	Trans Pacific Geotechnical Consultants, Inc.	Review of Design Drawings, Proposed Single-Family Residence
		09/14/89	William Cotton and Associates	FAX showing fill slope
		11/09/89	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, White Residence
	289 Kings Mountain Road	10/27/87	Watterman and Sun	Site Plan, Addition and Remodel, Levinthal Residence
			William Cotton and Associates	Geotechnical Review Sheet
		11/11/94	Upp Geotechnology, Inc.	Fault Location Study, Richeson Property
		12/06/94	Upp Geotechnology, Inc.	Supplemental Fault Location Investigation, Richeson property
	310 Kings Mountain Road	05/22/64	Gribaldo, Jacobs, Jones and Associates	Foundation Investigation, James Lagjss Residence
	320 Kings Mountain Road	03/24/87	Jo Crosby & Associates	Geotechnical Consultation on the Distress to Residence
			William Cotton and Associates	Geotechnical Review Sheet
		04/11/87	Wipson Incorporated	Plans with photo and annotations
		05/11/87	Jo Crosby & Associates	Foundation Repair Plan Review, Residence
		06/08/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Arnsten Foundation Repairs, P.A. #4099
		04/18/89	Jo Crosby & Associates	Geotechnical Investigation, Planned Addition to Residence
		05/09/98	Robelo/Kocjan Associates, Inc.	Structural Calculations
		10/06/98	Town of Woodside	Requirements to Final Project BP #6480
	325 Kings Mountain Road	02/14/11	Murray Engineers, Inc.	Geotechnical Investigation, Zambezi Creek Residence
	335 Kings Mountain Road	06/25/10	Earth Investigations Consultants	Geologic Investigation, Fault Location - Draft
		07/09/10	Town of Woodside	Review Comments on 6/25/10 report
		07/13/10	Earth Investigations Consultants	Geologic Investigation, Fault Location
	340 Kings Mountain Road	05/30/85	William Cotton and Associates	Geotechnical Review Sheet
		06/21/85	Baldwin Consultants	Soil and Foundation Investigation, Proposed Guest House
		06/25/85	Richard Hanson	Calculations - Foundation Design
		07/16/85	Baldwin Consultants	Plan Review, Proposed Guest House
		07/19/85	Baldwin Consultants	Plan Review, Proposed Guest House
		07/29/85	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Keek Guest House
		04/02/03	Earth Investigations Consultants	Geotechnical Review, Proposed Residence Addition
		08/27/10	Murray Engineers, Inc.	Fault Investigation, Schroll Property
		01/12/11	Murray Engineers, Inc.	Supplemental Investigation, Fault Rupture Hazard, Schroll Property
	360 Kings Mountain Road	11/30/10	Earth Investigations Consultants	Geologic Investigation, Fault Rupture Hazard, Wilmer Property
	481 Kings Mountain Road	01/11/89	JCP Geologists - Engineers	Engineering Geologic Study, Proposed Residence
		11/30/94	Applied Earth Sciences Consultants	A San Andreas Fault and Groundwater Investigation
		08/16/96	Cyme, Inc.	Geotechnical Engineering Investigation, Jaiswal-Family New Residential Development

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		01/27/06	Murray Engineers, Inc.	Geotechnical Investigation, Replacement Vehicle Bridge
	521 Kings Mountain Road	06/02/03	Earth Systems Consultants	Limited Soil Engineering Study, Proposed House Barns, Mounted Patrol Grounds
	661 Kings Mountain Road	06/26/95	Earth Investigations Consultants	Preliminary Geologic Hazard Assessment
		07/08/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residence
		08/09/00	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Landscape Retaining Walls
		08/13/03	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Landscape Retaining Walls
	680 Kings Mountain Road	01/21/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Additions and New Barn
10A	700 Kings Mountain Road	12/09/83	Hoskins Engineers, Inc.	Structural Calculations
		03/10/86	William Cotton and Associates	Geotechnical Review Sheet
		03/12/86	William Cotton and Associates	Preliminary Geologic Review, Lands of Goodfellow and Kampcik, Champman Variance 394
		09/04/86	Cleary Consultants, Inc.	Soil & Foundation Engineering Investigation
		09/10/86	Brian Kangas Foulk & Associates	Grading and Drainage Plan, Custom Home for Goodfellow and Kampcik, with annotations
		11/06/86	William Cotton and Associates	Geotechnical Review Sheet
		11/17/86	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Goodfellow and Kampcik, PA #3299
		12/04/86	Cleary Consultants, Inc.	Supplemental Evaluation, Goodfellow-Kampcik Residence
		12/18/86	Cleary Consultants, Inc.	Review of Foundation and Grading Plans, Goodfellow and Kampcik Residence
		01/15/87	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Goodfellow and Kampcik, PA #3299
11	LA HONDA ROAD			
	La Honda Road	04/06/79	Purcell, Rhoades & Associates	Preliminary Geotechnical Hazard Evaluation and Percolation Testing, 60-Acre Parcel Fronting along Old La Honda Road
		10/29/80	Edwin H. Smith	Preliminary Map, Lands of Parnas Corporation in Rancho El Corte Madera and Rancho Canada De Raynundo, with annotations
		02/02/81	William Cotton and Associates	Geotechnical Review Sheet - Macie and Pean LD #272
		03/04/81	William Cotton and Associates	Review of 4/6/79 PRA report
		05/18/81	Purcell, Rhoades & Associates	Preliminary Soil Report, Assessor's Parcel Nos. 75-060-110, 140, and 160, and 75-070-040
		0/0/85	James Guthrie & Associates, Inc.	Preliminary Site Plan
		12/20/85	William Cotton and Associates	Geotechnical Review Sheet - Macie LD #272
		01/02/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Lot Line Adjustment, Macie and Pean
	801 La Honda Road	11/15/83	Purcell, Rhoades & Associates	Soils and Foundation Study - Swimming Pool, Welch Residence
			William Cotton and Associates	Geotechnical Review Sheet
		12/05/83	William Cotton and Associates	Review - Welch Swimming Pool, 75-134-01
		10/02/05	Geo Forensics, Inc.	Geotechnical Investigation, Proposed New Residence Addition and Garage/Shop Addition
	1255 La Honda Road	02/27/84	JCP Geologists - Engineers	Geologic and Soil & Foundation Studies for Distressed Home and Proposed Addition
	1391 La Honda Road	09/12/95	Ting and Associates	Geotechnical Investigation, Proposed Single Family Residence
		09/12/95	Buckley Engineering Associates	Geologic Investigation, Proposed Addition
	1655 La Honda Road	09/30/85	William Cotton and Associates	Geotechnical Review Sheet, with Site Photographs
		10/07/85	William Cotton and Associates	Preliminary Geologic Review, Giarretto Addition
		06/10/86	Applied Earth Sciences Consultants	Geotechnical Evaluation, Proposed Addition
		08/07/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Giarretto Addition AP #2846
		08/26/86	Applied Earth Sciences Consultants	Plan Review, Proposed House Addition
		09/09/86	William Cotton and Associates	Supplemental Geotechnical Review, Giarretto Addition, AP #2846
11	LAKEVIEW DRIVE			
	115 Lakeview Drive	09/07/95	Harza	Geotechnical Investigation, Black Property
		05/30/96	Harza	Supplemental Basement Retaining Wall and Slab Recommendations, Black Residence
		11/12/96	Harza	Supplemental Swimming Pool Recommendations, Black Residence
		09/07/01	Harza	Geotechnical Investigation, Black Property
	122 Lakeview Drive	07/31/01	Nielsen Geotechnical, Inc.	Geotechnical Information (Draft Soils Report dated 7/6/99)
	170 Lakeview Drive	01/23/79	Donald E. Banta & Associates	Geotechnical Investigation, Noravian Residence, Parcel 1, Land Division No. 89
		03/27/79	Panco/Sinclair Associates, Inc.	Site Plan with annotations
		06/27/79	William Cotton and Associates	Geotechnical Review
		07/19/79	William Cotton and Associates	Geologic Review Lands of Noravian
		08/19/79	William Cotton and Associates	Geotechnical Review - Lands of Noravian
		01/14/02	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Deck
		04/30/02	American Soil Testing, Inc.	Supplemental Foundation Data, Proposed Deck
		07/26/02	American Soil Testing, Inc.	Supplemental Recommendations, Proposed Deck
		01/28/03	American Soil Testing, Inc.	Supplemental Data and Recommendations, Proposed Addition and Remodel
11	LANING DRIVE			
	100 Laning Drive	07/28/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Developments, Parcels 1 (100) and 2 (110 and 120)

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	110 Laning Drive	07/28/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Developments, Parcels 1 and 2, Canada Road at Laning Drive
		02/21/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development
		06/24/02	Earth Investigations Consultants	Supplemental Geotechnical Recommendations, Proposed Pool
	115 Laning Drive	12/12/00	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence, Shaw Property
		01/05/04	GeoForensics Inc.	Review of Plans and Report Update, Shaw Residence
		05/06/04	GeoForensics Inc.	Report Supplement, Proposed Barn
	120 Laning Drive	07/28/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Developments, Parcels 1 and 2, Canada Road at Laning Drive
		02/18/98	Lea & Sung Engineering, Inc.	Tentative Parcel Map, Lands of Dancer
		08/28/01	Earth Investigations Consultants	Supplemental Geotechnical Recommendations, Proposed Basement
	130 Laning Drive	06/04/98	Nielsen Geotechnical Incorporated	Soil Report
	155 Laning Drive	04/13/95	Earth Mechanics Consulting Engineers	Geotechnical Investigation
		06/12/01	Romig Engineers, Inc.	Geotechnical Investigation, New Residence
	225 Laning Drive	05/05/05	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Modifications to Existing Residence
	240 Laning Drive	11/12/99	Romig Consulting Engineers	Geotechnical Investigation, King Residence Improvements
		03/22/01	Town of Woodside	Engineering Geology Review
		03/02/01	Romig Consulting Engineers	Geotechnical Plan Review, New Garage and Pool House
		04/09/01	Geomatrix Consultants	Geotechnical Review
		07/31/01	Romig Consulting Engineers	Geotechnical Plan Review, New Garage and Pool House
	240 Laning Drive	10/16/02	Romig Consulting Engineers	Construction Observation, Project Phase I, Garage, Pool House & Pergola
	245 Laning Drive	01/29/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Bechtel Residence Additions
11A	LA QUESTA WAY			
	160 La Questa Way	02/08/06	Murray Engineers, Inc.	Geotechnical Investigation, Klein Guesthouse
		06/29/06	Murray Engineers, Inc.	Supplemental Grading Recommendations, Klein Guesthouse
	231 La Questa Road	05/15/95	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Addition
	240 La Questa Way	06/16/95	Nielsen Geotechnical Incorporated	Soil Report
		03/03/04	Nielsen Geotechnical Incorporated	Plan Review
	250 La Questa Way	06/12/92	Melvin R. Hill, Inc.	Soil Investigation
		09/21/92	Melvin R. Hill, Inc.	Addendum to Soil Report
		11/19/92	Melvin R. Hill, Inc.	Addendum to Soil Report
	271 La Questa Way	05/16/11	Romig Engineers, Inc.	Geotechnical Investigation, Marinucchi-Duncan Residence
	351 La Questa Way	09/27/74	Berloger, Long & Associates	Soils Engineering Geologic Investigation, Proposed Parcel Split, Single Family Residential Development
		08/06/96	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Remodel and Additions, Proudian Residence
		03/26/02	Upp Geotechnology, Inc.	Soil and Foundation Investigation Report Update and Supplemental Recommendations, Proposed Riding Arena, Barn, and Shop, Ditz Property
		05/29/09	Earth Investigations Consultants	Geotechnical Investigation, Site Mitigation
	375 La Questa Way	07/09/91	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Cottage
	400 La Questa Way	12/14/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
		05/16/00	Earth Investigations Consultants	Geotechnical Plan Review, proposed Pool Rehabilitation
		09/14/00	Geomatrix Consultants	Geotechnical Review, Proposed Building Addition, Georgakas Residence
		11/27/00	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Remodel
		04/25/01	Earth Investigations Consultants	Geotechnical Review, Proposed Pool Deck
		08/13/01	Earth Investigations Consultants	Geotechnical Final, Pool and Spa
	400 La Questa Way	05/22/02	Earth Investigations Consultants	Geotechnical Construction Observation - Final
	411 La Questa Way	09/27/74	Berloger, Long & Associates	
		08/16/78	Berloger, Long & Associates	Supplemental Consultation, Proposed Residence - Parcel 2, Lubin Land Division
		07/01/05	Michelucci & Associates, Inc.	Preliminary Geotechnical Evaluation, Proposed Front Entry Addition
	411 La Questa Way	09/15/05	Michelucci & Associates, Inc.	Supplement to Preliminary Geotechnical Evaluation, proposed Front Entry Addition
	427 La Questa Way	12/18/87	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Lands of Vaccaro
11A	LAS PULGAS DRIVE			
	Las Pulgas Drive / Cinnabar Road	04/07/78	Donald A. Woolfe and Associates	Environmental Assessment, Lands of Wirth (Crosby/Coonan)
		06/01/78	Frahm Elder Cannis	Preliminary Map (Aerial Photograph), Rancho De Las Pulgas Subdivision (Lands of Wirth)
		06/07/78	Leighton and Associates	Addendum to Report
		06/15/78	Leighton and Associates	Review

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		08/01/78	Donald A. Woolfe and Associates	Draft Environmental Impact Report, Lands of Wirth (Crosby/Coonan), Rancho De Las Pulgas Subdivision
	450 Las Pulgas Drive	09/13/06	Jo Crosby & Associates	Geotechnical Investigation, Proposed Residential Development, Lot 2, Las Pulgas Estates
	455 Las Pulgas Drive Rancho De Las Pulgas Subdivision		Jo Crosby & Associates	Geology and Soils Investigation, Rancho De Las Pulgas
	455 Las Pulgas Drive		William Cotton and Associates	Geotechnical Review Sheet
		09/16/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Hawks, PA-4862, SDP-16
		09/30/88	Town of Woodside	Application Notice
		10/05/88	Jo Crosby & Associates	Review of Foundation and Grading Plans, Lot 3, Las Pulgas Estates Subdivision
		05/07/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Suri Residence, SD #42
		09/21/90	Cannis Consulting Engineers	Grading / Drainage Plan
		10/02/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Suri Residence, SD #42
		01/25/91	Lee Engineers	Geotechnical Investigation, Lot 3
		04/16/91	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Suri Residence, Building Permits #8283 - #8286
		05/18/91	Lee Engineers	Supplemental Geologic and Geotechnical Review, Suri Residence
		06/05/91	Lee Engineers	Supplemental Structural Calculations for Revised Foundation
		06/11/91	Engotech, Inc.	Testing and Inspection During Grading, Proposed Residential Dwelling, Lot 3
		06/14/91	Lee Engineers	Supplemental Recommendations
		06/21/91	Engotech, Inc.	Compaction Data
		06/24/91	William Cotton and Associates	Supplemental Geotechnical Review, Suri Residence, Building Permits #8283 - #8286
		07/05/91	Engotech, Inc.	Response to Comments from Geotechnical Consultants, proposed Residential Dwelling, Lot 3, Las Pulgas Estates
		07/29/91	William Cotton and Associates	Supplemental Geotechnical Review, Suri Residence, Building Permits #8283 - #8286
		08/05/91	Engotech, Inc.	Geotechnical Consultants, Proposed Residential Dwelling, Lot 3, Las Pulgas Estates
		08/06/91	Dominic Chu	Structural Calculations, Suri Residence
		08/22/91	William Cotton and Associates	Supplemental Geologic Review, Suri Residence, Building Permits #8283 - #8286
		08/29/91	Engotech, Inc.	Response to Comments from Geotechnical Consultants, Proposed Residential Dwelling, Lot 3, Las Pulgas Estates
		09/27/91	William Cotton and Associates	Supplemental Geologic Review, Suri Residence, Building Permits #8283 - #8286
	455 Las Pulgas Drive	10/20/94	Harlan Tait Associates	Letter of Transmittal
	460 Las Pulgas Drive	06/08/93	Jo Crosby & Associates	Progress Report on the Problems
		05/18/94	Tredwell & Rollo	Preliminary Geotechnical Consultation and Construction Summary Report, Molakides Residence
		09/11/95	Ned Clyde Construction, Inc.	Soil Report for Pool and Guest House
	470 Las Pulgas Drive	05/09/00	Nielsen Geotechnical Incorporated	Soil Report
	475 Las Pulgas Drive	03/29/79	Frahm Elder Cannis	Percolation Test (Locations), Rancho de Las Pulgas Subdivision (Lands of Wirth)
		12/22/60	Joe Crosby & Associates	Final Report for the Observation and Testing of Site Grading, Las Pulgas Estates
		07/10/86	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Lot 5, Las Pulgas Drive, Las Pulgas Estates
			William Cotton and Associates	Geotechnical Review Sheet
		05/07/87	Brent Cottong, Landscape Architect	Grading Plan, Huang Residence, Lot 5, Las Pulgas Subdivision
		08/05/87	William Cotton and Associates	Preliminary Geologic Review, Huang, Las Pulgas Estates, Lot #5, Permit #4236
		08/14/87	Joe Crosby & Associates	Update of the Geotechnical Report for Lot 5, Las Pulgas Estates Subdivision
		08/21/87	Joe Crosby & Associates	Foundation Plan Review, Proposed Residence, Lot 5, Las Pulgas Estates Subdivision
		08/25/87	Joe Crosby & Associates	Addendum to Geotechnical Report: Recommendations for Retaining Walls, Swimming Pool, and Tennis Court Grading, Lot 5, Las Pulgas Sub.
		09/29/87	Joe Crosby & Associates	Review of Retaining Wall Plans, Lot 5, Las Pulgas Estates Subdivision
		01/27/88	William Cotton and Associates	Supplemental Geotechnical Review, Huang, Las Pulgas Estates Lot #5, PA #4236
		07/29/88	Joe Crosby & Associates	Update of Geotechnical Report, Lot 3, Las Pulgas Estates Subdivision
		08/16/88	Joe Crosby & Associates	Addendum to Geotechnical Report: Recommendations for Retaining Walls and Swimming Pool, Lot 3, Las Pulgas Estates Subdivision
		09/15/89	Joe Crosby & Associates	Swimming Pool Plan Review: Lot 5, Las Pulgas Estates Subdivision
	475 Las Pulgas Drive	10/20/94	Harlan Tait Associates	
	480 Las Pulgas Drive	12/22/95	Upp Geotechnology, Inc.	Geotechnical Investigation and Percolation Testing, Lands of Huang
		08/15/96	Harlan Tait Associates	Peer Review
		10/17/96	Upp Geotechnology, Inc.	Addendum Information and Plan Review, Prinz Residence
		11/07/06	Harlan Tait Associates	Supplementary Peer Review
		07/22/97	Upp Geotechnology, Inc.	Plan Review, Proposed Swimming Pool, Prinz Property
		09/24/97	Upp Geotechnology, Inc.	Status Letter, Construction Monitoring, Prinz
	485 Las Pulgas Drive	06/18/86	Joe Crosby & Associates	Foundation - Drainage Plan Review, Lot 6, Las Pulgas Estates
		08/12/86	William Cotton and Associates	Geotechnical Review Sheet
		06/09/88	B Clyde Beck Architect	Yen - New Residence
		08/15/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Yen, Las Pulgas Estates, Lot #6
		09/05/88	Joe Crosby & Associates	Review of Swimming Pool Plans, Lot 6, Las Pulgas Estates
		10/07/88	Joe Crosby & Associates	Recommendations for Stitch Pier Retaining System, Lot 6, Las Pulgas Estates Subdivision
		10/25/88	Joe Crosby & Associates	Supplemental Recommendations for Stitch Pier Retaining System, Lot 6, Las Pulgas Estates Subdivision
		11/01/88	Gene S. Shaw, PE	Structural Calculations, Yen's Residence
		11/02/88	Joe Crosby & Associates	Review of Remedial Plans for Fill Slope, Lot 6, Las Pulgas Estates Subdivision
		11/04/88	William Cotton and Associates	Memo to Mr. Yen RE: Project Approval
		11/23/88	Joe Crosby & Associates	Lens Grouting at David Yen Residence, Las Pulgas Estates
		12/03/88	Gene S. Shaw, PE	Structural Calculations
		12/28/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	490 Las Pulgas Drive	12/22/98	Fowler & Associates Geotechnical, Inc.	Geotechnical Investigation, Proposed Single Family Residence
		05/31/00	Fowler & Associates Geotechnical, Inc.	Supplemental Geotechnical Investigation, Proposed Single Family Residence
		06/10/06	Fowler & Associates Geotechnical, Inc.	Geotechnical Investigation, Proposed Single Family Residence
11A	LAWLER RANCH ROAD			
	Lawler Ranch Road	04/08/80	Earth Sciences Associates	Assessment of Geologic Hazards, Lawler Property
		03/10/82	Donald A. Woolfe and Associates	Environmental Assessment, Proposed Whiskey Hill Subdivision
			Brian Kangas Foulk	Whiskey Hill - Concept Map
		12/19/85	Nordmo Associates, Inc.	Soil Investigation, Proposed House, The Lawler Ranch
		12/04/89	Clearly Consultants, Inc.	Reconnaissance Geologic Investigation, 92 Acres (5 Parcels)
		07/29/91	?	Outline of Geologic Report, Subdivision #150, Lands of Lawler
		09/20/91	Donald Woolfe and Associates	Environmental Constraints/Concept Map, Lawler Ranch - Lot 69
		10/10/91	William Cotton & Associates	Preliminary Geologic and Geotechnical Review, Lawler Subdivision #150, Lawler Ranch Road
		07/09/92	Hawk Engineers, Inc.	Natural Land Features Study, Whiskey Hill Estates
		08/10/92	GeoForensics, Inc.	Geotechnical and Geologic Investigation, Proposed Residential Development, Whiskey Hill Estates
		12/21/92	GeoForensics, Inc.	Responses to Town's Geologic and Geotechnical Consultants' Comments, Whiskey Hill Estates
		02/01/94	Wagstaff and Associates	Draft Environmental Impact Report, Whiskey Hill Estates Subdivision
		07/14/94	Wagstaff and Associates	Final Environmental Impact Report, Whiskey Hill Estates Subdivision - Responses to Comments on the Draft EIR
		07/14/94	Wagstaff and Associates	Final Environmental Impact Report, Whiskey Hill Estates Subdivision
		05/25/95	GeoForensics, Inc.	Geotechnical Report Update, Whiskey Hill Estates
		05/20/95	Berry and Associates	Erosion and Drainage Control Analysis, Sand Hill Estates
		05/20/95	Berry and Associates	Natural Land Features Study, Sand Hill Estates
		05/26/95	Berry and Associates	Statements and Materials to Accompany Vesting Tentative Map, Sand Hill Estates
12	LINDENBROOK ROAD			
	205 Lindenbrook Road	10/04/83	Robert Mahoney	Landslide Repair Report
		10/25/83	William Cotton and Associates	Geotechnical Review Sheet
		11/18/83	William Cotton and Associates	Geotechnical Review, Matheson Landslide
		01/17/84	Joe Crosby & Associates	Geotechnical Investigation, Landslide Repairs
		02/04/84	Soil Engineering Construction, Inc.	Pile Calculations
		02/24/84	William Cotton and Associates	Geotechnical Review of Landslide Repair, Matheson
		04/09/84	Joe Crosby & Associates	Addendum I, Geotechnical Investigation, Landslide Repairs
		04/02/84	Joe Crosby & Associates	Aerial Geology Map and Site Plan
		04/19/84	Joe Crosby & Associates	Addendum, Geotechnical Investigation for Landslide Repairs
		05/24/84	William Cotton and Associates	Geotechnical Evaluation, Matheson Landslide Repair
		07/10/84	Joe Crosby & Associates	Addendum II, Geotechnical Investigation, Landslide Repairs
		08/01/84	William Cotton and Associates	Geotechnical Evaluation, Matheson Landslide Repair
		08/06/84	William Cotton and Associates	Geotechnical Evaluation, Matheson Landslide Repair
		12/11/84	William Cotton and Associates	Photographs of Matheson Landslide Repair
		12/13/84	William Cotton and Associates	Geologic Inspection of Site Conditions, Matheson Landslide Repair
		03/23/85	Soil Engineering Construction, Inc.	Structural Plans and Calculations for Repair of House Foundation
		05/09/85	Joe Crosby & Associates	Observation and Testing for Landslide Repair
		06/04/85	William Cotton and Associates	Preliminary Geologic Review, Septic Drainfield Site, Hart Residence
		08/24/85	Soil Engineering Construction, Inc.	Landslide Repair Plans, with annotations
		09/11/85	Soil Engineering Construction, Inc.	Design Calculations for Retaining Wall
		09/25/85	William Cotton and Associates	Review of Retaining Wall Design
		09/27/85	William Cotton and Associates	Geotechnical Evaluation, Mahoney Retaining Wall
		10/07/85	William Cotton and Associates	Supplemental Geotechnical Evaluation, Mahoney Landslide Repair and Residence Underpinning
		03/25/86	Joe Crosby & Associates	Geotechnical Evaluation of Repairs
		04/14/86	William Cotton and Associates ?	Preliminary and Final Comments on Various Crosby (?) Submittals
		04/16/86	Joe Crosby & Associates	Comments on the "Checklist" of WCA dated 4/14/86
		04/22/86	Joe Crosby & Associates	Comments on "Amended Checklist" of WCA
		04/28/86	Soil Engineering Construction, Inc.	Structural Calculations for Retaining Wall Below Driveway
		04/28/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Mahoney Distressed Residence and Landslide Repairs and Improvements
	245 Lindenbrook Road	04/30/84	Terrasearch, Inc.	Soil and Geologic Investigation, Lands of Hugo, Two Proposed Residences and Support Structures
		02/10/85	Rick Skierka	Tentative Map
		05/08/85	Rick Skierka	Tentative Map
		03/19/85	William Cotton and Associates	Geotechnical Review Sheet
		03/20/85	William Cotton and Associates	Preliminary Geologic Review, Hugo Lot Line Adjatment, LD 288
		06/09/88	JCP Geologists Engineers	Soil ans Foundation Services, Three Proposed Structures
		05/05/90	Joseph Parello	Structural Calculations
		05/26/90	House of Haws	Plans
			William Cotton and Associates	Geotechnical Review
		06/15/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed Residence and Garage
		07/13/90	William Cotton and Associates	Geologic and Geotechnical Review, Hugo Residence and garage, PA-7884
		08/23/90	JCP Geologists Engineers	Addendum to Soil and Foundation Study, Three Proposed Structures

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	250 Lindenbrook Road	09/11/90	JCP Geologists - Engineers	Engineering Geologic and Soil & Foundation Study, Proposed Addition and Garage
		11/15/90	JCP Geologists-Engineers	Review of Soil Engineering Aspects of Foundation Plans, Proposed New Residence and Garage
			William Cotton Associates	Geotechnical Review Sheet
		9 & 11/90	House of Haws	Plan with notes
		11/04/97	GeoForensics, Inc.	Geotechnical Report Update, Proposed New Garage and Addition, Kellenberger Property
	260 Lindenbrook Road	01/25/96	Hoexter Consulting, Inc. / Romig Consulting Engineers	Geologic and Geotechnical Investigation, McDowall Residence Renovation
		05/18/11	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Replacment Garage
	300 Lindenbrook Road	06/05/85	Brian Kangas Foulk & Associates	Topographic Survey, Portions of Lot II, Meadow Vista Subdivision
		10/04/85	Edward Dominion	Structural Calculations
		09/23/85	Howard F. Donley & Associates	Geotechnical Investigation, Proposed New Residence for Green
		01/07/86	Howard F. Donley & Associates	Review of Design Calculations an Architectural Drawings, Proposed Single Family Residence
		01/17/86	William Cotton and Associates	Geotechnical Review Sheet
		01/23/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Green
	305 Lindenbrook Road	08/15/86	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Residence
12	LOWER LAKE ROAD			
	110 Lower Lake Road	01/12/90	Freeman-Kem Associates, Inc.	Geotechnical Investigation, Guest Cottage
		04/30/02	JF Consulting, Inc.	Geotechnical Update Letter, Proposed Horse Barn, Lands of Watt/Tracy
12	LYNN WAY			
	115 Lynn Way	05/30/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel to Existing Residence
		01/22/07	Alliance Environmental and Soil Engineering	Geotechnical Investigation, Proposed Pool House & Swimming Pool
	125 Lynn Way	06/10/04	ARA Engineering Company	Geotechnical Engineering Study, Proposed Residential Development
		04/04/05	ARA Engineering Company	Addendum to Geotechnical Engineering Study, Planned Residential Development
		07/28/06	ARA Engineering Company	Geotechnical Engineering Services, Response to Town Comments
	125 Lynn Way	07/28/06	ARA Engineering Company	Geotechnical Engineering Services, Review of Design Plans & Specifications
	135 Lynn Way	04/15/97	Friar Associates, Incorporated	Geotechnical & Geologic Investigation, Addition to Existing Residence
	150 Lynn Way	10/20/03	Milstone Geotechnical	Geotechnical Investigation, Proposed Auxiliary Building
		03/05/04	Milstone Geotechnical	Geotechnical Investigation, Proposed Auxiliary Building
12	MANUELLA AVENUE			
	309 Manuella Avenue	04/08/96	Nielsen Geotechnical Incorporated	Soil Report
		12/06/97	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Addition
	395 Manuella Avenue			
12	MANZANITA WAY			
	105 Manzanita Way	04/05/88	Terrasearch, Inc.	Geotechnical Investigation, Proposed Residence
	200 Manzanita Way	04/27/87	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Parcel 073-122-150, Manzanita Way near Mountain Home Road
		04/30/87	PSC Associates, Inc.	Geotechnical Engineering Inverstigation, Proposed Residence, Lot 15 Manzanita Way
		06/22/87	Lea Engineering	Site and Drainage Plan
			William Cotton and Associates	Geotechnical Review Sheet
		07/30/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Wadell, PA #4229
		08/10/87	John Coyle & Associates, Inc.	Site Reconnaissance, Searsville Fault Trace, Wedell Property
		07/31/96	GeoForensics, Inc.	Geotechnical Investigations, Proposed Site Improvements, Barth Property
		05/08/97	GeoForensics, Inc.	Review of Plans, Proposed Waterhole/Pond
		05/21/97	Harlan Tait Associates	Review - Geotechnical Investigation, Proposed Addition, Guest House and Waterhole/Pond
	230 Manzanita Way now 101 Winding Way	06/14/99	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residential Addition
12A	321 Manzanita Way	07/03/96	Treadwell & Rollo	Gotechnical Investigation
		05/31/05	GFDS Engineers	Preliminary Structural Review, Wooden Bridge
		07/14/05	Gilpin Geosciences, Inc.	Emergency Status, Bridge Restoration Project, Bear Creek
		07/25/05	Treadwell & Rollo	Geologic and Geotechnical Investigation, Bridge Renovation
	325 Manzanita Way	09/11/85	Adel Nepomuceno	Soil and Foundation Investigation, Guest House Extension
		10/02/85	Adel Nepomuceno	Aquirre's Guest House
		04/24/92	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Residence
	345 Manzinata Way	08/27/07	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Site Improvements

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	410 Manzanita Way	09/14/82	Donald E. Banta & Associates	Geotechnical Investigation, Proposed Garage and Studio
	426 Manzanita Way	09/24/97	Ned Clyde Construction, Inc.	Plans and Specifications, Manzanita Way Property
	440 Manzanita Way	03/31/75	Richard E. Rowland	Geologic Investigation, Alden Property (Parcel 1, Lands of Estate of Johnson)
		08/30/83	Terrasearch, Inc.	Geotechnical Investigation, Slope Failure, Alden Residence
		02/15/99	Applied Earth Sciences Consultants	Geotechnical Investigation
		09/15/10	Neil O. Anderson and Associates	Geotechnical Investigation, Alden Residence Swimming Pool Remodel
	445 Manzanita Way	11/20/95	Hydro-Geo Consultants, Inc.	Preliminary Geological Evaluation, Canada-Hermit Fault
		12/01/95	Hydro-Geo Consultants, Inc.	Response to Town Review of 11/20/95 Report
		12/07/95	Hydro-Geo Consultants, Inc.	Response to Town Review of 12/1/95 Letter
		05/30/96	Nielsen Geotechnical Incorporated	Soil Report
		06/28/96	Nielsen Geotechnical Incorporated	Perimeter Cut-Off Drain
		09/12/96	Nielsen Geotechnical Incorporated	Building Fault Set-Backs, Jomson Residential Development
		05/30/97	Nielsen Geotechnical Incorporated	Supplemental Geotechnical Information, Proposed New Residence
		01/15/09	Murray Engineers, Inc.	Geotechnical Investigation, Johnson Guesthouse & Studio
	520 Manzanita Way	11/07/80	Perry R. Wood	Geologic Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
		09/27/83	Perry R. Wood	Soil Percolation Tests, Proposed Parcel 5, a Subdivision of Parcels 072-221-330, -340, -350, -360, -370, -280, and -390
		04/07/86	PSC Associates, Inc.	Geotechnical Engineering Investigation, Addition to the Guest House
		08/04/99	Upp Geotechnology, Inc.	Preliminary Report, Limited Geotechnical Investigation, Slope Stabilization and Drainage Improvements
		08/12/99	Upp Geotechnology, Inc.	Response to Town Review and Geotechnical Review Comments, Slope Stabilization and Drainage Improvements
		08/18/99	Upp Geotechnology, Inc.	Second Response to Town Review and Geotechnical Review Comments, Slope Stabilization and Drainage Improvements
		08/30/03	Upp Geotechnology, Inc.	Plan Review, Emergency Stabilization Plans (Zone 1), Lands of Martin
		08/31/99	Upp Geotechnology, Inc.	Preliminary Report, Limited Geotechnical Investigation, Slope Stabilization and Drainage Improvements
		01/27/00	Upp Geotechnology, Inc.	Addendum Report, Limited Geotechnical Investigation, Slope Stabilization and Drainage Improvements - Zone 2
		07/28/00	Upp Geotechnology, Inc.	Supplemental Information, Slope Stabilization and Drainage Improvements - Zone 2
		11/21/00	Upp Geotechnology, Inc.	Construction Monitoring, Slope Stabilization
	540 Manzanita Way	09/21/78	Edwin H. Smith	Preliminary Map, Lands of Stone, with annotations
		09/24/80	William Cotton and Associates	Geotechnical Review Sheet
		10/07/80	William Cotton and Associates	Geologic Review, Lands of Stone/Jensen - SD-138
		11/05/80	PSC Associates, Inc.	Soils Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
		11/07/80	Perry R. Wood	Geologic Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
		01/28/81	William Cotton and Associates	Review Comments - Lands of Stone, Subdivision #138
		06/29/81	Donald A. Woolfe and Associates	Environmental Setting Survey, Stone/Jensen Property
		08/06/81	William Cotton and Associates	Geologic Review, Stone/Jensen, SD-138
			William Cotton and Associates	Geotechnical Review Sheet
		11/22/83	William Cotton and Associates	Geologic Review, Proposed Lot 8, Lands of Mayacamas Corporation
		02/03/84	William Cotton and Associates	Preliminary Geologic Review, Lands of Mayacamas Corporation, SD-145
		03/29/85	Smith, Randlett, Foulk & Stock, Inc.	Concept Map, Subdivision Map, Resubdivision of Manzanita Hills, SD-138
		07/23/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review, Lands of Martin, AD-145, Resubdivision of Manzanita Hills
		07/29/85	PSC Associates, Inc.	Possible Landslide Hazard Area the Northeast Corner, Lot 8
		08/20/85	William Cotton and Associates	Supplemental Geologic / Geotechnical Review, Lands of Martin SD-145, Manzanita Hills Subdivision
		10/15/85	William Cotton and Associates	Geologic Evaluation, Lands of Martin, Lot 7, Manzanita Subdivision, SD-145
12A	555 Manzanita Way	06/23/78	Francis A. Stejer	Engineering Geologic Study, Proposed Guest House
		07/13/78	Dunham & Associates	Soil Investigation, Proposed Guesthouse
		07/27/78	Pennington & Pennington	Site and Plot Plan, Guest House for Carnochan
			William Cotton and Associates (?)	Summary of Office Review, Carnochan
		09/11/78	William Cotton and Associates	Geotechnical Review
		07/12/91	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Gymnasium, Studio and Pump House
		07/17/01	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Barn, Swimming Pool, and Stone House
13	580 Manzanita Way	07/08/83	Site Characteristics, Inc.	Faulty Investigation Report - Lands of Mosher
		07/13/83	William Cotton and Associates	Geotechnical Review Sheet
		08/03/83	William Cotton and Associates	Review - Lands of Mosher (Manzanita Hills), SD138
		09/25/84	Town of Woodside	Comments - Revision of Final Subdivision Map - SD-138, Manzanita Hills
		09/30/83	Site Characteristics, Inc.	Geotechnical Evaluation of Proposed Subdivision, Lands of Mayacamas Corporation
		12/10/03	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Thompson Property Improvements
		04/13/05	Pacific Geotechnical Engineering	Addendum Geotechnical Investigation, Thompson Residence Garage
	600 Manzanita Way	11/07/80	Perry A. Wood	Geologic Investigation, Proposed Lots 1, 2, 4, 7, and 8, Lands of Stone/Jensen
		07/14/85	Dominion Engineering Co.	Topographic Map, Lands of Gauthier
		08/20/84	William F. Jones, Inc.	Drainage Problem
		09/26/85	PSC Associates, Inc.	Report Update and Plan Review, Proposed Residence, Lot 4
		10/31/85	County of San Mateo	Sewage Disposal System
		05/26/86	William Cotton and Associates	Geotechnical Review Sheet of 11/7/80 Perry R. Wood and 9/26/85 PSC reports
		06/06/86	William Cotton and Associates	Preliminary Geologic and Geotechnical review, Lands of Gauthier, Manzanita Hill Subdivision, Lot 4
		08/03/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Barn
		05/26/99	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Additions to Existing Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	610 Manzanita Way	02/06/86	J. V. Lowney & Associates	Geotechnical Investigation, New Residence
	610/618 Manzanita Way	11/0/84	Smith, Randlett, Foulk & Stock, Inc.	Tentative Map, Lot Line Change between Lots 3 and 4, Manzanita Hills, SD #138
		04/12/85	William Cotton and Associates	Geotechnical Review Sheet
		04/16/85	William Cotton and Associates	Preliminary Geologic Review, Frantz-Mayacamas Lot Line Change (Lots 3 and 4), LD289
	625 Manzanita Way	09/23/99	Romig Consulting Engineers	Geotechnical Investigation, Caselton Guest Residence
	655 Manzanita Way	01/17/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
		05/21/03	Triad/Holmes Associates	500-Year Flood Survey
		06/05/03	Earth Investigations Consultants	Reply to Town Review, Geotechnical Investigation, Proposed Site Improvements
	660 Manzanita Way	03/18/75	Daniel J. Rhoades & Associates	Soil and Foundation Investigation, Portion of Lots 65 & 66, Block d, Portola Woods
		01/11/86	Earth Systems Consultants	Soil and Geologic Investigation, Proposed Addition to Residence
		03/12/87	Earth Systems Consultants	Soil Study Report, Proposed Residence Addition
		03/16/94	Jo Crosby & Associates	Geologic Investigation Report, Planned Residential Structures
		05/02/94	Jo Crosby & Associates	Addendum, Geologic Investigation, Planned Residential Structures
		07/11/94	Jo Crosby & Associates	Addendum, Geologic Investigation Report, Planned Residential Structures
		12/28/94	Nielsen Geotechnical Incorporated	Soil Report
		09/18/98	GeoForensics, Inc.	Geotechnical Report Update, Ivory Property
	680 Manzanita Way	09/18/00	Nielsen Geotechnical Incorporated	Soil Report
		03/13/03	Romig Engineers, Inc.	Geotechnical Investigation, Pool House & Site Improvements
	MAPLE WAY			
13	415 Maple Way	12/09/05	Murray Engineers, Inc.	Geotechnical Investigation, Walker Residence Addition
	420 Maple Way	08/10/76	Associated Geotechnical Engineers	Geotechnical Investigation, Proposed Vanderzyl Residence
		02/13/05	GeoForensics, Inc.	Geotechnical Investigation, proposed Replacement Deck, Balcon Residence
	430 Maple Way	09/25/03	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Residential Additions
	512 Maple Way	04/29/09	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Foundation Replacement/Remodel
		12/02/10	Michelucci & Associates, Inc.	Supplemental Geotechnical Recommendations, Proposed Site Retaining Walls
		11/24/10	Michelucci & Associates, Inc.	Structural Calculations
13	MARTIN LANE			
	20 Martin Lane	07/29/99	Romig Consulting Engineers	Geotechnical Investigation, York Residence Addition
	30 Martin Lane	09/23/96	Nielsen Geotechnical Incorporated	Soil Report
	35 Martin Lane	02/10/04	Romig Engineers, Inc.	Geotechnical Investigation, Page-Oberg Residence Addition
		07/30/04	Romig Engineers, Inc.	Liquefaction Evaluation, Pge/Oberg Garage Addition
	40 Martin Lane	02/10/03	PGSoils, Inc.	Geotechnical Conditions, Proposed Residential Addition
		03/24/03	PGSoils, Inc.	Supplement to Geotechnical Conditions Report, Proposed Residential Addition
	45 Martin Lane	03/24/04	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions
13	MARTINEZ ROAD			
	21 Martinez Road	05/01/97	Nielsen Geotechnical Incorporated	Soil Report
		06/21/99	Nielsen Geotechnical Incorporated	Zaccor Grading Study, Zaccor Property
		12/20/99	Nielsen Geotechnical Incorporated	Response to Letter of December 1, 1999 from Town Counsel
		05/23/00	Nielsen Geotechnical Incorporated	Request for Design, Zaccor Retaining Walls
		06/15/00	John Woodruff Geology	Geologic Reconnaissance
		06/27/00	Nielsen Geotechnical Incorporated	Plans and Supporting Documentation, Site Retaining Walls & Drainage
	21 Martinez Road	08/23/00	Nielsen Geotechnical Incorporated	Supplemental Information - Second Submittal, SD97-079 & BP00-394
	25 Martinez Road	12/14/07	Jo Crosby & Associates	Geotechnical Investigation, Stability of the Garage Addition
		12/01/10	Jo Crosby & Associates	Update Report, Geotechnical Investigation, Carport-Garage Remodel
		02/17/10	Jo Crosby & Associates	Geotechnical Investigation Update
	50 Martinez Road	10/16/90	Upp Geotechnical, Inc.	Geologic Reconnaissance Investigation, Lands of Samuels
			William Cotton and Associates	Geotechnical Review Sheet
		06/13/91	Hoskins Engineering Inc.	Structural Calculations, Single Family Residence
	50 Martinez Road	7/26.91	William Cotton and Associates	Preliminary Geologic Review, Samules Residence Repair, PA #8179
13	275 Martinez Road	04/26/84	William F. Jones, Inc.	Geotechnical Investigation, Fairman Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
			William Cotton and Associates	Geotechnical Review Sheet
		09/01/84	William F. Jones, Inc.	Review of Underpinning Plans, Fairman Residence
		09/18/84	William Cotton and Associates	Geotechnical Review Sheet
		09/19/84	William Cotton and Associates ?	Geologic Map of Fairman Residence by PCA
		09/24/84	William Cotton and Associates	Geologic and Geotechnical Review
		7/0/91	R. C. Hutton & Associates	Boundary and Topographic Survey showing >35% slopes
		12/04/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
		12/20/91	William F. Jones, Inc.	Town of Woodside Architect Review, Room Addition
		02/28/92	William F. Jones, Inc.	Supplemental Geotechnical Investigation and Level of Risk Evaluation
		04/20/92	William Cotton and Associates	Geologic and Geotechnical Review, Fairman Residential Additions
		05/11/92	William F. Jones, Inc.	Response to Geologic and Geotechnical Review
		06/29/92	William F. Jones, Inc.	Response to Meeting at Town Hall, Proposed Room Addition
		11/30/92	William F. Jones, Inc.	Plan Review, Proposed Room Additions
		02/18/93	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Fairman Residential Additions, 925-041
13A	MARVA OAKS DRIVE			
	117 Marva Oaks Drive	07/15/00	Town of Woodside	Comments
		09/29/00	Romig Engineers, Inc.	DRAFT Geotechnical Investigation, New Residence
		10/16/00	Town of Woodside	Comments
		07/01/06	Romig Engineers, Inc.	Geotechnical Investigation
		10/25/06	Romig Engineers, Inc.	New Residence
		06/05/07	Romig Engineers, Inc.	Supplemental Recommendations, Huhs Residence
		08/14/08	Romig Engineers, Inc.	Supplemental Recommendations, Huhs Detached Carport
	151 / 153 / 155 Marva Oaks Drive	12/30/82	Eareth Sciences Associates	Phase I Assesment of Geologic Hazards, lasco Property
		11/01/83	Donald A. Woolfe & Associates	Environmental Assessment, Lands of Jack and lasco for Proposed Subdivision
		08/27/84	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfields, Lands of Jack and lasco
		10/11/84	Earth Sciences Associates	Phase II Soil and Geologic Investigation, lasco Property (2 COPIES)
		09/20/85	Perry R. Wood	Addendum, Soil Percolation Tests and Recommended Septic Drainfields, Lands of Jack and lasco
		08/00/93	ESA Consultants	Geologic and Geotechnical Design Level Investigation, Marva Oaks Drive Cul de Sac and Joint Driveway
		12/03/93	ESA Consultants	Response to Town Comments
		06/15/01	Lowney Associates	Supplemental Geotechnical Recommendations for Landslide Mitigation, Proposed Development
	153 Marva Oaks Drive	03/21/90	Upp Geotechnology, Inc.	Percolation Testing, Lands of Jack/lasco
		05/12/98	Applied Earth Sciences Consultants	Geotechnical Review of Conceptual Site Plan, Julia Morgan Residence Restoration Project
		10/09/00	Lowney Associates	Geotechnical and Geologic Investigation
13A	155 Marva Oaks Drive	10/05/00	Lowney Associates	Geotechnical and Geologic Investigation
		09/21/01	Geomatrix Consultants	Permeability Tests Review, Falkenberg Tennis Court
		10/30/01	Lowney Associates	Response to Geomatrix Review, Tennis Court Permeability Results
		10/11/02	Lowney Associates	Geotechnical Recommendations, Tennis Court Preparation
		06/08/06	TRC Lowney	Supplemental Geotechnical Review of Project Plans, Falkenberg Residence
14	MEADOW ROAD			
	3 Meadow Road	08/28/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Foundation Improvements to Existing House, New Guesthouse
		03/11/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed New House
	28 Meadow Road	06/25/93	Hydro-Geo Consultants, Inc.	Geotechnical Site Evaluation for Single-Family Residence
		08/06/93	David W. Buckley	Geotechnical Investigation, Proposed Schilling Residence
		09/09/94	Applied Earth Sciences Consultants	Ground Water Investigation and Control Plan, Proposed On-Site Septic System
	28 Meadow Road	11/09/94	Applied Earth Sciences Consultants	As-Built Report for Ground Water Dewatering Trench for On-Site Septic System
	45 Meadow Road	05/03/78	William F. Jones, Inc.	Soil Investigation, Hogle Residence
		06/28/78	William F. Jones, Inc.	Swimming Pool Plan Review, Hogle Residence
		07/24/78	Leighton and Associates	Review Comments, Swimming Pool
14	MEDWAY ROAD			
	12 Medway Road	03/15/02	David Jones Associates	Engineering Geology Investigation, Proposed Andre Residence
		03/20/02	David Jones Associates	Geotechnical Investigation, Proposed Single-Family Residence (APN076-051-050, 076-042-090)
		07/01/02	David Jones Associates	Structural Calculations, Proposed Single Family Residence
		10/10/02	David Jones Associates	Geotechnical Response to Town Comments, Proposed Residence
	16 Medway Road	02/09/07	Fowler & Associates Geotechnical, Inc.	Geotechnical Investigation, Proposed Remodel of Guest Cottage
	20 Medway Road	04/17/07	Michelucci & Associates, Inc.	Geotechnical Investigation, Area of Existing Addition to Residence
14	MIDGLEN WAY			
	822 Midglen Way	02/17/00	Earth Systems Consultants	Geotechnical Investigation, Proposed Residential Development
		10/21/03	Earth Systems Consultants	Supplemental Geotechnical Recommendations, Proposed Pool

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
14	MIRAMONTES ROAD			
	141 Miramontes Road	09/06/90	William F. Jones, Inc.	Soils Investigation, McPherson Residence
	151 Miramontes Road	07/09/07	Romig Engineers, Inc.	Geotechnical Engineers, Inc., Miramontes Residence
		10/12/09	Romig Engineers, Inc.	Swimming Pool Design, Middler Property
	163 Miramontes Road	05/06/98	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence
		03/29/10	JF Consulting, Inc.	Geotechnical Investigation, New Swimming Pool, Lands of McAniff
		10/12/10	JF Consulting, Inc.	Geotechnical Investigation, Foundation Replacement for Cottage & New Car Port, Lands of McAniff
	203 Miramontes Road	02/04/99	Earth Investigations Consultants	Geotechnical Investigation
		04/28/06	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel
	208 Miramontes Road	08/15/90	DCM/Joyal Engineering	Preconstruction Geotechnical Engineering Investigation, Mariani Residence
		12/12/90	Soil Engineering Construction, Inc.	Structural Calculations, Stitch Pier Wall
			William Cotton and Associates	Geotechnical Review Sheet
		01/30/91	DCM/Joyal Engineering	Geotechnical Review of StitchPier Wall Design
		04/30/99	Nielsen Geotechnical Incorporated	Soil Report
	239 Miramontes Road	04/03/03	Michelucchi & Associates, Inc.	Geotechnical Investigation, Proposed New Residence
		07/16/03	Michelucchi & Associates, Inc.	Supplemental Geotechnical Recommendations, Proposed New Residence
		07/17/03	Michelucchi & Associates, Inc.	Supplemental Geotechnical Recommendations No. 2, Proposed Low Fill Slopes
		09/10/03	Michelucchi & Associates, Inc.	Review of Plans, Proposed Pool Shed and Supplemental Geotechnical Recommendations No. 4
		10/28/03	Michelucchi & Associates, Inc.	Proposed Rock Retaining Walls
		09/13/04	Michelucchi & Associates, Inc.	Geotechnical Recommendations, Proposed Swimming Pool
	289 Miramontes Road	12/04/97	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
	345 Miramontes Road	09/15/04	Murray Engineers Inc.	Geotechnical Investigation, Putnam Residence
		03/03/05	Murray Engineers Inc.	Supplemental Recommendations, Hardscape Improvements
	395 Miramontes Road	05/23/94	Haro, Kasunich and Associates, Inc.	Geotechnical Investigation
		05/15/95	Haro, Kasunich and Associates, Inc.	Verification of Subsurface Soil Environment, Proposed Main House Addition
		05/15/95	Haro, Kasunich and Associates, Inc.	Verification of Subsurface Soil Profile with Additional Hand Augered Exploratory Borings, Proposed Guesthouse
14	MISSION TRAIL ROAD			
	25 Mission Trail Road	05/21/76	Richard E. Roland	Geologic Investigation of Parcel No. 73-011-150
		11/0/76	Frahm Edler Cannis	Preliminary Map, Land Division, Pands of Herrmann & Klingele
		02/18/77	Leighton and Associates	Review of RER 5/21/76 Geologic Investigation of Parcel No. 73-011-150
	55 Mission Trail Road	06/27/89	Cleary Consultants, Inc.	Geotechnical Investigation
		02/02/11	JF Consulting, Inc.	Review of Soil Report, Addition, Putnam Residence and Our Comments
		various	various	Planning Commission Package on Putnam Creek Bank Project
	65?	06/17/85	Lee Engineers	Existing Soils Report Confirmation Review and Recommendations
14A	MONTECITO ROAD			
	6 Montecito Road	11/13/92	Applied Earth Sciences Consultants	Geologic Investigation, Site Development Feasibility, Parcel "B" Woodside Country Club Properties, Subdivision No. 1
		12/22/92	William Cotton and Associates	Supplemental Geologic Review, Markkula Building Site Feasibility
		04/22/94	Applied Earth Sciences Consultants	Supplemental Geologic Investigation, Parcel "B", Woodside Country Club Properties, Subdivision No. 1
		01/08/01	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Bowers
		07/17/01	Upp Geotechnology, Inc.	Summary Letter, Geotechnical Investigation, Lands of Bowers
	8 Montecito Road	10/15/08	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Swimming Pool
		08/04/09	Wayne Ting & Associates, Inc.	Revised Swimming Pool Recommendations
		08/05/09	Wayne Ting & Associates, Inc.	Update of Geotechnical Investigation, Proposed Addition and Swimming Pool
	21 Montecito Way (Road)	07/20/98	Nielsen Geotechnical Incorporated	Leachfield Stability Investigation
		08/19/99	John Coyle & Associates	Geologic Reconnaissance Letter Report, Proposed Leach Field Area
		06/27/05	Murray Engineers, Inc.	Geotechnical Investigation, Ladd Residence Improvements
		02/01/06	Murray Engineers, Inc.	Emergency Landslide Mitigation, Ladd property
		02/06/06	Murray Engineers, Inc.	Supplemental Information, Emergency Landslide Mitigation, Ladd Property
		05/03/06	Murray Engineers, Inc.	Supplemental Information, Landslide Mitigation, Ladd Property
		02/15/07	Murray Engineers, Inc.	Supplemental Recommendations and Plan Review, Landslide Mitigation, Ladd Property
	33 Montecito Road	10/12/83	Jo Crosby & Associates	Consultation on Proposed Concrete Filled Drilled Pier Retaining Walls
		05/19/03	Jo Crosby & Associates	Stability Analysis
		12/08/04	Romig Engineers, Inc.	Geotechnical Investigation, Vine Residence Improvements
		12/08/05	Romig Engineers, Inc.	Geotechnical Review, Residence Improvements

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
14A	MONTELENA COURT			
	1, 2, 3 Montelena Court	10/19/78	Jo Crosby & Associates	Geologic Investigation, 12+ Acres
		01/16/81	Jo Crosby & Associates	Addendum: Geologic Investigation, 12+ Acres
	1 Montelena Court	03/10/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Equestrian Improvements
	2 Montelena Court	06/02/86	Nordmo Associates, Inc.	Soil Investigation, Barnes/Law Property
		12/05/96	Lowney Associates	Foundation Investigation, Butler Residence
		09/15/97	Lowney Associates	Supplemental Geotechnical Information, Butler Residence Guesthouse
		03/28/03	Lowney Associates	Updated Geotechnical Investigation
		04/01/04	Lowney Associates	Geotechnical Response Regarding Liquefaction, Proposed Residence and Caretakers Cottage.
		06/24/04	Triad/Holmes Associates	Engineering Review Comments for BP03-549
14A	MONTICELLO COURT			
	4 Monticello Court	05/30/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Carport Conversion and Garage, Campbell Property
	6 Monticello Court	07/10/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Two Lot Subdivision
	7 Monticello Court	06/14/05	PGSoils, Inc.	Soils Conditions, Proposed Swimming Pool
		06/15/05	PGSoils, Inc.	Response to Town Comments
	8 Monticello Court	07/10/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Two Lot Subdivision
14A	MOORE ROAD			
	137 Moore Road	10/01/82	Carl W. Garbe	Geotechnical Study Outline, Proposed Subdivision, 7-Acre Parcel
		03/28/84	Howard F. Donley & Associates	Geotechnical Investigation
		03/29/84	William Cotton and Associates	Geotechnical Review Sheet
		04/06/84	William Cotton and Associates	Preliminary Geologic Review, Lands of Havre, LD-279
		06/28/85	Brian Kangas Foulk & Associates	Grading & Drainage Plan for Jerry Bagnani
		07/30/85	Howard F. Donley & Associates	Plan Review, Proposed Single Family Residence, Lot 7, Parcel B
		08/20/85	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Bagnani, Land Division 279
		01/03/96	Nielsen Geotechnical Incorporated	Soil Report
		12/04/97	Nielsen Geotechnical Incorporated	Supplemental Soil Report
	389 Moore Road	01/24/06	Murray Engineers, Inc.	Engineering Geologic & Geotechnical Reconnaissance, Site Development Feasibility
	475 Moore Road	03/14/07	Ronig Engineers, Inc.	Geotechnical Investigation, Roberts Residence
	490 Moore Road	08/12/76	Terrasearch, Inc	Soil & Geologic Investigation, Three-acre Parcel
		06/01/77	Town of Woodside	Review Comments
		06/23/77	Terrasearch, Inc	Supplemental Soil & Geologic Investigation, Three-acre Parcel
		06/24/77	Terrasearch, Inc	Supplemental Foundation Recommendations, Three-acre Parcel
		07/08/77	Town of Woodside	Review of Responses to Town Comments
		06/26/00	Alliance Environmental & Soil Engineering	Geotechnical Investigation, Proposed Swimming Pool
		07/06/02	GeoForensics Inc.	Geotechnical Investigation, Landslide Mitigation
		10/03/02	GeoForensics Inc.	Drawing Revision, Douglass Property
		08/27/03	Ronig Engineers, Inc.	Geotechnical Investigation, Douglas Residence Addition
		01/29/08	Ronig Engineers, Inc.	Geotechnical Investigation, Douglas Deck, Swimming Pool, and Pool House
		10/01/08	GeoForensics Inc.	Alternative Pool Location, Douglas Property
		11/19/08	GeoForensics Inc.	Retaining Wall Recommendations, Douglas Property
		11/20/08	GeoForensics Inc.	Retaining Wall Recommendations (#2), Douglas Property
		02/12/09	Ronig Engineers, Inc.	Geotechnical Recommendations, Douglas Pool House
14A	505 Moore Road	03/13/90	Melvin R. Hill, Inc.	Soil and Foundation Investigation, Proposed Single Family Residence
		01/12/90	Cannis Consulting Engineers	Concept Map, Parcel 2, Vol. 25, PM 1, Lands of Cardellini
		01/12/90	Cannis Consulting Engineers	Vesting Tentative Map, Parcel 2, Vol. 25, PM 1, Lands of Cardellini
		05/24/90	Cannis Consulting Engineers	Response to Town Planning Comments - LD #311, with annotations
		10/24/90	Cannis Consulting Engineers	Vesting Tentative Map, Parcel 2, Vol. 25, PM 1, Lands of Cardellini
		12/04/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Cardellini Vesting Tentative Map, LD 311
		02/18/00	Nielsen Geotechnical, Inc.	Soil Report
		09/17/00	Nielsen Geotechnical, Inc.	Plan Review
		07/19/02	Nielsen Geotechnical, Inc.	Construction Report
15	515 Moore Road	03/20/08	Murray Engineers, Inc.	Geotechnical Investigation, Mahoney Residence
	524 Moore Road	05/06/99	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Guest House and Access Driveway
		03/16/00	Michelucci & Associates, Inc.	Supplemental Letter, UBC Soil Profile Type and Related Criteria, Proposed Guest House
		06/07/00	Michelucci & Associates, Inc.	Supplemental Geotechnical Investigation, Proposed Guest House
	525 Moore Road	07/27/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Addition

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	525 Moore Road	07/12/05	Romig Engineers, Inc.	Geotechnical Investigation, Soffel Barn
	540 Moore Road	06/12/98	Cleary Consultants, Inc.	Soil and Foundation Engineering Investigation, Home Renovation
	505? / 545 Moore Road	04/09/74	Berlogar, Long & Associates	Soils and Geologic Investigation, Proposed Two Parcel Single Family Residential Development, 13.5 Acre Parcel
		04/30/74	William Cotton and Associates	Review of Soils and Geologic Investigation Report - Sogemeire Property
		05/02/74	Town of Woodside	Review of Soils Report - Sogemeire Land Division & Remaining Conditions
		05/03/74	Town of Woodside	Comments on Geologic Investigation Report
		07/25/78	Berlogar, Long & Associates	Soils Investigation, Proposed Single Family Residence, Parcel 2
		11/06/78	William Cotton and Associates	Field Review of 7/25/78 report
		11/13/78	William Cotton and Associates	Cardellini - Conformity: Geotechnical Review
			Robert L. Klemmedson, Architect & Planner	Preliminary Plot Plan, Cardellini Residence
	560 Moore Road	11/17/83	Brian Kangas Foulk & Associates	Tentative Parcel Map - Lands of Hayne
		03/28/84	Louis A. Richardson	Geologic Investigation, Lands of Hayne, APN 73-132-030
		03/28/84	William M. McMorrow & Associates	Geotechnical Engineering Investigation, Lands of Hayne - Proposed Lot Split
		04/20/84	William Cotton and Associates	Geotechnical Review Sheet
			William Cotton and Associates	Photographs
		04/16/84	William Cotton and Associates	Preliminary Geologic Review, Hayne Land Division 285
			Cody Associates	Grading/Drainage Plan, Grossi Pool & Tennis Court
		01/03/90	Earth Systems Consultants	Geotechnical Report, Grossi Residence
		01/24/90	Town of Woodside	Comments on Site Development #36 and Building #7674
		02/14/90	Town of Woodside	Comments on Site Development #36
		02/27/90	Earth Systems Consultants	Revised Geotechnical Report, Grossi Residence
		02/27/90	Earth Systems Consultants	Tennis Court and Swimming Pool Plan Review, Grossi Residence
			William Cotton and Associates	Geotechnical Review Sheet
		04/02/90	William Cotton and Associates	Geologic and Geotechnical Review
		08/16/90	Earth Systems Consultants	Revised Geotechnical Recommendations, Grossi Residence
		08/27/90	Earth Systems Consultants	Plan Review, Grossi Pool and Tennis Court
		05/17/96	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Bedroom Addition, Grossi House
	595 Moore Road	7/0/82	Brian Kangas Foulk & Associates	Tentative Parcel Map - A Resubdivision of A Portion of Lot 7, with annotations
		10/01/82	Carl W. Garbe	Geotechnical Study Outline, Proposed Subdivision, 7 Acre Parcel
		11/30/82	William Cotton and Associates	Geotechnical Review Sheet
		12/08/82	William Cotton and Associates	Geologic Review, Harve, LD 279
		03/28/84	Howard Donley Associates, Inc.	Geotechnical Investigation, Proposed Single Family Residence, Lot 7, Parcel B
		10/29/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	600 Moore Road	08/16/96	Nielsen Geotechnical Incorporated	Geotechnical Report
	1142 Moore Road	4/0/87	Brian Kangas Foulk Associates	Site Plan and Orthophotograph
			William Cotton and Associates	Geotechnical Review Sheet
		06/17/87	William Cotton and Associates	Preliminary Geologic Review, Zygarzewicz, Lot Line Adjustment #296
		03/25/98	Romig Consulting Engineers	Geotechnical Investigation, Machado Residence Pool & Pool House
	1144 Moore Road	09/22/95	Upp Geotechnology, Inc.	Geotechnical Investigation, Appurtenant Structures, Hirsch Property
		08/15/00	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation, New Pool Development, Hirsch Property
15	MOUNTAIN HOME COURT			
	370 Mountain Home Court	02/22/00	Michelucchi & Associates, Inc.	Geotechnical Investigation, Proposed Creek Bank Stabilization, Sonsini Property
		08/30/00	Michelucchi & Associates, Inc.	Response to Town Geologist Comments
		11/01/00	Michelucchi & Associates, Inc.	Response to Town Geologist Comments
	372 Mountain Home Court	07/26/83	Perry R. Wood	Soil Percolation Tests, Proposed Parcel A, Subdivision of Parcel 072-190-790
		3/0/83	Edwin H. Smith	Preliminary Map, Resubdivision of Parcel 2A of Land Division Map No. 241, with annotations
		01/06/84	PSC Associates, Inc.	Geotechnical Engineering Investigation, Proposed Residence, Parcel A
		02/13/84	William Cotton and Associates	Geotechnical Review Letter
		02/14/84	William Cotton and Associates	Preliminary Geotechnical Review, Mayacamas, LD-282
		08/25/86	PSC Associates, Inc.	Grading and Foundation Plan Review, Proposed Georgakas Residence on Parcel A
		10/12/87	Perry R. Wood	Additional Soil Percolation Tests and Recommended Septic Drain Field, APN 072-190-790
		04/18/88	PSC Associates, Inc.	Proposed Driveway Retaining Wall, Georgakas Residence, Parcel A
		03/16/94	Rick Skierka	Lot Line Adjustment
15	376 Mountain Home Court	06/22/94	Earth Systems Consultants	Updated Geotechnical Report, Proposed Landscape Improvements, Gilhuly Property
		03/31/08	Peters & Ross	Geotechnical Investigation, Gilhuly Residence
15A	MOUNTAIN HOME ROAD			
	181 Mountain Home Road	12/17/02	Earth Mechanics Consulting Engineers	Geotechnical Investigation Report, Planned Residence
		09/03/04	Murray Engineers Inc	Geotechnical Services, Edwards Residence
		09/24/04	Murray Engineers Inc	Supplemental Information, Geotechnical Investigation, Edwards Residence
		02/22/06	Murray Engineers Inc	Supplemental Geotechnical Recommendations, New Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	186 Mountain Home Road	05/11/98	John Coyle & Associates, Inc.	Geologic Reconnaissance Letter Report
		05/13/98	Nielsen Geotechnical Incorporated	Soil Report
		07/08/98	John Coyle & Associates, Inc.	Addendum Geologic Letter Report
		07/10/98	Nielsen Geotechnical Incorporated	Plan Review
		05/07/07	Murray Engineers, Inc.	Geotechnical Recommendations, New Tennis Court
	187 Mountain Home Road	07/21/94	Baker - CEG	Engineering Geologic Investigation, Possible Future Additions to Existing Residence
		07/31/94	GeoForensics, Inc.	Geotechnical Recommendations, Proposed Residential Additions
		06/18/95	Baker - CEG	Responses to Town Geologists' Review Comments on 7/21/94 Baker-CEG Report
		07/03/95	Michelucci & Associates, Inc.	Geotechnical Recommendations, Proposed Addition and Remodel Project
	189 Mountain Home Road	02/04/08	Murray Engineers, Inc.	Geotechnical Investigation, Burke Residence
		09/30/09	Murray Engineers, Inc.	Geotechnical Report Update, New Residence
		11/30/09	Murray Engineers, Inc.	Supplemental Foundation Recommendations, New Residence
		10/04/10	Murray Engineers, Inc.	Supplemental Foundation Recommendations, New Residence
	190 Mountain Home Road	08/14/07	Lea & Braze Engineering, Inc.	Hydrology Study, Matta Residence
	225 Mountain Home Road	10/01/85	William Cotton and Associates	Geotechnical Review Sheet - Miller LD #291
		9/0/85	Reimer Associates	Tentative Map, with annotations
		10/09/85	William Cotton and Associates	Preliminary Geologic Review
		10/10/85	Town of Woodside	Subdivision Review Committee Comments
	240 Mountain Home Road	04/30/07	Murray Engineers, Inc.	Geotechnical Investigation, Yohanan Residence
		09/27/07	Lea and Braze Engineering, Inc.	Hydrology Study, Yohanan Residence
		10/10/07	Murray Engineers, Inc.	Supplemental Recommendations, Landscaping Improvements & Immersion Room Foundation
		04/07/09	Murray Engineers, Inc.	Geotechnical Investigation, White Residence
		12/07/10	Murray Engineers, Inc.	Geotechnical Investigation, New Residence
	290 Mountain Home Road	02/25/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New garage and Patio, Millichap Property
	330 Mountain Home Road	07/11/00	Harlan Tait Associates	Geotechnical Investigation, Sherer Property
		03/18/03	Harlan Tait Associates	Geotechnical Investigation, Pettit Residence
		04/07/09	Murray Engineers, Inc.	Geotechnical Investigation, Dransfield/Bridger Residence
		08/03/09	Murray Engineers, Inc.	Geotechnical Plan Review, Dransfield/Bridger Residence
		03/18/03	Harlan Tait Associates	Geotechnical Investigation, Pettit Residence
15A	360 Mountain Home Road	06/01/99	Milstone Geotechnical	Geotechnical Investigation, Proposed Friedman Residence
		07/29/99	Milstone Geotechnical	Geotechnical Investigation, Proposed Residence
		10/08/01	Milstone Geotechnical	Geotechnical Investigation, Proposed Relocation and Remodel of Existing Residence
		07/10/02	Milstone Geotechnical	Geotechnical Report Update, Proposed Friedman Residence
15B	375 Mountain Home Road	06/17/85	Lee Engineers	Existing Soils Report Confirmation Review and Recommendations
	382 Mountain Home Road	10/02/97	Earth Investigations Consultants	Soil & Foundation Investigation, Proposed Pool and Spa
		07/10/09	Romig Engineers, Inc.	Geotechnical Investigation, Ricci Guest House, Pool House and Stable/Barn
	384 Mountain Home Road	09/30/74	Geolabs - Northern California, Inc.	Foundation Engineering Investigation, Parcel 4 West of Mountain Home Road and North of Mountain Wood Lane
		07/13/81	JCP Geologists	Soil and Foundation Study, Proposed Homesite located on Mountain Home Road
	386 Mountain Home Road	05/18/87	Terrasearch, Inc.	Geotechnical Investigation, Proposed Residence and Addition to Existing Residence
		10/26/92	DES Architects / Engineers	Structural Calculations
		10/27/92	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Stables, Swimming Pool and Cabana
		07/25/01	GeoForensics Inc.	Geotechnical Investigation, Proposed Site Improvements
		08/21/02	GeoForensics Inc.	Geotechnical Report Supplement, Cook/Ostby Property
	411 Mountain Home Road	02/18/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
		07/10/06	Applied Earth Sciences Consultants	Geotechnical Investigation, Pool Pavilion, Pasquesi Family
	450 Mountain Home Road	09/17/01	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Residence
		11/26/02	Earth Mechanics Consulting Engineers	Geotechnical Consultation
		07/08/02	Earth Mechanics Consulting Engineers	Geotechnical Responses to Plan Review Comments
	515 Mountain Home Road	07/22/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Additions to Miller Residence
	550 Mountain Home Road	09/18/98	Romig Consulting Engineers	Geotechnical Investigation, Ludwig Residence Addition
		02/29/00	Romig Consulting Engineers	Supplemental Geotechnical Investigation, Ludwig Residence
	556 Mountain Home Road	08/08/08	Jo Crosby & Associates	Results of the Exploratory Fault Investigation
	560 Mountain Home Road	10/05/77	Purcell, Rhoades & Associates	Fault and Geotechnical Hazards Investigation, Portion of Parcel 2, Land Division No. 129, Vol. 4, Page 10, Woodside, for Mr. Mark Campbell
		11/18/77	Leighton and Associates	review of above

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		12/02/77	Town of Woodside	Inter-Office Memo on Liquefaction Potential
		02/21/78	Leighton and Associates	Review of Land Division Map #240
		03/28/78	Town of Woodside	Report to the Planning Commission with several data attachments
		0/0/81	William Cotton and Associates	Geotechnical Review Sheet
		05/21/81	Edwin H. Smith	Land Division Map #240, Preliminary Map, Parcel 2 of Land Division Map # 129
		05/29/81	Town of Woodside	Cover Transmitting Earlier LD Correspondence
	566 Mountain Home Road	03/14/08	Jo Crosby & Associates	Geotechnical Investigation, Proposed Residential Development
		10/29/08	Jo Crosby & Associates	Response to Town Review Comments
15B	568 Mountain Home Road	02/28/95	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Structure, Scoren Property
16	578 Mountain Home Road	08/17/92	Cleary Consultants, Inc.	Geotechnical Investigation, Residence Additions
		06/08/93	Cleary Consultants, Inc.	Supplemental Geologic Letter, Residence Additions
		06/19/95	Cleary Consultants, Inc.	Geotechnical Investigation, New Pool and Associated Landscaping
		09/13/00	Cleary Consultants, Inc.	Geotechnical Investigation, Planned Guest House, Maintenance Building and Garage
	580 Mountain Home Road	12/18/96	Jo Crosby & Associates	Geotechnical Investigation, Planned Structures
		09/15/97	Jo Crosby & Associates	Response to Review Comments on 12/18/96 Report
		10/27/00	Jo Crosby & Associates	Fault Investigation, Tea House
	607 Mountain Home Road	06/08/93	Terrasearch, Inc.	Geotechnical Investigation, Proposed Additions
		08/04/93	Terrasearch, Inc.	Response to Town of Woodside Consultant's Review of 6/8/93 TI report
	618 Mountain Home Road	01/30/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Improvements
		12/15/04	Romig Engineers, Inc.	Landscape Retaining Wall, O'Leary Tennis Court
		08/12/04	Romig Engineers, Inc.	Supplemental Recommendations, New Swimming Pool
		05/23/05	Romig Engineers, Inc.	Geotechnical Recommendations, Generator Building and Pool Storage Building
		08/09/05	Romig Engineers, Inc.	Geotechnical Guidelines, Water Tank and Vault
	620 Mountain Home Road	11/19/96	Cleary Consultants, Inc.	Geotechnical Investigation, Residence Addition
		08/02/06	Cleary Consultants, Inc.	Geotechnical Investigation, Kitchen/Sitting Room Addition
	675 Mountain Home Road	04/08/01	GeoForensics Inc.	Limited Geotechnical Investigation, Proposed New Barn
	680 Mountain Home Road	10/00/97	Rick Skierka	Lot Line Adjustment
	725 Mountain Home Road	05/31/01	Signet Testing Labs, Inc.	Geotechnical Investigation
		03/06/02	Signet Testing Labs, Inc.	Review of Geotechnical Elements of Design Drawings, Gate House
		05/20/02	Signet Testing Labs, Inc.	Response to Comments From Town of Woodside, BP02-131, Gate House
		04/02/04	Applied Earth Sciences Consultants	Feasibility Assessment, Proposed Site Improvements
		05/05/04	D&M Consulting Engineers, Inc.	Geotechnical Investigation Report, New Buildings
		02/11/05	Applied Earth Sciences Consultants	Geotechnical Investigation, Tennis Court
		03/13/06	Applied Earth Sciences Consultants	Geotechnical Investigation and Recommendations, Proposed Gate House Maintenance Shed
		03/16/06	Applied Earth Sciences Consultants	Geotechnical Investigation & Recommendations, Proposed Tennis Court Trellis
		05/01/06	Applied Earth Sciences Consultants	Geotechnical Investigation & Recommendations, Proposed Pond Pavilion, Upper and Lower Stables
		06/19/06	Applied Earth Sciences Consultants	On-site Sewage Disposal Systems, Gatehouse Maintenance Shed and Lower Stable
		08/16/06	Applied Earth Sciences Consultants	Tennis Court Surface and Drainage Relative to Impervious Surface Calculations
	745 Mountain Home Road	05/01/95	Upp Geotechnology, Inc.	Fault Investigation, King Property
		06/02/95	Upp Geotechnology, Inc.	Addendum Fault Location Investigation, King Property
		03/12/96	Applied Earth Sciences Consultants	Geologic, Geotechnical Engineering, Seismologic and Hydrologic Investigation, Estate Redevelopment Feasibility
		06/20/96	Applied Earth Sciences Consultants	Supplemental Data Regarding the Old King Estate Well Identified as K-1
		12/15/96	Applied Earth Sciences Consultants	Geotechnical Foundation Investigation and Recommendations
		?	TS Nowack Consultants	Hydrology Calculations
		12/06/99	Applied Earth Sciences Consultants	A Geotechnical Report for Pond Bottom Lining
		09/06/00	Applied Earth Sciences Consultants	Monitor Well Readings
		05/04/01	Applied Earth Sciences Consultants	Monitor Well Readings
		07/05/01	Applied Earth Sciences Consultants	Production and Monitor Well Location Map Transmittal
		01/30/02	Applied Earth Sciences Consultants	Monitor Well readings
		02/17/02	Town of Woodside	Conditions of Approval
		0/0/02	Town Of Woodside	Memo from Town Geologist to Planning Director
		07/07/02	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2001-2002 Report
		06/01/03	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2002-2003 Report
		12/19/03	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2003-2004 Report
		09/21/07	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2006-2007 Report
		10/24/08	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2007-2008 Report
		0/0/09	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels and Water Quality Analysis, Annual 2008-2009 Report
		10/15/10	Applied Earth Sciences Consultants	Surface and Ground Water Well Production, Water Levels, and Water Quality Analysis, Annual 2009-2010 Report
	750 Mountain Home Road	01/18/01	Romig Engineers, Inc	Geotechnical Investigation, Barnett Residence
	780 Mountain Home Road	09/22/88	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Additions and New Structures

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		03/10/89	Raymond E. Lindahl, Inc.	Structural Calculations
			William Cotton and Associates	Geotechnical Review Sheet
		06/19/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Bossen Additions, PA #7285
	890 Mountain Home Road	06/21/91	Tejima and Associates, Inc.	Geotechnical Investigation Report, Proposed Accessory Quarters, Existing Declert Residence
	915 Mountain Home Road	03/25/05	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Carriage House Reconstruction
16	925 Mountain Home Road	08/24/81	Purcell, Rhoades & Associates	Preliminary Soils Report, Assessor's Parcel 92-221-180, Sand Hill Road and Mountain Home Road
		12/02/83	J. V. Lowney & Associates	Geotechnical Investigation, Residence Addition
		12/09/93	Town of Woodside	Use of Permeable Asphalt at 925 Mountain Home Road
		08/27/96	Town of Woodside	Construction and Use of a Permeable Asphalt Tennis Court
			Town of Woodside	Deposit Account Print-Out dated 11/14/01
16A	959 Mountain Home Road	6/0/83	Edwin H. Smith	Preliminary Map, Land Division, Lands of Hoffman
		09/30/83	Louis A. Richardson	Geologic Investigation Report, Lands of Hoffman, APN 072-221-150
		09/30/83	Dunham & Associates	Soils Engineering Evaluation, Potential Building Site and Land Division, Lands of Hoffman
		02/03/84	William Cotton and Associates	Geotechnical Review Sheheet
		02/07/84	William Cotton and Associates	Preliminary Geotechnical Review, Lands of Hoffmann LD 284
		12/19/86	Perry R. Wood	Soil Percolation Tests, Lot 2
		12/27/86	Perry R. Wood	Soil Percolation Tests and recommended Septic Drainfield, Lot 2 (Parcel 072-221-410)
		01/29/87	Carl W. Grabe	Soils & Foundation Report, Proposed Residence, APN 072-221-150, Lot 2
		07/09/87	Carl W. Grabe	Soils & Foundation Report, Proposed Residence, APN 072-221-150, Lot 2
		08/03/87	Carl W. Grabe	Soils Test Data (Expansion, Strength), Proposed Residence
		08/07/87	Carl W. Grabe	Soils & Foundation Report, Proposed Swimming Pool
		08/07/87	Carl W. Grabe	Geotechnical Review of Plans, Proposed Residence
			William Cotton and Associates	Geotechnical Review Sheet
		07/02/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Tse, AP #4080
		09/11/97	William Cotton and Associates	Supplemental Geotechnical Review, lands of Tse, Permit #4080
		06/29/92	Louis A. Richardson	Proposed Raab Residence
		06/30/92	Lowney Associates	Geotechnical Investigation and Geologic Reconnaissance, Raab Residence
	999 Mountain Home Road	09/30/83	Louis A. Richardson	Geologic Investigation Report, Lands of Hoffman (APN 072-221-150)
		06/29/92	Louis A. Richardson	Proposed Rabb Residence (update of 9/30/83 report)
		06/30/92	Lowney Associates	Geotechnical Investigation and Geologic Reconnaissance, Rabb Residence
	1000 Mountain Home Road	04/07/86	Upp Geotechnology	Geotechnical Investigation, Lands of Kirkwood (APN 072-211-450)
		4/0/86	John S. Bradbury	Structural Calculations
		04/24/86	Lubin Associates, Architects	Site Plan
		05/19/86	William Cotton and Associates	Geotechnical Review Sheet
		05/22/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kirkwood Residential Reconstruction
		01/22/99	Applied Earth Sciences Consultants	A San Andreas Fault Investigation
		05/30/99	Applied Earth Sciences Consultants	A Geotechnical Foundation Investigation
		07/28/99	Applied Earth Sciences Consultants	A Geotechnical Review of Garage Plans, Phillips Residence
		09/14/99	Applied Earth Sciences Consultants	A Geotechnical Review, Phillips, Residence Remodel Plans
		02/23/01	Applied Earth Sciences Consultants	Geotechnical Construction Observation and Testing and Recent Site Review, Main Residence Remodel
		08/08/01	Applied Earth Sciences Consultants	Geotechnical Construction Observation and Recent Site Review, Residence Remodel
	1005 Mountain Home Road	07/07/77	Perry R. Wood	Soil Percolation Rates in Areas Suitable for Septic Drain Facilities, Baldwin Property
		12/14/77	Leighton and Associates	daily report of site visit
		01/01/78	Frahm Elder Cannis	Preliminary Map, Meadowwood (Lands of Baldwin)
		01/09/78	Terratech, Inc.	Geologic/Geotechnical Investigation, Lands of Baldwin
		02/10/78	Town of Woodside	Review of Preliminary Map, Meadowwood, Landlock Corporation
		02/14/78	Town of Woodside	Summary of Subdivision Review Committee, Meadowwood Subdivision
		03/10/78	Terratech, Inc.	Comments on Wood Report
		04/12/78	Leighton and Associates	Request for Additional Information
		04/19/78	Terratech, Inc.	Response to Request for Additional Information
		05/17/78	Leighton and Associates	Review of Preliminary Map, Meadowwood, Landlock Corporation
		09/16/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Development, (APN 072-380-050)
	1015 Mountain Home Road	02/21/86	William Cotton and Associates	Geotechnical Review Sheet
		02/25/86	William Cotton and Associates	Preliminary Geologic Review, Diller Antenna/Tower, Variance 392
	1025 Mountain Home Road	various	Terratech, Inc.	various construction observation letters, Wendell Residence
		06/15/86	Perry R. Wood	Modified Septic Drainfield for New Residence
		06/26/95	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Kagle Property
		02/27/96	Town of Woodside / Kagles	Covennant and Agreement of pool house use
	1035 Mountain Home Road			
	1100 Mountain Home Road	09/12/05	Romig Engineers, Inc.	Geotechnical Review, Residence Improvements
		03/30/07	Town of Woodside	Memo on faulting issues and past development
		05/09/07	Murray Engineers, Inc.	Fault Location Investigation

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		05/09/07	Town Of Woodside	Fault Location Investigation Review Letter
16A	MOUNTAIN WOOD LANE			
	155 Mountain Wood Lane	04/06/06	Murray Engineers, Inc.	Geotechnical Investigation, Hodge Residence
	160 Mountain Wood Lane	02/17/93	John W. Leonard, Civil Engineer	Preliminary Geologic and Geotechnical Engineering Study
		02/28/96	Lowney Associates	Geotechnical Investigation, Pool, Pool House, Guest House and Exercise Facility
		03/11/98	Nielsen Geotechnical Incorporated	Soil Report
		12/04/00	Nielsen Geotechnical Incorporated	Design Recommendations, Accessory Structure at the Tennis Court
		03/05/01	Nielsen Geotechnical Incorporated	Plan Review, Phase 4, Tennis Court Building
16A	215 Mountain Wood Lane	08/18/85	JCP Geologists - Engineers	Soil and Foundation Study, Swimming Pool and Spa
		9/0/85	William Cotton and Associates	Geotechnical Review Sheet
		09/05/85	William Cotton and Associates	Preliminary Geologic Review, Watkins Pool
		01/29/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Watkins Pool
17	235 Mountain Wood Lane	12/09/91	Lowney Associates	Geotechnical Investigation and Geologic Reconnaissance, Perkins Residence
		02/21/94	Applied Earth Sciences Consultants	Interim Summary Report, A San Andreas Fault Investigation
		03/24/94	Applied Earth Sciences Consultants	A San Andreas Fault Investigation
		07/14/94	Applied Earth Sciences Consultants	San Andreas Fault Investigations and Associated Setback Recommendations, Perkins Property
	255 Mountain Wood Lane	02/01/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Additions
		09/10/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Improvements
		09/29/09	Earth Investigations Consultants	Geotechnical Review, Proposed Relocations of Swimming Pool and Spa
		04/21/10	Earth Investigations Consultants	Geotechnical Review, Proposed Site Improvements
	260 Mountain Wood Lane	11/16/01	Milstone Geotechnical	Geotechnical Investigation, Proposed Mohr Residence
		06/16/03	Milstone Geotechnical	Geotechnical Review, Garden Shed
		02/20/10	Milstone Geotechnical	Report Update, Geotechnical Investigation, Proposed Pool House and Swimming Pool, Mohr Residence
	263 ? Mountain Wood Lane	09/02/86	Earth Systems Consultants	Soil Investigation, Addition to Caretaker's Quarters
		06/11/86	Peterson Architects	Site Plan, with annotations
		07/14/86	William Cotton and Associates	Geotechnical Review Sheet
		07/15/86	William Cotton and Associates	Preliminary Geologic review, Davis Addition to Cottage
		09/10/86	Earth Systems Consultants	Plan Review, Addition to Caretaker's Quarters
		10/02/86	William Cotton and Associates	Supplemental Geotechnical Review, Davis Addition to Cottage, AP #3149
	265 Mountain Wood Lane	08/08/02	GeoForensics Inc.	Geotechnical Investigation, Proposed Barn, Liebeck Property
		11/07/02	GeoForensics Inc.	Retaining Wall Recommendations, Proposed Barn
	NEUMAN LANE			
17	25 Neuman Lane	11/26/02	Romig Engineers, Inc.	Geotechnical Investigation, New Residence
	45 Neuman Lane	10/20/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Pool, Game Room and Decks
		11/11/03	Earth Investigations Consultants	Geotechnical Plan Review, Proposed New Game Room and Decks
		03/18/04	Dodge Associates Surveying	Profile at Lands of Draeger
17	NOEL ROAD			
	10 Noel Road	03/03/00	GeoQuest, Inc.	Geotechnical Investigation, Goldberg Residence Additions
		02/21/08	GeoQuest, Inc.	Preliminary Plan Review and Supplemental Recommendations, Goldberg Residence Backyard Additions
		02/21/10	ARA Engineering Company	Geotechnical Engineering Study, Proposed House Addition, Goldberg Residence
	11 Noel Road	0/0/89	William Cotton and Associates	Geotechnical Review Sheet - Anzelc
		08/24/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Anzelc Addition, PA #7409
		11/09/89	Baldwin-Wright, Inc.	Geotechnical Investigation
		12/09/89	Lea Engineering	Structural Calculations
		02/12/90	Baldwin-Wright, Inc.	Geotechnical Plan Review, Proposed Addition and Swimming Pool
		03/14/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Anzelc Addition, PA #7409 and #7677
		03/21/90	Baldwin-Wright, Inc.	Response to Supplemental Geologic and Geotechnical Review, Proposed Addition and Swimming Pool
		04/12/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Anzelc Addition, PA #7409 and #7677
		09/20/90	Baldwin-Wright, Inc.	Review of Revised Retaining Wall Design, Proposed Wall Behind the Addition
17	NORMANDY LANE			
	115 Normandy Lane	04/10/11	Wayne Ting & Associates	Geotechnical Investigation, Proposed Pool House, Swimming Pool, and Pergola
		04/10/11	Wayne Ting & Associates	Geotechnical Investigation, Proposed Pool House, Swimming Pool, and Pergola
		4/10/11 (Revised)	Wayne Ting & Associates	Geotechnical Investigation, Proposed Pool House, Swimming Pool, and Pergola
		05/17/11	Wayne Ting & Associates	Respond to Town of Woodside
		06/10/11	Wayne Ting & Associates	Foundation Drain Recommendations

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	120 Normandy Lane	07/09/07	Murray Engineers, Inc.	Geotechnical Investigation, Louie Residence
	140 Normandy Lane	08/16/00	Friar Associates, Incorporated	Geotechnical Investigation, Proposed Addition
	150 Normandy Lane	07/25/02	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Remodeling/Additions
		08/30/02	Town of Woodside	Engineering Geology Review Comments
		09/12/02	Cotton, Shires & Associates, Inc.	Geotechnical Engineering Review, Rosenthal Residence
		09/18/02	Town of Woodside	Engineering Geology Review Comments
		11/29/02	Carl W. Garbe, P.E.	Response to Review Comments
		02/02/09	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Landscaping/Pool
		03/16/09	Carl W. Garbe, P.E.	Pool Support
17	NORTHGATE DRIVE			
	125 Northgate Drive	05/28/98	Nielsen Geotechnical Incorporated	Soil Report
	128 Northgate Drive	03/06/06	Romig Engineers, Inc.	Geotechnical Investigation, Heublein Residence
		11/30/06	Romig Engineers, Inc.	Supplemental Recommendations, Heublein Swimming Pool
17	NORTHRIDGE LANE			
	110 Northridge Lane	05/09/06	Earth Investigations Consultants	Geotechnical Investigation
		05/01/07	Earth Investigations Consultants	Supplemental Recommendations, Landscape Wall
		07/27/07	Earth Investigations Consultants	Supplemental Geotechnical Recommendations, Proposed Trellis
	140 Northridge Lane	11/06/79	Purcell, Rhoades & Associates	Underpinning Recommendations
	150 Northridge Lane	10/28/91	Milstone Geotechnical	Geotechnical Investigation, Proposed Addition, Moseman Residence
			William Cotton and Associates	Geotechnical Review Sheet
		06/11/92	Milstone Geotechnical	Geotechnical Review, Moseman Residence
		06/12/92	William Cotton and Associates	Geologic and Geotechnical Review, Moseman Addition, BP-8797
	155 Northridge Lane	01/31/01	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residence
		06/24/04	Murray Engineers Inc	Geotechnical Evaluation, New Swimming Pool
		10/13/04	Murray Engineers Inc	Geotechnical Review of Plans, Swimming Pool and Spa
17	OAKFORD ROAD			
	100 Oakford Road	05/25/06	Romig Engineers, Inc.	Geotechnical Investigation, PrahI Residence
	115 Oakford Road	06/10/96	Romig Consulting Engineers	Geotechnical Investigation, Residence & Garage Addition
	215 Oakford Road	03/15/90	AC&H - Civi Engineers	Site Improvements - Lot 61 Woodside Hills - Unit 1
			William Cotton and Associates	Geotechnical Review Sheet
		08/08/96	Upp Geotechnology, Inc.	Geotechnical Investigation
		09/21/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Distressed Residence
17A	OAKHAVEN WAY			
	7 Oakhaven Way	06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision
	21 Oakhaven Way	05/31/00	Friar Associates, Incorporated	Geotechnical Investigation
		10/13/02	Hydro-Geo Consultants, Inc.	Preliminary Engineering Geologic Evaluation
	61 / 71 Oakhaven Way	07/05/83	William Cotton and Associates, Inc.	Geotechnical Investigation, Oakhaven Way Landslide
		09/22/83	Town - Owners	Agreement - Exhibit A
	71 Oakhaven Way	06/22/04	Buckley Engineering Associates	Geotechnical Investigation, Proposed Elevator Addition
		07/10/07	Wayne Ting & Associates, Inc.	Retaining Wall Recommendations
	99 Oakhaven Way	05/13/75	Howard F. Donnelly & Associates	Foundation Investigation, Proposed Single Family Residence, Lot 6, Woodland Hills Unit 5
		08/11/77	Leighton and Associates	Review of 5/13/75 report
		10/04/77	Howard F. Donnelly & Associates	Supplemental Geotechnical Investigation, Proposed Single Family Residence, Lot 6, Woodside Hills Unit 5
		11/11/77		Site Photograph
		11/21/77	Leighton and Associates	Review of 10/4/77 report
		06/02/79	Gordon Dowsett, Architect	Site Plan with annotations
		06/27/79	Nordmo Associates	Consultation on Landslide, Lot 6, Woodside Hills Unit 5
		07/18/79	William Cotton and Associates	Geotechnical Review Sheet
		07/21/79	William Cotton and Associates	Geologic Review - Dowsett
		09/20/79	William Cotton and Associates	Geotechnical Review Sheet
17A	OAKHILL DRIVE			

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	7 Oakhill Drive	08/02/07	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	15, 20, 25 Oakhill Drive	09/09/82	Hallenbeck-McKay & Associates	Geotechnical Engineering Investigation, Landslide Oakhill Drive, Portions of Lots 17 (7), 8 (25), and 9 (20) - Tract 748
		01/03/83	William Cotton and Associates	Geotechnical Review Sheet
		01/18/83	William Cotton and Associates	Geologic Review, Landslide Repair
		10/03/83	Hallenbeck & Associates	Supplemental Recommendations, Oakhill Drive Landslide
		11/01/84	Hallenbeck & Associates	Engineering Observations of Landslide Winterization, Construction Sequence "A"
		5/0/1986	Tri State Engineering Company	Landslide Repair and Sections
		05/22/86	Hallenbeck & Associates	Review of Grading and Drainage Plan, Oakhill Drive Landslide Repair
		05/22/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Taylor Landslide Repair
		06/04/86	William Cotton and Associates	Supplemental Geotechnical Review, Taylor Landslide Repair
		07/24/86	Brobeck, Phleger & Harrison	Heeter/Grau, Rammier V. Taylor, et al.
		05/04/87	Hallenbeck & Associates	Engineering Observation of Grading, Landslide Repair, Oakhill Drive
	20 Oakhill Drive	12/07/87	Hallenbeck & Associates	Plan Review, 20 Oakhill Drive
		12/29/87	William Cotton and Associates	Geotechnical Review, Taylor Reconstruction, PA #4487, 20 Oakhill Drive
		01/18/88	W. & J. Lorell Structural Engineers	Structural Calculations, 20 Oakhill Drive
		03/01/88	Hallenbeck & Associates	Review of Plans, 320 Oakhill Drive
		03/15/88	William Cotton and Associates	Supplemental Geotechnical Review, Taylor Reconstruction, 20 Oakhill Drive PA #4487
		03/22/88	Hallenbeck & Associates	Review of Plans, 20 Oakhill Drive
		04/13/88	Hallenbeck & Associates	Engineering Observation of Pier Excavations, 20 Oakhill Drive
		04/18/88	Hallenbeck & Associates	Supplemental Letter, Engineering Observation of Pier Excavations, 20 Oakhill Drive
		03/25/08	Michelucci & Associates, Inc.	Geotechnical Evaluation, Proposed Addition to Residence
	25 Oakhill Drive	06/21/99	Soil Engineering Construction, Inc.	Geotechnical Evaluation and Letter Report, Stabilization of Failing Slope along Uphill Side of Entry Drive
		11/03/99	Earth Investigations Consultants	Geotechnical Investigation, Slope Repair of West Side of Driveway
		03/18/02	Earth Investigations Consultants	Geotechnical Evaluation, Landslide on West Side of Driveway
		10/21/02	Earth Investigations Consultants	Geotechnical Evaluation, Landslide on West Side of Driveway, Stability Analysis
		01/10/03	Earth Investigations Consultants	Geotechnical Plan Review, Repair of Landslide Complex on West Side of Driveway
		07/09/07	Earth Investigations Consultants	Geotechnical Update, Proposed Slope Stabilization, Upslope of Driveway
		03/24/10	Earth Investigations Consultants	Geotechnical Update, Proposed Landscape Terracing, Graham Residence
	30 Oakhill Drive	08/17/71	Blomquist Engineering	Geology Study, Lot 10, Partition Road
		07/01/86	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Addition
		08/28/86	Elisabeth Vespremi, Architect	Site Plan, with annotations
		09/02/86	William Cotton and Associates	Geotechnical Review Sheet
		09/15/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Rammier Additions, AP#3269
		10/27/86	JCP Geologists - Engineers	Review of Soil Engineering Aspects of Foundation Plan, Proposed Garage and Addition
		11/25/86	William Cotton and Associates	Supplemental Geotechnical Review, Rammier Garage/Attic, AP#3269
17A	OLD LA HONDA ROAD			
	Thornewood O S Preserve	10/09/07	Timothy C. Best, CEG	Engineering Geologic Review, Thornewood Open Space Preserve Trail Upgrades
	8 Old La Honda Road	02/21/94	Earth Investigations Consultants	Geotechnical Investigation, Proposed Carport and Second-Story Studio
	11 Old La Honda Road now 29 Preston Road	09/01/07	Earth Sciences Consultants	Geotechnical Investigation, Front East Deck and South Addition (APN 075-134-120)
		01/09/09	Romig Engineers, Inc.	Geologic Slope Evaluation
		01/26/09	Earth Sciences Consultants	Geotechnical Report Update and Seismic Factors, Front East Deck and South Addition
		08/10/10	Romig Engineers, Inc.	Geotechnical Recommendations, Site Retaining Wall
		03/18/11	Romig Engineers, Inc.	Geotechnical Investigation, 2,500 Gallon Water Tanks and Stabilization Wall
	12 Old La Honda Road	08/06/90	Hydro-Geo Consultants, Inc.	Geotechnical Evaluation, Single-Family Residence
			William Cotton and Associates	Geotechnical Review Sheet
			William Cotton and Associates	Copy of Plot Plan with annotations
		04/08/92	Hydro-Geo Consultants, Inc.	Geologic Considerations, Improvements
		04/17/92	Hydro-Geo Consultants, Inc.	Geologic Considerations, Improvements
		05/11/92	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Gilchrist Guest House, 8708 and 8709
		05/29/92	Hydro-Geo Consultants, Inc.	Response to 5/11/92 Review Comments from WCA, Proposed Gilcrest Guest House
		06/26/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Gilchrist Guest House, 8708 and 8709
	20 Old La Honda Road	07/24/87	Upp Geotechnology, Inc.	Geotechnical Investigation of Two Parcels (APN 075-134-210 & 220)
		06/02/87	Upp Geotechnology, Inc.	Limited Geotechnical Investigation of Landslide (APN 075-134-210 & 220)
		07/12/91	Upp Geotechnology, Inc.	Preliminary Geotechnical Investigation, Single-Family Homesite (APN 075-134-210 & 220)
		07/17/91	Upp Geotechnology, Inc.	Supplemental Information, Preliminary Geotechnical Investigation, Modified Slope Stability Analysis
		08/27/92	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Access Road Bridge, Slope Stabilization and Landslide Repair Options
		10/30/92	Upp Geotechnology, Inc.	Soil and Foundation Investigation, New Residence and Garage, Lands of Sedgwick
	133 Old La Honda Road	05/03/79	PSC Associates, Inc.	Geologic and Soil Engineering Feasibility Investigation, Proposed Residence, 6-Acre Parcel (Lots 23-33), Old La Honda and Home Roads
		06/07/79	William Cotton and Associates	Geotechnical Review Sheet
		06/18/79	William Cotton and Associates	Geologic review

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	145 Old La Honda Road	08/31/77	Purcell, Rhoades & Associates	Results of Additional Subsurface Investigation, Proposed Residence
		05/02/79	PSC Associates, Inc.	Geotechnical Investigation Report, Proposed Residence Between Old La Honda and Home Road (Lots 34, 36 and 38) - APN 75-283-020
		06/07/79	William Cotton and Associates	Geotechnical Review Sheet
		06/18/79	William Cotton and Associates	Geologic Review, Lands of Design Developers
		07/03/79	PSC Associates, Inc.	References for 5/2/79 report
		10/03/79	PSC Associates, Inc.	Supplemental Stability Analyses, Proposed Residence Between Old La Honda and Home Roads (Lots 34, 36 & 38)
		12/17/79	William Cotton and Associates	Review of Supplemental Stability Analysis Report
		02/05/80	PSC Associates, Inc.	comments on responsibility for unpermitted grading
		04/04/80	J. Michael Cleary and Associates	Soil and Geologic Investigation, Lands of Design Developers (APN 075-283-020)
		02/23/81	F.R. Strathdee & Associates	Tredwell Property Improvements APN 075-283-020
		04/24/81	Perry R. Wood	Soil Percolation Tests, Lots 34, 36 and 38 (Parcel 075-283-020)
			F.R. Strathdee & Associates	Residence for Matt Younger, with annotations
		06/01/81	F.R. Strathdee & Associates	Yreadwell-Younger Variance Request
		06/10/81	Cleary Consultants, Inc.	Review of Development Plans, Lands of Design Developers
		07/24/81	Perry R. Wood	Soil Percolation Tests, Lots 34, 36 and 38, Parcel 075-283-020, Between Pld La Honda Road and Home Road
		08/11/81		Structural Calculations for Bridge and Retaining Walls
		08/11/81	Cleary Consultants, Inc.	Review of Foundation Plans, Driveway Bridge, Lands of Design Developers
		06/17/82	Cleary Consultants, Inc.	Site Inspection, Lands of Design Developers
		07/18/83	Cleary Consultants, Inc.	Soil Engineering Services During Installation of Drilled Pier Foundations, Younger Residence
		09/26/83	Cleary Consultants, Inc.	Soil Engineering Services Durig Backfilling of Retaining Wall at Home Road, Younger Residence.
		09/26/84	William Cotton and Associates	Soil Engineering Services Durig Backfilling at Rear of Home, Younger Residence.
		08/21/86	Cleary Consultants, Inc.	Geotechnical reconnaissance of House and Property
		09/25/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Lands of McSweeney
		03/08/07	Earth Investigations, Inc.	Geotechnical Investigation, Proposed Driveway Rehabilitation
		06/15/07	Holmes Cully	Structural Calculations
		12/01/07	Holmes Cully	Supplemental Structural Calculations
		03/12/08	Holmes Cully	Supplemental Structural Calculations
		03/13/08	Earth Investigations, Inc.	Geotechnical Plan Review
		05/01/08	Peter T. Mason	Home Road Photographs
	171 Old La Honda	12/21/76	Purcell, Rhoades & Associates	Soil and Geologic Investigation, Lots 34, 36, 38, Portola Hills Subdivision
		01/03/77	Bill Campbell	General Conditions and Specifications
		02/07/77	Purcell, Rhoades & Associates	Revised Soil and Geologic Investigation, Lots 34, 36, 38, Portola Hills Subdivision
		02/11/77	Purcell, Rhoades & Associates	Addendum to Soil and Geologic Investigation for Tim O'Brian
		03/10/77	Leighton and Associates, Inc.	Review
		03/18/77	Purcell, Rhoades & Associates	Revised Site Plan
		03/29/77	Leighton and Associates, Inc.	Comments on Revised Site Plan
		03/31/77	Purcell, Rhoades & Associates	Discussion of Conclusions and Recommendation by Leighton and Associates, Inc. dated March 29, 1977
		04/07/77	Leighton and Associates, Inc.	Review Comments
		04/29/77	Purcell, Rhoades & Associates	Results of Additional Subsurface Investigation for Tim O'Brian
		06/07/77	Leighton and Associates, Inc.	Review Comments
		08/31/77	Purcell, Rhoades & Associates	Results of Additional Subsurface Investigation and Summary Conclusions, Geotechnical Investigation, Proposed residence
		09/14/77	Leighton and Associates, Inc.	Review Comments
		04/17/78	Sigrid Lorenzen Rupp, Architect	Letter to Leighton and Associates, Inc.
	207 Old La Honda Road	05/01/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Foundation Improvements, Mason-Dare Residence
		11/25/03	ASMO Consulting Engineers	Geotechnical Evaluation, Driveway Retaining Walls
		04/22/04	JF Consulting, Inc.	Geologic Letter Report, Proposed Driveway Retaining Walls, Lands of Mason
		06/04/04	ASMO Consulting Engineers	Response to Toen of Woodside Comments, Driveway Relocation and Associated Retaining Walls
		06/05/07	Earth Investigations Consultants	Geotechnical Investigation Up date, Proposed Parking Area & Garage Addition, Mason-Dare Residence
		06/05/07	Earth Investigations Consultants	Response to Town Comments, Proposed Parking Area & Garage Addition, Mason-Dare Residence
17A	227 Old La Honda Road	02/06/84	Ronald A. Meschino	Caisson Design
				Photographs of Landslide
		05/15/84	William M. McMorrow	Geotechnical Engineering Evaluation, Landslide Stabilization-Retaining Wall, Brugos Property
		06/05/84	William Cotton and Associates	Landslide Stabilization - Retaining Wall Evaluation, Brugos Property
		08/13/84	William M. McMorrow	Supplemental Information Requested by Cotton & Associates, Landslide Stabilization-Retaining Wall, Brugos Property
		08/30/84	William Cotton and Associates	Landslide Stabilization - Retaining Wall Evaluation, Brugos Property
		09/04/84	William Cotton and Associates	Landslide Stabilization - Retaining Wall Evaluation, Brugos Property
		05/14/96	Louis A. Richardson	Engineering Geologic Considerations, Residential Addition at Sinclair Residence
		05/22/96	William Cotton and Associates	Geotechnical Review Sheey
		06/04/96	William M. McMorrow	Geotechnical Engineering Evaluation & Plan Review, Single-Family Residence
18	245 Old La Honda Road	10/11/84	Earth Sciences Associates	Existing/Proposed Retention Pond
		10/19/84	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Ordemann Dam Reconstruction, APN: 75-240-14
		06/03/85	Earth Sciences Associates	Proposed Retention Pond, Ordemann Property
		06/13/85	Atkinson Farasyn	Violations of the Woodside Municipal Code
		07/12/85	Atkinson Farasyn	Comments to Town Geologist
		07/22/85	Herbert Frahm	Transmittal of Revised Plan
		08/23/85	Herbert Frahm	Report on History of Dam and Effect of Dam Failure
		09/23/85	Michael T. Dukes	Ordemann Dam Reconstruction, APN #75-240-14
		10/10/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Ordemann Dam Reconstruction, APN 075-240-14
		10/25/85	Atkinson Farasyn	Letter to Mr. Ordemann

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		12/20/85	Frahm Elder abd Cannis	Response to 10/10/85 WCA Comments
		04/18/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Ordemann Dam Reconstruction, APN 075-240-14
		11/18/87	County of San Mateo, Department of Health Services	Comments of Proposed Dam Reconstruction
		09/21/92	Hydro-Geo Consultants, Inc.	Preliminary Geological Evaluation, Two Proposed Single-Family Residence Sites
		01/15/96	Applied Earth Investigations Consultants	Geotechnical Investigation to Mitigate a Small Landslide at the Access Driveway, Schilling Estate
		09/03/09	Buckley Engineering Associates, Inc.	Geotechnical Investigation, Proposed Solar Array
		12/14/10	Buckley Engineering Associates, Inc.	Geotechnical Investigation Update, Proposed Solar Array
	302 Old La Honda Road	01/30/89	MS Geotechnical Consultants, Inc.	Geotechnical Engineering Study, Byrnes Residence
		10/19/89	William Cotton and Associates	Supplemental Geologic Review, Byrnes, Variance 451
	320 Old La Honda Road	10/07/96	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Single-Family Residence Between 302 and 360 Old La Honda Road
	360 Old La Honda Road	05/04/87	Applied Earth Investigations Consultants	Soil and Geologic Investigation, Single-Family Residence on APN 075-151-010
	370 Old La Honda Road	04/28/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Elder & Noble, Portion of Lot 12 - APN 075 151 020
		04/24/87	Questa Engineering Corporation	Sewage Disposal Site Plans, Old La Honda Road, APN 075-151-020
			William Cotton and Associates	Geotechnical Review Sheet
		12/08/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Elder, Variance #418
		06/27/89	Upp Geotechnology, Inc.	Addendum, Geotechnical Investigation, Proposed Water Tank, Lands of Elder/Noble
	370 Old La Honda Road	08/30/89	Upp Geotechnology, Inc.	Review of Plan Revisions, Elder & Noble Residence
	375 Old La Honda Road	08/01/68	Crosby & Associates	Soil Investigation, Proposed Building Site
	385 Old La Honda Road	12/01/77	Cooper-Clark & Associates	Engineering Geologic Investigation, Lots 112 and 117, Subdivision No. 2, Woodside Country Club
		12/22/77	Cooper-Clark & Associates	Report to Mr. William Patrick
		12/27/77	Town of Woodside	Review of Cooper-Clark & Associates reports
		04/19/07	Earth Investigations Consultants	Geotechnical Investigation, Proposed Deck Replacement
	400 Old La Honda Road	06/17/75	Dunham & Associates	Soil Investigation, Proposed House, Woodside Country Club Properties (APN 075-261-010)
		02/02/77	Leighton and Associates	Review of 6/17/75 DA report
		02/21/77	Richard E. Rowland	Geologic Evaluation, Old La Honda Road Property
		03/07/77	Dunham & Associates	Plan Review, Proposed Home, Woodside Country Club Properties #2
		03/09/77	Leighton and Associates	Review of 2/21/77 RER report
		10/21/81	William Cotton and Associates	Property, with annotations
		11/09/81	William Cotton and Associates	Geotechnical Review Sheet
		11/30/81	William Cotton and Associates	Preliminary Geologic review, Corcoran - Proposed Guest House
		05/21/82	William Cotton and Associates	Geotechnical Review Sheet
		06/10/82	William Cotton and Associates	Geologic Review
		07/07/82	Site Characteristics Inc.	Geotechnical Investigation, Corcoran Guest House
			William Cotton and Associates	Figure 3 from SCI report, with annotations
		07/29/82	William Cotton and Associates	Geologic Review of SCI report
		10/16/03	Nielsen Geotechnical, Incorporated	Slope Stability Analysis
	408 Old La Honda Road	08/25/89	Hydro-Geo Consultants, Inc.	Geotechnical Evaluation, Proposed Garage/Pool Site
			William Cotton and Associates	Geotechnical Review Sheet
		09/22/89	William Cotton and Associates	Preliminary Geologic Review, Mathews Car Barnm VAR #467
		11/01/89	Hydro-Geo Consultants, Inc.	Letter on Revised Site and Plot Plan
		11/01/89	William Cotton and Associates	Memo on Revised Site and Plot Plan
		06/11/90	Hydro-Geo Consultants, Inc.	Review of Plans and Specifications
		03/17/06	Murray Engineers, Inc.	Geotechnical & Engineering Geologic Investigation, Mathews Residence Improvements
	431 Old La Honda Road	01/15/80	Terratech, Inc.	Geologic and Geotechnical Investigation, Lands of Eldredge (APN 075-272-030)
	442 Old La Honda Road	04/22/77	Purcell, Rhoades & Associates	Soil and Geologic Investigation (APN 076-120-060)
		05/11/77	Town of Woodside	Review
		05/13/77	Purcell, Rhoades & Associates	Reply to Comments in Town Review
		05/18/77	Town of Woodside	Review of Reply to Comments in Town Review
		06/14/77	Purcell, Rhoades & Associates	Reply to Review of Reply to Comments in Town Review
		06/23/77	Town of Woodside	Review of Reply to Review of Reply to Comments in Town Review
		03/29/00	Terrasearch, Inc.	Preliminary Geologic Investigation, Recent Landslide
		08/08/02	Terrasearch, Inc.	Grading Plan Review
	464 Old La Honda Road	12/17/86	Upp Geotechnology	Preliminary Geotechnical Investigation, Lands of Bolton (APN 076-102-040)
	503 Old La Honda Road	02/04/11	Murray Engineers, Inc.	Geotechnical Evaluation, Thirty-Five Slopes, Serrurier Property
		06/17/11	Murray Engineers, Inc.	Geotechnical Investigation, Serrurier Residence
		07/06/11	Murray Engineers, Inc.	Supplemental Information, Proposed Demolition, Serrurier Property
		09/16/11	Murray Engineers, Inc.	Supplemental Information, Serrurier Residence
		09/23/11	Murray Engineers, Inc.	Supplemental Information, Serrurier Residence
	548 Old La Honda Road	04/24/89	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Residence, NW Corner APN 076-110-040
		10/10/91	Geotechnical Engineering Systems Co.	Slope Stability Analysis, Shaikh Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		10/19/91	Hydro-Geo Consultants, Inc.	Landslide Evaluation, Proposed Single-Family Residence Site (APN 076-110-040)
		02/18/92	Hydro-Geo Consultants, Inc.	Landslide Evaluation (APN 076-110-040)
		07/15/93	Hydro-Geo Consultants, Inc.	Response to Town Review, Proposed New Single-Family Residence
		10/27/94	Earth Investigation Consultants	Geotechnical Services, Proposed House
	560 Old La Honda Road	03/20/91	Carl W. Garbe, P.E.	Earthwork, Recreation Area
		01/21/92	Carl W. Garbe, P.E.	Supplemental Geotechnical Report, Recreation Area Earthwork
		09/20/93	Louis A. Richardson	Engineering Geologic Investigation, Existing Riding Ring
		10/25/93	Haro, Kasunich and Associates, Inc.	Slope Stability Analysis, Existing Riding Ring
	560 Old La Honda Road	01/25/94	Louis A. Richardson	Review of Site Plan, Drainage and Grading for Riding Ring
	572 Old La Honda Road	02/13/02	Romig Engineers, Inc.	Geotechnical Investigation, White Residence Additions
	580 Old La Honda Road	01/19/81	J. Michael Cleary and Associates	Geotechnical Investigation, Lots 26, 27 & 29 (Map of Portola Hills, Book 7, Page 20, San Mateo County)
		1/0/81	Paul E. Nowack and Associates, Inc.	Grading Plan Lot No. 23, a Portion of Lot 29, with annotations
		02/27/81	Cleary Consultants, Inc.	Review of Grading Plan, Lot No. 29, Map of Portola Hills
		05/05/81	William Cotton and Associates	Geotechnical Review Sheet
		07/09/81	Cleary Consultants, Inc.	Geotechnical Plan Review, Lot 29, Map of Portola Hills
		12/13/83	Cleary Consultants, Inc.	Site Reconnaissance and Geotechnical Update, Lot 25, Lot 27, and Lot 29
		12/23/83	William Cotton and Associates	Geologic Review - Lands of Szabo, BPA 912
		09/12/85	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Szabo, BPA 912
	630 Old La Honda Road	09/26/78	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Percolation Rate Testing, Lot Nos. 320 and 321, Woodside Country Club Subdivision
		07/30/79	Fisher Land Surveys	Topographic Map, with annotations
		08/20/79	William Cotton and Associates	Geotechnical Review Sheet
		11/01/79	Walter E. Eagle, Architect	Grading Plan, with annotations
		01/16/80	Purcell, Rhoades & Associates	Soils/Foundation Investigation - Lots No. 320 and 321
		01/29/80	Town of Woodside	Review of Revised Site Grading Plan, (Lencioni/Hayes)
		02/22/80	William Cotton and Associates	Review - Lencioni Conformity/Variance 255
		03/02/81	Purcell, Rhoades & Associates	Plan Review, Lots 320 and 321, Woodside Country Club Subdivision
		03/05/80	William Cotton and Associates	Review of 1/16/80 PR&A report
		03/21/81	William Cotton and Associates	Geologic Review
		04/15/81	Purcell, Rhoades & Associates	Plan Review, Lots 320 and 321, Woodside Country Club Subdivision
		04/22/81	Purcell, Rhoades & Associates	Plan Changes - Lots 320 and 321, Woodside Country Club Subdivision
		04/27/81	William Cotton and Associates	Geologic Review
			Town of Woodside	Variance 255, Resolution 1980-121
	632 Old La Honda Road	02/24/04	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Thornton Additions
		08/12/04	Pacific Geotechnical Engineering	Retaining Wall Recommendations, Thornton Property
18	736 Old La Honda Road	09/20/02	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Barn
18A	OLIVE HILL ROAD			
	131 Olive Hill Road	07/28/89	Upp Geotechnology, Inc.	Fault Location Investigation, Addition to Corfman Residence
		06/06/90	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Addition to Residence
			William Cotton and Associates	Geotechnical Review Sheet
		11/30/93	Harlan Tait Associates	Job Memorandum
		05/27/94	Upp Geotechnology, Inc.	Supplemental Recommendations, Addition to Corfman Residence
		06/03/94	Upp Geotechnology, Inc.	Supplemental Recommendations, Concrete Slab for Sunroom Addition to Corfman Residence
		10/16/03	Nielsen Geotechnical Incorporated	Geotechnical Recommendations
		07/01/04	Murray Engineers, Inc.	Geotechnical Services, Landscaping Improvements
		08/07/04	Murray Engineers, Inc.	New Engineer of Record, Corfman Swimming Pool
	140 Olive Hill Road	11/20/07	Connell Geotechnical, Inc.	Geotechnical Investigation, New Residence
	150 Olive Hill Lane	09/01/87	Earth Syatems Consultants	Foundation Recommendations, Proposed Addition to Residence
		01/21/04	Nielsen Geotechnical, Inc.	Geotechnical Recommendations
		02/01/05	Murray Engineers Inc.	Geotechnical Services, Bibbler Residence Improvements
	160 Olive Hill Road	05/21/00	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed House Additions
	164 Olive Hill Lane	10/21/91	Hallenbeck & Associates	Geotechnical Engineering and Geologic Hazard Investigation, Proposed 2nd Story Addition
		06/09/93	Hallenbeck & Associates	Addendum to Geotechnical Engineering Evaluation and Geologic Hazard Investigation
	165 Olive Hill Lane	01/04/94	Upp Geotechnology, Inc.	Fault Location Investigation
		01/14/94	Upp Geotechnology, Inc.	Supplemental Information, Fault Location Investigation
		01/25/94	Upp Geotechnology, Inc.	Supplemental Information, Site Plan Modification, Fault Location Investigation
	166 Olive (Tree) Hill Lane	03/05/08	Romig Engineers, Inc.	Geotechnical Investigation, Dutta Residence
	170 Olive Hill Lane	01/09/97	Steven F. Connolly	Fault Investigation, Conway Property
		01/17/97	Nielsen Geotechnical Incorporated	Soil Report

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		01/29/96	Earth Investigations Consultants	Fault Investigation Waiver, Proposed improvements
	187 Olive Hill Lane	11/20/97	Nielsen Geotechnical Incorporated	Geotechnical Report
	210 Olive Hill Lane	01/17/74	Berlogar, Long & Associates	Soil Investigation, Proposed Single Family Residential Development, 3+/- Acre Parcel
		06/11/79	J. Michael Cleary and Associates	Soil and Foundation Investigation, Demonet House Addition
		05/19/00	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Wang/Pope
		06/03/05	Upp Geotechnology, Inc.	Supplemental Recommendations, Proposed Swimming Pool and Associated Improvements, Wang Property
	222 Olive Hill Lane	05/21/99	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residence, Rohlen Property
		04/24/02	GeoForensics, Inc.	Basement Design Parameters, Proposed New Residence
		07/17/00	GeoForensics, Inc.	Response to Town Review, Proposed New Residence
		12/20/10	GeoForensics, Inc.	Geotechnical Investigation, Motor Court Expansion
		12/22/10	Murray Engineers, Inc.	Geotechnical Investigation, New Swimming Pool
		06/01/11	Murray Engineers, Inc.	Geotechnical Investigation, New Pool House
		06/30/11	BKF	Storm Drain Design Discussion
		08/29/11	Murray Engineers, Inc.	Response to Town Geology Division Review Comments, New Swimming Pool & Pool House
	300 Olive Hill Lane	07/24/01	Charles H. Hartsog	Soils and Geotechnical Report
		04/17/02	Charles H. Hartsog	Soils and Geotechnical Report
		05/28/03	Charles H. Hartsog	Soils/Geotechnical Report, Generator Structure
	306 Olive Hill Lane	01/18/00	Nielsen Geotechnical Incorporated	Soil Report
		04/28/08	Murray Engineers, Inc.	Supplemental Recommendations, New Swinning Pool
		06/09/08	Murray Engineers, Inc.	Alternative Swimming Pool Recommendations, New Swimming Pool
	306 Olive Hill Lane	02/23/09	Murray Engineers, Inc.	Alternative Exterior Slab Design Criteria, New Swimming Pool
	307 Olive Hill Lane	06/11/98	Steven F. Connelly	Geologic Investigation, Proposed Remodel, Roux Residence
		06/17/98	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Additions and Carport
	308 Olive Hill Lane	10/31/90	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Foundation Repair, Wiegand Residence
		04/04/05	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Barn
	310 Olive Hill Lane	08/29/77	Purcell, Rhoades & Associates	Reconnaissance Soil and Foundation Investigation and Recommendations, Foundation Design, Lot 5
		05/11/82	William Cotton and Associates	Geotechnical Review Sheet
		05/13/82	William Cotton and Associates	Geotechnical Review - Boles Pool
		04/14/82	Purcell, Rhoades & Associates	Pool Plan Review, Boles Residence
18A	500 Olive Hill Lane	12/05/80	PSC Associates, Inc.	Soil Engineering Investigation, Proposed House Addition
		10/08/93	Earth Investigations Consultants	Geotechnical Evaluation, Proposed Additions to Existing House
19	ORCHARD HILL ROAD			
	15 Orchard Hill Road	07/30/86	Joseph M. Bauer, Structures & Engineering	Structural Calculations, Proposed Kilmer Guest Cottage
		06/30/86	JCP Geologists Engineers	Soil and Foundation Services, Proposed Guest House
		08/11/86	JCP Geologists Engineers	Addendum to Soil and Foundation Services, Proposed Guest House
		08/28/86	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation Plan, Proposed Guest House
		10/15/86	William Cotton and Associates	Geotechnical Review Sheet
		10/20/86	JCP Geologists Engineers	Addendum to Soil and Foundation Services, Proposed Guest House
		11/03/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kimler Guest House
19	OTIS AVENUE			
	103 Otis Avenue	02/27/07	Romig Engineers, Inc.	Geotechnical Investigation, Lock Residence
	111 Otis Avenue	01/14/02	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Foundation Improvement
	128 Otis Avenue	10/03/74	Dunham and Associates	Soil Investigation, Proposed Home, Woodside Glens Unit 1
		01/15/86	Dunham & Associates	Proposed Improvements
		02/03/86	William Cotton and Associates	Geotechnical Review Sheet
		02/10/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Vaccaro Basement Floor and Spa Additions
	132 Otis Avenue	04/06/94	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Planned Foundation Repairs and Additions to Single-Family Residence
		10/18/95	Jo Crosby & Associates	Geotechnical Consultation, Residence
	140 Otis Avenue	05/22/89	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Mitigation of Distress to Existing Residence, Proposed Detached Garage, Jensen Residence
		12/11/92	Upp Geotechnology, Inc.	Feasibility and Preliminary Plan Review, Proposed Foundation Repair and Detached Garage Addition, Nickell Residence
		07/29/93	Raleigh Engineering	Geological and Geotechnical Report
		01/23/07	PGSoils, Inc.	Geotechnical Investigation, Proposed Retaining Wall, Nickel Property
	143 Otis Avenue	04/25/03	Romig Engineers, Inc.	Geotechnical Investigation, Lewis Garage
		02/06/09	Romig Engineers, Inc.	Supplemental Recommendations, Lewis Garage

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	no address	01/23/85	Howard F. Donley & Associates	Potline of Geotechnical Report, Resubdivision of APN 73-061-200
		1/0/85	Rick Skierka	Concept Map, with annotations
		07/12/85	William Cotton and Associates	Geotechnical Review Sheet
		07/16/85	William Cotton and Associates	Preliminary Geologic Review, Lands of Drees, LD 287
		08/01/85	Town of Woodside	Subdivision Review Meeting - Land Division 287
		09/26/85	Howard F. Donley & Associates	Geotechnical Investigation, Proposed New Residence
		10/16/85	Rick Skierka	Tentative Map
		11/04/85	William Cotton and Associates	
		05/29/86	Howard F. Donley & Associates	Review of Architectural Drawings and Design Calculations, Proposed Single Family Residence
		08/08/86	William Cotton and Associates	Geotechnical Review Sheet
		08/11/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
	157 Otis Avenue	09/26/85	Howard F. Donley & Associates	Geotechnical Investigation, Proposed New Residence
		05/29/86	Howard F. Donley & Associates	Review of Architectural Drawings and Design Calculations, Proposed Single Family Residence
		08/11/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Drees, AP #3138
		02/11/87	Lawrence B. Karp	New Residence - Foundation Construction
		02/25/87	Wipson Incorporated	Construction Observation Letter
		04/17/08	Murray Engineers, Inc.	Supplemental Information, Geotechnical Investigation, Kalinowski Property
		05/04/08	Murray Engineers, Inc.	Engineering Geologic & Geotechnical Investigation, Kalinowski Residence Improvements
	160 Otis Avenue	07/31/05	Wayne Ting & Associates, Inc.	Proposed Deck
		11/08/07	Wayne Ting & Associates, Inc.	Response to County Concerns
	163 Otis Avenue	02/05/93	Upp Geotechnology, Inc.	Geotechnical Investigation, Two Adjoining Undeveloped Parcels, Lands of Vellequette
		01/18/94	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation, Two Adjoining Undeveloped Parcels, Lands of Vellequette
	168 Otis Avenue	04/09/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Addition to Goldberg Residence
			William Cotton and Associates	Geotechnical Review Sheet
		09/21/88	Upp Geotechnology, Inc.	Review of Foundation Plans, Addition to Goldberg Residence
		10/03/88	Richard Hanson, Civil Engineer	Structural Calculations
		10/05/88	William Cotton and Associates	Preliminary Geotechnical and Geologic Review, Goldberg Additions, PA #4889
	172 Otis Avenue	07/31/00	Herzog Geotechnical Consulting Engineers	Geotechnical Investigation Report
		12/28/00	Herzog Geotechnical Consulting Engineers	Engineering Geologic Report/Supplemental Geotechnical Report
19	PALM CIRCLE			
	8 Palm Circle	09/28/11	GeoForensics, Inc.	Geotechnical Evaluation, Garage Foundation Repairs
	10 Palm Circle	08/29/00	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence
19	PARTITION ROAD			
	3540 Partition Road	09/09/05	Romig Engineers, Inc.	Geotechnical Investigation, Wennblom Retaining Wall Replacement
	3555 Partition Road	05/25/83	Howard Donley Associates, Inc.	Landslide Investigation
		02/27/84	Howard Donley Associates, Inc.	Progress Report, Construction Inspection, Repair of Landslide
		09/15/93	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Underpinning and Additions
	3560 Partition Road	09/02/77	Terrasearch, Inc.	Geologic Investigation, Partition Road Property (Hanson)
		09/25/78	Purcell, Rhoades & Associates	Geotechnical Hazard Investigation, ≈ 2.7-Acre Parcel
		11/03/78	Robert Mahnoy	Foundation Design - 2.7-Acre Parcel
		01/29/79	Randlett & Fouik, Inc.	Site Development Plan, with annotations
		02/00/79	Washington - Jensen & Associates	Structural Calculations
		03/19/79	R.I. Whaley	Review of Site Development Plan, Johnson
		04/08/79	William Cotton and Associates	Geotechnical Review Sheet
		04/23/79	William Cotton and Associates	Review
		04/25/79	Soil Engineering Construction, Inc.	Leach Foeld Comments, Johnson Lot - Land Division Map 181
		07/23/79	Soil Engineering Construction, Inc.	Supplemental Investigations - Johnson Lot, Parcel A, Land Division Map 181
		10/05/79	Charles E. Randlett	Retaining Wall Design / Calculations
		10/11/79	Soil Engineering Construction, Inc.	Landslide Area South of House, Johnson Lot, Parcel A, Land Division Map 181
		12/10/79	Soil Engineering Construction, Inc.	Soil & Geologic Investigation, Johnson Lot
		02/18/80	William Cotton and Associates	Geologic Review
		06/16/82	Soil Engineering Construction, Inc.	Comments on Grading and Landslide, APN 72-093-080
		01/22/85	Soil Engineering Construction, Inc.	Observations on Stability, Drainage, and Grading, APN 72-093-080
		00/00/85	William Cotton and Associates	Geotechnical Review Sheet
		05/01/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Johnson (B and J Construction)
	3600 Partition Road	04/29/80	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Percolation Testing, Approximat 3.5-Acre Parcel
		07/14/80	William Cotton and Associates	Geotechnical Review Sheet
		07/18/80	William Cotton and Associates	Review of 4/29/80 PR&A report
		09/13/88	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, Lands of Taromi (APN 072-173-020)
		02/14/87	Arcturus Land Survey	Topographic Map

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
			William Cotton and Associates	Geotechnical Review Sheet
		07/29/92	William Cotton and Associates	Preliminary Geologic Review, Taromi Single Family Residence
		01/17/01	Harlan Tait Associates	Preliminary Geologic Evaluation, Septic System
		11/19/01	Harlan Tait Associates	Geotechnical Feasibility Evaluation, Septic System
		08/20/02	Harlan Tait Associates	Geotechnical Investigation, Rogers Residence
		08/13/03	Harlan Tait Associates	Geologic Mapping, Rogers Property
		01/18/04	Harlan Tait Associates	Geotechnical Investigation, Rogers Residence
		05/21/04	Harlan Tait Associates	Supplemental Investigation and Response to Geologic Review Comments, Rogers Property
		06/17/05	Harlan Tait Associates	Geotechnical Consultation, Rogers Property
	3635 Partition Road		Hardesty Associates	Layout and Lighting Plan
		08/30/88	Joseph M. Bauer, C.E.	Structural Calculations
		08/12/88	Charles H. Hartsog & Associates	Soil Report
			William Cortton and Associates	Geotechnical Review Sheet
		06/17/88	William Cortton and Associates	Preliminary Geologic and Geotechnical Review, Barker Exterior Improvements, PA #4684
	3640 Partition Road			
		09/22/83	John T. O'Rourke & Associates	Landslide Evaluation
		10/28/83	John T. O'Rourke & Associates	Additional Subsurface Data
		07/18/84	John T. O'Rourke & Associates	Report of Horizontal Drains
		08/26/85	Kimand Associates	Retaining Wall Design Parameters, Ringold Residence
		09/11/85	Charles E. Phillips	Retaining Wall & Pavement Plan & Section
		09/24/85	John T. O'Rourke & Associates	Review of Driveway Improvements
		10/15/85	William Cotton and Associates	Geotechnical Review Sheet
		11/01/85	William Cotton and Associates	Preliminary Geologic Review, Lands of Ringold, Driveway Retaining Wall
		11/12/85	John T. O'Rourke & Associates	Response to Town Comments - Cross Sections
		11/21/85	John T. O'Rourke & Associates	Response to Town Comments - Cross Sections
		11/22/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Ringold Driveway Retaining Wall
		05/25/07	Michelucci & Associates, Inc.	Geotechnical and Geologic Investigation, Planned Site Improvements, Lars Ahlstrom Property
		03/12/08	Michelucci & Associates, Inc.	Proposed New Retaining Wall, Lars Ahlstrom Residence
19A	PATROL COURT			
	Patrol Court Landslide	06/04/05	Earth Sciences Associates	Patrol Road Landslide Investigation, Phases I & II
	20 Patrol Court	10/12/00	Romig Engineers, Inc.	Geotechnical Investigation, Plum Residence Adition
	25 Patrol Court	07/09/82	Clearly Consultants, Inc.	Landslide Repair Investigation
		08/05/86	Clearly Consultants, Inc.	Investigation of February, 1986 Landslide, Heyeck Property
		various	William Cotton and Associates ?	Miscellaneous photographs, mps, and sections
		09/25/86	William Cotton and Associates	Mitigation Recommendations, Heyeck Landslide
		04/28/98	Harlan Tait Associates	Patrol Court Crib Wall Mitigation/Repair Alternatives
	30 Patrol Court	12/14/95	Alan Kropp & Associates, Inc.	Geologic/Geotechnical Investigation, Moll Residence Landslide
19A	PATROL ROAD			
	Patrol Road Landslide	06/04/85	Earth Sciences Associates	Patrol Road Landslide Investigation, Phases I & II
	518 Patrol Road	11/09/06	Murray Engineers, Inc.	Geotechnical Investigation, Joost Residence Underpinning
	558 Patrol Road	03/04/09	Romig Engineers, Inc.	Geotechnical Investigation, Wimmer Residence Addition
		09/13/10	Romig Engineers, Inc.	Geotechnical Response, Wimmer Property Drainage
		10/04/10	Romig Engineers, Inc.	Geotechnical Plan Review, Wimmer Residence Addition
	559 Patrol Road	09/24/01	Romig Engineers, Inc.	Geotechnical Investigation, Herbert Residence
	573 Patrol Road	08/09/07	Romig Engineers, Inc.	Geotechnical Investigation, New Retaining Wall and Deck Replacement
	580 Patrol Road	01/11/01	Geo Forensics, Inc.	Geotechnical Report Update, Proposed Residential Addition
		03/12/01	GeoForensics, Inc.	Report Supplement, Reed/Siegal Property
		07/02/01	GeoForensics, Inc.	Response (to review comments), Reed/Siegal Property
	580 Patrol Road	03/18/02	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	581 Patrol Road	01/10/97	Michelucci & Associates, Inc.	Preliminary Geotechnical Evaluation
		02/17/06	Romig Engineers, Inc.	Geotechnical Investigation, Residence Underpinning
	617 Patrol Road	03/06/89	Baldwin-Wright, Inc.	Geotechnical Evaluation, Retaining Wall & Drainage Evaluation
		12/10/96	Steve Brooks, R.E.H.S.	Malfunctioning Sewage Disposal System Repair
		04/10/97	Earth Investigations Consultants	Geotechnical Investigation, Leachfield Stability Analysis
		06/13/97	Earth Investigations Consultants	Response to Initial Town Geologist Review (of 4/10/97 report)
	635 Patrol Road	11/20/79	Francis A. Stejer	Special Landslide Study, Proposed Garage

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		01/14/80	William Cotton and Associates	Geotechnical Review Sheet
		02/18/80	William Cotton and Associates	Review of FAS 11/20/79 Report
		02/25/80	Francis A. Stejer	Addendum - Special Landslide Study, Proposed Garage
		03/05/80	William Cotton and Associates	Review Notes
		03/27/80	William Cotton and Associates	Review of Addendum Report
		10/00/06	Murray Engineers, Inc.	Geotechnical Investigation, Robbins Property Landslide
	640 Patrol Road	06/08/78	Purcell, Rhoades & Associates	Geotechnical Investigation, Proposed Swimming Pool, Murphy Residence
		01/23/87	C. S. Stewart Associates	Mitigation of House Distress
		09/18/87	C. S. Stewart Associates	Geotechnical Engineering Report, Murphy Residence Foundation Repair
			unknown	2 geologic sections through 1982 Patrol Court/Patrol Road landslide
		09/05/87	Engineering Systems Construction	Site Plan: New Retaining Wall and Foundations, Murphy Residence
			William Cotton and Associates	Geotechnical Review Sheet
		12/15/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Murphy Foundation repair, PA #4436
		01/07/88	Steve Deal Associates	Plan Review: Murphy Property Mitigation
19A	660 Patrol Road	05/15/02	Romig Engineers, Inc.	Geotechnical Investigation, MacLeod Residence Addition
20	685 Patrol Road	05/17/83	Donald A. Meschino	Caisson Calculations
		06/18/83	William M. McMorrow & Associates	Geotechnical Engineering and Geologic Services, Landslide Stabilizations, Egli Residence
		06/22/83	Town of Woodside	Road Access Concerns
		08/09/85	Louis A. Richardsom	Landslide and Road Repair Investigation
		02/14/91	Town of Woodside	Town of Woodside vs. Robert Russell
		07/18/91	Michelucci & Associates	Geotechnical Investigation
		09/06/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Russell Additions
		10/09/91	Michelucci & Associates	Geotechnical Consultation
		03/09/92	Michelucci & Associates	Geotechnical Evaluation, Proposed Septic Leachfield
		04/13/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Russell Additions
		05/21/92	Lea & Sung Engineering, Inc.	Stitch Pier Design Structural Calculations
		05/22/92	Michelucci & Associates	Planned Modifications & Repairs
		06/01/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Russell Additions
		08/17/92	Lea & Sung Engineering, Inc.	Structural Calculations
		09/01/92	Michelucci & Associates	Review of Plans
		04/10/95	Harlan Tait Associates	Preliminary Evaluation, Landslide
		08/18/11	Murray Engineers, Inc.	Geotechnical Investigation, Furukawa Site Improvements
	700 Patrol Road	07/14/99	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Milton
		02/14/03	Cotton, Shires & Associates, Inc.	Geotechnical Engineering Review
		08/11/03	Upp Geotechnology, Inc.	Supplemental Geotechnical Investigation and Response to Review Comments, Lands of Lovazzano
		11/07/03	Upp Geotechnology, Inc.	Supplemental Response to Review Comments, Lands of Lovazzano
		09/24/04	Upp Geotechnology, Inc.	Plan Review and Supplemental Response to Review Comments, Lands of Lovazzano
		10/04/04	Upp Geotechnology, Inc.	Supplemental Response to Review Comments, Lands of Lovazzano
		10/04/04	Upp Geotechnology, Inc.	Plan Review, Lands of Lovazzano
		01/05/05	Upp Geotechnology, Inc.	Plan Review, Lands of Lovazzano
		06/02/08	Upp Geotechnology, Inc.	Construction Observations, Site Drainage, Site Grading, Drilled Piers, Concrete Slabs-On-Grade
		10/12/09	Upp Geotechnology, Inc.	Limited Soil and Foundation Study Report, Proposed New Decks and Leachfield Relocation
		04/08/10	Upp Geotechnology, Inc.	Supplemental Recommendations and Discussion Proposed New Decks and Storage Area, Kerko Property
		05/05/10	Upp Geotechnology, Inc.	Plan Review and Response to Plan Comments by the Town of Woddsie, Proposed New Decks and Leachfield Relocation, Kerko Property
	760 Patrol Road	10/14/08	Romig Engineers, Inc.	Geotechnical Investigation, Harson Residence Additions
	815 Patrol Road	11/29/99	Terrasearch, Inc.	Geologic and Geotechnical Investigation, Proposed Retaining Walls and Cutoff Trench
	830 Patrol Road	05/20/85	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed Lap Pool
			Freeman-Kern Associates, Inc.	Site Plan with annotations
		02/07/86	William Cotton and Associates	Geotechnical Review Sheet
		02/16/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Passal Pool
	850 Patrol Road	05/28/01	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Swimming Pool & Spa Site (APN 072-071-140)
		10/18/01	Hydro-Geo Consultants, Inc.	Geotechnical Report, Swimming Pool and Spa
		05/15/02	Questa Engineering Corporation	Geotechnical and Engineering Geologic Investigation, Proposed Swimming Pool
		06/18/08	Questa Engineering Corporation	Addendum for Addition and Deck Improvements (5/15/02 report)
		04/22/09	Questa Engineering Corporation	Revised Addendum for Addition and Deck Improvements (5/15/02 report)
	875 Patrol Road	04/09/85	JCP Geologists- Engineers	Soil and Foundation Study, Proposed Addition to Residence
	885 Patrol Road	05/07/07	Romig Engineers, Inc.	Geotechnical Investigation, Staats Site Improvements
		06/07/07	Romig Engineers, Inc.	Supplemental Recommendations, Staats Retaining Wall
20	PHILLIP ROAD			
	100 Phillip Road	05/02/96	Earth Investigations Consultants	Fault Location Assessment, Proposed House
		05/07/96	Earth Investigations Consultants	Soil and Ground Water Exploration, Proposed On-Site Sewage Disposal

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		07/11/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residence
		04/07/05	Earth Investigations Consultants	Geotechnical Supplement, Proposed Swimming Pool
	120 Phillip Road	10/21/97	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Guest House, Suber Property
		10/21/99	GeoForensics, Inc.	Addendum to Geotechnical Investigation Report
		02/06/01	GeoForensics, Inc.	Report Update, Proposed Residential Additions
	135 Phillip Road	02/15/11	Sigma Prime Geosciences, Inc.	Geotechnical Study, Proposed Detached Carport, Cooney Property
		05/24/11	Sigma Prime Geosciences, Inc.	Geotechnical Study, Proposed Detached Carport, Cooney Property
		07/18/11	Sigma Prime Geosciences, Inc.	Plan Review Letter, Proposed Carport, Remodeled Garage
		07/19/11	Sigma Prime Geosciences, Inc.	Addendum to Soils report, Proposed Carport and Garage Remodel
		07/25/11	Sigma Prime Geosciences, Inc.	Response to Geotechnical Comments, Proposed Carport, Remodeled Garage
	145 Phillip Road	05/30/94	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions, Nathan Residence
		12/21/95	GeoForensics, Inc.	Geotechnical Report Update, Proposed Pool House and Residential Additions
	160 Phillip Road	07/21/99	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Residence
		10/21/99	Earth Mechanics Consulting Engineers	Addendum to Geotechnical Investigation Report
		09/30/00	Earth Mechanics Consulting Engineers	Geotechnical Investigation, Planned Pool and Pool House
		03/13/02	Earth Mechanics Consulting Engineers	Response to Geotechnical Review Comments, Proposed Water Feature
	175 Phillip Road	07/17/91	Applied Soil Mechanics, Inc.	Preliminary Geologic and Soil Engineering Study, Proposed Giovenco Residence on 2 Acre Site
		01/16/92	Earth Systems Consultants - Northern California	Updated Construction Plan Review, Proposed Giovenco Residence
			William Cotton and Associates	Geotechnical Review Sheet
		02/10/92	Earth Systems Consultants - Northern California	Final Grading and Foundation Plan Review, Proposed Giovenco Residence
		02/27/92	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Giovenco New Residence, PA #8694, 8695, 8696
		05/13/92	William Cotton and Associates	Supplemental Geotechnical Review, Giovenco New Residence, PA #8694, 8695, 8696
		01/02/92	Mission Engineers, Inc.	Preliminary Grading and Drainage Plan, Lands of John Giovenco
		06/12/00	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Pool/Spa
		10/01/00	Carl W. Garbe, P.E.	Retaining Wall Section
	190 Phillip Road	10/07/74	Dunham & Associates	Soil Investigation, Proposed Addition (APN 075-292-130)
		05/09/86	Jo Crosby & Associates	Geotechnical Report, Landslide
20	PORTOLA ROAD			
	1231 Portola Road	03/21/78	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, One-Acre Lot off Portola Road
		07/19/02	United Soil Engineering, Inc.	Geotechnical Investigation, Proposed Minor Additions and New Deck
	1239 Portola Road	11/20/97	Jo Crosby & Associates	Geotechnical Investigation, Planned Additions
		01/22/98	Jo Crosby & Associates	Addendum, Geotechnical Investigation, Planned Additions and Alterations
		03/30/98	Jo Crosby & Associates	Engineering Geology, Planned Additions and Alterations
		04/15/98	Jo Crosby & Associates	Response to Town Review Comments (4/3/98), Planned Additions and Alterations
		05/14/98	Jo Crosby & Associates	Response to Town Review Comments (5/7/98), Planned Additions and Alterations
		06/04/98	Jo Crosby & Associates	Response to HTA Review Letter (6/4/98) Comments
		06/04/98	Jo Crosby & Associates	Geotechnical Review of Plans, Additions
		08/27/98	Jo Crosby & Associates	Observation of Excavations for Foundations, Additions
		12/07/01	Jo Crosby & Associates	Response to Town Review Comments (10/19/01), Garage Foundations
		04/24/02	Jo Crosby & Associates	Response to Town Comments (1/22/02), Remodeling Garage
		03/11/03	Romig Engineers, Inc.	Geotechnical Investigation, Russell Garage Foundation Reconstruction
	1301 Portola Road	08/04/00	Friar Associates, Incorporated	Geotechnical Investigation, Addition to Studio Building
		03/21/04	Amso Consulting Engineers (ACE)	Geotechnical Investigation, House Addition
		4/11/04 ?	Amso Consulting Engineers (ACE)	
	1307 Portola Road	01/19/07	Sigma Prime Geosciences, Inc.	Geotechnical Report, Proposed Single Family Dwelling
		09/10/09	Sigma Prime Geosciences, Inc.	Geotechnical Report, House Remodel
20A	1380 Portola Road		William Cotton and Associates	Geotechnical Review Sheet
				Topographic Map / Site Plan, with annotations
		12/16/85	William Cotton and Associates	Preliminary Geologic Review, Thomas / Willow Tree Farm Use Permit, File #80-91
		03/10/86	William Cotton and Associates	Supplemental Geologic Review, Thomas/Willow Tree Farm Use Permit, File #80-19
	1400 Portola Road	02/09/87	Fowler & Associates	Geological Investigation, The Family Farm
			William Cotton and Associates	Geotechnical Review Sheet
		03/05/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Family Farm Fault Trenching, Use Permit 80-96
		12/31/87	Fowler & Associates	Geotechnical Investigation, Proposed Expansion of the Family Farm
		05/17/99	Treadwell & Rollo	Geotechnical/Geological Investigation, Family Farm Landslide
	1407 Portola Road	06/21/95	Buckley Engineering Associates	Geologic Investigation, Proposed Residential Additions
		06/23/95	Ting & Associates	Geotechnical Investigation, Proposed Additions
		08/26/96	Buckley Engineering Associates	Response to Review, Proposed Additions
		09/04/96	Ting & Associates, Inc.	Response to Review, Geologic and Geotechnical Investigation, Proposed Additions

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	1439 Portola Road	see 1439 Home Road		
	1460 Portola Road	03/14/77	Francis A. Stejer	Engineering Geologic Study, Proposed Parcel No. 1 (APN 075-294-060)
		04/11/77	Dunham and Associates	Soil Investigation, Fragulia, Proposed Home
	1475 Portola Road	06/19/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed Replacement Retaining Wall, King Property
	1510 Portola Road	03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation (APN 075-294-160)
	1530 Portola Road	07/20/09	Romig Engineers, Inc.	Geotechnical Investigation, Miller Residence
		11/09/10	Romig Engineers, Inc.	Updated Geotechnical Review, Miller Pool House
	1543 Portola Road	02/14/77	Purcell, Rhodes & Associates	Soil and Geologic Investigation, Intersection of Portola Road and Old La Honda Road
		04/25/77	Town of Woodside	Review
		?	?	Plot Plan
		?	William Cotton and Associates	Geotechnical Review Sheet
		08/26/87	Lee Engineers	Swimming Pool Construction Soil Investigation
		09/18/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Berger Pool, P.A. #4186
	1545 Portola Road	05/09/05	Connell Geotechnical, Inc.	Geotechnical Investigation Report, New Riding Arena, Portola Farms
		02/27/08	Connell Geotechnical, Inc.	Geotechnical Investigation Report, New Cover for Existing Riding Arena, Portola Farms
	1820 Portola Road	06/13/05	Murray Engineers, Inc.	Geotechnical Investigation, Residence Improvements
		08/17/05	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Barn Addition
		09/14/05	Murray Engineers, Inc.	Supplemental Recommendations, Spa, Trellis & Site Retaining Walls
	1835 Portola Road	06/17/05	Lawrence B. Karp	various documents addressing proposed remodel in fault zone
	1840 Portola Road	09/30/75	Richard E. Roland	Geologic Report, Mogensen Property (APN 075-291-050)
		07/27/78	Mattson and Mattson	Site Plan, Morey Residence, with Annotations
		08/30/78	William Cotton and Associates	Geotechnical review
	1909 Portola Road	09/28/84	Fowler & Associates	AP Special Studies Zone Investigation, Gilmore Residence
		09/18/84	Doug Thom	Site Plan
		09/30/84	Susan Burr and Douglas Thom	Letter to Planning Commission
		10/11/84	William Cotton and Associates	Geotechnical Review Sheet
		10/11/84	?	Color Photographs of Trench Site (after backfill) and Creek
		10/16/84	William Cotton and Associates	Preliminary Geologic Review, Gilmore Addition, VAR 358
		ca 1984	?	Copies of Photographs of Property
		07/06/99	Fowler & Associates	Geotechnical Investigation, Proposed Addition
		05/09/06	Romig Engineers, Inc.	Geotechnical Review, Residence Remodel
		08/29/06	Romig Engineers, Inc.	Slope Reconstruction, Bridgman Residence
	1965 Portola Road	08/14/80	Howard Donley Associates, Inc.	Site Investigation, Proposed Swimming Pool
		08/19/80	William Cotton and Associates	Geotechnical Review Comments
		08/27/80	William Cotton and Associates	
		09/14/94	Earth Systems Consultants Northern California	Fault Evaluation Study
		12/20/94	Earth Systems Consultants Northern California	Soil Engineering Study, Proposed Facciola Residence Additions
		10/05/94	Earth Systems Consultants Northern California	Addendum, Fault Evaluation Study
	1990 Portola Road	04/01/77	Purcell, Rhoades & Associates	Geotechnical Investigation, Property NE of Intersection of Phillips and Portola Road (APN 072-211-250)
			Design 2	Site Plan with trenches
		05/06/77	Town of Woodside	Review of Geotechnical Investigation
		05/24/77	Purcell, Rhoades & Associates	Response to Town Review
		06/01/77	Town of Woodside	Review of Response to Town Comments
		01/29/87	Purcell, Rhoades & Associates	Soil Engineering Study and Foundation Recommendations, Proposed Swimming Pool
	2083 Portola Road	05/18/05	Romig Engineers, Inc.	Geotechnical Investigation, Mohsenin Residence Additions
	2087 Portola Road	10/14/02	J. Yang and Associates	Geotechnical Site Investigation
		10/28/04	Hoexter Consulting, Inc.	Engineering Geologic Reconnaissance, New Residence
		11/20/04	J. Yang and Associates	Geotechnical Site Investigation, Revision 1
		11/20/04	J. Yang and Associates	Geotechnical Review Comments
		12/23/04	J. Yang and Associates	Geotechnical Review Comments
		06/27/05	Hoexter Consulting, Inc.	Response to Review Letter, Construction of New Residence
	2089 Portola Road	09/22/95	William Cotton and Associates	Geotechnical Investigation, Landslide Mitigation
	2091 Portola Road	09/22/95	William Cotton and Associates	Geotechnical Investigation, Landslide Mitigation
20A	2095 Portola Road	04/10/74	Richard Rowland	Geologic Report, Alembique Ceek Parcel, Ellis Property

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
21	3000 Portola Road	11/29/76	Leighton and Associates	Field Review of Trench
			Leighton and Associates	Field Review Notes
		12/02/76	Burkland and Associates	School Property
		12/27/76	Applied Earth Sciences Consultants	Geologic and Seismic Hazards Evaluation, Schroll Property
		02/28/77	Town of Woodside	Memo - Review of Burkland & Associates Report dated 12/27/76
		03/03/77	Burkland and Associates	School Property - Supplemental Data
		03/14/77	Leighton and Associates	Memo - Comment on Response to 2/28/77 Memo
		00/00/87	Earth Systems Consultants	Geologic and Seismic Hazards Evaluation, The Schroll Property
		06/08/00	Applied Earth Sciences Consultants	Comments on Meeting with Town Geologist
		07/13/00	Applied Earth Sciences Consultants	Supplemental Comments on Meeting with Town Geologist re. Fault Investigation
		07/14/00	Town of Woodside	Memo to Applied Earth Sciences Consultants re. Fault Investigation
		08/14/00	Applied Earth Sciences Consultants	Memo to Town Geologist re. Fault Investigation
		08/15/00	Town of Woodside	Memo to Applied Earth Sciences Consultants re. Fault Investigation re. Fault Investigation
		09/12/00	Town of Woodside	Memo to Applied Earth Sciences Consultants re. Fault Investigation re. Fault Investigation
		04/13/01	Applied Earth Sciences Consultants	A Geotechnical Investigation for Subdivision Feasibility, The Schroll Estate
		04/17/01	Town of Woodside	Pre-Application: Subdivision, Engineering Geology Comments
		05/09/01	Town of Woodside	Pre-Application: Subdivision, Engineering Geology Comments
		07/12/01	Town of Woodside	Subdivision Review Comments
		10/07/03	Upp Geotechnical, Inc.	Preliminary Findings, Geotechnical Investigation, Residence
		10/08/05	Town of Woodside	Pre-Application: Residence, Engineering Geology Comments
		11/14/03	Upp Geotechnology, Inc.	Geotechnical Investigation, Virtual Management Property
		05/10/05	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Phase 2A Improvements, Residence
		06/01/05	Upp Geotechnology, Inc.	Phase 2B On-Site Sewage Disposal System for Gym and Recreation Building
		06/01/05	Applied Earth Sciences Consultants	On-Site Sewage Disposal System, Siting, Construction, System Use and Maintenance (Phase 2B Permit SOW)
		06/03/05	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Phase 2B Improvements, Residence
		05/03/05	Applied Earth Sciences Consultants	On-Site Sewage Disposal Systems, Main Residence, Pool House and Cabana
		10/21/05	Applied Earth Sciences Consultants	On-Site Sewage Disposal Systems, Caretakers Residence, Maintenance Building, and Kennel
		11/03/05	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Phase 3 Improvements, Portola Road Residence
		01/28/08	Upp Geotechnology, Inc.	Supplemental Recommendations, Adobe House Renovation, Portola Road Residence
		04/29/08	Upp Geotechnology, Inc.	Supplemental Geotechnical Recommendations, Adobe Road House, Portola Road Residence
21	PRESTON ROAD			
	19 Preston Road	05/09/94	Nielsen Geotechnical Incorporated	Soil Report
		07/19/05	Murray Engineers, Inc.	Limited Geotechnical Evaluation & Foundation Recommendations, Residential Improvements
	22 Preston Road	07/11/97	Steven F. Connelly, C.E.G.	Geologic Investigation, Whalen Property
	25 Preston Road	06/20/78	Burkland and Associates	Geotechnical Investigation, Macie Property
		10/02/78	Burkland and Associates	Supplemental Geologic Investigation, Macie Property
		10/22/02	Earth Systems Consultants	Final Report on Construction Activity, Retaining Wall Plank Replacement Project, Thomas Residence
	27 Preston Road	01/07/80	William Cotton and Associates	Geotechnical Review Sheet
		03/06/80	Earth Systems Consultants	Progress Summary - Geotechnical Investigation, Proposed Lorenzini Residence
		04/04/80	Earth Systems Consultants	Draft Geotechnical Investigation, Lorenzini Property
		04/28/80	Earth Systems Consultants	Geotechnical Investigation, Lorenzini Property
		06/02/80	William Cotton and Associates	Review - Lorenzini
		04/10/85	Earth Systems Consultants	Foundation Plan Review
		04/15/85	James K. Bell	Site Plan, with annotations
		04/23/85	William Cotton and Associates	Geotechnical Review Sheet
		05/01/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of McMillen
	29 Preston Road (11 Old La Honda Road)			
	235 Preston Road	06/20/78	Burkland & Associates	Geotechnical Investigation, Nalie Property
		10/02/78	Burkland & Associates	Geotechnical Investigation, Malie Property
	359 Preston Road	07/16/98	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Retaining Wall Repair
		10/28/98	Upp Geotechnology, Inc.	Limited Soils and Foundation Investigation, Repair of Landslide Scar, Lands of Yoshida
21	PROSPECT AVENUE			
	60 Prospect Avenue	04/03/81	Purcell, Rhoades & Associates	Preliminary Soils Investigation, Parcel 2, LD #223
		04/21/81	Perry R. Wood	Soil Percolation Tests, LD #273
		05/13/81	Town of Woodside	Review Comments, Sy LD #273, Preliminary Map Review
		05/15/81	William Cotton and Associates	Geotechnical Review Sheet
		06/16/81	William A. Bartlett	Preliminary Map, LD #273, Subdivision Portion of Parcel A
		08/12/81	Perry R. Wood	Soil Percolation Tests, Parcel 2, LD #273
		09/21/81	William Cotton and Associates	Geologic Review, LD #273
		04/17/86	Purcell, Rhoades & Associates	Geotechnical Engineering and Foundation Recommendations, Blick Residence
		04/02/03	Nielsen Geotechnical Incorporated	Soil Report
	80 Prospect Avenue	07/30/80	Applied Earth Consultants	Geotechnical Engineering, Proposed Swimming Pool, Lands of Enos

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		0/0/80	William Cotton and Associates	Geotechnical Review Sheet
		06/23/81	William Cotton and Associates	Review of Pool Site - Enos (Pool) BP 1004
		08/10/81	Applied Earth Consultants	Geologic Inspection of Swimming Pool Excavation
		04/12/06	Buckley Engineering Associates, Inc.	Geotechnical Engineering, Proposed Foundation Improvement, Pool House
	155 Prospect Avenue	12/15/75	Berloger, Lomg & Associates	Engineering Geologic Fault Investigation, Bryson Property
		10/27/97	Nielsen Geotechnical Incorporated	Geotechnical Report
		06/07/00	Nielsen Geotechnical Incorporated	Tennis Court
		09/05/01	Nielsen Geotechnical Incorporated	Plan Review, Tennis Court
		10/03/02	Nielsen Geotechnical Incorporated	Final Construction Report, Tennis Court
		01/13/06	Murray Engineers, Inc.	Geotechnical Investigation, Hartman Cottage
		05/16/07	Murray Engineers, Inc.	Supplemental Geotechnical Recommendations, Landscaping Improvements
	169 Prospect Avenue	08/06/99	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence
	169 Prospect Avenue	06/12/00	Fowler & Associates	Geotechnical Consultation and Plan Review
21	183 Prospect Avenue	03/28/95	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Garage
		06/13/95	Michelucci & Associates, Inc.	Geotechnical Evaluation of "Point Bar" Creek Bank Erosion Mitigation Project, Weinstein Property
21A	QUAIL MEADOWS COURT			
	1 Quail Meadows Court	10/09/78	Purcell, Rhoades & Associates	Geotechnical Investigation
		05/08/86	Terrasearch Inc.	Soil Investigation, Proposed Residence, Quail Meadows (APN 073-270-070)
	3 Quail Meadows Court	06/28/86	Purcell, Rhoades & Associates	Soil Engineering and Foundation Design Report, Lot 2, Quail Meadows Court
	5 Quail Meadows Court	04/11/86	Dunham & Associates	Soil Investigation, Proposed Home (APN 073-270-050)
		04/04/86	?	Site Plan
		?	William Cotton and Associates	Geotechnical Review Sheet
		08/04/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Investigation - Moore
21A	QUAIL MEADOWS DRIVE			
	Quail Meadows Subdivision	07/21/69	W. A. Wahler & Associates	Geologic and Soils Investigation, Vista Del Sol
		02/01/77	Leighton and Associates	Review of 7/21/69 Geologic and Soil Investigation report
	2 Quail Meadows Drive	04/25/86	Dunham & Associates	Soil Investigation, Proposed Home, Lot 9, Quail Meadows (APN 073-270-130)
		05/21/87	Melvin R. Hill Inc.	Pool Design
			William Cotton & Associates	Geotechnical Review Sheet
		07/08/87	William Cotton & Associates	Preliminary Geotechnical Review, Morey Swimmih Pool and Spa, PA #4188
		07/22/87	Melvin R. Hill Inc.	Pool Design
		08/26/87	William Cotton & Associates	Supplemental Geotechnical Review, Morey Swimming Pool and Spa, PA #4188
	4 Quail Meadows Drive	08/30/94	Fowler & Associates	Engineering Geologic Report, Proposed Chenevich Residence
		09/01/94	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Home
		10/26/07	Romiq Engineers, Inc.	Geotechnical Investigation, Garage, Pool House, and Lap Pool
	6 Quail Meadows Drive	05/31/85	Purcell, Rhoades & Associates	Soil Engineering Study, Lot 7, Quail Meadows (APN 073-270-110)
		03/20/08	Terra Firma Engineering and Science	Geotechnical Investigation for Photovoltaic Array
	10 Quail Meadows Drive	06/10/86	Purcell, Rhoades & Associates	Soil Engineering and Foundation Design Report, Lot 5, Quail Meadows (APN 073-270-090)
		03/06/01	Jo Crosby & Associates	Geotechnical Investigation for Proposed Swimming Pool
	12 Quail Meadows Drive	12/04/85	Purcell, Rhoades & Associates	Soil Engineering and Foundation Design Report, Lot 4, Quail Meadows (APN 073-270-080)
		07/31/03	Wayne Ting & Associates, Inc.	Geotechnical Investigation, Proposed Liu Residence
		07/31/03	Hoexter Consulting, Inc.	Engineering Geology Reconnaissance, New Residence
21A	RANCH ROAD			
	25 Ranch Road	09/04/08	Romiq Engineers, Inc.	Geotechnical Investigation, Snyder Residence Additions
	50 Ranch Road	07/24/92	Clearly Consultants, Inc.	Soil and Foundation Investigation, Residence Expansion
	75 Ranch Road	00/00/77	George L. Quick	Geologic Investigation, Lot 4, Block 6, Skywood Acres (APN 075-013-080)
		07/07/77	Geo-Ekta Laboratories	Foundation Soils Investigation, Lot 4, Block 6, Skywood Acres
	80 Ranch Road	10/12/77	Purcell, Rhoades and Associates	Supplemental No. 2, Soil and Geologic Investigation of Proposed Home, Lot 12, Block 3, Skywood Acres
		10/14/77	Leighton and Associates	review of above report
	85 Ranch Road	12/23/86	Upp Geotechnology	Preliminary Investigation, Vasquez Property
		12/16/02	Earth Investigations Consultants	Engineering Geologic Evaluation
		01/23/03	Stimac Associates, Inc.	Geotechnical Investigation, Proposed Additions and Remodel
		01/23/04	Stimac Associates, Inc.	Geotechnical Investigation
		08/25/04	Stimac Associates, Inc.	Geotechnical Review of Plans, Residential Remodel for Griggs

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	90 Ranch Road	09/09/02	Charles H. Hartsog	Soils Report
		12/26/02	Charles H. Hartsog	Geo Plan Review Comments, Proposed Remodeling
21A	RAVINE DRIVE			
	165 Ravine Drive	03/21/02	Upp Geotechnology, Inc.	Reconnaissance Geotechnical Investigation, Proposed Barn, Darbonne Property
		10/03/02	Upp Geotechnology, Inc.	Construction Observations, Site Grading, Darbonne Property
21A	RAYMUNDO DRIVE			
	141 Raymundo Drive	11/15/85	Upp Geotechnology	Soil and Foundation Investigation, Fontana Swimming Pool
			William Cotton and Associates	Geotechnical Review Sheet
			Val's Custom Pools	Site Plan, with annotations
		11/27/85	Upp Geotechnology	Plan Review, Fontana Swimming Pool
		12/16/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Fontana Pool
	166 Raymundo Drive	06/20/96	Upp Geotechnology, Inc.	Fault Location Investigation, Reese Trust Property
		12/04/06	Earth Investigations, Consultants	Geotechnical Evaluation, Equestrian Arena Improvements
		04/04/07	Earth Investigations, Consultants	Supplemental Geologic Data, Soil Exploration Logs & Hermit Fault, Equestrian Arena Improvements
	173 Raymundo Drive	09/21/84	Upp Geotechnology	Soil and Foundation Investigation, Swimming Pool
		08/31/89	JCP	Engineering Geologic Study, Proposed Barn, Guest House, Tennis Court, and Additions
	314 Raymundo Drive	01/09/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel
	317 Raymundo Drive	09/29/93	Earth Investigations Consultants	Engineering Geological Site Reconnaissance, Kaul Property (APN 072-032-010)
		10/24/94	Earth Investigations Consultants	Engineering Geological Site Reconnaissance, Proposed Drainfield - Kaul Property (APN 072-032-010)
		07/03/95	Earth Investigations Consultants	Engineering Geological Site Reconnaissance, Proposed Drainfield - Kaul Property (APN 072-032-010)
		09/29/97	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Single Family Residence
		7/0/98	Phillip A. Frame	Engineering Geology Report
	317 Raymundo Drive	07/15/98	Milstone Geotechnical	Geotechnical Investigation, Proposed Thalapaneni Residence
21A	386 Raymundo Drive	09/04/99	North Coast Engineering	Geotechnical and Geologic Investigation of Landslide
		04/22/09	Earth Investigations Consultants	Geotechnical Investigation, Newly-Constructed Porches and Proposed Deck Expansion, McCauley Residence
		03/17/10	Earth Investigations Consultants	Geotechnical Investigation, Proposed Room Addition, McCauley Residence
22	416 Raymundo Drive	11/05/03	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Willford Property
		11/20/03	Louis A. Richardson	Engineering Geologic Feasibility Considerations, New Residential Construction
		06/17/05	GeoForensics, Inc.	Geotechnical Recommendations, New Riding Rink
		06/30/05	GeoForensics, Inc.	Retaining Wall Alternative, Proposed Riding Rink
		07/20/05	GeoForensics, Inc.	Retaining Wall Calculations, Proposed Riding Rink
		09/01/05	GeoForensics, Inc.	Review of Civil Plan - Slide Impact, Proposed Riding Rink
		09/09/05	GeoForensics, Inc.	Commentary on "Retaining Walls", Proposed Riding Rink
	421 Raymundo Drive	01/21/81	William M. McMorrow & Associates	Accomplishment of Slope Rehabilitation
		07/13/96	William M. McMorrow	Geotechnical Engineering Investigation, Proposed Swimming Pool and Spa
		08/22/96	William M. McMorrow	Supplemental Geotechnical Data, Proposed Swimming Pool & Spa
		07/08/99	William M. McMorrow	Geotechnical Engineering Evaluation, Proposed New Pool House & Porch
		02/02/00	William M. McMorrow	Geotechnical Engineering Review, Proposed New Pool House
		05/05/00	Steven F. Connelly	Engineering Geologic Investigation, Proposed Pool House and Landslide Repair
		05/31/00	Frederick Maurer, Jr.	Geotechnical Investigation, Proposed Pool House and Landslide Repair, Poletti Residence
		08/04/00	Frederick Maurer, Jr.	Supplemental Recommendations and Slope Stability Analyses, Geotechnical Investigation, Proposed Pool House and Landslide Repair
		08/11/00	Geomatrix Consultants	Geotechnical Review, Proposed Pool House and Landslide Repair, Poletti Residence
		08/22/00	Frederick Maurer, Jr.	Geotechnical Plan Review and Response to Town Comments, Proposed New Pool House and Landslide Repair
		08/22/00	Frederick Maurer, Jr.	Response to Town Review Comments, Supplemental Slope Stability Analyses and Additional Recommendations
		01/19/01	Frederick Maurer, Jr.	Summary Report, Construction Observation Services, Proposed Pool House
		03/28/01	Frederick Maurer, Jr.	Final Geotechnical Plan Review, Proposed Pool House
		07/09/01	Frederick Maurer, Jr.	Final Geotechnical Plan Review, Proposed Pool House Revisions
		12/14/01	Frederick Maurer, Jr.	Final Report, Construction Observation Services, Proposed Pool House
	460 Raymundo Drive	08/26/81	McMorrow & Associates/Francis A. Stejer, C.E.G.	Geologic Fault Study-Soils Foundation Investigation, Lot 12, Rancho Canada, Tract 567
		12/28/88	John Coyle & Associates, Inc.	Preliminary Engineering Geologic Investigation, Tuck Property
		11/16/88	Snyder & Associates	Geotechnical Investigation, Proposed Tuck Residence
		02/18/89	Snyder & Associates	Supplement to Geotechnical Investigation, Proposed Tuck Residence
		05/18/89	Snyder & Associates	Supplemental Information, Proposed Tuck Residence
		05/16/89	John Coyle & Associates, Inc.	Supplement Letter Report, Preliminary Engineering Geologic Investigation, Tuck Property
		04/09/93	Upp Geotechnology, Inc.	Geotechnical Review, Lands of Tuck
		11/29/95	Upp Geotechnology, Inc.	Plan Review, Preliminary Grading and Drainage Plans, Foundation Plans, Tuck Residence
		01/25/96	Upp Geotechnology, Inc.	Addendum Plan Review, Grading and Drainage Plans, Foundation Plan, Tuck Residence
		03/16/98	Upp Geotechnology, Inc.	Engineering Geologic and Fault Location Investigation Report, Lands of Storm
		09/11/00	Phillip A. Frame	Fault Investigation Report
		05/09/01	Advance Soil Technology, Inc.	Soil and Foundation Investigation, Proposed Single Family Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		05/17/02	SPI Consulting	Creek Stabilization with Geoweb Cellular Confinement System, Design Calculations
		07/27/06	Phillip A Frame	Update of Fault Investigation Report
		07/28/06	Phillip A Frame	Engineering Geology Report, Storm Residence
		09/18/06	AST Advance Soil Technology, Inc.	Response to Plan Check Comments, Proposed Single Family Residence
		11/14/06	Phillip A. Frame	Existing Data on the Old Landslide Mapped on the Storm Property
		11/30/06	AST Advance Soil Technology, Inc.	Proposed Single Family Residence, Supplemental Information, Proposed Single Family Residence
		04/16/07	Phillip A Frame	Geologic Investigation, Old Mapped Landslide
		04/20/07	AST Geotechnical & Environmental Consulting Engineers	Slope Stability Analysis, Old Mapped Landslide, Storm Residence
		05/25/07	Schaaf & Wheeler	Storm Residence Driveway Drainage
		09/17/07	AST Advance Soil Technology, Inc.	Supplemental Data - Geotechnical Recommendations for the Proposed Dam Structure (Retaining Wall)
		10/10/07	Biggs Cardoso Associates, Inv.	Structural Calculations for Storm Residence Detention Basin
		10/15/07	AST Advance Soil Technology, Inc.	Plan Review (Detention Wall), Proposed Single Family Residence
	463 Raymundo Drive	04/24/98	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Proposed Pool House, Lands of Clark
	486 Raymundo Drive	05/23/85	William Cotton and Associates ?	Notes from Fault Trench Inspection
		05/31/85	Tim J. Manzagol	A Geologic Investigation
		06/16/85	Melinda Fitch, owner	Letter to William Cotton and Associates, with WCA annotations on attached map
		07/08/85	William Cotton and Associates	Preliminary Geologic Review, Lands of Fitch - Fault Investigation, proposed Residential Addition
22A	RIDGE COURT			
	32 Ridge Court	09/25/95	Carl W. Garbe	Soils and Foundation Investigation
		01/15/96	Carl W. Garbe	Review - Geotechnical Investigation, Proposed Addition
		2/22/96	Carl W. Garbe	Supplemental Review - Geotechnical Investigation, Proposed Addition, Garage
	63 Ridge Court	09/30/05	Romig Engineers, Inc.	Geotechnical Investigation, Kravitz Residence
22A	RIDGEWAY ROAD			
	Ridgeway Road	09/12/66	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Woodside Hills Unit No. 6
	130 Ridgeway Road	01/19/98	Nielsen Geotechnical Incorporated	Soil Report
		09/09/00	Nielsen Geotechnical Incorporated	Project Review & Soil Report Update
		05/15/01	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Swimming Pool
	140 Ridgeway Road	04/30/03	PGSoils, Inc.	Geotechnical Investigation, Proposed Landscaping Improvements
		07/07/05	PGSoils, Inc.	Subsurface Conditions, proposed Back Yard Landscaping improvements
	150 Ridgeway Road	04/22/09	Romig Engineers, Inc.	Geotechnical Investigation, Huberty Residence Additions
	175 Ridgeway Road	02/01/91	JCP Geologist - Engineers	Soil and Foundation Study for Proposed Residence
			William Cotton and Associates	Geotechnical Review Sheet
		05/22/91	William Cotton and Associates	Supplemental Geotechnical Review, Stankovic, PA #8228, 8229, 8230
		02/13/91	Oakley and Associates	Site Plan, with annotations
	230 Ridgeway Road	04/14/86	JCP Geologists - Engineers	Soil and Foundation Study, Proposed Additions
	255 Ridgeway Road	06/25/01	Ajay Singh	Geotechnical Engineering Recommendation, Proposed Schonfeld Residence Modifications
		10/10/01	Ajay Singh	Plan Review, Proposed Schoenfeld Residence Modifications
		12/04/01	Ajay Singh	Foundation Observations, proposed Schonfeld Residence Modifications
		11/11/02	Ajay Singh	Final Report, Proposed Schoenfeld Residence Modifications
	285 Ridgeway Road	01/29/10	Murray Engineers, Inc.	Geotechnical Investigation, Housser Residence Addition
	290 Ridgeway Road	06/30/06	PGSoils, Inc.	Geotechnical Conditions, Proposed Pool Area Accessory Building
	300 Ridgeway Road	04/05/07	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
		04/15/07	J. Yang and Associates	Response to the Concerns of Town of Woodside, Proposed Smythe Addition
		10/04/07	J. Yang and Associates	Geotechnical Review Comments, Proposed In-Law Residence
	330 Ridgeway Road	04/03/08	Murray Engineers, Inc.	Limited Geotechnical Evaluation, Site Improvements
		03/16/09	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Bath/Spa Structure
	331 Ridgeway Road	09/24/99	GeoForensics Inc.	Geotechnical Investigation, Proposed New Guest House, Renski Property
22A	ROAN PLACE			
	5 Roan Place	06/03/95	GeoForensics Inc.	Geotechnical Observations of Reported Residential Distress, Ahmed Residence
		09/22/99	GeoForensics Inc.	Geotechnical Investigation for Mitigation of Residential Distress, Ahmed Property
		11/01/99	GeoForensics Inc.	Report Correction
		01/06/00	GeoForensics Inc.	Review of Revised Plans
		03/30/00	GeoForensics Inc.	Response to Town Review

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		07/15/07	GeoForensics Inc.	Review of Revised Plans #2
		09/14/00	GeoForensics Inc.	Report Supplement - Drainage
		09/14/00	GeoForensics Inc.	Review of Revised Plans #3
		10/13/00	GeoForensics Inc.	Response to Geomatrix Review
	25 Roan Place	02/17/90	Edward W. Baca	Survey Map, with annotations
		05/01/91	Earth Systems Consultants	Geotechnical Report, Landes Residence
		05/13/91	Earth Systems Consultants	Review of Grading Plans
		06/12/91	William Cottonand Associates	Preliminary Geologic and Geotechnical Review, Landes, VAR-499, XSD-77, Site Design 36
		06/04/92	William Cottonand Associates	Geologic and Geotechnical Review, Landes, Variance 517
	30 Roan Place	05/04/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
		06/02/06	Earth Investigations Consultants	Geotechnical Parameters, Proposed Retaining Wall
	45 Roan Place	12/14/71	Terrasearch, Inc. (Reynolds & Associates)	Soil & Geological Investigation, Benson Property
	75 Roan Place	09/30/93	JCP Engineers - Geologists	Geotechnical Causation and Mitigation Study, Distressed Home
		09/26/95	GeoForensics, Inc.	Geotechnical Investigation of Reported Residential Distress
		06/04/96	GeoForensics, Inc.	Response to Town Geotechnical Review, Partial Foundation Repairs
		10/24/08	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residence Remodel and New Second Story Addition
	80 Roan Place	12/05/91	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Proposed Addition Above Existing Garage
		01/24/92	Michelucci & Associates, Inc.	Review of Plans, Proposed Remodel and Addition, Barrett Residence
			William Cotton and Associates, Inc.	Geotechnical Review Sheet
			William Cotton and Associates, Inc.	Preliminary Geotechnical Review, Barrett Additions, #8652
		02/13/92	Michelucci & Associates, Inc.	response to William Cotton and Associates review comments
		02/14/92	Michelucci & Associates, Inc.	clarification to 2/13/92 letter
		02/19/02	Michelucci & Associates, Inc.	Supplemental Geotechnical Investigation, Planned Addition and Remodel Project
22A	ROBERTA DRIVE			
	45 Roberta Drive	04/14/00	Romig Engineers, Inc.	Geotechnical Investigation, Congress Guest House
	75 Roberta Drive	07/28/94	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Addition to Existing Residence (APN 072-201-16)
		04/15/98	Hydro-Geo Consultants, Inc.	Response to Letter from Town's Geotechnical Consultant
	85 Roberta Drive	11/04/99	Nielsen Geotechnical Incorporated	Soil Report
		02/25/02	Nielsen Geotechnical Incorporated	Soil Report, Swimming Pool
		04/29/05	Murray Engineers, Inc.	New Engineer-of Record & Alternative Foundation Recommendations, Residence Additions
	170 Roberta Drive	11/01/73	United Soils Engineering, Inc.	Soil and Geological Investigation, Lot 2 Jacqueline Subdivision
	190 Roberta Drive	08/29/89	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Additions
		10/24/91	Michelucci & Associates, Inc.	Review of Plans, Proposed Addition and Accessory Building
			William Cotton and Associates	Geotechnical Review Sheet
		03/02/92	William Cotton and Associates	Geotechnical Review, Messmer Additions, PA #8700 and 8701
22A	ROBLES DRIVE			
	45 Robles Drive	09/24/90	Fowler & Associates	Geotechnical Investigation, Proposed Exercise/Storage Building
	45 Robles Drive	01/18/06	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Landscape Improvements
22A	65 Robles Drive	06/29/93	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, Percolation Testing, Lands of O'Malley Trust (APN 072-201-042)
		01/03/94	Upp Geotechnology, Inc.	Limited Geotechnical Investigation, Supplemental Percolation Testing, Expansion Field - Proposed Parcel 2
23	ROCKY WAY			
	514 Rocky Way	03/30/99	Upp Geotechnology, Inc.	Geotechnical Investigation, Additions to Carlson Residence
	529 Rocky Way	06/12/98	Fowler & Associates	Geotechnical Investigation, Proposed Single Family Residence and Guest House
		09/05/00	Fowler & Associates	Geotechnical Consultation, Proposed Single Family Residence
		07/10/00	Fowler & Associates	Geotechnical Plan Review and Consultation, Proposed Single Family Residence
		04/24/07	PGSoils, Inc.	Geotechnical Investigation Report Update, Proposed Residence
		12/19/08	PGSoils, Inc.	Pier Hole Drilling Observation, BP07-266 & -267, Proposed Residence
		01/06/09	PGSoils, Inc.	Construction Observations, BO07-266 & -267, New Residence
		08/25/09	PGSoils, Inc.	Pier Hole Drilling Observation, BP07-266 & -267, Proposed Residence
		05/03/10	PGSoils, Inc.	Water Pipe Under Driveway, BO07-266 & -267, New Residence
		05/25/10	PGSoils, Inc.	Construction Observations Summary, BO07-266 & -267, New Residence
	546 Rocky Way	03/25/99	GeoForensics Inc.	Geotechnical Investigation, Hall Property
		11/03/99	GeoForensics Inc.	Review of Plans, Proposed New Residence
		09/18/01	GeoForensics Inc.	Construction Observations, New Residence and Accessory Building

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
23	ROMERO ROAD			
	115 Romero Road	02/10/97	Nielsen Geotechnical Incorporated	Soil Report
	116 Romero Road	03/31/05	Murray Engineers, Inc.	Geotechnical Investigation, North Residence
	147 Romero Road	06/07/99	Nielsen Geotechnical Incorporated	Soil Report
		08/15/02	Nielsen Geotechnical Incorporated	Construction Report
	163 Romero Road	03/27/75	R. C. Harlan and Associates	Soil Investigation
		04/04/07	Romig Engineers, Inc.	Geotechnical Investigation, Mawson Residence Addition
		07/03/08	Romig Engineers, Inc.	Supplemental Design Parameters, Driveway Retaining Walls
		10/10/08	Romig Engineers, Inc.	Geotechnical Plan Review, Replacement Retaining Wall
		09/02/11	Romig Engineers, Inc.	Geotechnical Recommendations, Site Retaining Walls
	179 Romero Road	03/01/00	Nielsen Geotechnical Incorporated	Soil Report
	191 Romero Road	04/18/79	William Cotton and Associates	Geotechnical Review Sheet
		04/23/79	William Cotton and Associates	Geological Review - Giannone Variana
	198 Romero Road	02/28/03	GeoForensics Inc.	Geotechnical Investigation, Proposed New Residence
23	RUNNYMEDE ROAD			
	880 Runnymede Road	12/30/82	Earth Sciences Associates	Phase I Assessment of Geologic Hazards, IASCO Property
		10/11/84	Earth Sciences Associates	Phase II Soil and Geologic Investigation IASCO Property
		08/16/90	Earth Sciences Associates	Update of Soil and Geologic Investigation Report for IASCO Property
		05/15/07	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Structure, Dearborn Stables
	922 Runnymede Road	10/14/74	Berloger, Long & Associates	Fault Investigation, Martines Property
		07/09/03	Steven A. Arnold	Geotechnical Evaluation
		10/22/03 rev	Steven A. Arnold	Geotechnical Evaluation
		10/21/03	Steven A. Arnold	Geotechnical Review Response
		9/3/03 rev	Steven A. Arnold	Geotechnical Evaluation
		08/25/05	PGSoils, Inc.	Geotechnical Investigation, Proposed Barn Modifications and "Hot Walker" Structure
		09/20/05	PGSoils, Inc.	Geotechnical Investigation, Proposed Deck and Trellis Additions
		09/08/06	PGSoils, Inc.	Geotechnical Report Update
	980 Runnymede Road	12/27/89	Tredwell & Associates, Inc.	Foundation Support - Cookhouse
		07/13/90	Tredwell & Associates, Inc.	Drilled Pier Installation - Cookhouse
		01/18/02	Tredwell & Rollo, Inc.	Geotechnical Consultation, Runnymede Farm Equipment Shed
		03/04/02	Tredwell & Rollo, Inc.	Plan Review, Runnymede Farm Equipment Shed
		04/25/02	Tredwell & Rollo, Inc.	Drilled Pier Installation, Farm Equipment Building, Runnymede Farm
		03/04/04	Tredwell & Rollo, Inc.	Geotechnical Design Parameters, Footbridge Replacement, Runnymede Farm
		12/21/04	Gilpin Geosciences, Inc.	Draft Fault Hazard Evaluation, Proposed Accessory Dwelling Unit
		01/07/05	Town of Woodside	Geology Departments Comments on 12/21/04 draft report
		02/23/05	Gilpin Geosciences, Inc.	Fault Hazard Evaluation, Proposed Accessory Dwelling Unit
		03/17/05	Tredwell & Rollo, Inc.	Geotechnical Consultation, Accessory Dwelling Unit, Runnymede Farm
		03/18/05	Town of Woodside	Geology Departments Comments on 1/23/05 final report
		03/24/05	Tredwell & Rollo, Inc.	Revised Report, Geotechnical Consultation, Accessory Dwelling Unit, Runnymede Farm
		10/16/07	Tredwell & Rollo, Inc.	Geotechnical Investigation, Vehicle Bridge
		11/05/07	Gilpin Geosciences, Inc.	Fault Hazard Evaluation, Caretaker's House
		11/14/07	Tredwell & Rollo, Inc.	Geotechnical Investigation, Cartaker's Residence
		12/21/07	Adolph S. Rosekrans, Inc. Architects	Project Manual for Caretaker's House
		03/16/10	Tredwell & Rollo, Inc.	Cookhouse Shade Structure
23	SAND HILL COURT			
	10, 20, & 30 Sand Hill Court	11/12/80	Purcell Rhoades & Associates	Geotechnical Hazards Assessmant, APN 72-221-180, Sand Hill Road and Mountain Home Road
		01/09/81	Town of Woodside	Preliminary Map Review
		01/13/81	William Cotton & Associates	Geotechnical Review Sheet
		01/15/81	William Cotton & Associates	Geologic Review of PRA Hazards Assessmant dated 11/12/80
		01/16/81	Town of Woodside	Review of Preliminary Map, Capinvest, Inc., LD 271
			William Cotton & Associates	Geotechnical Review Sheet
		09/22/81	William Cotton & Associates	Memo on Conditions of Approval
		08/24/81	Purcell Rhoades & Associates	Preliminary Soil Report, APN 72-221-180, Sabd Hill Road and Mounrain Home Road
		09/24/81	Town of Woodside	Preliminary Map LD #271 Comments
		09/24/81	County of San Mateo, Department of Health Services	Rejection of Septic System for Proposed Parcels
		10/14/81	Purcell Rhoades & Associates	Addendum to 8/24/81 Report - Additional Percolation Studies, Preliminary Map LD #271
		11/11/81	William Cotton & Associates	Geologic Review of PRA Hazards Assessmant dated 11/12/80
		11/20/81	Edwin H. Smith	Preliminary Map, LD Capinvest, Inc., APN072-221-180
		12/11/81	William Cotton & Associates	Geotechnical Review Sheet
		02/17/87	William Cotton & Associates	Supplemental Geologic and Geotechnical Review, Capinvest, LD 271

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		09/21/87	William Cotton & Associates	Supplemental Geologic and Geotechnical Review, Capinvest, LD 271
		11/17/87	William Cotton & Associates	Supplemental Geotechnical Review, Capinvest, LD 271
23	SAND HILL ROAD			
	Sand Hill Road			
23	SARGENT LANE			
	41 Sargent Lane	10/24/01	Romig Engineers, Inc.	Geotechnical Investigation, Judd Residence Addition
		12/14/10	BAAG Engineers	Geotechnical Engineering Investigation, Proposed Residential Remodel and Addition
		06/02/11	BAAG Engineers	Report Addendum, Geotechnical Engineering Investigation, Proposed Residential Remodel and Addition
23A	SHADOWBROOK LANE			
	1 & 2 Shadowbrook Lane	11/22/74	Berloger, Long and Associates	Geologic and Soils Report
		01/24/78	Town Staff	Report to the Planning Commission
		09/15/87	Purcell, Rhoades & Associates	Preliminary Soil Analysis and Fluid Percolation Testing, Parcels 2 and 3
		09/28/87	Purcell, Rhoades & Associates	Soil Engineering and Geotechnical Study, Parcels 2 and 3
		10/07/87	Purcell, Rhoades & Associates	Notes on Observation of Trenches to Determine Groundwater Level
			William Cotton and Associates	Geotechnical Review Notes
		11/04/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Haas, PA #4345
		12/03/87	Purcell, Rhoades & Associates	Plan Review, Parcels 2 and 3
		12/23/87	Purcell, Rhoades & Associates	Potential for Seismic Failure of Proposed Pond, Parcel 3
		01/18/88	William Cotton and Associates	Supplemental Geotechnical Review, Haas, PA #4345
23A	SHERIDAN WAY			
	115 Sheridan Way	11/20/97	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Additions, Kalkhoven House
	119 Sheridan Way	06/16/06	Murray Engineers, Inc.	Geotechnical Investigation, Hills Residence Improvements
		02/17/11	Murray Engineers, Inc.	Supplemental Site Retaining Wall Foundation Recommendations, Hills Property
	121 Sheridan Way	10/10/07	Romig Engineers, Inc.	Geotechnical Investigation, McBride Trellis
	130 Sheridan Way	07/02/03	Bay Area Geotechnical Group	Geotechnical Consultation, Webster Residence Flatwork Subgrade
		04/20/07	Henry Justiniano & Associates	Geotechnical Investigation, Proposed Reconstruction of Single Family Dwelling
	135 Sheridan Way	01/31/05	Romig Engineers, Inc.	Geotechnical Investigation, Burow/Sweeney Residence Additions
23A	SKYLINE BOULEVARD			
	Vicinity of Skyline Boulevard	06/10/73	Deborah R. Harden	Engineering Geology and Slope Stability of Part (South) of the Town of Woodside
	Southwest Portion of Town		William Cotton and Associates	Draft Movement Potential Map ?
	Skyline Boulevard	12/20/85	William Cotton and Associates	Geotechnical Review Sheet - Skylanda Center
		12/0/85	ESA	Skylanda Center Environmental Assessment
		12/31/85	William Cotton and Associates	Preliminary Geologic Review, Skylanda Center
	17288 Skyline Boulevard	01/26/94	ETIC	Site Characterization, Remedial Excavation, and Confirmation of Sampling - Unocal 76 Station - Alice's Restaurant
		09/14/95	Smith-Emery GeoServices	Workplan for Septic System Investigation, Alice's Restaurant
		10/20/95	Smith-Emery GeoServices	Septic System Recommendations, Alice's Restaurant
	17865 Skyline Boulevard	08/16/95	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition and Remodel Project
	18033 Skyline Boulevard	09/21/00	ADCO Engineering	Foundation Repair Investigation
		04/23/01	Nielsen Geotechnical Incorporated	Drainage Recommendations, Roof Drainage
		09/09/02	ADCO Engineering	Soil and Foundation Investigation, Proposed Addition
		02/07/03	Hydro-Geo Consultants, Inc.	Preliminary Geologic Engineering Assessment
		02/21/03	ADCO Engineering	Revised Soil and Foundation Investigation, Proposed Addition
		05/14/03	ADCO Engineering	Response to Town Comments, Proposed Addition
		10/27/04	ADCO Engineering	Update of Geotechnical Investigation Report, Proposed Addition
23A	SKYWOOD WAY			
	40 Skywood Way	11/21/80	Terrasearch, Inc.	Geologic Investigation, Proposed Residence (APN 072-035-050)
		11/01/82	Dunham & Associates	Soil Investigation, Alfred Residence
		06/02/83	William Cotton and Associates	Geotechnical Review Sheet
		09/01/83	Dunham & Associates	Plan Review, Proposed Home
		09/13/83	William Cotton and Associates	Geologic Review, Alfred Residence
		11/08/83	Dunham & Associates	Soil Engineering Recommendations, Proposed Pool
		11/09/83	William Cotton and Associates	Geotechnical Review Sheet

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		12/02/83	William Cotton and Associates	Geotechnical Review, Algrid Swimming Pool
	65 Skywood Way	05/07/01	Cleary Consultants, Inc.	Geotechnical Investigation, Residence Addition
	85 Skywood Way	04/07/09	BAGG Engineers	Limited Geotechnical Investigation, Wood Deck Foundations
	90 Skywood Way	08/30/93	Fowler & Associates	Geotechnical Investigation, Proposed Swimming Pool
		02/07/94	Fowler & Associates	Geotechnical Consultation and Plan Review
		06/02/05	Fowler & Associates	Geotechnical Consultation, Proposed Addition
		03/29/06	Fowler & Associates	Construction Observation, Proposed Addition
	95 Skywood Way	03/16/88	Cleary Consultants, Inc.	Soil and Geologic Investigation, Proposed Additions, William New Residence
			William Cotton and Associates	Geotechnical Skywood Way
		11/28/88	Cleary Consultants, Inc.	Soil and Geologic Investigation, Proposed Accessory Living Quarters and Carport
		4/0/1989	Nelle Ingraham Associates, Inc.	Structural Calculations - New Residence - Phase I, Accessory Living Quarters
		05/31/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, New, #7265
		06/29/89	Cleary Consultants, Inc.	Supplemental Geotechnical Engineering Analyses, Slope Stability of Dormant Slide
		07/12/89	Nelle Ingraham Associates, Inc.	Structural Calculations, New Residence
		07/14/89	Cleary Consultants, Inc.	Evaluation of Dormant Slide Stability
		07/24/89	Cleary Consultants, Inc.	Supplemental Geologic and Geotechnical Review, New, #7265
		08/04/89	Jacobson Silverstein Winslow, Architects	Geologic and Geotechnical Review, New, #7265
		08/23/89	William Cotton and Associates	Supplemental Geologic Review, New, PA #7265
		01/15/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		02/05/90	Cleary Consultants, Inc.	Supplemental Geotechnical Letter, William New Residence - Phase 2 Main House Addition
		02/07/90	Cleary Consultants, Inc.	Analyzed Profiles for Stability Calculations, Main House Addition
		02/12/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		02/20/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		02/27/90	Cleary Consultants, Inc.	Main Residence and Detached Studio/Garage Addition, New Residence
		05/10/90	Hydro-Geo Consultants, Inc.	Proposed Addition to a Single-Family Residence
		05/15/90	William New, Jr., MD, PhD	Third Party Geotechnical Review, Extension of Main Residence with Detached Garage/Office, William New, PA #7617
		06/07/90	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, New, Main Residence and Detached Studio/Garage, PA #7617
		06/15/90	Cleary Consultants, Inc.	Supplemental Geotechnical Response, Additions to Main Residence and Detached Studio/Garage, William New Residence
		08/21/90	Cleary Consultants, Inc.	Progress Report, Soil Engineering Services During Site Grading and Foundation Installation Phases, House and Garage Additions
	100 Skywood Way	03/26/75	William F. Jones	Soil Investigation, Proposed Spiller Residence, (APN 075-035-110)
		08/31/00	Upp Geotechnology, Inc.	Reconnaissance Geologic and Geotechnical Investigation, Addition to Residence, Bourgeois Property
		06/29/07	Upp Geotechnology, Inc.	Addendum Geotechnical Investigation and Plan Review, New Deck, Bourgeois Property
23A	SMOKE TREE LANE			
	20 Smoke Tree Lane	01/07/97	Freeman-Kern Associates, Inc.	Fault Investigation, Baldwin Property
		02/26/99	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Lands of Baldwin
	25 Smoke Tree Lane	07/15/05	Romig Engineers, Inc.	Geotechnical Investigation, New Horse Barn
	57 Smoke Tree Lane	09/16/91	Nordmo Associates, Inc.	Geotechnical Investigation Report, Property Improvements & Remodeling
			William Cotton and Associates	Geotechnical Review Sheet
		12/04/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Hurlbut Additions, BP #8592, 8593, and 8602
		12/05/91	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
		12/09/91	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
		01/30/92	William Cotton and Associates	Memo with Comments on 1/30/92 Nordmo letter
		01/30/92	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
		01/31/92	Nordmo Associates, Inc.	Plan Review, Property Improvement/House Remodeling
		02/14/92	William Cotton and Associates	Supplemental Geotechnical Review, Hurlbut Additions, BP #8592, 8593, and 8602
		01/24/06	Nordmo Associates	Geotechnical Engineering Report, Proposed Master Bath Addition
	73 Smoke Tree Lane	02/25/09	Murray Engineers, Inc.	Geotechnical Investigation, Proposed Pool House/Guesthouse
23A	SOMERSET PLACE			
	10 Somerset Place	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision
		09/17/89	Cleary Consultants, Inc.	Estimated Maximum and Repeatable Ground Accelerations, Somerset Place Homes
		01/08/90	Alan Kropp & Associates, Inc.	Foundation Investigation, Rafanelli Residence
		05/11/90	Alan Kropp & Associates, Inc.	Plan Review, Rafanelli Residence
		05/18/93	Alan Kropp & Associates, Inc.	Geotechnical Update, Lot #2
		06/30/93	Alan Kropp & Associates, Inc.	Plan Review, Landes Residence
		08/05/93	Darwin Myers Associates	Geologic Hazards Reconnaissance
	14 Somerset Place	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision on Godetia Drive
			William Cotton and Associates	Geotechnical Review Sheet
		03/15/89	Kwan & Associates	Structural Calculations
		09/15/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Fieber, PA #7381, Simba Lot 3

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		09/20/89	The Russell Group, Architects	Site Plan with annotations
		09/25/89	Cleary Consultants, Inc.	Review of Grading and Foundation Plans, Lot 3, Somerset Place Luxury Homes
		09/26/89	Cleary Consultants, Inc.	Review of Landscaping Plans, Lot 3, Somerset Place Luxury Homes
		09/27/89	William Cotton and Associates	Supplemental Geotechnical Review, Fiebe, PA #7381, Simba Lot 1
	18 Somerset Place	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigation, Lands of Simba Group, Five Lot Subdivision on Godetia Drive
			William Cotton and Associates	Geotechnical review Sheet
		03/27/89	Kwan & Associates	Structural Calculations
		09/12/89	Cleary Consultants, Inc.	Review of Foundation Plan, Lots 4 and 5, Somerset Place
		09/15/89	William Cotton and Associates	Geologic and Geotechnical Review, Girouard, Lot 4 Simba Subdivision, PA #7373
		09/25/89	Cleary Consultants, Inc.	Review of Grading Plans, Lots 4 and 5, Somerset Place
		09/26/89	Cleary Consultants, Inc.	Review of Landscape Plans, Lots 4 and 5, Somerset Place Luxury Homes
		09/27/89	William Cotton and Associates	Supplemental Geotechnical Review, Girouard, Lot 4 Simba Subdivision, PA #7374
		09/29/89	Cleary Consultants, Inc.	Review of Grading Plans, 9/28/89 Revision, Lots 4 and 5, Somerset Place
		10/16/89	William Cotton and Associates	Supplemental Geotechnical Review, Girouard, Lot 4 Simba Subdivision, PA #7374
	23A 22 Somerset Place	10/06/87	Cleary Consultants, Inc.	Soil and Foundation Investigations, Lands of Simba Group, Five Lot Subdivision on Godetia Drive
			William Cotton and Associates	Geotechnical Review Sheet
		03/24/89	Kwan & Associates	Structural Calculations
		09/12/89	Cleary Consultants, Inc.	Review of Foundation Plans, Lots 4 and 5, Somerset Place
		09/15/89	William Cotton and Associates	Geologic and Geotechnical Review, Hirsch, Lot 5 Simba Subdivision, PA #7374(3)
		09/25/89	Cleary Consultants, Inc.	Review of Grading Plans, Lots 4 and 5, Somerset Place
		09/26/89	Cleary Consultants, Inc.	Review of Landscape Plans, Lots 4 and 5, Somerset Place
		09/27/89	William Cotton and Associates	Supplemental Geotechnical Review, Hirsch, Lot 5 Simba Subdivision, PA #7373
		09/29/89	Cleary Consultants, Inc.	Review of Grading Plans, 9/28/89 Revision, Lots 4 and 5, Somerset Place
		10/16/89	William Cotton and Associates	Supplemental Geotechnical Review, Hirsch, Lot 5 Simba Subdivision, PA #7373
	24 SOUTHDAL WAY			
	605 Southdale Way	09/11/89	Applied Earth Sciences Consultants	Summary Percolation Tests, 1.3 Acres addressed as 611 Southdale Way (APN 068-291-070)
		02/21/91	Applied Earth Sciences Consultants	Soil and Geologic Investigation, 1.3 Acres addressed as 611 Southdale Way (APN 068-291-070)
		06/17/93	Applied Earth Sciences Consultants	Conceptual Site Plan Review, Two Lots on Southdale Way (APN 068-291-090 and APN 068-291-100)
		09/22/93	Applied Earth Sciences Consultants	Geotechnical Review of Revised Conceptual Site Plan, Two Lots on Southdale Way (APN 068-291-090 and APN 068-291-100)
		05/01/96	Applied Earth Sciences Consultants	Site Plan Review and Supplemental Field Investigation, Proposed On-Site Sewage Disposal System
		08/29/97	Applied Earth Sciences Consultants	Supplemental Geotechnical Report
		09/29/97	Applied Earth Sciences Consultants	On-Site Sewage Disposal System Design, Construction and Maintenance
		various	various	Town Council Agenda, November 5, 1996 Meeting
	605 Southdale Way	various	various	Town Council Agenda, February 11, 1997 Meeting
	636 Southdale Way	07/20/00	Nordmo Associates	Geotechnical Investigation, Proposed Residence
		06/21/01	Kern Consulting, Inc.	Geologic Investigation
		08/14/01	Nordmo Associates	Supplement and Plan Review, Proposed Perkins/Reed Residence
		09/24/01	Nordmo Associates	Supplement Two and Plan Review, Proposed Perkins/Reed Residence
		04/04/05	Nordmo Associates	Report Update, Proposed Residence
		06/13/05	Nordmo Associates	Geotechnical Review
		08/20/07	Nordmo Associates	Building Plan Review, Replacement Retaining Wall
		11/27/07	Nordmo Associates	Proposed Retaining Extension Downhill of Structures
		03/08/08	Nordmo Associates	Geotechnical Investigation of Slope Western Side of Driveway/Residence
		03/10/08	Nordmo Associates	Supplemental Geotechnical Investigation of Slope Western Side of Driveway/Residence
		05/24/08	Nordmo Associates	Response to Town Memo, Proposed Retaining Walls
		07/22/08	Nordmo Associates	Regarding Proposed Retaining Walls
	651 Southdale Way	02/28/06	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Addition
	659 Southdale Way	03/22/02	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Addition
		09/29/03	Dunham & Associates	Geotechnical Engineering Recommendations, Proposed Pool
	659 Southdale Way	10/16/03	Neil O. Anderson & Associates, Inc.	Freidenrich Residence Pool
	711 Southdale Way	05/23/06	JF Consulting, Inc.	Geotechnical Study, New Driveway, Lands of Milne
	24 SOUTHGATE DRIVE			
	11 Southgate Drive	02/26/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
		08/04/08	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Site Improvements
		09/24/08	Earth Investigations Consultants	Geotechnical Review, Proposed Garden Retaining Wall
		04/18/11	Earth Investigations Consultants	Geotechnical Update, Proposed Backyard Landscape Improvements
	24 SOUTHVIEW WAY			
	North of Southview Way in RC	03/08/88	Edward W. Baca	Pre-Zoning Map
			William Cotton and Associates	Geotechnical Review Sheet
		04/11/88	William Cotton and Associates	Preliminary Annexation and Pre-Zoning, Vicinity of Southview Way and Summit Way

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	746 Southview Way	04/24/08	ACRE Soil Engineering	Soil and Foundation Investigation, Residential Additions
		05/14/08	ACRE Soil Engineering	Foundations for the Storage Addition, Residential Additions
24	STADLER DRIVE			
	1, 10, 16 and 18 Stadler Drive	01/14/77	Cooper Clark & Associates	Compilation to Reports & Correspondence, Proposed Sites for Residences, 28-Acre Portion of Stadler Subdivision
		07/19/76	Cooper Clark & Associates	Geotechnical Investigation, Proposed Sites for Residences, Portion of Stadler Subdivision
		10/08/76	Cooper Clark & Associates	Response to 7/16/76 Review (missing)
		12/10/76	Cooper Clark & Associates	Supplemental Consultation, Proposed Sites for Residences, 28-Acre Portion of Stadler Subdivision
		01/07/77	Cooper Clark & Associates	Comments on Leighton and Associates Memo Dated 12/29/76
		01/14/77	Cooper Clark & Associates (John O'Rourke)	Septic Tank Drainfields, Proposed Sites for Residences, 28-Acre Portion of Stadler Subdivision
	10 Stadler Drive	08/24/76	Geo-Ekta Laboratories	Response to Review by Leighton and Associates
	16 Stadler Drive	10/22/03	Signa Prime Geosciences, Inc.	Geotechnical Study, Proposed Detached Structure
	50 Stadler Drive	06/23/93	JCP Geologists - Engineers	Soil and Foundation Services, Proposed Home Reconstruction and Garage-Guest House Structure
	60 Stadler Drive	05/06/05	JF Consulting, Inc.	Geotechnical Investigation, Lands of Stronck, Remodel & Additions to Residence
		12/21/07	JF Consulting, Inc.	Geotechnical Comments, Proposed Spa and Low Retaining Walls, Lands of Stronck
	70 Stadler Drive	05/12/97	Fowler & Associates	Geotechnical Investigation, Proposed Remodeling
	75 Stadler Drive	02/24/04	Romig Engineers, Inc.	Geotechnical Investigation, Residence Addition
	99 Stadler Drive	12/08/03	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Deck Remodel
		07/21/04	Murray Engineers, Inc.	Geotechnical Investigation, Weiss Residence Addition
		09/13/05	Murray Engineers, Inc.	Supplemental Recommendations, Weiss Residence
	115 Stadler Drive	11/15/05	Murray Engineers, Inc.	Geotechnical Investigation, Carter Residence Improvements
		02/10/06	Murray Engineers, Inc.	Supplemental Information, Geotechnical Investigation, Carter Residence Improvements
	125 Stadler Drive	05/30/76	Howard F. Donley & Associates	Geologic-Soils Investigation, Proposed Single-Family Residence, Lot 3, Section 103, Skywood Acres, Sky Londa No. 1
		05/30/76	Howard F. Donley & Associates	Design details and Structural Calculations
		10/26/76	Howard F. Donley & Associates	Clarification, Geologic-Soils Investigation Report dated May 30, 1976
		06/01/77	Town of Woodside	Review Comments
		06/09/77	Howard F. Donley & Associates	Response to Town Review Comments
		06/30/77	Town of Woodside	Review of Response to Town Review Comments
24A	STILL CREEK ROAD			
	3 Still Creek Road	06/30/98	Michelucci & Associates, Inc.	Temporary Clearing of Access Driveway
		07/09/98	Michelucci & Associates, Inc.	Geotechnical Investigation, Landslide Problem
		06/21/00	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Retaining Wall and Existing Deck Foundation Improvement
	7 Still Creek Road			
SOME OF THE FOLLOWING REPORTS ADDRESS THE ORIGINAL 4-LOT SUBDIVISION AND/OR 35 STILL CREEK ROAD (LOT 4) - SEE ALSO 1/14/77 COOPER CLARK & ASSOCIATES WITH STADLER DRIVE				
INCLUDES COTTON AND ASSOCIATES FILE MATERIALS NOT INDIVIDUALLY REFERENCED FOR 45 STILL CREEK AND FOR THE 4-LOT SUBDIVISION (ID 228)				
	45 Still Creek Road	07/19/76	Cooper-Clark & Associates	Geotechnical Investigation, Proposed Sites for Residences, Portion of Stadler Subdivision
		pre 8/19/76	Cooper-Clark & Associates	Proposed Subdivision Parcel D (APN 075-020-01 and 075-020-09)
		08/19/76	Leighton and Associates	Review of pre 8/19/76 report
		10/08/76	Cooper-Clark & Associates	Response to 7/16/76 Review (missing)
		12/10/76	Cooper-Clark & Associates	Supplemental Consultation, Proposed Sites for Residences, 28-Acre Portion of Stadler Subdivision
		12/29/76	William Cotton and Associates	Review of 12/10/76 Report
		12/29/76	Leighton and Associates	Review of 12/10/76 Report
		02/03/77	Cooper-Clark & Associates	Review of Supplemental Data, Dr. New, et al. Property, Portion of Stadler Subdivision
		02/22/77	Leighton and Associates	Review of 2/3/77 Report
		06/17/77	George L. Quick	Engineering Geologic Investigation of Access Road and Proposed Building Sites, Lots 2 and 3, Lands of Seitle, Et Al
		06/28/77	Leighton and Associates	Review of pre 6/28/77 Report
		07/14/77	George L. Quick	Memo Response to 7/28/77 Review by Leighton and Associates
		07/20/77	Cooper-Clark & Associates	Letter Response to 6/28/77 Review by Leighton and Associates
		03/31/82	Cooper-Clark & Associates	Consultation Services, Review of Revised House and Garage Locations, Lot 4 (3), Land Division #228
		08/16/77	Leighton and Associates	Review of 7/14/77 memo and 7/28/77 reports
		04/15/91	Hydro-Geo Consultants, Inc.	Preliminary Review of Geologic Conditions, Lot 3, Lands of Seitle
		05/16/91	William Cotton and Associates	Review of 4/15/91, 7/19/76, and 6/17/77 reports
		09/12/95	Romig Consulting Engineers	Workscope for Geotechnical Services, Proposed Burton Residence
		10/10/95	Romig Consulting Engineers	Field, Laboratory and Stability Results, Proposed Burton Residence
		10/20/95	Romig Consulting Engineers	Geotechnical Investigation, Proposed Burton Residence
		02/02/96	Louis A. Richardson	Supplemental Geologic Information for Geotechnical Investigation, Proposed Burton Residence
		02/07/96	Romig Consulting Engineers	Supplemental Geologic and Geotechnical Information, Proposed Burton Residence
		04/23/96	Romig Consulting Engineers	Supplemental Geologic and Geotechnical Information, Proposed Burton Residence
		04/25/96	Louis A. Richardson	Additional Supplementary Geologic Information for Geotechnical Investigation, Proposed Burton Residence
		07/17/96	Louis A. Richardson	Proposed Septic Drainfield Site, Burton Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
24A	STOCKBRIDGE AVENUE			
	2120 Stockbridge Avenue	06/26/00	J. Yang and Associates	Geotechnical Site Investigation, Proposed Residence
		04/30/01	J. Yang and Associates	Geotechnical Review, Proposed Residence
	2170 Stockbridge Avenue	07/01/96	Fowler & Associates	Geotechnical Investigation, Two Proposed Single Family Residences
	2180 Stockbridge Avenue	07/01/96	Fowler & Associates	Geotechnical Investigation, Two Proposed Single Family Residences
	2210 Stockbridge Avenue	01/30/96	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Additions and House Remodel
		02/13/97	Michelucci & Associates, Inc.	Supplemental Recommendations and Design Criteria, proposed Swimming Pool and Master Bedroom Wood Deck
	2220 Stockbridge Avenue	07/21/92	William Cotton and Associates	Geotechnical Investigation, Pivnicka Residence
		10.17/05	Earth Mechanics Consulting Engineers	Geotechnical Reconnaissance, Planned Pool
		01/17/07	Earth Mechanics Consulting Engineers	Geotechnical Consultation, Planned Improvements
	2290 Stockbridge Avenue	03/08/02	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Upgrade
	2298 Stockbridge Avenue	06/30/05	Eddy's Engineering & Construction Services	Soil Investigation, Including Geologic Reconnaissance and Recommendations for Construction of Retaining Walls
		07/15/09	Romig Engineers, Inc.	Site Improvements
25	SUMMERHILL LANE			
	110 Summerhill Lane	07/08/96	Earth Mechanics Consulting Engineers	Geotechnical Reconnaissance Report, Planned Additions and Improvements to Residence
		09/26/96	Earth Mechanics Consulting Engineers	Results of Exploration Program and Plan Review, Additions and Alterations
	135 Summerhill Lane	10/19/06	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Addition & Remodel
	140 Summerhill Lane	07/12/07	Murray Engineers, Inc.	Geotechnical Investigation, Residence Improvements
25	SUMMIT ROAD			
	9 Summit Road	09/27/87	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, 7 Lots (APN 076-052-001), Woodside Country Club Sub. No. 4
		10/05/87	PSC Associates, Inc.	Geotechnical Engineering Investigation, Proposed Residence and Garage, 4 Lots
		11/20/02	PSC Associates, Inc.	Review and Update of 10/5/87 Report
		10/21/02	PSC Associates, Inc.	Retaining Walls at Carver Mead Residence, Summit Road
		04/19/93	PSC Associates, Inc.	Supplemental Foundation Engineering Investigation, Proposed Retaining Walls, Mead Residence
		04/29/93	PSC Associates, Inc.	Addendum to the Foundation Recommendations
	Summit Road	01/09/81	J. Michael Cleary and Associates	Soil and Foundation Investigation, Combined Lots APN 076-052-020 and 076-082-010
		03/13/81	William Cotton, Town Geologist	Geotechnical Review Sheet
		03/23/81	William Cotton, Town Geologist	Review Comments
		11/21/05	Pacific Geotechnical Engineering	Geologic Feasibility Investigation, Mead/Smith Property APN 076-052-020 and 076-082-010
		12/14/05	San Mateo County Environmental Health	Septic Test Pits
		12/15/05	Langley Hill Quarry	Perc Test Results
		05/26/05	Woodside Fire Protection District	Requirements
				Easement Grant
		06/06/06	Stoecker and Northway Architects, Inc.	APN 076-052-020 and 076-082-010
		06/15/06	Town	Pre-Application Geology Department Comments
	135 Summit Road	09/17/02	Pacific Geotechnical Engineering	Geologic and Geotechnical Investigation, Garfinkle Residence
	145 Summit Road	08/31/00	Romig Engineers, Inc.	Geotechnical Investigation, Residence Remodel
25	SUMMIT SPRINGS ROAD			
	Summit Springs Road at Partition	10/01/85	William Cotton and Associates	Proposal for Geotechnical Services, Slope Monitoring and Geotechnical Evaluation of Road Distress at SST/PR Intersection
		03/13/86	William Cotton and Associates	Geologic Map and Section, SSR/PR Landslide
		03/19/86	William Cotton and Associates	Proposal for Geologic Monitoring of Landslide, SSR/PR Landslide
	450 Summit Springs Road	05/22/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed Site Improvements, Steenkamp Property
		02/18/02	GeoForensics, Inc.	Review of Drainage Plans (#3)
	460 Summit Springs Road	10/02/02	Steven A. Arnold	Deck Repair and Deck Expansion, Lonergan Residence
		05/21/03	Steven A. Arnold	Deck Repair / Expansion
	470 Summit Springs Road	05/25/77	J. Walter Hoskins	Soil Investigation
		07/11/77	Francis A. Stejer	Engineering Geology Study, Lot 9, Block, Woodside Oaks Unit No. 2 (APN 072-081-120)
		09/16/77	J. Walter Hoskins	Revised Soil Investigation
		12/30/77	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Lot 9, Block 1, Woodside Oaks Unit No. 2
		02/10/78	Town of Woodside	Review of Purcell, Rhoades & Associates report
		11/06/84	Tim J. Manzagol	Soil and Geologic Investigation

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		11/16/84	William Cotton and Associates	Landslide Repair
		11/19/84	William Cotton and Associates	Landslide Repair
		11/24/84	Town of Woodside	Memo from Town Engineer to Town Manager on Landslide Repair
		?	William Cotton and Associates	Geotechnical Review Sheet
		12/14/84	William Cotton and Associates	Preliminary Geologic and Geotechnical Review. Home Equity - Landslide Repair
	475 Summit Springs Road	07/13/73	Geo-Ekta Laboratories / Goss & Associates, Inc.	Slope Stability Analysis, Lot 8, Tract 714, Woodside Oaks II
		11/28/90	Hydro-Geo Consultants, Inc.	Preliminary Geologic Review (Lands of Wang)
		03/31/91	Frank Lee & Associates	Soil and Foundation Investigation, Proposed Two-Story Single-Home
		11/22/91	Hydro-Geo Consultants, Inc.	Supplement to Preliminary Geologic Report
		09/07/99	McLeod and Associates	35% Slope Analysis
	480 Summit Springs Road	06/28/63	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Parcels 7 (490) and 8 (480), Block 1, Tract 714
		01/13/75	Daniel J. Rhoades & Associates	Soil Report
		09/02/76	Purcell, Rhoades & Associates	Site Inspection and Consultation, 480 Summit Springs Road
		11/17/76	Soil Engineering Construction, Inc.	Slope & Structural Repairs
		11/22/76	Purcell, Rhoades & Associates	Comments on Slide Repair Design
		11/30/76	Purcell, Rhoades & Associates	Soil and Geological Engineering Report
		12/02/76	Leighton and Associates	Comments on Slide Repair
		12/06/76	Randlett & Foulk, Inc.	Slide Repair
		12/06/76	Randlett & Foulk, Inc.	Structural Calculations
		12/08/76	Leighton and Associates	Review of Revised Slide Repair
		03/13/02	Ting & Associates, Inc.	Geotechnical Investigation, Proposed Garage
		03/23/04	Ting & Associates, Inc.	Deck Recommendations, Proposed Decks
		08/30/04	Louis A. Richardson	Engineering Geologic Reconnaissance Study (APN 072-081-110)
		05/08/05	Ting & Associates, Inc.	Proposed Remodeling, Garage, and Deck Recommendations (DRAFT)
		05/08/05	Ting & Associates, Inc.	Proposed Remodeling, Garage, and Deck Recommendations
	485 Summit Springs Road	05/19/67	Crosby & Associates	Slide Repair
		07/03/68	Hawke Engineers	Soil Investigation and Consultation, Single Family Residence
		05/26/69	Technical Services Company, LTD.	Site Plan, Sections, Logs, Etc. for Proposed Design for Correction of Slide Damage
		08/22/69	Technical Services Company, LTD.	Existing Conditions, Proposed Septic Tank System
		08/26/69	Technical Services Company, LTD.	Letter to Town
		12/16/74	Civil & Construction Consultants, Inc.	Foundation Piers Boring Logs for Driveway Structure
		02/23/77	Civil & Construction Consultants, Inc.	Addition to Cramer Residence
		03/18/77	Leighton and Associates	Review of References
		03/14/83	William Cotton and Associates	Summit Springs Road - Kramer Landslide
		06/09/83	Civil & Construction Consultants, Inc.	Proposed Retaining Wall Construction Adjacent to the Public Roadway
		06/29/83	William Cotton and Associates	Geotechnical Review Sheet
		07/13/83	William Cotton and Associates	Cramer Retaining Wall
	490 Summit Springs Road	06/28/63	Gribaldo, Jacobs, Jones and Associates	Soil Investigation, Parcels 7 (490) and 8 (480), Block 1, Tract 714
		04/22/05	Upp Geotechnology, Inc.	Limited Geotechnical Investigation
	550 Summit Springs Road	11/02/78	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Lot 5, Block 3, Woodside Oaks Unit No. 2
		12/15/78	Gary L. Holmes, Architect	Site Plan with annotations
		01/05/79	William Cotton and Associates (?)	Summary of Field Review on 1/3/78
		01/26/79	William Cotton and Associates (?)	Geologic Review - Holmes Conformity
	555 Summit Springs Road	04/17/68	Cooper-Clark & Associates	Soil Investigation Report, Proposed Residence, Lot 1, Block 2, Woodside Oaks Unit 2 (APN 072-083-160)
		03/30/88	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Swimming Pool and Deck Addition, Flood Residence
	560 Summit Springs Road	11/02/78	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Lot 5, Block 3, Woodside Oaks Unit 2 (APN 072-082-050)
		04/18/02	GeoForensics Inc.	Geotechnical Investigation of Fireplace Distress, Matthews Property
	575 Summit Springs Road	05/04/77	Purcell, Rhoades & Associates	Soil and Geologic Investigation, Lot 2
		06/01/77	Town of Woodside	Review
		06/02/77	Purcell, Rhoades & Associates	Plan Review
	580 Summit Springs Road	03/31/99	American Soil Testing, Inc.	Soil and Foundation Investigation, Proposed Addition & Remodeling
		12/03/99	Hydro-Geo Consultants, Inc.	Engineering Geologic Assessment, Proposed Remodeling of Single-Family Residence
		12/22/99	American Soil Testing, Inc.	Supplemental Recommendations, Proposed Addition & Remodeling
		11/30/06	Romig Engineers, Inc.	Geotechnical Investigations, Greening Residence Addition
		06/25/07	Romig Engineers, Inc.	Geotechnical Report Update, Greening Residence Remodel
		01/19/09	Romig Engineers, Inc.	Geotechnical Recommendations, Driveway Retaining Walls
	25 600 Summit Springs Road	06/09/61	Woodward-Clyde-Sherard and Associates	Preliminary Soil Investigation, Proposed Summit Springs Subdivision
		06/16/81	Donald A Wolfe & Associates	Environmental Assessment, Summit Springs Property
		03/23/79	Howard Donley Associates, Inc.	Preliminary Terrain Analysis Report, Proposed 625 acre Housing Development, Summit Springs Property
		06/23/97	Pacific Geotechnical Engineering	Preliminary Geologic Feasibility Evaluation, Keenan Project, MPROSD Property
25A	Summit Springs Subdivision	08/04/86	William Cotton and Associates	Geotechnical Review Sheet
		08/12/10	William Cotton and Associates	Summit Springs Grading for Access Road

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		07/06/08	Brian Kangas Foulk	Map - Grading Permit Application - Summit Springs Testing Program
25A	SUNRISE DRIVE			
	105 Sunrise Drive	09/13/84	Melvin R. Hill, Inc.	Soil Investigation
			William Cotton and Associates	Geotechnical Review Sheet
		10/31/84	Baronian & Danielson	Location Plan, with annotations
		07/24/85	William Cotton and Associates	Preliminary Geologic Review and Geotechnical Investigation Evaluation, Lands of Bastei, #2730
		07/08/89	Melvin R. Hill, Inc.	Plan Review
		09/28/89	SOHA	Structural Calculations
		08/10/89	William Cotton and Associates	Review Comments - Soil Investigation (9/84)
		08/14/89	Melvin R. Hill, Inc.	Response to Town Review Comments
		0/0/89	William Cotton and Associates	Geotechnical Review Sheet - Basti
	125 Sunrise Drive	09/08/87	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Clausen
			William Cotton and Associates	Geotechnical Review Sheet
		10/26/87	Soil Engineerng Construction, Inc.	Retainin Wall Calculations
		11/02/87	Soil Engineering Construction, Inc.	Site Plan
		11/16/87	Upp Geotechnology, Inc.	Review of Retaining Wall Plans, Clausen Residence
		11/24/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Causen Landslide Mitigation, PA #4443
				Photographs
		12/17/87	Upp Geotechnology, Inc.	Addendum Geotechnical Investigation of Landslide, Lands of Clausen
		01/11/88	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Clausen Landslide Mitigation, PA #4443
		03/24/88	Upp Geotechnology, Inc.	Construction Monitoring, Drainage System, Landslide Mitigation, Clausen Residence
	125 Sunrise Drive	05/04/89	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Addition to Stockdale Residence
	140 Sunrise Drive	01/01/85	William Cotton and Associates	Preliminary Geologic Review, Anderson Pool, Variance 368
		01/11/85	Lifetime Pools	Site Plan, with annotations
		01/21/85	William Cotton and Associates	Geotechnical Review Sheet
	140 Sunrise Drive	02/22/90	Baldwin-Wright, Inc.	Geotechnical Investigation, Proposed Addition
	150 Sunrise Drive	09/30/97	Romig Consulting Engineers	Geotechnical Investigation, Braunstein Residence Slide Repair
		12/16/93	Nielsen Geotechnical Incorporated	Soil Report, Residential Additions
	155 Sunrise Drive	09/18/88	Upp Geotechnology, Inc.	Geotechnical Investigation, Slope Stabilization
		09/18/02	Upp Geotechnology, Inc.	Geotechnical Investigation Report Update and Plan Review, Muller Property
		10/22/02	Upp Geotechnology, Inc.	Response to Town Comments and Supplemental Plan Review, Slope Stabilization
		01/30/03	Upp Geotechnology, Inc.	Construction Observation, Retaining Wall and Deck, Muller Property
		12/03/04	Upp Geotechnology, Inc.	Supplemental Recommendations, Deck Piers, Muller Property
		12/22/04	Upp Geotechnology, Inc.	Supplemental Recommendations, Deck Piers, Muller Property
	160 Sunrise Drive	07/25/95	Earth Investigations Consultants	Geotechnical Consultation, Garage Foundation Rehabilitation
		07/31/95	Earth Investigations Consultants	Geotechnical Consultation, Proposed Leachfield Rehabilitation
		08/08/95	Earth Investigations Consultants	Geotechnical Consultation, Addendum to Report, Proposed Leachfield Rehabilitation
		08/31/95	Nielsen Geotechnical Incorporated	Geotechnical Review, Leach Field Repair - Deep Sumps
	160 Sunrise Drive	09/12/95	Nielsen Geotechnical Incorporated	Response to Town's Review, Deep Sumps Septic System
	165 Sunrise Drive	04/17/07	Applied Earth Investigations Consultants	Single Family Residential Site Development Feasibility (Geotechnical) - Lot 9
	170 Sunrise Drive	09/20/76	Terrasearch, Inc.	Soil Investigation, Proposed Additions
	175 Sunrise Drive	08/11/80	Nordmo Associates	Soil Engineering Services, Proped Recreational Facility
25A	TANDIN LANE			
	1502 Tandin Lane	03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation
		01/22/88	William F. Jones, Inc.	Site Investigation, Proposed Residence, Corner of Tandin Lane and Portola Road
		12/02/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kelley, Permit Application #5073
		01/10/89	William F. Jones, Inc.	Responses to Town Geologist's Review Letter
		02/14/89	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Kelley, Permit Application #5073
	1510 Tandin Lane	03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation
	1518 Tandin Lane	03/16/77	Purcell, Rhoades & Associates	Geotechnical Investigation
25A	TODO EL MUNDO			
	100 Todo El Mundo	02/05/73	Crosby & Associates	Foundation Investigation, Jacobs Site, Oakhaven Way and Woodside Drive
		02/15/73	Town of Woodside	Question to Town Attorney
		02/21/73	Jon C. Cummings, Town Geologist	Review of 2/5/73 CA Addendum Report
		03/20/73	Joe Crosby & Associates	Addendum to Report Dated February 5, 1979, Supplemental Geologic Investigation
		4/0/78	Edwin H. Smith	Preliminary Map, Resubdivision of Parcel 1, Land Division Map No. 189
		04/28/73	Jon C. Cummings, Town Geologist	Review of 4/28/73 JCA Report
		06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		07/25/78	Leighton and Associates, Inc.	Review of 6/29/78 PRA report
		08/08/78	William Cotton and Associates	Geotechnical Review - Coleman Land Division
	150 Todo El Mundo	06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision
		11/11/85	Michael S. Helm - Architect	Site Plan, with annotations
		03/21/86	Washington - Jensen & Associates	Structural Calculations for Residence
		04/23/86	Purcell, Rhodes & Associates	Soil Engineering and Geology Report Update, Proposed Residence
		06/12/86	William Cotton and Associates	Geotechnical Review Sheet
		06/19/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Erlin
		05/14/87	Purcell, Rhodes & Associates	Plan Review, Proposed Swimming Pool
		07/02/87	William Cotton and Associates	Supplemental Review, Erlin Pool, P.A. #4161
	200 Todo El Mundo	06/29/78	Purcell, Rhodes & Associates	Geotechnical Hazard and Preliminary Soil Foundation Investigation, Proposed Four-Parcel Resubdivision
	210 Todo El Mundo	03/11/85	Jo Crosby & Associates	Geotechnical Investigation, Proposed Addition to Garage
		11/14/02	Soil Engineering Construction Inc.	Soil and Foundation Report, Home Remodeling
		07/24/03	Soil Engineering Construction Inc.	Minimum Geotechnical Report, Remodeling Work
		09/29/03	Soil Engineering Construction Inc.	Geotechnical Engineering Review
	220 Todo El Mundo	06/23/89	Shen & Associates	Geotechnical Investigation, Proposd Addition
		04/24/08	Sigma Prime Geosciences, Inc.	Geotechnical Study, Merwin Property
		03/13/09	Sigma Prime Geosciences, Inc.	Geotechnical Study, Merwin Property
	220 Todo El Mondo	03/18/09	Sigma Prime Geosciences, Inc.	Response Letter, Remodel
	230 Todo El Mundo	12/12/01	Romig Engineers, Inc.	Geotechnical Investigation, Upton Residence
		10/10/03	Romig Engineers, Inc.	Supplemental Recommendations, Residence Addition
25A	TOYON COURT			
	103 Toyon Court	12/03/96	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
		03/04/97	Earth Investigations Consultants	Supplemental Geotechnical Parameters, Proposed Foundation Retaining Wall, Room Addition
		01/14/98	PGSoils, Inc.	Geotechnical Investigation, Proposed Additions
		04/14/99	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Remodel
		07/10/01	Earth Investigations Consultants	Geotechnical Plan Review, Proposed Addition
		09/04/01	Earth Investigations Consultants	Supplemental Geotechnical Information, Seismic Design Parameters, Residential Remodel
		09/17/01	Earth Investigations Consultants	Geotechnical Update and Plan Review
	115 Toyon Court	05/23/84	Earth Systems Consultants	Summary Report - Geotechnical Study, Adams Residence
		07/23/84	William Cotton and Associates	Geotechnical Review Sheet
		07/27/84	William Cotton and Associates	Preliminary Geologic/Geotechnical Review, Adams Residence - Remedial Repairs
		08/06/84	Earth Systems Consultants	Response to Review Consultants Comments, Adams Residence
		08/16/84	William Cotton and Associates	Geologic Review, Adams Residence - Remedial Repairs
		08/20/84	Earth Systems Consultants	Response to Review Consultants Comments Letter of August 16, 1984
		08/23/84	William Cotton and Associates	Supplemental Geologic/Geotechnical Review, Adams Residence - Remedial Repairs
		01/10/85	Upp Geotechnology	Geotechnical Investigation of Distressed Property, Adams Residence
		04/18/85	Harrison, Teasley & Associates, Inc.	Structural Calculations, Adams Residence
		05/10/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review, Adams Repairs for Distressed Residence, APN 73-033-28
	118 Toyon Court	12/26/95	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Addition
25A	120 Toyon Court	10/29/89	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Addition
26	TRAIL LANE			
	20 Trail Lane	02/15/06	Murray Engineers, Inc.	Preliminary Fault Location Evaluation
	30 Trail Lane	02/02/77	Purcell, Rhoades & Associates	Geotechnical Hazard and Soil Foundation Investigation, Proposed New Structures
		09/12/00	Louis A Richardson	Fault Trenching Investigation
		09/14/00	Nielsen Geotechnical Incorporated	Transmittal of 9/12/00 report
		08/28/02	Nielsen Geotechnical Incorporated	Soil Report
		07/03/03	Nielsen Geotechnical Incorporated	Recommendations, Marks House
		07/17/03	Nielsen Geotechnical Incorporated	Geotechnical Review Response
		07/29/03	Nielsen Geotechnical Incorporated	Geotechnical Review Response
		08/11/03	Northwest Hydraulic Consultants	100-Year Flood Elevations
		08/28/03	Nielsen Geotechnical Incorporated	Soil Report, New Marks House
		01/08/04	RJ Dalley Construction Co.	Settlement Monitor Log
		09/16/04	Murray Engineers Inc	Supplemental Geotechnical Recommendations, Marks Swimming Pool
26	TRIPP COURT			
	10 Tripp Court	04/26/00	Nielsen Geotechnical Incorporated	Soil Report
	30 Tripp Court	06/02/80	Howard Donley Associates, Inc.	Site Investigation, Residential Swimming Pool

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		06/12/80	William Cotton and Associates	Review of Geotechnical Letter report - Sudano Pool Site
		07/21/80	Howard Donley Associates, Inc.	Soil Investigation, Swimming Pool
		08/19/80	William Cotton and Associates	Geotechnical Review Sheet
		08/27/80	William Cotton and Associates	Geotechnical Review Sheet
		06/08/94	JCP - Engineers and Geologists	Soil and Foundation Study, Proposed Addition and Retaining Wall
		11/29/94	GeoForensics, Inc.	Geotechnical Report, Proposed Study Addition, Bowles Residence
	35 Tripp Court	01/14/08	Murray Engineers, Inc.	Geotechnical Services, Ahern Residence
	40 Tripp Court	05/23/00	Cyme, Inc.	Geotechnical Investigation, Addition and Remodel, Begun Residence
		02/14/01	Cyme, Inc.	Geotechnical Review of Final Design Plans and Response to Town Review Comments
	45 Tripp Road	07/07/05	PGSoils, Inc.	Geotechnical Investigation, Proposed Residential Additions
	55 Tripp Court	03/17/01	Nielsen Geotechnical Incorporated	Soil Report
		08/11/03	Nielsen Geotechnical Incorporated	Construction Report, Basement Addition
	60 Tripp Court	06/29/65	San Mateo County Public Health & Welfare	Letter to Dr. Daniel Liebovitz
		04/20/77	Soil Engineering Construction, Inc.	Soil and Geologic Investigation
		05/11/77	Leighton and Associates	Review of 4/20/77 SEC report
			Soil Engineering Construction, Inc.	Logs of Test Pits 1 dn 2
	65 Tripp Court	08/17/94	Nielsen Geotechnical Incorporated	Soil Report
26	TRIPP ROAD			
	3301 Tripp Road	05/15/91	Michelucci & Associates, Inc.	Fault-Hazard Investigation, Proposed Garage-Guest House
		08/19/96	Clearly Consultants, Inc.	Fault Location Investigation, Residence Addition
		01/14/97	Nielsen Geotechnical Incorporated	Soil Report
	3366 Tripp Road	04/13/89	Design Plus	Site Plan with annotations
			William Cotton and Associates	Geotechnical Review Sheet
		06/07/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Pederson #7284
	3530 Tripp Road	08/02/79	PSC Associates, Inc.	Geologic and Soil Engineering Investigation, Proposed Swimming Pool
		08/28/00	Nielsen Geotechnical Incorporated	Soil Report
		09/05/02	Nielsen Geotechnical Incorporated	Construction Report
	3573 Tripp Road	10/01/70	County of San Mateo	Letter on Percolation Test Results
		05/15/71	William G. Rummel	2 letters with this date on Septec Systemtest Results
		04/25/75	Daniel J. Rhoades & Associates	Soil and Geologic Hazard Study, Portion of Lot 4, tract 3, greer Partition
		09/24/76	Purcell, Rhoades & Associates	Review of 4/25/75 Report
		10/04/76	Town of Woodside	Review of 4/25/75 and 9/24/76 Reports
		11/19/76	Town of Woodside	Review of Revised Building Location
		02/28/77	Purcell, Rhoades & Associates	Fault Location on a Portion of Lot 4, Tract 3, Greer Partition (APN 072-141-030)
		3/0/77	Fisher Land Surveying	Preliminary Map
		03/22/77	Town of Woodside	Fault Location - Portion of Lot 4, Tract 3, Greer Partition
		09/06/83	Purcell, Rhoades & Associates	Soil and Geologic Study, APN 072-141-030
		03/20/85	Purcell, Rhoades & Associates	Soils Report Update (APN 072-141-030)
		04/02/85	Purcell, Rhoades & Associates	Plam Review - APN 072-141-030
		04/09/85	William Cotton and Associates ?	Geotechnical Review Sheet
		04/12/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review
		04/30/85	Purcell, Rhoades & Associates	Plan Review Update - APN 072-141-030
		05/14/85	William Cotton and Associates ?	Notes on Fault Trench Inspection
		05/16/85	William Cotton and Associates ?	Notes on Fault Trench Inspection
		0/0/85	William Cotton and Associates	Photographs of Fault Trench
				Plat Plan, with annotations
		06/17/85	Purcell, Rhoades & Associates	Fault Evaluation Study (APN 072-141-030)
		07/03/85	William Cotton and Associates	Supplemental Geologic Review, Lands of Bullock (Schlosser), Fault Investigation
		08/13/03	Earth Investigations Consultants	Soil Investigation, Existing Carriage House
	3577 Tripp Road	08/23/74	Geolabs - Northern California, Inc.	Magnetometer and Subsurface Investigation, Portion of Lot 4, Tract 3
		09/10/74	Town of Woodside	Review of Geolabs Report
		09/24/74	Town of Woodside	Review of Geolabs Report
		10/16/74	Town of Woodside	Approval Letter
	3585 Tripp Road	06/06/00	Romig Engineers, Inc.	Geotechnical Investigation, Witter Residence Addition
	3590 Tripp Road	05/24/00	John H. Dailey	Geotechnical Investigation, Proposed Residential Additions
		09/27/00	John H. Dailey	Response to Town Comments
	3600 Tripp Road	04/07/99	Hydro-Geo Consultants, Inc.	Geotechnical Report, Proposed Addition, Existing Residence & Swimming Pool
		04/27/11	PGSoils, Inc.	Geotechnical Conditions, Fox Residence Remodeling

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	3615 Tripp Road	08/16/10	Romig Engineers, Inc.	Geotechnical Investigation, Pilch Residence Addition
	3635 Tripp Road	10/27/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Pool and Pool House
		06/04/02	Earth Investigations Consultants	Geotechnical Site Review, Proposed Garage Expansion
		01/19/09	Earth Investigations Consultants	Geotechnical Investigation, Proposed Covered Porch
	3660 Tripp Road	12/14/00	Romig Engineers, Inc.	Geotechnical Investigation, Patterson Residence Addition
		05/19/09	Connell Geotechnical, Inc.	Geotechnical Investigation, Dearing Residence Addition
		05/15/09	Louis A. Richardson	Engineering Geologic Reconnaissance Study
		10/05/11	Connell Geotechnical, Inc.	Supplemental Geotechnical Engineering Recommendations, Detached Accessory Structure
26	3710 Tripp Road	08/25/03	Alliance Environmental and Soil Engineering	Soil and Foundation Investigation, Residential Addition and Remodeling
		01/30/04	Alliance Environmental and Soil Engineering	Clarification, Residential Second Story Addition
26A	TUM SUDEN WAY			
	67 Tum Suden Way	12/29/89	Shen & Associates	Geotechnical Investigation, Proposed Addition and New Garage
		09/12/89	ARC Associates	Site Plan, Tum Suden Residence
			William Cotton and Associates	Geotechnical Review Sheet
		04/07/98	Earth Investigations Consultants	Geotechnical Investigation, Stoker Residence
	70 Tum Suden Way	10/16/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed New Front Porch and Deck
	71 Tum Suden Way	03/17/08	PGSoils, Inc.	Geotechnical Investigation, Proposed Wood Deck Replacement
	82 Tum Suden Way	10/03/86	Ling Chen Associates	Site Plan, with annotations
		10/12/86	SJK Structural Design	Soil and Geologic Investigation, Proposed Residence, Parcel 19 and 20, Block 602
			William Cotton and Associates	Geotechnical Review Sheet
		12/10/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kohl Residence, PA #3347
	91 Tum Suden Way	11/13/02	Earth Investigations Consultants	Geotechnical Investigation, Proposed Addition
		09/23/03	Earth Investigations Consultants	Engineering Geological Site Review, Proposed 2-Lot Residential Subdivision, Parcel B, 91 Tum Suden Way
		12/23/05	Earth Investigations Consultants	Geotechnical Investigation, Proposed Detached Garage and Driveway
26A	TURKEY FARM LANE			
	1 Turkey Farm Lane	05/05/86	TransPacific Geotechnical Engineers, Inc.	Geotechnical Investigation, Proposed Pool House and Swimming Pool, Ellison's Residence
		07/03/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Ellison Pool and Pool House
		10/11/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Pool House
		01/27/97	GeoForensics, Inc.	Report Update and Plan Review, Proposed New Pool and Spa
	25 Turkey Farm Lane	07/25/96	Earth Investigations Consultants	Geotechnical Services, Soil and Foundation Investigation, Proposed Second-Story Addition
		01/13/97	Earth Investigations Consultants	Geotechnical Services, Response to Town Comments on Soil and Foundation Investigation
	45 Turkey Farm Lane	07/21/89	Cleary Consultants, Inc.	Geotechnical and Geologic Investigation, Kitchen Addition
		07/24/98	Cleary Consultants, Inc.	Geotechnical Investigation, Pool House Addition
26A	UPENUF ROAD			
	25 Upenuf Road	05/27/86	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Parcel 076-102-040
		7/0/86	Brian Kangas Foulk & Associates	Topographic Survey, Lot 267-271 Woodside Country Club Subdivision 3, with septic system annotations
		08/07/86	County of San Mateo	Letter to Mr. Bolton
		09/15/86	County of San Mateo	Letter to Mr. Woods
		09/24/86	Upp Geotechnology	Trenching, Bolton Site
		11/06/86	Perry R. Wood	Letter to San Mateo County Department of Health Services
		12/04/86	Perry R. Wood	Letter to Mr. Bolton
		12/17/86	Upp Geotechnology	Preliminary Geotechnical Investigation, Lands of Bolton (APN 076 102 040), Old La Honda Road
			William Cotton and Associates	Geotechnical Review Sheet
		01/23/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Bolton Building Site feasibility
		06/19/87	Upp Geotechnology	Geotechnical Investigation, Lands of Bolton (APN 076 102 040), Old La Honda Road
		07/13/87	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield, Parcel 076-102-040
		07/17/87	William Cotton and Associates	Supplemental Geotechnical Review, Bolton Building Site Feasibility, APN 076-102-040
		03/22/88	Perry R. Wood	Letter to Mr. Bolton
		10/12/89	Upp Geotechnology, Inc.	Geologic Update, Lands of Perry, Old La Honda Road, APN 076 102 040
		10/0/90	Brian Kangas Foulk & Associates	Topographic Survey, Lot 267-271 Woodside Country Club Subdivision 3, with > 35% slope annotations
		02/27/90	Questa Engineering Corporation	Sewage Disposal Evaluation
		08/16/90	Upp Geotechnology, Inc.	Review of Foundation Plans, Perry Residence, Old La Honda Road, APN 076 102 040
		02/01/91	Upp Geotechnology, Inc.	Review of Foundation Plans, Perry Residence, Old La Honda Road, APN 076 102 040
		05/20/91	William Cotton and Associates	Preliminary Geotechnical Review, Perry, PA #8215
	87 Upenuf Road	01/06/78	Purcell, Rhoades & Associates	Preliminary Soils and Geologic Investigation, Proposed Pool

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		02/17/78	Leighton and Associates	Review
		04/24/78	Purcell, Rhoades & Associates	Reply to Conclusions in Review By Leighton and Associates
		06/26/78	Purcell, Rhoades & Associates	Plan Review and Request for Additional Information for Proposed Swimming Pool
		07/13/78	Leighton and Associates	Review
		09/01/71	Sandis and Associates	Contour Map
26A	UPPER LAKE ROAD			
	15 Upper Lake Road	01/15/80	Terratech, Inc.	Geologic and Geotechnical Investigation, Lands of Eldredge
		01/15/80	Terratech, Inc.	Proposed Road Improvements
		01/17/80	Terratech, Inc.	Plan Review, Lands of Eldredge
		02/14/80	William Cotton and Associates	Geologic Review - Eldridge Property
		05/20/80	Terratech, Inc.	Plan Review - Alternative Access Roads, APN 75-272-030
		05/22/80	Fischer Land Surveying	Tree Loss Estimates and Grading Quantities
		06/12/80	William Cotton and Associates	Geologic Review - Eldridge Property
		07/08/80	Terratech, Inc.	Alternate Homesite, APN 75-272-030
		08/18/80	William Cotton and Associates	Geologic Review - Eldridge Property
		05/30/85	Terratech, Inc.	Geotechnical Information - Nusbaum Residence
		07/10/85	William Cotton and Associates	Geotechnical Review Sheet - Nusbaum
		07/12/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review - Nusbaum
		08/02/85	Terratech, Inc.	Update of Geologic and Geotechnical Investigation - Nusbaum Property
		08/02/85	Hoskins Engineering, Inc.	Structural Calculations - Nusbaum Water Tank
		08/08/85	Donald W. Nusbaum	Nusbaum Property - Supplemental Geologic/Geotechnical Review
		08/26/85	William Cotton and Associates	Supplemental Geologic/Geotechnical Review - Lands of Nusbaum
		03/11/86	William Cotton and Associates	Supplemental Geologic Review - Nusbaum Water Tank Variance
	17 Upper Lake Road	12/06/77	Purcell Rhoades & Associates	Soil and Geologic Investigation
		04/03/78	Town of Woodside	Review of Soil and Geologic Investigation and Plans
		04/17/85	Frahm Elder Cannis	Site Drainage / Water Supply / Septec Tank-Leachfield Plan, with annotations
		05/01/85	various	Application to Variance Necessary to Construct a Single Family Residence APN 075-240-110
		05/02/85	William Cotton and Associates	Geotechnical Review Sheet
		05/15/85	William Cotton and Associates	Preliminary Geologic / Geotechnical Review, Lands of Thayer, Variance 376
		05/20/85	Purcell Rhoades & Associates	Addendum to Soil and Geologic Investigation
		06/02/85	Mr. Thayer	Letter to Town responding to request for additional information
		06/06/85	Town of Woodside	Review by Town Engineer
		06/09/85	Mr. Thayer	Comments on alternative schemes for new residence
		06/11/85	William Cotton and Associates	Supplemental Geologic / Geotechnical Review, Lands of Thayer, Variance 376
		06/16/85	Mr. Thayer	Letter to Town responding to request for additional information
		06/19/85	Mr. Thayer	Letter to Town responding to William Cotton and Associates review
		06/19/85	Purcell Rhoades & Associates	Alternative Site Plan Review
		07/03/85	Donald W. Nusbaum	Letter to Thayer OK road widening
		07/31/85	Frahm Elder Cannis	Upper Lake Road Improvements, Lands of Thayer
		08/23/85	Purcell Rhoades & Associates	Plan Review
		09/18/85	William Cotton and Associates	Supplemental Geologic / Geotechnical Review, Lands of Thayer
		11/01/85	Purcell Rhoades & Associates	Plan Review - Upper Lake Road Improvements
		11/15/85	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Thayer
26A	VALLEY COURT / ROAD			
	Valley Court	06/19/87	Terratech, Inc.	Geologic Feasibility Evaluation, Lands of Halperin
		09/16/88	Terratech, Inc.	Geotechnical Investigation, Lands of Halperin
	45 Valley Court	01/24/92	Louis A. Richardson	Engineering Geologic Considerations, Residential Construction (APN 073-141-220)
		02/19/92	William McMorrow	Geotechnical Engineering Evaluation, Proposed New Home Construction (APN 073-141-220)
		08/18/93	William McMorrow	Geotechnical Engineering Plan Review & Response to Review Comments on 2/19/92 Report, Single-Family Residence
		10/25/93	Louis A. Richardson	Response to Review Comments and 1/24/92 Report
	50 Valley Court	02/12/08	Romig Engineers, Inc.	Geotechnical Investigation, Medina Residence
		02/12/08	Romig Engineers, Inc.	Geotechnical Investigation, Medina Residence
		09/25/09	Romig Engineers, Inc.	Supplemental Recommendations, Medina Residence
		01/22/10	Romig Engineers, Inc.	Response to Town Comments, Medina Residence
		04/01/10	Michelucci & Associates, Inc.	Planned New Rock Walls, Medina Residence
	60 Valley Court	05/31/98	Nielsen Geotechnical Incorporated	Soil Report (APN 073-141-350)
		09/22/01	Nielsen Geotechnical Incorporated	Construction Report, Berry House and Cottage (APN 073-141-350)
		03/17/08	Murray Engineers, Inc.	Geotechnical Recommendations, New Barn & Swimming Pool
	60 Valley Court	11/25/08	Murray Engineers, Inc.	Supplemental Recommendations, Site Retaining Walls, Newton Barn
	70 Valley Court	08/31/98	Frederick Maurer, Jr.	Geotechnical Investigation, Chuter Residence
		04/19/01	Frederick Maurer, Jr.	Supplemental Report, Geotechnical Investigation, Proposed Chuter Residence Barn
26A	80 Valley Court	07/06/95	Terratech, Inc.	Geologic and Geotechnical Update and Review of Initial Foundation Plans, Proposed Dow Residence
		04/24/97	Terratech, Inc.	Geotechnical Recommendations, Proposed Dow Residence Pool and Pool House

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		10/09/01	Bay Area Geotechnical Group	Limited Geotechnical Investigation, Dow Property
27	VINEYARD HILL ROAD			
	3 Vineyard Hill Road	04/12/77 06/02/78	Cooper Clark & Associates Dunham & Associates	Investigation of Potential Geologic Hazards, Parcel 1, LD #153 Soil Investigation, Proposed Home, Parcel 3, Land Division 237 (APN 072-211-680)
	7 Vineyard Hill Road	04/12/77 4/13/96	Cooper Clark & Associates Nielsen Geotechnical Incorporated	Investigation of Potential Geologic Hazards, Parcel a, LD#153 Soil Report
	10 Vineyard Hill Road	08/08/97 09/18/97 10/17/97 07/27/99 10/09/99 03/05/00 10/11/00 various	Jo Crosby & Associates Jo Crosby & Associates Jo Crosby & Associates Applied Earth Sciences Consultants Applied Earth Sciences Consultants Applied Earth Sciences Consultants Geomatrix Consultants, Inc. provided by Applied Earth Sciences Consultants	Geotechnical Review, Planned Grading and Drainage Geotechnical Review, Planned Grading and Drainage Revised Geotechnical Analysis, Planned Grading and Drainage Geotechnical Report, Backyard Drainage Control and Landscape Pond Construction Response to Town of Woodside Questions re: Proposed Landscape Pond Response to Geotechnical Review Letter dated 1/7/00 re: Proposed Landscape Pond Hydrologic/Seismic Review, Proposed Drainage Control and Landscape Pond Attachmanrs 1 - 8 for Pond Project
	12 Vineyard Hill Road	11/15/91	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Walsh Additions/Remodel
27	VINTAGE COURT			
	1, 3, and 5 Vintage Court	03/02/70 08/07/70 08/25/70 10/20/70 10/31/70 10/12/77 03/20/78 06/06/78 8/0/78 08/15/78 08/29/78 11/06/78	Jo Crosby and Associates Ben Page Reynolds and Associates Willard Somers Ben Page Brian Kangas Foulk & Associates Terrasearch, Inc. Terrasearch, Inc. Brian Kangas Foulk & Associates William Cotton and Associates William Cotton and Associates William Cotton and Associates	Geologic Investigation, Land Division 146 Field Observations of San Andreas Fault trenches Soil Engineering and Geologic Investigation Owners Response Supplemental Comments on Observations Preliminary Site Development Plan Soils and Geologic Investigation, Goumas Property, Parcel M, Land Division Map No. 22 Percolation Test Results, Goumas Property Preliminary Map - Land Division No. 248 Review Comments on 3/20/78 report Geotechnical Reviews - Goumas Land Division Geotechnical Review - Goumas Land Division
	1 Vintage Court	07/02/01 09/09/04 12/23/04 04/12/08	GeoForensics Inc. J. Yang and Associates J. Yang and Associates J. Yang and Associates	Geotechnical Investigation, Proposed New Pool and Tennis Court Geotechnical Site Investigation, Proposed Retaining Wall Repair Geotechnical Site Investigation, Revision 1, Proposed Retaining Wall Repair Geotechnical Site Investigation, Proposed New Barn
	3 Vintage Court	05/20/85 02/20/90 05/04/90 05/22/90 08/31/90 09/13/90 09/24/90 03/04/02	Terrasearch, Inc. Terrasearch, Inc. William Cotton and Associates William Cotton and Associates Terrasearch, Inc. William Cotton and Associates Terrasearch, Inc. Wm. Jay Hammond, Cical Engineer Earth Investigations Consultants	Update of Soil Investigation, Lot 2, Soficon Way Update Geotechnical and Geological Investigation and Supplemental Recommendations, Lot 2, Soficon Way Geotechnical Review Sheet Preliminary Geologic Review, Hooper Site Development, 2 Soficon Way Supplemental Geologic Investigation, Lot 2, Soficon Way (Vintage Court) Supplemental Geologic and Geotechnical Review, Hooper, PA #7978 Grading and Foundation Plan Review, Lot 2, Soficon Way Structural Calculations, Hooper Residence, PA #7978, 2 Soficon Way Geotechnical Investigation, Proposed Residential Site Improvements
	5 Vintage Court	03/20/78 09/21/78 11/19/84 03/25/85 04/19/85 05/20/85 11/01/94 01/12/95 01/25/95 03/20/95	Terrasearch, Inc. Terrasearch, Inc. Terrasearch, Inc. Elmore Design August E. Waegmann William Cotton and Associates Terrasearch, Inc. Harlan Tait Associates Terrasearch, Inc. Harlan Tait Associates	Soil and Geologic Investigation, Goumas Property, Parcel M, Land Division Map No. 22 Addendum, Soils and Geologic Investigation, Goumas Property, Parcel M, Land Division Map No.22 Swimming Pool Recommendations, Storm Residence Site Plan Structural Calculations Preliminary Geologic Review, Storm Swinning Pool, Variance 377 Foundation Plan Review, Pejcha Residence Review - Geologic / Geotechnical Investigation, Proposed Addition Response to Geologic/Geotechnical Review and Supplemental Foundation Plan Review Review - Response to Geologic/Geotechnical Review and Supplemental Foundation Plan Review Letter, Proposed Addition
27	WARD WAY			
	2145 Ward Way	06/11/08	Murray Engineers, Inc.	Geotechnical Investigation, Foundation Improvements
	2165 Ward Way	09/22/03	William M. McMorrow	Geotechnical Engineering Evaluation & Plan Review, Proposed Masonry Block Retaining Wall
	2175 Ward Way	03/13/08	Murray Engineers, Inc.	Geotechnical Investigation, Epstein Residence Improvements
27	WEST CALIFORNIA WAY			
	710 West California Way	04/24/78 01/26/82	Purcell, Rhoades & Associates Francis A. Steiger	Engineering Geologic Study APN 068-134-010 & -060

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		05/01/84	Rick Skierka	Concept Map with annotations
		06/08/84	William Cotton and Associates	Geotechnical Review Letter
		06/14/84	William Cotton and Associates	Preliminary Geologic Review, Welz, LD 286
		07/30/84	Hallenbeck & Associates	Proposed Leach Field - Parcel 1, APN 068-134-010 & -060
		08/15/84	William Cotton and Associates	Review of Welz, LD 286
		11/08/95	Upp Geotechnology, Inc.	Soil and Foundation Investigation, Additions to Gibson Residence
		04/02/96	Upp Geotechnology, Inc.	Plan Review and Response to Woodside Town Review, Additions to Gibson Residence
		11/05/96	Upp Geotechnology, Inc.	Supplemental Soil and Foundation Recommendations, Gibson Residence
		11/20/96	Upp Geotechnology, Inc.	Plan Review, Drilled Pier Foundation, Gibson Residence
		06/28/00	Upp Geotechnology, Inc.	Update Soil and Foundation Investigation, New Swimming Pool, Elfisaway Property
	729 West California Way	08/08/05	Romig Engineers, Inc.	Geotechnical Investigation, Toddart Basement Addition
	730 West California Way	07/13/06	Treadwell & Rollo	Geotechnical Investigation, Cropper Residence
	740 West California Way	05/26/95	William Cotton and Associates	Geotechnical Investigation, Fisher Residence Additions
		03/14/02	Cotton, Shires & Associates, Inc.	Geotechnical Investigation, Proposed Swimming Pool
	756 West California Way	10/01/06	J. Yang and Associates	Geotechnical Site Investigation, Proposed New Residence
	760 West California Way	04/19/89	JCP Geologists Engineers	Soil and Foundation Serices, Proposed Residence and Swimming Pool
		06/12/89	JCP Geologists Engineers	Addendum to Soil and Foundation Study and Review of Soil and Foundation Engineering Aspects of Foundation and Grading Plans
		08/05/89	JCP Geologists Engineers	Soil and Foundation Serices, Proposed Residence
			William Cotton and Associates	Geotechnical Review Sheet
		03/20/90	JCP Geologists Engineers	Soil and Foundation Study
		04/02/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans, Proposed Residence, Lot 17
		06/11/89	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kolnes, PA-7711
	764 West California Way	04/19/89	JCP Geologists Engineers	Soil and Foundation Study, Proposed Residence and Swimming Pool
			William Cotton and Associates	Geotechnical Review Sheet
		06/12/89	JCP Geologists Engineers	Addendum to Soil and Foundation Study
		02/26/90	Joseph Parello, Civil Rngineer	Structural Calculations
		03/21/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans for Two Proposed Residences on Lots 18 and 19
		04/02/90	JCP Geologists Engineers	Foundation and Grading Plan Review
		06/11/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kolnes, PA-7765
		08/20/90	William Cotton and Associates	Memo with Comments
		09/12/90	JCP Geologists Engineers	Response to Preliminary Geologic and Geotechnical Review Letter
	768 West California Way		William Cotton and Associates	Geotechnical Review Sheet
		03/06/90	Joseph Parello, Civil Engineer	Structural Calculations, Custom Residence @ Lot 19
		03/21/90	JCP Geologists Engineers	Review of Soil Engineering Aspects of Foundation and Grading Plans for Two Proposed Residences on Lots 18 & 19
		06/11/90	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kolnes, PA 7766
		08/20/90	William Cotton and Associates	Review Notes
	806 West California Way	06/19/08	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Additions
	844 West California Way	12/29/77	Purcell, Rhoades & Associates	Geotechnical Investigation, Lot on Northwest Corner of West California and Jefferson Streets (APN 068-241-180)
27A	WEST GLEN WAY			
	622 West Glen Way	07/07/78	Dunham & Associates	Soil Report
		05/26/98	Nicholas Engineering Consultants	Geotechnical Update, Proposed Residential Addition
		10/15/98	Nicholas Engineering Consultants	Supplemental Information, Proposed Residential Addition
		02/16/04	J. Yang and Associates	Geotechnical Site Investigation, Proposed Residence Remodel
		07/28/04	J. Yang and Associates	Revision, Geotechnical Repost, Proposed Residence Remodel and New Barn
		08/03/09	Murray Engineers, Inc.	Geotechnical Investigation, Site Improvements
	622 West Glen Way	08/03/09	Murray Engineers, Inc.	Geotechnical Investigation, Site Improvements
	625 West Glen Way	06/13/84	Purcell, Rhoades & Associates	Percolation Test Results, Lot 44
		12/01/85	Purcell, Rhoades & Associates	Engineering Geologic and Foundation Recommendations Report, Lot 44
		12/20/85	William Cotton and Associates	Geotechnical Review Sheet
		01/03/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Habenicht, New Home Site
	638 West Glen Way	05/10/07	Romig Engineers, Inc.	Geotechnical Investigation, Brauner Residence Additions
	643 West Glen Way	02/20/78	Howard Donley Associates	Geotechnical and Drainfield Investigation, Single Family Residence, Lots 40 and 41, Block 2, Estates of Emerald Lake Subdivision 1
		08/19/87	Thakore D. Sunderwala, Civil - Structural Engineer	Structural Calculations
		09/22/87	Purcell, Rhodes & Associates	Soils Report Update and Plan Review - Lots 40 and 41, Block 2, Estates of Emerald Lake Subdivision 1
			William Cotton and Associates	Geotechnical Review Sheet
		12/14/87	Purcell, Rhodes & Associates	Plan Review - Lots 40 and 41, Block 2, Estates of Emerald Lake Subdivision 1
		01/11/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Frank, Emerald lake Subdivision, PA #4422

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		03/02/88	Purcell, Rhodes & Associates	Plan Review, Single-Family Residence, Lots 40 and 41, Block 2, Estates of Emerald Lake Subvission 1
		03/03/88	Thakore D. Sunderwala, Civil - Structural Engineer	Suoolemental Structural Calculations
		04/14/88	William Cotton and Associates	Supplemental Geotechnical Review, Lands of Frank, Variance and PA #4422
	650 West Glen Way	01/08/78	William Cotton and Associates	Field Review
		09/15/78	Steve J. Kilimowski	Foundation Investigation, Lot 23 Block 3
		12/20/78	Steve J. Kilimowski	Site Plan, Lot 23, Block 3 Estates of Emerald Lake - Parcel 068-282-030
		01/20/79	William Cotton and Associates	Geologic Review
	657 West Glen Way	11/08/78	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Soil Foundation Investigation, Lots 53 and 36, Block 2, Emerald Lakes Subdivision One
	659 West Glen Way	12/19/06	Romig Engineers, Inc.	Geotechnical Evaluation, Slopes on Chappelle Property
		04/21/08	Romig Engineers, Inc.	Updated Geotechnical Investigation, Chappelle Residence
			Romig Engineers, Inc.	Updated Figure 2 from 4/21/08 Report Showing Grading and Slopes >35%
		08/11/09	Romig Engineers, Inc.	Updated Geotechnical Report, Chappelle Residence
	650 West Glen Way	08/10/09	Romig Engineers, Inc.	Swimming Pool Recommendations, Chappelle Residence
	713 West Glen Way	07/12/05	Murray Engineers, Inc.	Geotechnical Inrvstigation, McDevitt Site Improvements
		07/23/09	Murray Engineers, Inc.	Geotechnical Investigation, McDivitt Residence Improvements
	740 West Glen Way	07/11/95	Earth Investigations Consultants	Geotechnical Design Parameters, Proposed Foundation Rehabilitation, Existing House and Attached Carport
	742 West Glen Way	12/23/05	Earth Investigations Consultants	Limited Soil & Foundation Investigation, Proposed Remodel and Addition
27A	WEST MAPLE WAY			
	447 West Maple Way	02/27/03	Romig Engineers, Inc.	Geotechnical Investigation, Bareket Residence Addition
		06/27/03	Romig Engineers, Inc.	Geotechnical Plan Review, Bareket Rsidence Addition
	470 West Maple Way	12/16/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Site Improvements
	481 West Maple Way	09/30/09	Romig Engineers, Inc.	Removal of Undocumented Fill, Fantelle Property
		11/12/09	Romig Engineers, Inc.	Backfilling of Buker
	482 West Maple Way	12/02/86	Carl W. Garbe, P.E.	Soils and Foundation Report, Proposed Residence
			William Cotton and Associates	Geotechnical Review Sheet
		02/19/88		Structural Calculations
		04/01/88	San Mateo County	Soil Percolation Test Report
		07/25/88	Neil Moore & Associates	Plan Check Comments
		09/26/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Tsukushi, PA #4790
		11/22/88	Carl W. Garbe, P.E.	Geologic and Geotechnical Review, Soils and Foundation Report of December 1987, Proposed Residence
		12/22/88	William Cotton and Associates	Supplemental Geotechnical Review, Tsukushi, PA #4790
	489 West Maple Way	09/21/93	JCP Geologists-Engineers	Soil and Foundation Study, Proposed Additions
		10/25/93	JCP Geologists-Engineers	Addendum, Soil and Foundation Services, Proposed Additions
27A	WHISKEY HILL ROAD			
	225 Whiskey Hill Road	07/03/02	Gilpin Geosciences, Inc.	Preliminary Ground-Rupture Hazard Evaluation
		05/22/03	Gilpin Geosciences, Inc.	Draft Surficial Geology Map
		06/10/03	Treadwell & Rollo	Geotechnical Investigation, Hawk Hill Residence
		01/15/04	Gilpin Geosciences, Inc.	Driveway Fill Slope
		11/15/04	Murray Engineers Inc.	Supplemental Geotechnical Investigation, Hawk Hill Residence
		04/07/05	Murray Engineers Inc.	Supplemental Pier Foundation Recommendations, Hawk Hill Swimming Pool
		06/10/03	Treadwell & Rollo	Geotechnical Investigation, Hawk Hill Residence
	270 Whiskey Hill Road	06/11/03	Steven F. Connelly	Engineering Geology Investigation, Proposed Bridge Upgrade, Balkanski Property
		07/09/03	Nielsen Geotechnical, Inc.	Soil Report
		07/11/03	Nielsen Geotechnical, Inc.	Foundation Recommendations, Bridge Upgrade
		12/05/03	Steven F. Connelly	Fault Investigation, Proposed Cottage, Balkanski Property
		01/08/04	Steven F. Connelly	Response Letter to Town Review of Fault Investigation, Proposed Cottage, Balkanski Property
		02/25/04	Nielsen Geotechnical, Inc.	Revised Drainage Recommendations, Balkanski House
		07/10/04	Murray Engineers Inc	Geotechnical Recommendations, Phase 2 Development, Creekside House
		10/25/04	Murray Engineers Inc	Supplemental Foundation Recommendations, Phase 3 Development, Creekside House
	290 Whiskey Hill Road	05/23/84	Terrasearch, Inc.	Soil and Geologic Investigation, Proposed Marshall Residence Addition
		01/13/87	JCP Geologists-Engineers	Soil and Foundation Study, Proposed Tennis Court
		11/16/87	Harding Lawson Associates	Geotechnical Investigation, Marshall Residence
		11/17/87	Walker & Moody Architects	Site Plan: Caretakers House
			William Cotton and Associates	Geotechnical Review Sheet
		12/14/87	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Marshall, PA #4462 and #4462
		01/13/09	Harding Lawson Associates	Post-Report Consultation, Geotechnical Investigation, Marshall Residence
		01/29/88	Harding Lawson Associates	Post-Report Consultation, Geotechnical Investigation, Marshall Residence (Draft)

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		02/01/88	Harding Lawson Associates	Post-Report Consultation, Geotechnical Investigation, Marshall Residence
		02/02/88	William Cotton and Associates	Geologic and Geotechnical Review, Marshall, PA #4429 and #4462
	300 Whiskey Hill Road	04/20/79	Nordmo Associates	Soil Engineering Services, Proposed Swimming Pool
		12/18/95	Michelucci & Associates, Inc.	Geotechnical Investigation, Landslide, Gates Property
		09/22/03	Nielsen Geotechnical Incorporated	Soil Report
		06/04/04	Murray Engineers	Geotechnical Services, Site Retaining Walls
		04/07/06	Michelucci & Associates, Inc.	Update to 1995 Geotechnical Investigation, Landslide Above Tennis Court
	303 Whiskey Hill Road	07/12/74	Berloger, Long & Associates	Soils Engineering and Engineering Geologic Investigation, Proposed Parcel Split, Single Family Residential Development
		02/15/74	Edwin H. Smith	Preliminary Map, Land Division No. 204, Lands of Chamberlain
		03/08/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed House and Swimming Pool (APN 073-090-540)
27A	310 Whiskey Hill Road	12/01/01	Nielsen Geotechnical Incorporated	Soil Report, New (Replacement) Residence
		10/21/03	Nielsen Geotechnical Incorporated	Soil Report, Proposed Replacement Garage
		04/27/07	Romig Engineers, Inc.	Geotechnical Recommendations, Koppl Garage Remodel
28	410 Whiskey Hill Road	06/30/05	Murray Engineers, Inc.	Geotechnical Investigation, Dressel Barn Renovation
		05/25/07	Murray Engineers, Inc.	Geotechnical Investigation, Dressel Residence
	437 Whiskey Hill Road	04/12/99	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed Smythe Residence
		08/31/99	Freeman-Kern Associates, Inc.	Response to Reviewers Comments
	441 Whiskey Hill Road	07/07/77	Dunham & Associates	Soil Investigation, Lot 3, Land Division Map 232 (APN 073-090-450)
		02/01/05	Ting & Associates, Inc.	(Geotechnical Investigation) Proposed Smythe Addition
		04/25/05	Ting & Associates, Inc.	Response to the Concerns of the Town of Woodside, Proposed Smythe Addition
		11/09/09	Ting & Associates, Inc.	Geotechnical Investigation, Proposed Arbor, Pool Remodel, Decks and Fence Walls
	443 Whiskey Hill Road	08/27/87	Purcell, Rhoades & Associates	Soil Engineering and Foundation Study
		09/28/93	Jo Crosby & Associates	Geotechnical Investigation, Proposed Guest House Site
		04/30/01	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Rosendin Property
	445 Whiskey Hill Road	09/27/10	Murray Engineers, Inc.	Geotechnical Investigation, New Detached Garage, Paterson Family Trust Property
	447 Whiskey Hill Road	05/05/08	Romig Engineers, Inc.	Geotechnical Investigation, Bates Outdoor Arena and Storage Building
		05/11/09	Romig Engineers, Inc.	Geotechnical Response Bates Barn Renovation
		05/12/09	Romig Engineers, Inc.	Piers for Site Retaining Wall Bates Barn Renovation
	449 Whiskey Hill Road	02/08/07	Neil O. Anderson	Geotechnical Investigation Addendum
		02/17/07	Neil O. Anderson	Geotechnical Investigation Addendum
	450 Whiskey Hill Road	06/08/81	Earth Systems Consultants	Geotechnical Investigation, Pool House Addition, Blokker Residence
		08/09/04	Murray Engineers Inc.	Geotechnical Investigation, Deck Reconstruction, Blokker Residence
		05/13/08	Murray Engineers Inc.	Limited Geotechnical Investigation, Residence Addition
	457 Whiskey Hill Road	10/13/06	Murray Engineers, Inc.	Geotechnical Investigation, New Residence
		06/15/09	Murray Engineers, Inc.	Geotechnical Report Update, New Residence
	485 Whiskey Hill Road	02/28/07	Murray Engineers, Inc.	Geotechnical Investigation, Peterson Residence
		02/27/04	Town	Aerial and Ground Photos
	490 Whiskey Hill Road	10/26/09	Murray Engineers, Inc.	Geotechnical Investigation, Residence Improvements
	550 Whiskey Hill Road	06/10/08	Clearly Consultants, Inc.	Geotechnical Investigation, New Residence
	580 Whiskey Hill Road	05/22/86	Upp Geotechnology, Inc.	Geotechnical Investigation, Lands of Kahl
			William Cotton and Associates	Geotechnical Review Sheet
		07/20/86	SEDCO Structural Engineering & Development	Structural Calculations
		12/05/86	Upp Geotechnical, Inc.	Review of Foundation Plans, Single Family Home, Lands of Kahl
		01/16/97	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Kahl Residence, PA 3225
	590 Whiskey Hill Road	03/13/99	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence, Dali Property
	610 Whiskey Hill Road	06/27/79	PSC Associates, Inc.	Geologic and Soil Engineering and Foundation Investigation, Hewes
		07/20/79	PSC Associates, Inc.	Remodeling Plan Review - Proposed Building Additions
		07/26/79	William Cotton and Associates	Geotechnical Review Sheet
		07/27/79	William Cotton and Associates	Hewes - Geotechnical Review
		06/18/87	Clearly Consultants, Inc.	Soil and Foundation Investigation, Additions to Hewes Residence
		06/08/04	Charles H. Hartzog	Soils Report
		09/07/04	Charles H. Hartzog	Soil / Geotechnical Report Only
28	WHY WORRY LANE			

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	Why Worry Subdivision #148	08/01/86	Upp Geotechnology, Inc.	Geotechnical Feasibility Investigation
	20 Why Worry Lane	06/26/90	Upp Geotechnology, Inc.	Geotechnical Investigation, Lot 2 - Why Worry Farm Subdivision
	100 Why Worry Lane	05/09/00	Bay Area Geotechnical Consultants	Geologic Evaluation & Geotechnical Investigation, Proposed Building Remodel, Liautaud Residence
		09/14/02	Bay Area Geotechnical Consultants	Geotechnical Consultation, Proposed Generator Vault, Kelley
		05/04/07	Bay Area Geotechnical Consultants	Update to Geotechnical Engineering Investigation
		02/25/09	Murray Engineers, Inc.	Geotechnical Investigation, Proposed Pool House/Guesthouse
28	WILDWOOD WAY			
	115 Wildwood Way	10/26/11	Milstone Geotechnical	Geotechnical Investigation, Proposed Ferrari Residence
28	WINDING WAY			
	101 Winding Way	06/14/99	Bay Area Geotechnical Group	Geotechnical Investigation, Proposed Residential Addition
		08/26/03	Bay Area Geotechnical Group	Addendum to Geotechnical Engineering Investigation, Proposed Swimming Pool, Ballinger Residence
	201 Winding Way	06/06/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed Site Improvements
		08/02/99	Earth Investigations Consultants	Geotechnical Report Update and Plan Review, Proposed House Addition
	225 Winding Way	10/29/85	Earth Investigations Consultants	Geotechnical Study, Williams Property
		05/08/85	Town of Woodside	Letter to Owner Williams regarding problems with landslide and repair activities and associated erosion
		11/15/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Williams Landslide Repair
		01/15/86	William Cotton and Associates	Notes of Site inspection and conversations with geotec and landscape architect - repair not inspected by geotec.
		01/20/86	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Williams Landslide Repair
		08/01/11	Neil O. Anderson	Geotechnical Investigation, Kissick Swimming Pool Renovation
	233 Winding Way	08/20/74	Berloger, Long & Associates	Fault Investigation, Vaughn Property (APN 072-221-230)
		04/11/97	Pacific Geotechnical Engineering	Geotechnical Investigation, Proposed Improvements, Lacob Property
		10/28/04	Westfall Engineers, Inc.	Structural Calculations, New Barn
		04/26/10	Murray Engineers, Inc.	Geotechnical Investigation, Andrews Residence
	235 Winding Way	06/05/09	Romig Engineers, Inc.	Geotechnical Investigation, Juelsgaard Residence
	250 Winding Road	02/22/08	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Residential Storage Shed
		03/11/08	Michelucci & Associates, Inc.	Review of Plans, Proposed New Storage Shed
		08/18/08	Michelucci & Associates, Inc.	Pavement Recommendations, Adjacent to Proposed New Storage Shed
	250 Winding Road	08/28/08	Michelucci & Associates, Inc.	Summary Review of Plans, Proposed New Storage Shed
	290 Winding Way	10/27/86	Freeman-Kern Associates, Inc.	Geotechnical Investigation, Proposed Addition
		08/08/89	BFL	Entrance Gate
28	WOODHILL DRIVE			
	75 Woodhill Drive	03/07/08	Murray Engineers, Inc.	Geotechnical Investigation, Dearborn Residence Improvements
28	WOODSIDE DRIVE			
	135 Woodside Drive	06/16/10	Romig Engineers, Inc.	Geotechnical Investigation, Schemers Swimming Pool, Pool House, and Addition
	170 Woodside Drive	05/24/11	Romig Engineers, Inc.	Geotechnical Investigation, Lashkoff Residence Addition, Garages, and InLaw Unit
	215 Woodside Drive	05/13/02	Nielsen Geotechnical Incorporated	Soil Report
	225 Woodside Drive	05/20/96	Nielsen Geotechnical, Incorporated	Soil Report
	235 Winding Way	06/05/09	Romig Engineers, Inc.	Geotechnical Investigation, Juelsgaard Residence
	245 Woodside Drive	02/04/91	Michelucci & Associates, Inc.	Geotechnical Investigation, Distressed Goodmanson Residence
		03/03/93	Michelucci & Associates, Inc.	Geotechnical Investigation, Distressed Goodmanson Residence
	265 Woodside Drive	01/30/02	GeoForensics Inc.	Geotechnical Investigation, Proposed Residential Additions
		10/06/06	Romig Engineers, Inc.	Geotechnical Investigation, Residence Improvements
		09/07/10	Romig Engineers, Inc.	Supplemental Geotechnical Recommendations, Van Der Linde Residence
		07/29/11	Romig Engineers, Inc.	Geotechnical Plan Review, Residence Repair Plans
		09/20/11	Romig Engineers, Inc.	Supplemental Recommendations, Residence Repair Plans
	275 Woodside Drive	06/22/99	Dunham & Associates	Geotechnical Engineering Investigation, Proposed Additions and Garage
	285 Woodside Drive	04/11/94	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Single-Family Residence
		01/03/11	Romig Engineers, Inc.	Geotechnical Investigation, Livermore Exercise Studio
		05/12/11	Romig Engineers, Inc.	Response to Geologic Review, Livermore Exercise Studio

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	315 Woodside Drive	04/12/05	Frank Lee & Associates	Soil and Foundation Investigation, Proposed Two-Story Addition
		06/06/05	Frank Lee & Associates	Supplemental Design and Construction Recommendations, Swimming Pool
		10/03/05	Frank Lee & Associates	Addendum to Soils and Foundation Report, Proposed Two-Story Additions
		05/03/06	Frank Lee & Associates	Addendum 2 to Soils and Foundation Report, Proposed Two-Story Additions
		12/20/05	Frank Lee & Associates	Driveway Recommendations, Proposed Two-Story Additions
		12/19/06	Frank Lee & Associates	Foundation Plan Review
	335 Woodside Drive	03/10/97	Steven A. Arnold	Site Inspection
		06/06/97	Cleary Consultants, Inc.	Geotechnical Investigation, Planned Master Bedroom Addition
	435 Woodside Drive	10/31/96	Nielsen Geotechnical Incorporated	Soil Report, Gabion Retaining Wall
		11/22/99	Earth Investigations Consultants	Geotechnical Investigation, Fill Slope Stability Improvements
		05/06/00	GeoForensics, Inc	Geotechnical Investigation to Address Slope Stability, Dorsey Property
		10/15/02	GeoForensics, Inc	Response to Town Review, Proposed Slope Repair
		05/07/03	Baker - CEG	Engineering Geologic Evaluation Response to Comment #1), Proposed Slope Restoration
		06/06/03	GeoForensics, Inc	Response to Town Review (#3)
		07/29/03	GeoForensics, Inc	Plans (Drawings GF-1 to 3)
		09/25/03	GeoForensics, Inc	Plate 2 Transmittal
	520 Woodside Drive	11/16/04	Friar Associates, Incorporated	Soil Bearing Capacity, Existing Garage Structure
		08/01/05	Friar Associates, Incorporated	Foundation Design Information, Existing Garage Structure
		12/15/05	Friar Associates, Incorporated	Response Letter, Proposed Tennis Court
		11/06/06	Friar Associates, Incorporated	Proposed Garage Structure
		04/30/08	Friar Associates, Incorporated	Proposed Garage Addition
	565 Woodside Drive	05/20/95	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions
	640 Woodside Drive	07/27/93	Lowney Associates	Geotechnical Investigation, Hepper Residence
28	645 Woodside Drive	02/02/96	Romig Consulting Engineers	Geotechnical Study, Pool House Addition
29	650 Woodside Drive	12/23/97	Alcon Engineering	Response to Plan Check Comments
	665 Woodside Drive	09/26/94	Nielsen Geotechnical Incorporated	Soil Report
		04/08/96	Nielsen Geotechnical Incorporated	Supplemental Geotechnical Information, Proposed Additio/Remodel and Retaining Wall
	710 Woodside Drive	08/14/03	Ting & Associates, Inc.	Foundation Recommendations, Proposed Addition
		07/07/06	Murray Engineers, Inc.	Geotechnical Investigation, Louie Residence
		08/14/06	Murray Engineers, Inc.	Supplemental Recommendations, Driveway Pavement, Louie Residence
	746 Woodside Drive	09/04/90	Jo Crosby & Associates	Geotechnical Investigation, Distress to the Residence
		10/24/90	Robert Lyon Associates	Plans, with annotations
		12/11/90	Jo Crosby & Associates	Foundation Repair Plan Review, Shaw Residence
			William Cotton and Associates	Geotechnical Plan Review
	805 Woodside Drive	05/03/94	Haro, Kasunich and Associates, Inc.	Geotechnical Reconnaissance (APN 069-150-056)
		08/12/94	Haro, Kasunich and Associates, Inc.	Geotechnical Investigation
	809 Woodside Drive	01/22/08	Buckley Engineering Associates, Inc.	Geotechnical Investigation, Proposed New Residence
	811 Woodside Drive	11/22/01	Earth Investigations Consultants	Geotechnical Investigation, Proposed Basement Addition
	850 Woodside Drive	05/21/02	Nielsen Geotechnical Incorporated	Soil Report
	851 Woodside Drive	11/05/01	Nielsen Geotechnical Incorporated	Foundation Recommendations
		10/20/03	Nielsen Geotechnical Incorporated	Review of Foundation Conditions
		12/03/03	Nielsen Geotechnical Incorporated	Construction Report, House Remodel
29	WOODSIDE ROAD			
	Village Hill	02/28/74	Whisler-Patri	Exhibits to Application for Conditional Use Permit for Village Hill Property
		01/21/74	Lowney-Kaldveer Associates	Preliminary Geotechnical Investigation, Lincoln Hill Office Building
		03/10/74	William R. Cotton	Review of Village Hill Preliminary Geotechnical Investigation Report
	2300 Woodside Road	10/11/02	Bay Area Geotechnical Group	Geotechnical Engineering Investigation, Proposed Terrace Remodel, Menlo Country Club
	2360 Woodside Road	12/27/95	Lee Engineers	Geotechnical Investigation, Guest House
		02/07/96	Lee Engineers	Addendum to Geotechnical Investigation, Guest House
		05/24/03	Lee Engineers	Soil Investigation, House Addition
	2879 Woodside Road	10/08/02	Sigma Prime Geosciences, Inc.	Engineering Geologic and Geotechnical Report for Proposed Residence

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	HALDEN / HAWK HILL SUBDIVISION - 2883 and 2884 Woodside Road			
	2883 Woodside Road	10/06/88	Applied Earth Sciences Investigations	Location of Existing On-Site Sewage Disposal System and Preparation of Recommendations to Upgrade the System
		04/02/89	Applied Earth Sciences Investigations	Soil and Geologic Investigation, Proposed New Garage Location
		04/19/89	Applied Earth Sciences Investigations	Foundation Addition for the Remodel of the Existing Single Family Residence
		04/25/89	Applied Earth Sciences Investigations	Observation of Pier Drilling, New Pier and Grade Beam Foundations, New Additions to Existing Residence
		05/29/90	Applied Earth Sciences Investigations	Final Inspection, New Foundation Construction, Remodel to Existing Residence
		08/31/91	Brian Kangas Foulk	Conceptual Map - Tentative Map, Lands of Haldan
			William Cotton and Associates	Geotechnical Review Sheet
		09/10/91	Brian Kangas Foulk	Natural Land Feature Study
		11/11/91	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Halden, Subdivision #151
		12/08/91	GeoForensics Inc.	Geotechnical Observations of Leach Field Test Excavations, Four Proposed Lots
		12/12/91	GeoForensics Inc.	Geotechnical Investigation for Proposed Subdivision
		01/14/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Halden / Hawk Hill Subdivision #151
			Cultural Resource Planning	Cultural Resource Assessment
		02/17/92	GeoForensics Inc.	Geotechnical and Geologic Response to Issues Raised by Town Geologist, Proposed Residential Site
		03/30/92	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Halden / Hawk Hill Subdivision #151
		04/07/92	GeoForensics Inc.	Report Clarification, Proposed Residential Sites
		07/20/92	Oswald G. Villard	Letter to Planning Commission regarding Halden Subdivision
		09/01/93	Mills Associates	Draft Focused Environmental Impact Report, Hawk Hill Subdivision
		11/01/93	Mills Associates	Response to Comments, Hawk Hill Subdivision EIR
		08/01/94	Mills Associates	Addendum, Hawk Hill Subdivision EIR
	2887 Woodside Road	04/07/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Remodeling and Seismic Upgrade Project
		05/11/06	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed House Modifications and New Spa
		06/11/07	Michelucci & Associates, Inc.	Supplemental Recommendations and Design Criteria, Proposed Swimming Pool and Related Exterior Improvements
29	2891 Woodside Road	07/29/98	Nielsen Geotechnical Incorporated	Foundation Recommendations, Barn
		02/15/99	John Coyle & Associates, Inc.	Limited Geologic Reconnaissance, Lower Area, Maroney Property
		03/08/99	Nielsen Geotechnical Incorporated	Soil Report
		06/29/07	Murray Engineers, Inc.	New Engineer of Record & Supplemental Recommendations, New Cabana
29A	2905 Woodside Road	05/07/92	JCP Geologists - Engineers	Letter Geologic and Soil & Foundation Study, Proposed Home (APN 073-090-170)
		03/12/93	JCP Geologists - Engineers	Additional Recommendations, Pier Foundation Design, Proposed Home
		04/22/93	JCP Geologists - Engineers	Addendum - Letter Geologic and Soil & Foundation Study, Proposed Home (APN 073-090-170)
	2907 Woodside Road	11/03/09	Sigma Prime Geosciences, Inc.	Geotechnical Study, Kamara Property
	2909 Woodside Road	10/01/02	Carl W. Garbe, P.E.	Soil & Foundation Report, Proposed Emergency Generator
		02/05/10	Romig Engineers, Inc.	Geotechnical Investigation, Residence Remodel & Site Improvements
	2915 Woodside Road	07/18/97	Associated Terra Consultants, Inc.	Soils and Foundation Investigation, Lands of Siebel
	2925 Woodside Road	05/13/94	Earth Investigations Consultants	Geotechnical Evaluation, Proposed Additions to Pioneer Building
	2934 Woodside Road	06/12/05	Wayne Ting & Associates, Inc.	Foundation Recommendations, Proposed Remodeling
		08/24/05	Wayne Ting & Associates, Inc.	Supplemental Desing Recommendations
	2955 Woodside Road	08/30/00	Nielsen Geotechnical Incorporated	Soil Report, Community House
		09/25/03	Nielsen Geotechnical Incorporated	Construction Report, Woodside Community House
	2955 Woodside Road	08/23/89	William Cotton and Associates	Geotechnical Investigation, Town Hall Site
		11/11/89	Town of Woodside	Building Requirements, Contract Conditions, and Specifications
	2965 Woodside Road	08/02/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed 2-Story Office Building (APN-073-112-320)
	2967 / 2969 Woodside Road	07/21/98	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel and Expansion
	2991 / 2995 Woodside Road	01/18/79	Geoconsultants, Inc.	Geological Reconnaissance and Geophysical Survey, Proposed Comercial Complex
		01/24/79	Howard Donley Associates, Inc.	Geotechnical Investigation, Fault Investigation of Canada Fault
		02/15/80	Donald A. Woolfe and Associates	Environmental Impact Report, Gilbert Project: Retail, Office and Service Facilities
		03/18/80	William Cotton and Associates	Review of Preliminary Site Plan - Gilbert Center
		10/06/80	Howard Donley Associates, Inc.	Soil and Foundation Investigation, Proposed Shopping Center - Gilbert Center
		10/29/80	William Cotton and Associates	Geotechnical Review Sheet
		11/11/80	William Cotton and Associates	Review of 10/6/80 HD&A report
	3015 Woodside Road	07/25/85	JCP Geologists Engineers	Soil and Foundation Services, Proposed Addition to Robert's Grocery
	3050 Woodside Road	08/27/76	Howard F. Donley & Associates	Feasibility Level Geotechnical Investigation, Proposed Canada Corners Shopping Complex and Land to North
		09/09/76	Leighton and Associates, Town of Woodside	Geotechnical Review of above
		01/24/78	Town Staff	Report to Planning Commission, Conditunal Use Permit 80-81 - Canada Corners
	3100 Woodside Road	06/13/95	Michelucci & Associates, Inc.	Geotechnical Evaluation of "Point Bar" Creek Bank Erosion Mitigation Project, Weinstein Property

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
	3105 Woodside Road	02/15/08	Romig Engineers, Inc.	Geotechnical Investigation, Ehikian Residence Improvements
	3111 Woodside Road	06/13/90	J. V. Lowney & Associates	Geotechnical Investigation, Woodside Fire Station
	3140 Woodside Road	04/06/11	PGSoils, Inc.	Geotechnical Investigation, Proposed Upgrades, Woodside Library Building
	3145 Woodside Road	05/31/00	Michelucci & Associates, Inc.	Geotechnical Investigation, Proposed Addition
	3180 Woodside Road	06/24/94	Robert B. Rogers, P.E., M. Eng.	Foundation Investigation, New Residence and Garage
	3195 Woodside Road	09/01/88	William F. Jones, Inc.	Soil Investigation, Proposed Relocation, Woodside School Library
		10/11/93	Lowney Associates	Geotechnical Investigation, Woodside Elementary Classroom Addition
		11/25/97	Lowney Associates	Geotechnical Investigation, Multi-purpose and Classroom Buildings, Woodside Elementary School
		03/23/00	Lowney Associates	Supplemental Geotechnical Investigation and Geologic Hazards Evaluation, Woodside Elementary School Improvements
	3204 Woodside Road	05/29/00	Nielsen Geotechnical Incorporated	Soil Report
		03/07/01	Nielsen Geotechnical Incorporated	Plan Review, Jenkins House Restoration & Addition
		04/15/01	Nielsen Geotechnical Incorporated	Footing Observations, Addition
		09/15/01	Nielsen Geotechnical Incorporated	Plan Review - 2
		09/16/04	Nielsen Geotechnical Incorporated	Construction Report
	3324 Woodside Road	09/02/99	Romig Engineers, Inc.	Geotechnical Investigation, Brown Residence Improvements
		05/09/08	Romig Engineers, Inc.	Geotechnical Investigation, Brown Swimming Pool
	3370 Woodside Road	05/23/97	Upp Geotechnology, Inc.	Geotechnical Investigation, New Residence and Office, Thieriot Property
	3373 Woodside Road	12/10/09	Murray Engineers, Inc.	Geotechnical Investigation, Sculley Residence
	3383 Woodside Road	09/16/04	Earth Investigations Consultants	Geotechnical Investigation, Proposed Residential Addition
	3411 & 3417 Woodside Road	02/27/07	Murray Engineers, Inc.	Geotechnical Investigation, Bear Gulch Creek Partners Property
		11/08/07	Murray Engineers, Inc.	Supplemental Recommendations, Proposed Swimming Pool, Bear Gulch Creek Partners Property
29A	3445 Woodside Road	09/28/78	Purcell, Rhoades & Associates	Geotechnical Hazard Evaluation and Soils Foundation Investigation, Parcel Fronting Woodside Road, Bear Gulch and West Union Creeks
		7/0/78	Fred Blomquist & Associates	Site Plan
		10/16/78	William Cotton and Associates	Field Review Notes
		11/07/78	William Cotton and Associates	Geotechnical Review: Martinez - Conformity
30	3480 Woodside Road	12/06/96	Earth Investigations Consultants	Geologic Investigation, Fault Location, Proposed Single Family Residence Development
		05/09/97	Earth Investigations Consultants	Geological Services, Supplemental Fault Investigation, Proposed New Residence
		05/15/97	Earth Investigations Consultants	Geotechnical Investigation, Proposed New Residence
		05/18/99	Earth Investigations Consultants	Wet Weather Test Hole Locations, Proposed House
		06/10/99	Earth Investigations Consultants	Subdrain and Observation Well Abandonment
		04/26/00	Earth Investigations Consultants	Supplemental Geotechnical Investigation, Proposed House
		01/30/02	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Pool and Spa
		05/09/03	Earth Investigations Consultants	Geotechnical Investigation Update
		10/06/03	Earth Investigations Consultants	Soil and Foundation Investigation, Proposed Site Improvements
		03/09/04	Earth Investigations Consultants	Geotechnical Clarification, Proposed Pool and Adjoining Terrace
		05/20/04	Earth Investigations Consultants	Geotechnical Parameters, Mat Slab for Proposed Barn and Conservatory
	3500 Woodside Road	06/17/98	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence
		11/28/00	GeoForensics, Inc.	Pool Recommendations
		06/07/04	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Water Feature and Meditation Structure
	3555 Woodside Road	08/11/87	Upp Geotechnology, Inc.	Fault Location Study, Additions to Residence, Lands of Alexander
		08/21/87	Upp Geotechnology, Inc.	Supplemental Information, Fault Location Study, Additions to Residence, Lands of Alexander
	3585 Woodside Road	09/25/98	Upp Geotechnology, Inc.	Geotechnical Investigation, Proposed New Residence, Lands of Alexander
		08/22/01	Upp Geotechnology, Inc.	Supplemental Recommendations, Proposed Swimming Pool, Alexander Property
		10/25/01	Upp Geotechnology, Inc.	Construction Observation, Residence and Garage, Alexander Property
		06/14/02	Upp Geotechnology, Inc.	Construction Observation, Swimming Pool, Alexander Property
	3610 Woodside Road	05/02/84	Edward Dominion	Plot Plan and Details, with annotations
		05/22/84	Perry R. Wood	Soil Percolation Tests and Recommended Septic Drainfield
		05/30/84	Terratech, Inc.	Geologic Investigation, Lands of Jelincich
		05/31/84	Terratech, Inc.	Review of Foundation Plans, Additions to Jelincich Residence
		06/06/84	William Cotton and Associates	Geotechnical Review Sheet
		06/11/84	Terratech, Inc.	Supplemental Information and Addendum to Plans, Jelincich Property
		06/14/84	William Cotton and Associates	Preliminary Geologic Review, Jelincich Additions
		10/10/84	Freeman-Kem Associates, Inc.	Geologic and Geotechnical Investigation, 4.98 Acres
		10/17/10	Edward Dominion	Structural Calculations
		11/24/84	Freeman-Kem Associates, Inc.	Plan Review

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		11/08/84	William Cotton and Associates	Preliminary Geologic Review, Jelincich
		11/27/84	Freeman-Kern Associates, Inc.	Plan Review, Drainage Plans
	3620 Woodside Road	03/22/99	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Guest House and Residence, Cromwell & Chiaro Property
		04/26/00	GeoForensics, Inc.	Basement Design Parameters, Proposed New Residence
		05/01/02	GeoForensics, Inc.	Recommendations for Landscaping Walls, Proposed New Residence
		11/11/02	GeoForensics, Inc.	Recommendations for Pool Construction, Proposed New Residence
	3665 Woodside Road	09/23/83	Purcell, Rhoades & Associates	Soils and Foundation Study - Swimming Pool, Hoffacker Residence
		07/15/83	Anthony Pools	Site Plan, with annotations
		08/30/83	William Cotton and Associates	Geotechnical Review Sheet
		09/13/83	William Cotton and Associates	Geologic Review, Hoffacker Pool
		10/18/83	William Cotton and Associates	Engineering Geologic Review, Hoffacker Pool
	Woodside Road at Oakhill Drive	03/10/09	William Cotton and Associates	Geotechnical Investigation, California Water Service Company, Station 16, Woodside Reservoir
	3784 Woodside Road	11/29/84	Jo Crosby & Associates	Geotechnical Report, Slope Failure
		09/09/85	Jo Crosby & Associates	Preliminary Plan Review, Proposed Addition
		10/03/85	Robelo / Kocjan Associates, Inc.	Structural Calculations
		10/31/85	Jo Crosby & Associates	Completion Report - Consultation and Slope Support Recommendations
		11/05/85	William Cotton and Associates	Geotechnical Review Sheet
		11/22/85	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Braniff
		02/25/11	Romig Engineers, Inc.	Geotechnical Study, Sadlier Site Retaining Walls
	3787 Woodside Road	09/13/96	GeoForensics, Inc.	Geotechnical Investigation, New Residence, Lego Property
	3789 Woodside Road	11/14/01	Nielsen Geotechnical Incorporated	Geotechnical Recommendations, Remodel of Existing Barn
		11/11/02	Nielsen Geotechnical Incorporated	Soil Report
		03/11/03	Nielsen Geotechnical Incorporated	Construction Report, Barn Remodel
		06/25/04	Nielsen Geotechnical Incorporated	Review of Project Plans, Jordan-Bennett House
		08/03/04	Nielsen Geotechnical Incorporated	Construction Report, Grading
		08/09/04	Murray Engineers, Inc.	New Engineer of Record, New Residence
		09/15/04	Murray Engineers, Inc.	Supplemental Information, Geotechnical Investigation, Proposed Guest House
	3799 Woodside Road	06/26/98	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation, Proposed Creek Bank Stabilization, Momsen Property
		03/28/07	Murray Engineers, Inc.	Geotechnical Investigation, Open Water South Property Improvements
		01/10/08	Murray Engineers, Inc.	Supplemental Liquefaction Evaluation, Open Water South Property Improvements
		06/26/08	Murray Engineers, Inc.	Supplemental Foundation Recommendations, Open Water South Property Improvements
	3860 Woodside Road	03/30/11	Romig Engineers, Inc.	Geotechnical Recommendations, Clabert Residence Remodel
		04/13/11	Romig Engineers, Inc.	Response to Geologic Review, Clabert Residence Remodel
		08/24/11	Romig Engineers, Inc.	Geotechnical Recommendations, Pool Heaters and Propane Tanks
30	3875 Woodside Road	04/21/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed Residential Additions
		12/31/97	Upp Geotechnology, Inc.	Limited Soil and Foundation Investigation, New Guest House, Lands of Solomon
		02/10/98	Upp Geotechnology, Inc.	Response to Geological and Geotechnical Review, New Guest House, Lands of Solomon
30A	3970 Woodside Road	10/15/99	Terrasearch, Inc.	Geotechnical Investigation, Proposed New Residence
		03/05/01	Terrasearch, Inc.	Supplemental Letter/Report, proposed New Residence
	4105 Woodside Road	11/10/69	Crosby & Associates	Soil and Geologic Investigation, Proposed Forest Glade Estates
		04/16/74	Geolabs - Northern California, Inc.	Magnetometer Survey, Proposed Forest Glade Estates
		06/21/74	Geolabs - Northern California, Inc.	Subsurface Investigation of Splinter Fault Trace
		07/25/77	Richard E. Rowland	Geologic Report, Portion of Hume Property
		09/14/77	Dunham & Associates	Soil Investigation, Hume, Woodside Road, Woodside
		11/02/77	Leighton and Associates	Review of above 2 reports
		11/22/77	Town Staff	Report to Planning Commission on Hume
		10/14/97	Lowney Associates	Geotechnical and Geologic Hazard Investigation, Hume Residence
		01/22/99	Jo Crosby & Associates	Review of the Geological and Geotechnical Data, Proposed Parcel B, 3 Lot Subdivision, Gilo and Hume Subdivision
		02/05/99	Lowney Associates	Geologic Review of Potential Fault Rupture Hazards, Hume Residence
	4155 Woodside Road	07/24/78	Cooper Clark & Associates	Evaluation of an Inferred Type "C" Fault Trace, Portion of Land Division #227
		01/07/81	Cooper Clark & Associates	Discussion of 1978 Fault Investigation
		07/05/84	Perry R. Wood	Potential Geologic Hazard Posed by Sliver Fault of the San Andreas Fault System, and Potential Erosion Hazard Along Drainage Courses
		10/18/85	Testing Engineers, Inc.	Compaction Test Results
		04/10/86	PSC Associates, Inc.	Geotechnical Engineering Investigation, Lot 1, Land Division No. 265
		07/14/86	PSC Associates, Inc.	Foundation Plan Review Letter, Proposed Residence, Lot 1, Land Division 265
		07/18/86	PSC Associates, Inc.	Geotechnical Observation of Foundation Pier Drilling, Lot 1
		02/02/87	PSC Associates, Inc.	Geotechnical Observation of Site Drainage and Results of Density Testion Services for Paved Areas, Lot 1
		4/31/88	Carl W. Garbe, P.E.	Soils & Foundation Report, Proposed Swimming Pool, Tennis Court, Cabana
			William Cotton and Associates	Geotechnical Review Sheet
		05/24/88	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Feeney Pool, Tennis Court and Cabana, PA #4652, #4924, and #4671
		06/08/88	Carl W. Garbe, P.E.	Review of Plans, Proposed Swimming Pool

BOX	ADDRESS	DATE	PREPARED BY:	TITLE
		06/21/88	Carl W. Garbe, P.E.	Daily Field Report (Compaction Tests)
		06/30/88	Carl W. Garbe, P.E.	Preliminary Geologic & Geotechnical Review, Proposed Pool, Tennis Court, Cabana
	4175 Woodside Road	07/24/78	Cooper Clark & Associates	Evaluation of an Inferred Type "C" Fault Trace, Portion of Land Division #227
		01/07/81	Cooper Clark & Associates	Discussion on Additional Fault Investigation
		03/26/81	PSC Associates, Inc.	Soil Engineering Investigation, Proposed Residence, Parcel 2 (Land Division No. 265)
			Frederick R. Strathdee	Site/Grading Plan
		04/10/86	PSC Associates, Inc.	Geotechnical Engineering Report Update, Lot 2, (Land Division No. 265
		07/31/86	PSC Associates, Inc.	Grading and Foundation Plan Review for Lot 2 (Land Division No. 265)
		08/26/86	PSC Associates, Inc.	Letter Report - Geologic Fault Investigation, Lot 2 (Land Division No. 265)
		10/01/86	William Cotton and Associates	Geotechnical Review Sheet
		10/20/86	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Wilson Development
	5000 Woodside Road	09/11/90	Jo Crosby & Associates	Remedial Work, Coral Area
		09/12/90	Gene Kunit & Associates	Grading & Drainage Plan
		09/13/90	David Allen Henderson	description of proposed project
		09/14/09	David Allen Henderson	grading quantities
		08/03/04	Milstone Geotechnical	Geotechnical Investigation, Proposed Improvements, McDade Residence
		09/29/04	Milstone Geotechnical	Response to Town of Woodside Geotechnical Review Comments, Proposed Improvements
	5001 Woodside Road	02/22/08	Murray Engineers, Inc.	Geotechnical Investigation, Dearborn Stables
30A	WOODSIDE WAY			
	610 Woodside Way	04/14/99	Earth Investigations Consultants	Geotechnical Investigation, Proposed Remodel/New House
		08/31/00	Earth Investigations Consultants	Engineering Geologic Evaluation, Proposed Leachfield, Proposed New Residence
	620 Woodside Way	01/15/81	Purcell, Rhoades & Associates	Results of Percolation Tests, Lot 17, Block 201, Emerald Lake Estates
		01/26/96	Bay Area Geotechnical Group	Foundation Investigation, Proposed Single-Family Residence
		10/24/97	Bay Area Geotechnical Group	Proposed Septic System and Existing French Drain
		11/21/97	Bay Area Geotechnical Group	Proposed French Drain Collection of Shallow Subsurface Seepage
		07/06/98	Questa Engineering Corporation	Septic System Review
		08/11/98	Questa Engineering Corporation	Drainage Plans
		04/23/99	Bay Area Geotechnical Group	Geotechnical Review of Development Plans
		07/17/03	Bay Area Geotechnical Group	Geotechnical Report Update and Plan Review, Proposed Deck and Cabana
	623 Woodside Way	02/26/80	Purcell, Rhoades & Associates	Percolation Test Results, Combined Lots 11, 12, and 13, and Combined Lots 9 and 10, Estates of Emerald Lake
		04/25/85	TransPacific Geotechnical Engineers, Inc.	Geotechnical Investigation, Proposed Hurley Residence
		8/0/85	Monarch Associates, Inc.	Plot Plan for Robert Hurley, with annotations
		08/13/85	Purcell, Rhoades & Associates	Site Evaluation and Percolation Field Update for Lots 9 and 10
		08/20/85	County of San Mateo, Department of Health Services	Comments on 8/13/85 PRA letter
		09/16/85	Steve Deal Associates	Supplemental Subsurface Study
		09/20/85	William Cotton and Associates	Geotechnical Review Sheet
		09/20/11	William Cotton and Associates	Preliminary Geologic and Geotechnical Review, Lands of Hurley, Variance 388
		10/02/85	Purcell, Rhoades & Associates	Leachfield Evaluation Update for Lots 9 and 10
		10/15/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Lands of Hurley, Variance 388
		06/02/86	Arthur Keyes Architect	Letter to Town Staff Regarding Change in Drainfield Location
		07/18/94	Earth Investigations Consultants	Geotechnical Investigation
	629 Woodside Way	02/26/80	Purcell, Rhoades & Associates	Percolation Test Results, Combined Lots 11, 12, and 13, and Combined Lots 9 and 10, Estates of Emerald Lake
	635 Woodside Way	02/26/80	Purcell, Rhoades & Associates	Percolation Test Results, Combined Lots 11, 12, and 13, and Combined Lots 9 and 10, Estates of Emerald Lake
	638 Woodside Way	10/28/03	Earth Investigations Consultants	Geotechnical Investigation, Proposed Garage and Deck Additions
	642 Woodside Way	06/06/94	Michelucci & Associates, Inc.	Geotechnical Engineering Investigation
	643 Woodside Way	12/09/10	Earth Investigations Consultants	Geotechnical Investigation, Proposed Lower Story Room Addition
30A	WOODVIEW LANE			
	5 Woodview Lane	11/05/96	GeoForensics, Inc.	Geotechnical Investigation, Proposed New Residence and Pool, Andrighetto Property
		08/14/97	GeoForensics, Inc.	Response to Town Geotechnical Review, Andrighetto Property
		05/01/98	GeoForensics, Inc.	Supplementary Evaluation, Andrighetto Property
	15 Woodview Lane	10/19/90	Purcell, Rhoades & Associates	Evaluation of the Hazards of Surface Rupture, Proposed Home Conversions
	35 Woodview Lane	08/15/85	Raymond Pestrong	Geologic Investigation, Gamble Property
		09/25/85	Purcell, Rhoades & Associates	Soil and Foundation Study, Pool House
		09/04/85	William Cotton and Associates	Geotechnical Review Sheet
		09/18/85	William Cotton and Associates	Preliminary Geologic Review, Gamble, APN 076-302-110
		10/11/85	William Cotton and Associates	Supplemental Geologic and Geotechnical Review, Gamble Pool House, APN 076-302-110
		04/23/07	William M. McMorrow	Geotechnical Engineering Evaluation & Plan Review, Proposed Additions & Alterations, Hanham Residence

